

Duty to Investigate												
Section 19 Investigations												
Lincolnshire County Council Section 19 Investigations - Boston Borough Council & South Holland District Council Network Area - Area Highways Manager Andy Wharff (South)												
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Risk Management Authorities with Responsibilities and whether they are exercising functions	Proposed Action/Works	Consideration for inclusion in future Common Works Programme	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
6 July 2012	Donington	Quadring Road - PE11 4TB	The footway along the front of the property is lower than the carriageway and has its own series of gullies. The carriageway is served by gullies and drained separately. The Highway Authority (LCC) has no records of the carriageway or footway drainage piped system in this area. 1 property	1	Completed	LCC - Yes	TBC	TBC	LCC	On-going	TBC	S19-039
6 July 2012	Gosberton	High Street - PE11 4NW	Heavy rainfall caused the piped and open dykes within the village to overflow which caused internal flooding. 1 property	1	Completed	Welland and Deepings IDB - Yes LCC - Yes	Maintenance to highway drainage system and riparian ditches and piped drains undertaken.	No	LCC WDIDB	Completed	Complete Spring 2013	S19-040
22 May 2014	Long Sutton	London Road - PE12 9EE	During heavy rainfall the resident reported water had entered his property damaging flooring. Surface water flowed off the carriageway over the footway and onto his neighbours drive, subsequently flowing onto his property. The water entered into the house via air bricks located below ground level. 1 property	1	Completed	LCC - Yes	System has been cleansed and jetted, and will be inspected by LCC Highways on a regular basis.	No	LCC	Completed	Complete	S19-077
8 August 2014	Sutton Bridge	Bridge Road - PE12 9SH	During heavy rainfall the business reported water had entered its property damaging flooring. Surface water flowed off the carriageway over the footway and onto the tarmac & gravel frontage, subsequently entering the property. 1 property	1	Completed	LCC - Yes	System has been cleansed and jetted, and will be inspected by LCC Highways on a regular basis.	No	LCC	Completed	Complete	S19-078
20 July 2014	Swineshead	Market Place - PE20 3LJ	Flooding to the business occurred following a heavy downpour. The business suffered internal flooding due to surface water runoff from the carriageway entering the car park and subsequently entering the property. 1 commercial property	1	Completed	LCC - Yes	New connections, chamber pots and minor highway alterations are currently in the works programme for next financial year.	No	LCC	Completed	1st January 2020	S19-103
20 July 2014	Crowland	Chapel Street - PE6 0AR	The road gully outside the property was unable to cope with the excessive amount of rainfall which resulted in surface water entering into the property, causing damage to the dining room and lounge. 1 property	1	Completed	LCC - Yes	Further Drainage Investigations to be carried out in due course. An enforcement letter has been sent to the property opposite which is discharging water onto the highway. Meeting with owner of property opposite to identify any amendments which may be required to their roof water dispersal system. Preliminary designs, undertaken for proposed alterations to LCC Surface Water drainage. Scheme in programme for 2017/18. Bid submitted for assistance from Floods and Water as this is not maintenance.	No	LCC	On-going	2020/21	S19-113
13 July 2014	Freiston	Oak House Lane - PE22 0PJ	Following a short period of heavy rain, surface water from the highway entered an external building where stock was stored for the business. 1 property	1	Completed	LCC - Yes	Works are programmed during 2015.	No	LCC	Completed	Complete Summer 2015	S19-110
24 August 2013	Spalding	Roman Bank - PE11 2HS	Originally investigated and did some repairs on but then has since resurfaced as in the last storm in May / June the water was very close to entering the property again. 1 property	1	Completed	LCC - Yes	Division have arranged for changes to the surface water system and carriageway surfacing to adjust levels. This is funded from divisional drainage maintenance budget. This work is programmed for April / May 2016.	No	LCC	Completed	Spring 2016	S19-140

Duty to Investigate												
Section 19 Investigations												
Lincolnshire County Council Section 19 Investigations - Boston Borough Council & South Holland District Council Network Area - Area Highways Manager Andy Wharff (South)												
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Risk Management Authorities with Responsibilities and whether they are exercising functions	Proposed Action/Works	Consideration for inclusion in future Common Works Programme	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
23 August 2015	Sutton St James	Chapelgate - PE12 0EF	The owner of the property reports that this is a recurring problem that we have tried to resolve in the past. The levels of the site are such that in heavy rain water runs onto the property from the highway into the rear garden and through the back door. The owner has also hardened what was a grassed area within his property without installing any drainage. Flooding occurring again and entering property even though works carried out a few years ago. (POSTBOOK 340-627) - 1 property	1	Completed	LCC - Yes	The proposal is to install an additional gully to the left of the vehicle access, an aco drain across the shop doorway and increase the frequency of cleansing for the drainage system at this location. This work was completed in May 2016.	TBC	LCC	Completed	TBC	S19-141
22 June 2016	Gedney Drove End	Marsh Road - PE12 9PJ	Heavy rainfall, following a period of inclement weather appears to have overwhelmed the existing sewers and watercourses with water following ground contours. Internal flooding of the property was via kitchen door. The Parish Council had no knowledge of the flooding incident. The preliminary investigation concludes that there is a need to improve the maintenance regime of the drainage systems by introducing a new gully nearer to the property affected by the flooding. SHIDB is the Drainage Authority for this area. It has no record of any flooding on this occasion but is aware of past problems in the village. Anglian Water has few assets in the village and none within the area of the property. 1 property	1	Completed	South Holland IDB - Yes LCC - Yes	LCC Highways Authority team confirmed that they undertake the cleaning of the gulleys on an annual basis and on the 30/06/16 they cleansed the pipe on Winston Close and 3 catch pits.	TBC	LCC	Completed	TBC	S19-172
17 June 2016	Spalding	Stonegate - PE11 2PH	Customer states that this is the 5th time the properties have flooded since November 2011. The customer states that the drainage system is too old and cannot take the rain in exceptional rain. They say the drains are not man enough and the fire brigade has also said this. Customer states that the properties were flooded yesterday 16/06 in the evening and the fire brigade attended. Customer states that if it rains again the properties will once again get flooded. The customer states that the current drains need cleaning out and the whole system needs replacing with a better more modern system. 4 properties	4	Completed	LCC - Yes AW - Yes EA - Yes South Holland IDB - Yes SHDC - Yes	CCTV survey required. IDB have cleansed and inspected their pipe.	TBC	LCC	Completed	TBC	S19-171
10 June 2016	Spalding	Little London - PE11 2TA	Surface water run off from the highway entered the property. 1 property	1	Completed	LCC - Yes AW - Yes Welland & Deeping IDB - Yes	TBC	TBC	LCC	On-going	TBC	S19-174
16 June 2016	Kirton	Penny Gardens - PE20 1HN	Water has started to enter properties after persistent rain for most of the afternoon. Customer believes that this is due to a blocked gully. 1 property	1	Completed	BBC - Yes AW - Yes Black Sluice IDB - Yes LCC - Yes	Further investigations required to establish maintenance responsibilities and potential future works.	TBC	TBC	Completed	TBC	S19-169
16 June 2016	Kirton	Station Road - PE20 1EE	Flooding from rainfall and blocked drain. 3 properties	3	Completed	BBC - Yes AW - Yes Black Sluice IDB - Yes LCC - Yes	Further investigations required to establish maintenance responsibilities and potential future works. AW will liaise directly with their customers to manage the sewer blockage by foreign objects.	TBC	TBC	Completed	TBC	S19-169
16 June 2016	Kirton	Green Lane - PE20 1DX	It is likely that the property may have been inundated as a consequence of the extreme nature of the event but the severity of the flooding may not have been so severe, and a lower degree of ponding noted, if the system in the Hardwick Estate surface water system was operating efficiently, but the intensity of the rainfall and the property's location were probably major factors. 1 property	1	Completed	BBC - Yes AW - Yes Black Sluice IDB - Yes LCC - Yes	Further investigations required to establish maintenance responsibilities and potential future works.	TBC	TBC	Completed	TBC	S19-169
27 June 2016	Freiston	Oak House Lane	Customer states that the rain flows down the road and into the shop. The customer has requested the fire brigade attend last year and they had to pump the shop out. The shop flooded again yesterday 26/06/16 and they managed to clear it themselves with a lot of work and help. The customer states there was a new drain put in, but this is doing nothing to alleviate the situation. 1 property	1	On-going	TBC	Awaiting report	TBC	TBC	On-going	TBC	S19-181

Duty to Investigate												
Section 19 Investigations												
Lincolnshire County Council Section 19 Investigations - Boston Borough Council & South Holland District Council Network Area - Area Highways Manager Andy Wharff (South)												
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Risk Management Authorities with Responsibilities and whether they are exercising functions	Proposed Action/Works	Consideration for inclusion in future Common Works Programme	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
23 July 2016	Spalding	Cathedral Drive - PE11 1PQ	Surface water run off from the highway entered the property on two occasions. 1 property	1	Complete	LCC - Yes	Consider upgrading the current highway system. Further investigation is required into the provision of an overflow system.	TBC	LCC	Completed	TBC	S19-184
25 June 2016	Spalding	Woolram Wygate - PE11 3PA	Contacted by a building consultant who is investigating an insurance claim regarding surface water flooding at this property. The lounge of the property flooded on two occasions 25th June and 28th August 2016 during intense rainfall and water drains quickly once rainfall stops. 1 property	1	Completed	Inconclusive as the owner of the drainage assets is unknown at this stage.	To be raised at the local Flood and Drainage Risk Management Group	TBC	TBC	Completed	TBC	S19-182
16 June 2016	Low Fulney	Mallard Road - PE12 6ND Weston Hills Road - PE12 6NE	After the recent heavy rainfall, surface water ran off the road & possibly surrounding land and flooded these properties. This is a private road and there is very little positive drainage. 3 of these properties on Mallard Road flooded again on 27 August 2016. 8 properties	8	Completed	LCC - Yes SHIDB - Yes SHDC - Yes EA - Yes	LCC and SHIDB are working in partnership to investigate and identify potential improvements to the surface water drainage in the local area.	TBC	TBC	On-going	2020/21	S19-185
27 August 2016	Frampton	Middlegate Road - PE20 1BX	Water entered dining room. 1 property	1	Completed	LCC - Yes EA - Yes AW - Yes Black Sluice IDB - Yes	IDB will arrange an inspection of their culvert.	TBC	TBC	Completed	TBC	S19-183
28 June 2017	Kirton	London Road - PE20 1JA	Water came off the highway into neighbours drive and garden which then travelled to customers property. Water is getting into the air bricks and damaging the wallpaper and flooring. 1 property	1	Completed	TBC	TBC	TBC	TBC	On-going	TBC	S19-189
20 July 2017	Tydd St Mary	Church Way - PE13 5QY	Water entered the kitchen of the property through the brickwork. The customer believed there was 2-3 inches of water which was caused by heavy rainfall/porous brickwork. The customer states that the footway cambers away from the road where the drains are and instead cambers towards the property. 1 property	1	Completed	LCC - Yes South Holland IDB - Yes AW - Yes	Further investigations into the highways drainage system is required, there is also some responsibility for the householder to manage their curtilage water.	TBC	TBC	On-going	TBC	S19-191
10 June 2016	Deeping St Nicholas	Coronation Avenue	Reported to LCC on 8 June 2017 1st property: The water came up through the floor and flooded the kitchen. All underneath the cupboards were wet. 2nd property: Parts of the property flooded - living room, kitchen, hall, all down stairs 3rd property: Living room and front door leading to stairway was flooded. On the 27 August the garden flooded again but water didnt get into the house. 3 properties	3	Completed	LCC - Yes Welland & Deeping IDB - Yes SHDC - Yes AW - Yes	TBC	TBC	TBC	On-going	TBC	S19-138
27 December 2017	Spalding	Little London - PE11 2UE	Surface water run off entered the bar area of the pub. 1 property	1	Completed	LCC	Raise Kerbs, Cleanse the system, and consider additional carriageway drainage	No	LCC	Completed	TBC	S19-197
01 August 2018	Swineshead	Coles Lane - PE20 3NS	Surface or ground water entering the foul system causing it to surcharge. 1 property	1	Complete	LCC AW Black Sluice EA BBC	TBC	TBC	TBC	On-going	TBC	S19-200

Duty to Investigate

Section 19 Investigations

Lincolnshire County Council Section 19 Investigations - Boston Borough Council & South Holland District Council Network Area - Area Highways Manager Andy Wharff (South)

Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Risk Management Authorities with Responsibilities and whether they are exercising functions	Proposed Action/Works	Consideration for inclusion in future Common Works Programme	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
27 July 2018	Surfleet	Gosberton Road - PE11 4AB	Internal flooding was caused by surface water bypassing the road gullies spilling onto the pavement combined with the carrier drain being overwhelmed and not removing the volume of water quickly enough. 1 property	1	Completed	LCC - Yes	Cleanse and monitor the performance of the drainage system.	No	LCC	Completed	Gullies jetted 17/08/2018 and 2 new gullies installed in front of the property and the carriageway re-profiled on 28/11/2018	S19-209
13 August 2018	Spalding	Pennygate - PE11 1LX	Surface water flowed from the road, over the path and into the shop. 1 property	1	Completed	LCC - Yes WDIDB - Yes AW - Yes	Gully cleanse to be carried out. Water check reinstated March 2019. Performance of drainage system to be monitored.	No	LCC	Completed	TBC	S19-216
13 August 2018	Kirton	Station Road - PE20 1EE	Surface water flooding. 3 properties	3	Completed	LCC - Yes BBC - Yes Black Sluice IDB - Yes	TBC	TBC	TBC	On-going	TBC	S19-217
13 August 2018	Gosberton	Wargate Way - PE11 4HE	Surface water flowed over the pavement and into the property. 1 property	1	Completed	LCC - Yes WDIDB - Yes SHDC - Yes	Since the flooding the kerbs have been raised to provide a water check and an additional gully has been installed. The performance of the drainage system will be monitored.	No	LCC	Completed	TBC	S19-219
11 June 2019	Pinchbeck	Brownlow Crescent	TBC	1 TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-050
11 June 2019	Kirton	King Road	TBC	1 TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-161
11 June 2019	Quadring	St Margarets	TBC	1 TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-193
11 June 2019	New Bolingbrooke	Main Road	TBC	2 TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-223
11 June 2019	Spalding	Pinchbeck Road	TBC	2 TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-226
12 June 2019	Long Sutton	Gedney Road	TBC	1+ TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-230
12 June 2019	Wrangle	Main Road	TBC	3 TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-231
14 June 2019	Spalding	St Thomas Road	TBC	2+ TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-238
14 June 2019	Boston	Paddock Grove	TBC	1 TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-239
14 June 2019	Spalding	Stonegate - PE11 2PH	TBC	3+ TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-241
14 June 2019	Spalding	Neville Avenue	TBC	1 TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-242
14 June 2019	Spalding	St Andrews Road	TBC	1 TBC	On-going	TBC	TBC	TBC	TBC	On-going	TBC	S19-243
10 June 2019	Wrangle	Main Road	Internal flooding to a domestic property. 1st flooded on 10th June 2019 and then flooded on the 27th August 2019. 1 property	1	On-going	Awaiting report	TBC	TBC	TBC	On-going	TBC	S19-249