

Duty to Investigate											
Section 19 Investigations											
Lincolnshire County Council Section 19 Investigations - East Lindsey District Council Network Area - Area Highways Manager Russell Crockford (East)											
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
28 June 2012	Horncastle	East Street	Extreme rainfall (estimated to be a 1 in 50 year event) caused overland and highway surface water flows to collect at the low area of East Street and Stanhope Road. The extreme rainfall overwhelmed the highway drainage system which was also suffering from surcharged outfalls due to high river levels. 2 properties	2	Completed	A bid for an overall surface water study for Horncastle has been submitted with feasibility and design programmed for 2014/15 if approved; works to be programmed 2015/16/17.	LCC - Yes	LCC AW	Completed	2014 & 2015 - 2017	S19-001
28 June 2012	Horncastle	West Street - LN9 5AD	Extreme rainfall (estimated to be a 1 in 50 year event) caused significant overland flows from the adjacent school field, hillside and Lincoln Road. The surface water collected at the bottom of the hill causing flooding to the Grammar School and adjacent properties in West Street. 4 properties	4	Completed	Blockages removed and gas main relocated. A bid for an overall surface water study for Horncastle has been submitted with feasibility and design programmed for 2014/15 if approved; works to be programmed 2015/16/17.	LCC - Yes Anglian Water - Yes	LCC	Completed	2014 & 2015 - 2017	S19-002
28 June 2012	Horncastle	South Street	Extreme rainfall (estimated to be a 1 in 50 year event) caused overland and highway surface water flows to collect at the low area of the Bull Ring and South Street overwhelming the Anglian Water sewer systems; which were also suffering from surcharged outfalls due to high river levels. 3 properties	3	Completed	LCC gullies and system checked and repaired. Anglian Water checking surface water systems and may consider improvement works in future asset management plans. Feasibility and design programmed for 2014/15 and if approved; works to progress in 2015/16/17. Additional minor works to be included in the future works programme.	Anglian Water - Yes LCC - Yes	LCC	On-going	2018/19	S19-003
28 June 2012	Horncastle	Langton Hill	Extreme rainfall (estimated to be a 1 in 50 year event) caused significant overland flows from the adjacent hillside and agricultural land, which was not contained by the interceptor ditch. Combined overland and highway surface water overwhelmed both the highway and surface water sewer drainage systems on Langton Hill and West Street, and caused flooding at the bottom of the hill. 4 properties	4	Completed	Highway drainage system repaired and functioning. Anglian Water checked the surface water system and it is working acceptably. Initial works delivered. Consideration should be given to an overall surface water study for Horncastle	LCC - Yes Anglian Water - Yes Witham 3rd IDB - Yes	LCC	On-going	2019/20	S19-004
28 June 2012	Horncastle	Mark Avenue Accommodation Road Prospect Street	Extreme rainfall (estimated to be a 1 in 50 year event) caused significant overland flows from the adjacent hillside and agricultural land. This was exacerbated by the interceptor ditch being restricted at its entrance to the culvert system, which caused flooding to properties in Mark Avenue, Accommodation Road and Prospect Street. 14 properties	14	Completed	Riparian ditches cleaned out. Anglian Water has fitted a new grill on its sewer and access points to deal with safety concerns related to cleaning debris from watercourse. An LCC capital scheme is included in the Medium Term Plan for works in 2020/21	Anglian Water - Yes Witham 3rd IDB - Yes ELDC - Yes	LCC AW Witham 3rd IDB	Completed	2018/19	S19-005
28 June 2012	Horncastle	Bowl Alley Lane	Extreme rainfall (estimated to be a 1 in 50 year event) caused significant overland flows from the adjacent school field and Bowl Alley Lane. The surface water collected at the lowest point causing flooding to the adjacent properties in Bowl Alley Lane. 3 properties	3	Completed	Partnership scheme developed between LCC Highways, Education and AW. Initial work delivered in 2015/16.	Anglian Water - Yes LCC - Yes	LCC AW	Completed	2014 & 2015 - 2017	S19-006
28 June 2012	New Bolingbrooke	Station Row	Extreme rainfall (estimated to be a 1 in 40 year event) caused highway surface water flows to collect in the low area of Main Road/Station Row overwhelming the highway drainage system in the footway. 7 properties	7	Completed	Dropped kerbs outside the post office replaced with full height kerbs. Drainage system found to be damaged by buildings/trees and a new outfall is required. Solution being designed and costed.	LCC - Yes	LCC	On-going	2014 - 2016	S19-007
28 June 2012	Roughton Moor	Horncastle Road (Adjacent to the old railway line) - LN10 6YQ	Metalling works to the Spa Trail has affected the natural overland flow routes. This has caused surface water to be trapped on the south side of the trail, which has caused flooding to one property. 1 property	1	Completed	LCC has carried out remedial works to reduce flood risk to properties by the installation of a cross drain.	LCC - Yes	LCC	Completed	Complete Autumn 2012	S19-008
28 June 2012	Skegness	Sunningdale Close	Extreme rainfall caused highway surface water flows to bypass kerb gullies and collect in the low area of Sunningdale Close. Overland flows from the rear of the houses also contributed to the flooding. 4 properties	4	Completed	Capacity issues checked and found to be acceptable; ELDC installed new gullies.	LCC - Yes Anglian Water - Yes ELDC - Yes	ELDC	Completed	Complete Autumn 2013	S19-009

Duty to Investigate											
Section 19 Investigations											
Lincolnshire County Council Section 19 Investigations - East Lindsey District Council Network Area - Area Highways Manager Russell Crockford (East)											
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
28 June 2012	Toynton St Peter	Ings Lane	Extreme rainfall caused overland flows to surcharge a number of watercourses in the area resulting in flooding to a low lying property in Ings Lane. 1 property	1	Completed	LCC have completed a feasibility report. An outline business case for FDGiA is being prepared for delivery of a scheme after 2021.	Witham 4th IDB - Yes LCC - Yes	LCC	On-going	Possible works 2021/22	S19-010
28 June 2012	Woodhall Spa	Albany Road	Heavy rainfall caused surcharging of the highway drainage system (which flows into Tattershall Road) causing backflow into Albany Road. This, together with the flows collected from Albany Road, were unable to enter the watercourse crossing Albany Road and the watercourse to the rear of Witham Road. This is due to a combination of blocked watercourses and partially blocked culvert crossing Albany Road. 5 properties	5	Completed	Culvert designed by LCC. Works due to start on site 23rd June 2014 to install a new culvert	Witham 3rd IDB - Yes LCC - Yes	LCC	Completed	Complete Summer 2014	S19-011
29 June 2012	Chapel St Leonards	The Esplanade	Surcharging from the highway drainage system due to blockages within the system, root ingress and possible concerns over the number of gullies. 2 properties	2	Completed	NM awaiting information from IDB regarding possible connection to water course	LCC - Yes	LCC	Completed	April 2017	S19-012
28 June 2012	Chapel St Leonards	Fairfield Avenue	Surcharging of Anglian Water surface water system due to displaced pipe work, and possible concerns over capacity. 1 property	1	Completed	All works completed Nov 2013	Anglian Water - Yes	LCC	Completed	Complete Winter 2013	S19-013
28 June 2012	Saltfleet	Main Road - LN11 7RZ	Soil and vegetable matter washing into the channel in front of the property causing blockage to the adjacent gully. 1 property	1	Completed	Works completed Nov 2013	LCC - Yes	LCC	Completed	Complete Winter 2013	S19-014
28 June 2012	Saltfleet	Pump Lane - LN11 7RL	Overland and highway surface water flows entering low lying property due to collapsed and silted surface water drainage system. 1 property	1	Completed	All work completed Nov 2013	ELDC - Yes	ELDC	Completed	Complete Winter 2013	S19-015
28 June 2012	Louth	Riverhead Terrace - LN11 0DD	During heavy rainfall (estimated to be a 1 in 60 year event) flooding took place in Riverhead Terrace due to overland flows from adjacent Riverhead development, and flows from the Terrace area being unable to escape. 9 properties	9	Completed	ELDC commissioned a hydrological study in April 2013 which is now complete. The report makes a number of recommendations - the most significant being to install a much larger AW pumping station. AW to make a scheme submission as part of their Price Review 14 process. Works have commenced (Aug 2014) into the upgrade of the sewer system. Work to be carried out in two phases, first being Ramsgate Road Area and then Phase two to include improvements to the Riverhead Area. All works to be completed by the end April 2015.	ELDC - Yes Anglian Water - Yes	AW ELDC	Completed	Completion due Summer 2015	S19-016
28 June 2012	Wainfleet	Station Road	Internal flooding to four properties, during intense rainfall, due to inoperative highway drainage system. This was caused by damage from utility companies and the outfall/ditch not being maintained. 4 properties	4	Completed	LCC have cleaned all gullies, restored the highway drainage system and ensured they are running efficiently to the River Steeping - further monitoring to be carried out	LCC - Yes	LCC	Completed	Spring 2015	S19-017
28 June 2012	Skegness	Sunningdale Drive - PE25 1AU	Intense rainfall overwhelmed AW surface water sewer system causing internal flooding to one property. 1 property	1	Completed	Blockage/damages have now been addressed by AW and the private drainage system cleared. AW has applied for funding to CCTV survey the remainder of the system.	Anglian Water - Yes	AW	Completed	Spring 2015	S19-018
28 June 2012	Firsby	Station Road - PE23 5PX	Following intense rainfall, water from the B1195 Station Road passed over a covered highway gully down the drive of, and flooded, a residential property. 1 property	1	Completed	Defective gully uncovered and all work carried out.	LCC - Yes	LCC	Completed	Complete	S19-019

Duty to Investigate

Section 19 Investigations

Lincolnshire County Council Section 19 Investigations - East Lindsey District Council Network Area - Area Highways Manager Russell Crockford (East)

Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
28 June 2012	Goulceby	Shop Lane	Overland flows from the adjacent hillside and agricultural land has been exacerbated by the overgrown/silted interceptor ditch, and the inlet to the culvert system being restricted by debris and silt. The combined flows caused flooding to a property opposite which is lower than the restricted culvert/ditch system. 1 property	1	Completed	All works completed Nov 2013	LCC - Yes	Witham 3rd IDB LCC	Completed	Complete Winter 2013	S19-020
30 June 2012	Hundleby	Brick Yard Lane - PE23 5NG	Overland flows from agricultural land surcharged culvert under Brick Yard Lane (reported 9th May 2013 by IDB) which is a private road 1 property	1	Completed	Recomendations provided to Riparian owner	LCC - Yes	LCC	Completed	Complete	S19-021
6 July 2012	Croft	Croft Bank	Overland and highway surface water flows entering property access due to low kerb threshold. 1 property	1	Completed	LCC have investigated and undertaken reshaping works to divert flows away from property access.	LCC - Yes	LCC	Completed	Complete Winter 2013	S19-022
6 July 2012	Huttoft	Mumby Road	Overland and highway surface water flows entering low lying property due to suspected lack of capacity in the surrounding highway drainage system. 1 property	1	Completed	LCC to install new gullies and raised kerbs	LCC - Yes	LCC	Completed	Complete Sept 2013	S19-023
6 July 2012	Burgh Le Marsh	High Street	Overland and highway surface water flows entering low lying property due to suspected lack of capacity and defects in the surrounding highway drainage system, despite previous kerbing works aimed to mitigate problem. 1 property	1	Completed	Works to raise kerbs and regrade footway in hand. New surface water sewer/drain in carriageway with outfall to Catchwater Drain is budget dependent. Initial discussions with LMIDB have been undertaken to investigate routing and outfall locations. No further action to be taken.	LCC - Yes	LCC LMIDB	Completed	2014/15	S19-024
19 July 2012	Skegness	Lumley Avenue	Extreme rainfall caused both highway surface water and overland flows to funnel down the unadopted lane and collect in the low area behind the properties of Lumley Avenue. 2 properties	2	Completed	New gullies installed by LCC. Recommendations provided to the owners of the private road .	LCC - Yes	LCC	Completed	Complete	S19-027
3 August 2012	Mumby	Coots Lane - LN13 9JZ	Following intense rainfall, water flowed down Coots Lane entering a property which is situated at the lowest point. A combination of water from the carriageway and driveway was believed to be the cause. 1 property	1	Completed	LCC to undertake drainage survey. LMIDB to request cleansing/maintenance of dyke (confirmed on 08/12/2017 as being complete)	LCC - Yes Lindsey Marsh IDB - Yes	LCC LMIDB	Completed	February 2017	S19-028
17 March 2013	Bucknall	Main Street - LN10 5DT	Following intense rainfall, overland flows from adjacent fields flowed through the rear garden and entered the property. 1 property	1	Completed	Witham 3rd IDB has checked the work has been carried out and it is maintained on a regular basis.	LCC - Yes Witham 3rd IDB - Yes	LCC Witham 3rd IDB	Completed	Complete Summer 2013	S19-029
9 June 2014	Salfleet	Pump Lane - LN11 7RL	Extreme rainfall estimated at a 1 in 60 year event caused significant overland and surface water flow to enter this low lying property due to capacity issues of existing surface water drainage system. Lack of effective drainage within the property boundary is also a contributing factor. The same property also experienced similar internal / external flooding on 28th June 2012 - Report Ref S19-015 1 property	1	Completed	LCC Highways to undertake drainage improvement work and carry out improvements to the vehicular access of the property.	LCC - Yes	LCC	Completed	Completed 4/9/15	S19-087
9 June 2014	Hagworthingham	Sausthorpe Road	Following torrential rainfall, drains were unable to expell the surface water causing it to flow onto the driveway and enter the property owners conservatory. 1 property	1	Completed	Drainage system has been jetted and cleansed awaiting report. If required a CCTV investigation will be carried out to identify any problems within the system.	LCC - Yes	LCC	Completed	Summer 2015	S19-092
9 June 2014	Bucknall	Platts Lane	Extreme rainfall caused significant surface water to flow along the highway. The highway drains were unable to cope, allowing water to flow over the kerbed accesses to the properties, causing internal flooding. 2 properties	2	Completed	Following the cleansing and jetting of the entire system highway maintenance work and further drainage investigations will be funded during 2015. Minor works completed to raise level of footway.	LCC - Yes	LCC	Completed	2016	S19-093

Duty to Investigate											
Section 19 Investigations											
Lincolnshire County Council Section 19 Investigations - East Lindsey District Council Network Area - Area Highways Manager Russell Crockford (East)											
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
9 June 2014	Saltfleet	Main Road - LN11 7RZ	Extreme rainfall (1 in 60 year event) meant the highway drains were unable to cope with the amount of surface water on the carriageway and overland flow from the surrounding land. 1 property	1	Completed	Root cutting.	LCC - Yes	LCC	Completed	2016	S19-094
9 June 2014	Manby	Chapel Lane - LN11 8HQ	Following the two periods of extreme rainfall that fell during Monday 9th June, the surface water highway drains were unable to cope with upto 31mm of rain falling in 1 hour. Majority of the surface water was initially discharged from ELDC carpark and adjacent playground onto the carriageway. Lincolnshire Fire & Rescue attended the scene to pump out excessive surface water. 1 property	1	Completed	Work to upgrade the existing drainage system has been completed; the installation of the holding tank is due to be carried out very soon by ELDC.	LCC - Yes	ELDC	Completed	41974	S19-095
24 June 2014	Horncastle	Langton Hill	Extreme rainfall estimated at being a 1 in 30 to 1 in 100 year event resulted in significant overland flows from the surrounding land. The combined surface water and overland surface water flow overwhelmed the highway sewer system on Langton Hill and West Street and caused flooding at the bottom of the hill which affected one property. It is reported that the property flooded on 24 June 2014, 28 June 2014 & 19 September 2014. 1 property	1	Completed	Refilling of the footway is currently underway along with the completion of outstanding works; all due to be completed by the end of March 2015. The cleaning out of the ditch is yet to be undertaken by the riparian owner.	LCC - Yes	LCC Witham 3rd IDB AW	Completed	Completion due Spring 2015	S19-096
8 August 2014	Louth	High Holme Road - LN11 0HE	Extreme rainfall caused significant overland flow and highway surface water to enter low lying properties; this was due to capacity issues of the existing surface water drainage system. Residents in the properties were evacuated to temporary accommodation due to internal flooding. 2 properties	2	Completed	Slit channel installed in front of property. Capacity issues	LCC - Yes	LCC	Completed	Spring 2015	S19-088
9 June 2014	Skegness	North Parade - PE25 2TE	Intense summer rainfall caused internal flooding to the hotel. Surface water entered the building via the ladies toilets. 1 property	1	Completed	After further investigations carried out by AW additional works are planned, including running of a new model. Recommendations advised to property owners.	LCC - Yes Anglian Water - Yes	AW	On-going	43891	S19-101
24 June 2014	Skegness	Sunningdale Close - PE25 1BA	Following torrential rain, the highway drains were unable to cope with the amount of surface water on the carriageway. The flood water entered the property. 2 properties	2	Completed	Further investigations to be carried out by AW and IDB to establish outfall. Anglian water removed gas service pipes intruding in the surface water system in 2015.	LCC - Yes Anglian Water - Yes	AW LMIDB	On-going	Spring 2015	S19-098
24 June 2014	Skegness	Sunningdale Drive - PE25 1AU	Following torrential rain, the highway drains were unable to cope with the amount of surface water on the carriageway. The flood water entered the property, whilst the owners were away on holiday. The property also flooded on 13 July 2014. 1 property	1	Completed	Further investigations to be carried out by AW, LMIDB, LCC and ELDC.	LCC - Yes	AW LMIDB	On-going	Spring 2015	S19-099
24 June 2014	Skegness	Grand Parade - PE25 2UG	Following torrential rain, the highway drains were unable to cope with the amount of surface water on the carriageway and a property was flooded. 1 commercial property	1	Completed	Further investigations to be carried out by AW & ELDC. AW to check new model.	LCC - Yes	AW ELDC	On-going	Spring 2015	S19-100
10 July 2014	Anderby Creek	Lakeside - PE24 5XS	Intense summer rainfall last night caused several properties in the area internal flooding Cause and No of properties to be confirmed. 3 properties	3	Completed	All proposed works have now been completed	LCC - Yes	LMIDB ELDC LCC	Completed	42064	S19-123
8 August 2014	Friskney	Fold Hill - PE22 8RG	Intense rainfall that fell over a short period of time and flowed over agricultural land causing internal flooding to one property. 1 property	1	Completed	Witham 4th IDB have agreed to clean out and adopt a short section of ditch downstream of the culverted system (confirmed on 15/01/2018 as being adopted). ELDC and LCC are contributing to an investigation and a one off clean of the riparian system.	LCC - Yes Witham 4th IDB - Yes ELDC - Yes	LCC ELDC Witham 4th IDB	Completed	Summer 2016	S19-117

Duty to Investigate

Section 19 Investigations

Lincolnshire County Council Section 19 Investigations - East Lindsey District Council Network Area - Area Highways Manager Russell Crockford (East)

Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
8 August 2014	Wainfleet All Saints	Bethlem Crescent	Intense rainfall that fell over a short period of time caused internal flooding to one property. 2 properties	2	Completed	Further investigations to be carried out by AW	LCC - Yes Anglian Water - Yes	AW	Completed	Summer 2015	S19-118
8 August 2014	Skegness	Ida Road - PE25 2AU	Intense rainfall that fell over a short period of time caused internal flooding to one property. 1 property	1	Completed	The property owner has been made aware of property resilience measures that should help alleviate flooding in the future.	LCC - Yes Anglian Water - Yes	LCC AW	Completed	Winter 2014	S19-119
19 September 2014	Horncastle	East Street	Extreme rainfall caused significant highway flows to collect at the low area of Stanhope Road; Property flooded actually is on East Street NOT Stanhope Road. Overwhelming both the Anglian Water Surface Water Sewers and the highway drainage system. 1 property	1	Completed	A meeting has been planned with AW to discuss the findings of both the CCTV surveys, consider the work required and to ensure a collaborative resolution.	LCC - Yes Anglian Water - Yes	LCC AW	Completed	September 2016	S19-120
8 August 2014	Wainfleet All Saints	High Street	Extreme rainfall caused significant highway flows. The rainfall on the carriageway overwhelmed the highway surface water systems on the High Street, Which flowed over the kerb and the movement of passing vehicles caused flooding to one property. 2 properties	2	Completed	Works to clean and jet the surface water system to be programmed but there are issues whilst working near railways that need to be addressed prior to any works commencing.	LCC - Yes	LCC	Completed	October 2016	S19-121
8 August 2014	Louth	Sandringham Drive - LN11 0JE	Extreme rainfall in the Louth area, caused a property to flood internally. The property is located at a low point and surface water from the highway entered the garage and flooded the living room and conservatory. The surface water gully located in the carriageway outside the vehicle access may of been blocked or the amount of surface water may of overwhelmed the drainage system causing the internal flooding to the property. 1 property	1	Completed	Investigate this further as it is believed the kerbs are high enough	LCC - Yes	LCC	Completed	End of 2015	S19-126
8 August 2014	Louth	Westgate - LN11 9YH	Extreme rainfall in the Louth area, caused 2 properties to flood internally. The properties are at a particular low topographical point of the town and subject to overland and highway surface water to flow from the higher land in the south. 2 properties	2	Completed	System jetted and running OK, low point on network. No further action to be taken.	LCC - Yes	LCC	Completed	End 2015 TBC	S19-124
10 August 2014	Chapel St Leonards	South Road - PE24 5TR	Highway surface water entered the property through the vehicular access and flooded the driveway and then entered the living area of the dwelling. Property flooded again on 27/8/2016 - (REPORT AND WORKS STILL ON-GOING) 1 property	1	Completed	CCTV drainage investigation to be carried out in due course. Along with the installation of an additional gully and increasing the upstand of the vehicular access to +25mm. Order in system programmed for 2018/19.	LCC - Yes	LCC	On-going	March 2019	S19-125
8 August 2014	Irby In The Marsh	Wainfleet Road	Extreme rainfall caused significant highway flows. The rainfall on the carriageway overwhelmed the highway surface water systems on Wainfleet Road, flowing over the dropped access kerbs and causing flooding to one property. 1 property	1	Completed	Initial works to install a tarmac bund in the access have been carried out. Works to clean and jet the gull and connections to be carried out shortly	LCC - Yes	LCC	Completed	Summer 2016	S19-122
May 2012	Woodhall Spa	Green Lane - LN10 6QY	Internal Flooding due to a Riparian owned ditch overtopping and entered property notified LLFA feb 15 flooding incident 2012 1 property	1	Completed	To clean out the blocked/overgrown watercourse and ensure it is regularly maintained. Witham 3rd IDB to monitor the maintenance of the riparian ditch and take appropriate enforcement action if required in the future.	LCC - Yes Witham 3rd IDB - Yes	LCC Witham 3rd IDB	Completed	End 2015	S19-143
10 June 2016	Binbrook	Orford Road - LN8 6DU	Surface water bypassed the highways drainage system and flowed over the vehicular access causing internal flooding to the property. 1 property	1	Completed	LMDB have worked in conjunction with the riparian owners with regards to maintenance.	EA - Yes AW - Yes Lindsey Marsh IDB - Yes LCC - Yes Binbrook Parish Council - Yes ELDC - Yes	LCC	Completed	TBC	S19-177

Duty to Investigate

Section 19 Investigations

Lincolnshire County Council Section 19 Investigations - East Lindsey District Council Network Area - Area Highways Manager Russell Crockford (East)

Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
31 December 2015	Langton by Spilsby	Langton Road	Internal Flooding occurred when a re-build drain which is blocked within the drainage system flooded the area and entered the property 1 property	1	On-going	Further investigations required to identify blockage/collapse within the sewer system. Repairs to surface water drains completed.	LCC - Yes Anglian Water - Yes	LCC AW	Completed	Summer 2017	S19-146
31 May 2016	Burgh Le Marsh	Wainfleet Road - PE24 5BN	Water is running down callers drive and entering the property via the air vents. 1 property	1	Completed	Replace under-sized length of Surface Water sewer.	LCC - Yes ELDC - Yes AW - Yes	ELDC	Completed	Summer 2017	S19-163
Christmas Period in 2015	Louth	Eastfield Road - LN11 7AP	Property flooded twice over the xmas period due to surface water running down the highway 1 property	1	Completed	Gully installed at the top of the private driveway. Further investigations required with regards additional works.	LCC - Yes	LCC	Completed	Summer 2017	S19-151
27 August 2016	Chapel St Leonards	The Esplanade - PE24 5TB	LPP used to remove large amount of water. 2 properties	2	On-going	TBC	TBC	TBC	On-going	TBC	S19-195
27 August 2016	Chapel St Leonards	St Leonards Drive - PE24 5UZ	Main pump used 1 property	1	On-going	TBC	TBC	TBC	On-going	TBC	S19-196
09 January 2018	Sibsey	Main Road - PE22 0TW	Flooding was caused due to damaged surface water drainage system. 1 property	1	Completed	The resident may need to consider installation of the land drainage system and consider connecting to the foul water drainage system. LCC to monitor the performance of the riparian drainage systems in the area.	LCC - Yes Witham Fourth IDB - Yes ELDC - Yes	LCC	Completed	TBC	S19-198
02 April 2018	Louth	Grimsby Road - LN11 0ED	Fire & Rescue attended and pumped out 3 properties and put preventative measures in place to prevent further flooding. 3 properties	3	On-going	TBC	TBC	TBC	On-going	TBC	S19-199
02 June 2018	Woodhall Spa	Witham Road - LN10 6RA Tor-O-Moor Road - LN10 6TD	Surface water flooding. 3 properties	3	On-going	TBC	TBC	TBC	On-going	TBC	S19-203
02 June 2018	Burgh on Bain	Main Road - LN8 6JY	Surface water flooding. 1 property	1	On-going	TBC	TBC	TBC	On-going	TBC	S19-204
12 March 2018	Partney	Chapel Lane	Surface water flooding. 1 property	1	Completed	TBC	LCC Highways - Yes LMDB - Yes EA - Yes AW - Yes ELDC - Yes	TBC	On-going	TBC	S19-206
27 July 2018	Skegness	Sunningdale Drive - PE25 1AU	Surface water caused internal flooding to properties. 6 properties	6	Completed	TBC	LCC - Yes AW - Yes Lindsey Marsh IDB - Yes EA - Yes ELDC - Yes	TBC	On-going	TBC	S19-210
27 July 2018	Horncastle	Churchill Avenue - LN9 6EP	Surface water flooding. 2 properties	2	Completed	TBC	LCC - Yes Witham 3rd IDB - Yes ELDC - Yes AW - Yes EA - Yes	TBC	On-going	TBC	S19-211
27 July 2018	Skegness	Roman Bank - PE25 1RN	The drainage system was unable to cope and surface water was consequently unable to enter the system which contributed to internal flooding. 1 property	1	Completed	TBC	LCC - Yes AW - Yes Lindsey Marsh IDB - Yes EA - Yes ELDC - Yes	TBC	On-going	TBC	S19-212

Duty to Investigate

Section 19 Investigations

Lincolnshire County Council Section 19 Investigations - East Lindsey District Council Network Area - Area Highways Manager Russell Crockford (East)

Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
27 July 2018	Horncastle	West Street - LN9 5AF	Surface water flooding which entered the property through the back door and flooded the kitchen and dining room. 1 property	1	Completed	TBC	LCC - Yes AW - Yes Witham 3rd IDB - Yes EA - Yes ELDC - Yes	TBC	On-going	TBC	S19-220
16 August 2018	Ingoldmells	Sea Lane - PE25 1PQ	Surface water flooding into shops. 8 commercial properties	8	Completed	TBC	LCC - Yes AW - Yes Lindsey Marsh IDB - Yes EA - Yes ELDC - Yes	TBC	On-going	TBC	S19-221
07 December 2018	Wainfleet	St Johns Street - PE24 4DJ	Surface water flooding to property through the garage. 1 property	1	Completed	TBC	Householder - Yes LCC - Yes Lindsey Marsh IDB - Yes ELDC - Yes AW - Yes	TBC	On-going	TBC	S19-222
11 June 2019	Skegness	Royal Oak Terrace	TBC 3 properties	3 TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-155
11 June 2019	Chapel St Leonards	Trunch Lane	TBC 1 Commercial property	1 TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-166
11 June 2019	Utterby	Main Road	TBC 1 property	1 TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-224
11 June 2019	Thimbleby	Main Road	TBC 1 property	1 TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-225
12 June 2019	Horncastle	Station Yard	TBC 1 Commercial property	1 TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-227
12 June 2019	Holbeach	Battlefields Lane	TBC 1 property	1 TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-228
12 June 2019	Partney	Spilsby Road	TBC 1 property	1 TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-229
14 June 2019	Alvingham	Lock Road	TBC 1 property	1 TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-235
14 June 2019	Goulceby	Butt Lane	TBC 1 property	1 TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-236
14 June 2019	Burgh Le Marsh	Storeys Lane	TBC 2+ properties	2+ TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-237
14 June 2019	Great Steeping	Main Road	TBC 10+ properties	10+ TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-240
19 June 2019	Kirkby On Bain	Kirky On Bain Village - No Location	TBC 6 properties	6+ TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-245
19/06/2019	Burgh on Bain	Main Road	TBC	1 TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-246

Duty to Investigate											
Section 19 Investigations											
Lincolnshire County Council Section 19 Investigations - East Lindsey District Council Network Area - Area Highways Manager Russell Crockford (East)											
Date of Incident	Town / Locality	Street / Road Name	Description of Flooding	Number Of Properties	Investigation Status	Proposed Action/Works	Risk Management Authorities with Responsibilities and whether they are exercising functions	Promoter	Works Status	Estimated Timescales Recommendation / Scheme Completion	S19 Report File Reference
11 June 2019	Horncastle	Stanhope Road	TBC 1 Commercial Property	1 TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-247
11th June 2019	Wainfleet All Saints	Various Locations Throughout Village	Prolonged rainfall led to surface water flooding, fluvial flooding following the breach of the Wainfleet diversion channel. 64+ properties	64+ TBC	On-going	TBC	TBC	TBC	On-going	TBC	S19-248
11th June 2019	Horncastle	Stanhope Road	Internal flooding to a domestic property. This confirmation was passed onto PB at a opublic meeting in Horncastle on the 10/09/19. 1 property	1	On-going	Awaiting report	TBC	TBC	On-going	TBC	S19-250