

Incident Recording System

Identifier

FRS Incident Number: ECEC001740-17072021

Incident status: Published

Recording FRS: Lincolnshire

Recording station: Lincoln South Fire Station

'Over the border' incident: No

Call

Origin of call: Other

Incident type at call: Building

▶ Timings

Time of call: 17 July 2021 01:36:45

Late call: No

Date/time of stopped message: 17 July 2021 02:17:55

Date/time closed: 17 July 2021 03:42:19



Incident Recording System

Attendance

Incident category: Fire

Type of property: Building > Dwelling > Purpose Built Flat/Maisonette - multiple

occupancy > Up to 3 storeys

Property regulated: No

Number of appliances deployed: 2

Victims involved: No

Evacuation involved: Yes

Attack on firefighters: No

Derelict buildings involved: No

Chimney fire: No

Location of incident

Building number: 12

Street: OAK AVENUE

Town: LINCOLN

Postcode: LN2 6PP

Location description: 12 OAK AVENUE, LINCOLN, LN2 6PP

X-coordinate: 0653272

Y-coordinate: 0123456



Incident Recording System

Other Details

Multiple seats: No

Time between ignition and discovery: 5 to 30 minutes

Time between discovery and call: Under 5 minutes

How the fire was discovered: Automatic alarm system

Cause/motive: Accidental

Occupied at time of incident: Yes

Building normally occupied: Yes - occupied

State of building's means of escape: Not applicable

State of building's compartmentation found: Not applicable

Alarm systems

Alarm System Type Location Operated Reason for poor Outcome

Smoke alarm - battery On same floor as fire Yes and raised

type not known alarm

Were hazardous materials involved: No



Incident Recording System

Resources

Number of non-rider officers: 2

Vehicles

Type: Pumping - Water tender ladder

Time mobilised: 17 July 2021 01:38:05

Deployed from Home Station: Lincolnshire > North Hykeham Fire Station

Time mobile: 17 July 2021 01:43:38

Time at scene: 17 July 2021 01:50:42

Time available: 17 July 2021 02:24:42

Demounted resource: No

Number of crew: 6

FRS Callsign EC00P6

Type: Pumping - Water tender ladder

Time mobilised: 17 July 2021 01:38:07

Deployed from Home Station: Lincolnshire > Lincoln South Fire Station

Time mobile: 17 July 2021 03:35:33

Time at scene: 17 July 2021 01:44:46

Time available: 17 July 2021 01:44:46

Demounted resource: No.

Number of crew: 4

FRS Callsign EC00P3



Incident Recording System

Type: Transport - Officer's car

Time mobilised: 17 July 2021 01:39:43

Deployed from Home Station: Lincolnshire > Lincoln North Fire Station

Time mobile: 17 July 2021 01:50:30

Time at scene: 17 July 2021 01:55:17

Time available: 17 July 2021 03:27:17

Demounted resource: No

Number of crew: 1

FRS Callsign ECX12

Type: Transport - Officer's car

Time mobilised: 17 July 2021 01:41:00

Deployed from Home Station: Lincolnshire > Lincoln North Fire Station

Time mobile: 17 July 2021 01:50:31

Time at scene: 17 July 2021 01:59:21

Time available: 17 July 2021 02:38:09

Demounted resource: No

Number of crew: 1

FRS Callsign ECR225

Equipment

Туре	Number Used
Water Delivery - Hosereel - high pressure	1
RPE - CABA - standard duration	2
Ladders - Short extension	1
Detection/Location Equipment - Thermal imaging camera	2
Small Tools - Shovels/Forks/Brooms/Chimney Rods	1

▶ Fire officers

RCC Callsign	FRS Callsign
	ECX12

ECR225



Action

Delay in commencing firefighting action: No delay

Main action taken by the general public

prior to arrival:

None

Main action taken by FRS personnel: Hosereel (high pressure) (HRJ) - augmented supply

Damage - How the fire started

Main cause of fire: Faulty fuel supply - electricity

Person or action that caused the fire: electrical fault

Source of ignition: Electricity supply - Wiring, cabling, plugs

Powered the ignition: Electric

Item that ignited first: Clothing/Textiles - Other textiles

Item mainly responsible for spreading fire: Clothing/Textiles - Other textiles

Rapid fire growth caused by:

No rapid fire growth

Damage - Substances/explosions involved

Dangerous substances involved: None

Explosion: No



Incident Recording System

Damage - Property information

Factors contributing to start of fire:

Type of room/compartment fire started in: Bathroom/Toilet

Household occupancy at time of incident: Couple both under pensionable age with no

children None

6 - 10

Impairment due to suspected drugs/alcohol: No

. .

Special method of building construction: None

Heat and smoke damage only: No

Size of fire when fire service arrived: Limited to room of origin

Distance from adjacent properties (m):No other property affected

Distance from adjacent properties at stop (m): No other property affected

Damage restricted to:Limited to room of origin

Extent of the fire damage at stop: Up to 5

Extent of the total area damaged (sq. m at 6 - 10

stop):

Approximate size of room/compartment of Up to 5

fire's origin(sq. m):

Approximate size of floor at fire's origin (sq.

n):

Number of floors above ground: 2

Number of floors below ground: 1

Floor fire originated: 1

Persons

Number of casualties: 0

Number of casualties aged 0 to 15: 0

Number of casualties aged 16 and over: 0