



Sky High

Count On Us

Client:	Lincolnshire County Council
Project:	9320 / Lincoln By Pass
Site:	EW1 - A158 Wragby Road East
Survey Date:	Monday 2nd June - Saturday 7th June 2014
Survey Period:	07:00 - 19:00
Method:	Video Observation

Incidents / Observations:

There were no incidents reported over the survey period.



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Monday 2nd June 2014

AM Weather: Mild & Heavy Rain
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	10	0	0	0	0	0	0	10
00:15	5	0	0	0	0	0	0	5
00:30	7	0	0	0	0	0	0	7
00:45	4	0	0	0	0	0	0	4
1 Hr	26	0	0	0	0	0	0	26
01:00	6	0	0	0	0	0	0	6
01:15	4	0	0	0	0	0	0	4
01:30	6	0	2	0	0	0	0	8
01:45	1	0	0	0	0	0	0	1
1 Hr	17	0	2	0	0	0	0	19
02:00	7	0	0	0	0	0	0	7
02:15	2	1	0	0	0	0	0	3
02:30	2	0	0	1	0	0	0	3
02:45	2	0	0	1	0	0	0	3
1 Hr	13	1	0	2	0	0	0	16
03:00	1	0	0	0	0	0	0	1
03:15	2	0	0	1	0	0	0	3
03:30	1	1	0	1	0	0	0	3
03:45	3	0	0	0	0	0	0	3
1 Hr	7	1	0	2	0	0	0	10
04:00	4	2	1	0	0	0	0	7
04:15	2	2	3	1	0	0	0	8
04:30	7	3	1	0	0	0	0	11
04:45	1	1	0	1	0	0	0	3
1 Hr	14	8	5	2	0	0	0	29
05:00	4	1	1	1	0	0	0	7
05:15	2	3	1	4	0	0	0	10
05:30	10	0	3	4	0	0	0	17
05:45	16	2	0	4	0	0	0	22
1 Hr	32	6	5	13	0	0	0	56
6 Hrs	109	16	12	19	0	0	0	156

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	9	0	0	0	0	0	0	9
00:15	7	0	1	2	0	0	0	10
00:30	5	2	0	1	0	0	0	8
00:45	2	1	0	0	0	0	0	3
1 Hr	23	3	1	3	0	0	0	30
01:00	2	0	0	0	0	0	0	2
01:15	0	0	0	0	0	0	0	0
01:30	6	0	1	0	0	0	0	7
01:45	2	0	0	0	0	0	0	2
1 Hr	10	0	1	0	0	0	0	11
02:00	3	0	1	0	0	0	0	4
02:15	0	0	0	0	0	0	0	0
02:30	2	0	0	0	0	0	0	2
02:45	2	0	0	0	0	0	0	2
1 Hr	7	0	1	0	0	0	0	8
03:00	4	0	0	0	0	0	0	4
03:15	5	1	0	0	0	0	0	6
03:30	3	0	0	0	0	0	0	3
03:45	5	2	1	0	0	0	0	8
1 Hr	17	3	1	0	0	0	0	21
04:00	4	4	0	0	0	0	0	8
04:15	11	2	0	2	0	0	0	15
04:30	4	5	0	4	0	0	0	13
04:45	19	2	1	4	0	0	0	26
1 Hr	38	13	1	10	0	0	0	62
05:00	14	2	0	5	0	1	0	22
05:15	21	10	2	8	0	0	0	41
05:30	37	11	0	8	0	1	0	57
05:45	31	13	1	3	0	0	0	48
1 Hr	103	36	3	24	0	2	0	168
6 Hrs	198	55	8	37	0	2	0	300

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	1	0	0	1
17:30	2	0	0	2
17:45	0	0	0	0
1 Hr	3	0	0	3
18:00	0	0	0	0
18:15	0	0	0	0
18:30	1	0	0	1
18:45	0	0	0	0
1 Hr	1	0	0	1
3 Hrs	4	0	0	4
6 Hrs	4	0	0	4

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	0	0	0
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	1	0	1
1 Hr	1	0	1
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	0	0	0
3 Hrs	1	0	1
6 Hrs	1	0	1

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	20	9	6	6	1	0	0	42
06:15	19	8	5	4	2	1	0	39
06:30	46	14	5	3	1	0	0	69
06:45	37	16	8	4	0	0	0	65
1 Hr	122	47	24	17	4	1	0	215

49	10	1	4	0	1	0	65
54	12	2	6	0	0	0	74
66	14	3	5	0	0	0	88
104	33	5	5	2	1	0	150
273	69	11	20	2	2	0	377

07:00	53	19	5	3	1	0	0	81
07:15	85	25	6	3	2	2	0	123
07:30	100	17	19	2	1	0	0	139
07:45	85	29	13	6	0	0	0	133
1 Hr	323	90	43	14	4	2	0	476

110	31	4	6	1	1	0	153
137	24	2	4	0	1	0	168
150	29	7	5	1	2	0	194
147	20	5	1	1	4	0	178
544	104	18	16	3	8	0	693

08:00	66	25	17	6	1	1	0	116
08:15	65	29	15	4	0	0	0	113
08:30	85	30	6	4	0	0	0	125
08:45	78	21	5	5	0	0	0	109
1 Hr	294	105	43	19	1	1	0	463

207	13	2	2	2	2	0	228
111	12	6	3	2	1	0	135
181	15	8	5	2	0	0	211
181	20	5	8	0	0	0	214
680	60	21	18	6	3	0	788

09:00	81	30	8	2	2	0	0	123
09:15	74	23	13	3	1	0	0	114
09:30	79	18	10	4	0	0	0	111
09:45	85	14	4	2	0	1	0	106
1 Hr	319	85	35	11	3	1	0	454

113	10	2	7	1	1	0	134
156	9	9	4	0	0	0	178
118	20	7	1	1	1	0	148
141	12	8	9	1	0	0	171
528	51	26	21	3	2	0	631

10:00	91	19	8	6	2	0	0	126
10:15	95	21	4	1	1	0	0	122
10:30	114	17	6	4	0	0	0	141
10:45	114	15	5	1	1	1	0	137
1 Hr	414	72	23	12	4	1	0	526

132	16	2	4	0	0	0	154
168	20	9	5	2	0	0	204
123	20	7	4	1	2	0	157
150	16	5	3	3	1	0	178
573	72	23	16	6	3	0	693

11:00	141	20	8	9	0	0	0	178
11:15	163	7	7	2	1	1	0	181
11:30	143	17	3	6	2	0	0	171
11:45	122	13	3	3	0	1	0	142
1 Hr	569	57	21	20	3	2	0	672

156	21	4	3	0	0	0	184
153	23	9	6	0	2	0	193
128	22	4	0	1	0	0	155
101	18	4	8	0	1	0	132
538	84	21	17	1	3	0	664

6 Hrs	2041	456	189	93	19	8	0	2806
-------	------	-----	-----	----	----	---	---	------

3136	440	120	108	21	21	0	3846
------	-----	-----	-----	----	----	---	------

12 Hrs	2150	472	201	112	19	8	0	2962
--------	------	-----	-----	-----	----	---	---	------

3334	495	128	145	21	23	0	4146
------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Monday 2nd June 2014

AM Weather: Mild & Heavy Rain
 PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	160	15	5	4	1	1	0	186
12:15	144	13	5	6	1	0	0	169
12:30	127	21	4	4	4	0	0	160
12:45	154	15	4	7	1	0	0	181
1 Hr	585	64	18	21	7	1	0	696

12:00	108	7	5	3	0	2	0	125
12:15	154	18	4	3	1	2	2	184
12:30	121	12	4	2	2	1	0	142
12:45	115	14	6	1	0	2	0	138
1 Hr	498	51	19	9	3	7	2	589

13:00	130	16	6	6	0	0	0	158
13:15	136	9	5	5	2	0	0	157
13:30	138	14	6	7	0	3	0	168
13:45	132	12	6	7	0	1	0	158
1 Hr	536	51	23	25	2	4	0	641

13:00	126	22	4	5	0	0	2	159
13:15	143	16	8	6	0	1	0	174
13:30	98	8	6	5	1	0	0	118
13:45	171	16	7	5	0	1	0	200
1 Hr	538	62	25	21	1	2	2	651

14:00	110	15	2	3	0	0	0	130
14:15	117	14	6	3	1	1	1	143
14:30	155	15	6	5	2	4	1	188
14:45	111	9	5	6	0	1	0	132
1 Hr	493	53	19	17	3	6	2	593

14:00	101	17	5	2	0	1	0	126
14:15	110	21	6	5	0	0	0	142
14:30	99	14	5	3	2	2	1	126
14:45	102	17	9	3	0	3	0	134
1 Hr	412	69	25	13	2	6	1	528

15:00	148	16	7	8	3	3	0	185
15:15	149	12	2	8	1	2	0	174
15:30	128	18	5	6	0	4	0	161
15:45	145	13	7	8	0	0	0	173
1 Hr	570	59	21	30	4	9	0	693

15:00	110	13	8	2	0	0	0	133
15:15	102	18	8	3	0	0	0	131
15:30	132	27	11	11	2	0	0	183
15:45	123	17	7	4	1	0	0	152
1 Hr	467	75	34	20	3	0	0	599

16:00	155	19	2	1	0	4	0	181
16:15	148	10	4	4	1	0	1	168
16:30	187	22	6	5	1	1	0	222
16:45	161	20	2	6	0	1	0	190
1 Hr	651	71	14	16	2	6	1	761

16:00	125	21	6	4	1	0	1	158
16:15	119	19	7	5	1	1	0	152
16:30	114	25	9	4	0	0	0	152
16:45	126	21	1	3	2	0	0	153
1 Hr	484	86	23	16	4	1	1	615

17:00	149	21	6	7	1	0	0	184
17:15	161	15	6	4	0	2	0	188
17:30	209	18	3	2	3	2	0	237
17:45	175	17	2	2	0	3	1	200
1 Hr	694	71	17	15	4	7	1	809

17:00	100	21	5	4	0	1	0	131
17:15	108	25	4	4	1	1	0	143
17:30	104	16	6	3	2	2	0	133
17:45	131	17	3	6	2	1	0	160
1 Hr	443	79	18	17	5	5	0	567

6 Hrs	3529	369	112	124	22	33	4	4193
-------	------	-----	-----	-----	----	----	---	------

6 Hrs	2842	422	144	96	18	21	6	3549
-------	------	-----	-----	----	----	----	---	------



Sky High

Count On Us

Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Monday 2nd June 2014

AM Weather: Mild & Heavy Rain
 PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	139	17	2	1	0	4	2	165
18:15	120	10	1	1	1	1	0	134
18:30	93	9	0	1	0	2	0	105
18:45	95	10	0	1	0	0	0	106
1 Hr	447	46	3	4	1	7	2	510

93	15	1	2	1	0	0	0	112
95	11	2	0	1	0	1	1	110
119	12	0	1	0	0	0	0	132
98	3	0	1	0	1	0	0	103
405	41	3	4	2	1	1	1	457

19:00	96	10	1	1	1	0	0	109
19:15	74	4	1	2	0	0	1	82
19:30	84	10	2	0	0	0	0	96
19:45	82	4	1	1	1	0	0	89
1 Hr	336	28	5	4	2	0	1	376

72	8	4	4	3	1	1	1	93
68	9	3	3	1	0	1	1	85
56	5	2	1	1	2	0	0	67
56	4	2	0	0	1	0	0	63
252	26	11	8	5	4	2	2	308

20:00	61	2	2	0	2	0	0	67
20:15	53	8	1	0	0	1	0	63
20:30	56	1	0	1	0	0	1	59
20:45	66	4	0	0	0	1	0	71
1 Hr	236	15	3	1	2	2	1	260

47	1	2	1	0	1	0	0	52
36	8	0	1	0	2	0	0	47
32	4	0	1	1	2	0	0	40
31	2	1	0	0	0	0	0	34
146	15	3	3	1	5	0	0	173

21:00	56	5	1	0	1	1	0	64
21:15	38	3	1	0	0	0	0	42
21:30	38	2	1	0	0	0	0	41
21:45	30	2	0	0	0	0	0	32
1 Hr	162	12	3	0	1	1	0	179

33	1	0	0	0	1	0	0	35
32	1	1	1	0	3	0	0	38
16	2	1	2	0	2	0	0	23
17	1	0	0	1	0	0	0	19
98	5	2	3	1	6	0	0	115

22:00	33	0	0	0	0	0	0	33
22:15	30	1	0	1	0	0	0	32
22:30	25	0	1	0	0	0	0	26
22:45	12	0	0	0	0	0	0	12
1 Hr	100	1	1	1	0	0	0	103

19	0	1	0	0	1	0	0	21
10	0	0	1	0	0	0	0	11
12	3	0	1	0	0	0	0	16
7	1	0	0	0	0	0	0	8
48	4	1	2	0	1	0	0	56

23:00	17	1	2	0	0	0	0	20
23:15	7	4	1	2	0	0	0	14
23:30	21	0	1	0	0	0	0	22
23:45	12	0	0	1	0	0	0	13
1 Hr	57	5	4	3	0	0	0	69

8	0	0	0	0	0	0	0	8
9	1	0	0	0	0	0	0	10
5	1	1	0	0	0	0	0	7
8	1	0	1	0	0	0	0	10
30	3	1	1	0	0	0	0	35

6 Hrs	1338	107	19	13	6	10	4	1497
-------	------	-----	----	----	---	----	---	------

979	94	21	21	9	17	3	1144
-----	----	----	----	---	----	---	------

12 Hrs	4867	476	131	137	28	43	8	5690
--------	------	-----	-----	-----	----	----	---	------

3821	516	165	117	27	38	9	4693
------	-----	-----	-----	----	----	---	------

Total	7017	948	332	249	47	51	8	8652
-------	------	-----	-----	-----	----	----	---	------

7155	1011	293	262	48	61	9	8839
------	------	-----	-----	----	----	---	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Tuesday 3rd June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	6	1	0	0	0	0	0	7
00:15	7	1	0	0	0	0	0	8
00:30	7	1	1	2	0	0	0	11
00:45	5	1	0	2	0	0	0	8
1 Hr	25	4	1	4	0	0	0	34
01:00	2	0	1	0	0	0	0	3
01:15	4	1	0	2	0	0	0	7
01:30	2	2	0	1	0	0	0	5
01:45	2	0	1	1	0	0	0	4
1 Hr	10	3	2	4	0	0	0	19
02:00	4	0	0	0	0	0	0	4
02:15	2	0	1	1	0	0	0	4
02:30	5	0	0	0	0	0	0	5
02:45	3	1	0	1	0	0	0	5
1 Hr	14	1	1	2	0	0	0	18
03:00	4	1	1	1	0	0	0	7
03:15	3	2	0	0	0	0	0	5
03:30	5	0	0	1	0	0	0	6
03:45	1	1	2	0	0	0	0	4
1 Hr	13	4	3	2	0	0	0	22
04:00	1	2	1	0	0	0	0	4
04:15	2	3	1	0	0	0	0	6
04:30	5	5	1	1	0	0	0	12
04:45	1	1	0	4	0	0	0	6
1 Hr	9	11	3	5	0	0	0	28
05:00	4	0	0	2	0	0	1	7
05:15	6	2	3	4	0	0	0	15
05:30	9	3	6	3	0	0	0	21
05:45	17	3	5	4	0	0	0	29
1 Hr	36	8	14	13	0	0	1	72
6 Hrs	107	31	24	30	0	0	1	193

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	4	2	0	1	0	0	0	7
00:15	8	3	2	0	0	1	0	14
00:30	2	1	0	0	0	0	0	3
00:45	4	1	0	1	0	0	0	6
1 Hr	18	7	2	2	0	1	0	30
01:00	0	0	1	2	0	0	0	3
01:15	5	1	1	0	0	0	0	7
01:30	3	0	0	0	0	0	0	3
01:45	6	0	1	2	0	0	0	9
1 Hr	14	1	3	4	0	0	0	22
02:00	2	0	0	0	0	0	0	2
02:15	0	0	0	0	0	0	0	0
02:30	0	0	1	0	0	0	0	1
02:45	2	1	0	1	0	0	0	4
1 Hr	4	1	1	1	0	0	0	7
03:00	1	0	0	0	0	0	0	1
03:15	1	2	0	0	0	0	0	3
03:30	3	1	0	0	0	0	0	4
03:45	3	0	0	0	0	0	0	3
1 Hr	8	3	0	0	0	0	0	11
04:00	5	0	1	1	0	0	0	7
04:15	3	1	0	4	0	0	0	8
04:30	8	2	1	1	0	0	0	12
04:45	6	4	0	3	0	0	0	13
1 Hr	22	7	2	9	0	0	0	40
05:00	6	3	1	4	0	0	0	14
05:15	17	1	1	2	0	0	0	21
05:30	30	4	1	5	0	1	0	41
05:45	44	9	3	3	0	1	0	60
1 Hr	97	17	6	14	0	2	0	136
6 Hrs	163	36	14	30	0	3	0	246

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	0	0	0	0
18:00	0	0	0	0
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	0	0	0	0
3 Hrs	0	0	0	0
6 Hrs	0	0	0	0

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	0	0	0
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	1	0	1
1 Hr	1	0	1
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	0	0	0
3 Hrs	1	0	1
6 Hrs	1	0	1

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	16	13	5	3	1	0	0	38
06:15	22	5	5	3	2	1	0	38
06:30	27	24	5	3	0	0	0	59
06:45	43	14	6	10	1	0	0	74
1 Hr	108	56	21	19	4	1	0	209

29	8	3	4	0	0	1	45
57	9	1	5	0	0	0	72
61	11	5	12	0	3	1	93
89	19	3	9	1	0	0	121
236	47	12	30	1	3	2	331

07:00	51	15	10	1	3	0	0	80
07:15	77	24	10	5	0	0	0	116
07:30	84	21	7	7	1	1	0	121
07:45	95	31	9	4	0	1	0	140
1 Hr	307	91	36	17	4	2	0	457

116	29	5	5	0	0	0	155
117	22	7	3	1	0	0	150
163	33	3	1	0	2	0	202
177	21	6	3	2	1	0	210
573	105	21	12	3	3	0	717

08:00	75	20	13	14	0	0	0	122
08:15	73	16	13	8	0	0	0	110
08:30	82	25	2	6	0	1	0	116
08:45	62	30	7	7	0	1	0	107
1 Hr	292	91	35	35	0	2	0	455

171	16	5	6	1	3	0	202
135	16	5	4	3	2	0	165
149	17	3	6	0	3	0	178
133	7	2	9	0	0	0	151
588	56	15	25	4	8	0	696

09:00	78	24	4	6	3	2	0	117
09:15	61	18	6	6	3	0	0	94
09:30	95	26	2	2	0	1	0	126
09:45	75	14	12	2	3	0	0	106
1 Hr	309	82	24	16	9	3	0	443

129	11	10	1	0	0	0	151
132	16	5	5	0	0	0	158
139	9	4	8	3	2	0	165
101	6	12	5	1	0	0	125
501	42	31	19	4	2	0	599

10:00	96	14	9	6	2	0	0	127
10:15	69	16	7	8	2	2	0	104
10:30	83	13	3	2	0	2	0	103
10:45	87	14	10	6	3	1	0	121
1 Hr	335	57	29	22	7	5	0	455

104	11	11	9	1	2	0	138
108	14	6	6	3	0	0	137
98	14	5	4	5	0	0	126
95	11	15	3	0	2	0	126
405	50	37	22	9	4	0	527

11:00	90	15	5	6	1	2	0	119
11:15	102	14	9	5	1	2	0	133
11:30	97	11	4	8	0	0	0	120
11:45	91	18	5	5	0	1	0	120
1 Hr	380	58	23	24	2	5	0	492

107	12	5	2	0	2	0	128
108	4	2	3	0	1	0	118
99	14	11	7	1	1	0	133
102	14	8	4	0	1	0	129
416	44	26	16	1	5	0	508

6 Hrs	1731	435	168	133	26	18	0	2511
-------	------	-----	-----	-----	----	----	---	------

2719	344	142	124	22	25	2	3378
------	-----	-----	-----	----	----	---	------

12 Hrs	1838	466	192	163	26	18	1	2704
--------	------	-----	-----	-----	----	----	---	------

2882	380	156	154	22	28	2	3624
------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Tuesday 3rd June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	107	14	4	4	1	2	0	132
12:15	109	16	7	4	0	0	1	137
12:30	85	9	3	4	0	0	0	101
12:45	112	13	5	4	1	1	0	136
1 Hr	413	52	19	16	2	3	1	506

12:00	90	20	4	5	0	2	0	121
12:15	114	24	11	5	0	0	0	154
12:30	77	12	9	4	2	0	0	104
12:45	108	19	5	6	0	0	0	138
1 Hr	389	75	29	20	2	2	0	517

13:00	105	5	6	4	0	1	0	121
13:15	116	16	6	6	2	3	0	149
13:30	114	10	4	2	0	1	0	131
13:45	107	12	8	5	0	1	0	133
1 Hr	442	43	24	17	2	6	0	534

13:00	90	18	8	3	0	2	0	121
13:15	98	13	8	9	0	1	0	129
13:30	95	11	5	5	1	1	0	118
13:45	98	19	3	1	0	2	0	123
1 Hr	381	61	24	18	1	6	0	491

14:00	105	17	4	5	0	1	0	132
14:15	102	12	3	7	4	0	0	128
14:30	105	13	5	1	3	0	1	128
14:45	117	14	6	4	0	5	0	146
1 Hr	429	56	18	17	7	6	1	534

14:00	104	23	10	2	0	0	0	139
14:15	75	17	5	3	1	0	0	101
14:30	92	13	5	3	2	2	0	117
14:45	84	18	10	5	0	0	0	117
1 Hr	355	71	30	13	3	2	0	474

15:00	125	20	5	6	1	0	0	157
15:15	101	11	3	3	1	0	0	119
15:30	162	18	7	2	0	2	0	191
15:45	148	21	6	3	1	3	0	182
1 Hr	536	70	21	14	3	5	0	649

15:00	112	25	12	4	2	1	0	156
15:15	102	15	5	4	1	0	0	127
15:30	107	19	6	5	2	1	0	140
15:45	91	29	6	3	0	0	0	129
1 Hr	412	88	29	16	5	2	0	552

16:00	154	22	3	2	0	0	2	183
16:15	155	22	5	3	3	0	1	189
16:30	148	20	2	3	0	2	1	176
16:45	161	20	2	5	0	5	0	193
1 Hr	618	84	12	13	3	7	4	741

16:00	100	26	10	4	0	0	2	142
16:15	83	26	7	0	0	1	0	117
16:30	106	20	9	4	2	1	1	143
16:45	103	22	7	4	2	0	0	138
1 Hr	392	94	33	12	4	2	3	540

17:00	176	18	5	3	1	1	0	204
17:15	169	17	5	0	0	1	0	192
17:30	166	16	4	4	3	3	0	196
17:45	157	16	2	4	0	4	1	184
1 Hr	668	67	16	11	4	9	1	776

17:00	120	17	5	5	2	1	1	151
17:15	106	12	11	1	1	1	0	132
17:30	112	15	6	2	3	0	0	138
17:45	139	28	4	1	0	2	0	174
1 Hr	477	72	26	9	6	4	1	595

6 Hrs	3106	372	110	88	21	36	7	3740
-------	------	-----	-----	----	----	----	---	------

6 Hrs	2406	461	171	88	21	18	4	3169
-------	------	-----	-----	----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Tuesday 3rd June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	152	11	1	1	0	0	0	165
18:15	126	8	2	2	0	4	1	143
18:30	100	11	0	1	1	0	0	113
18:45	88	6	0	1	0	2	0	97
1 Hr	466	36	3	5	1	6	1	518

18:00	98	13	6	0	2	1	1	121
18:15	90	13	2	1	1	3	0	110
18:30	114	8	5	5	2	7	0	141
18:45	85	8	2	0	0	1	1	97
1 Hr	387	42	15	6	5	12	2	469

19:00	96	12	0	2	0	2	0	112
19:15	98	6	2	1	1	0	0	108
19:30	59	5	1	1	1	0	0	67
19:45	73	5	0	0	0	2	0	80
1 Hr	326	28	3	4	2	4	0	367

19:00	74	1	1	3	1	1	4	85
19:15	49	7	1	0	0	0	0	57
19:30	52	2	1	4	1	0	0	60
19:45	43	7	1	0	3	0	1	55
1 Hr	218	17	4	7	5	1	5	257

20:00	84	2	1	2	0	2	0	91
20:15	77	1	4	1	1	1	1	86
20:30	63	0	1	1	0	0	2	67
20:45	35	3	0	4	0	0	1	43
1 Hr	259	6	6	8	1	3	4	287

20:00	43	3	0	3	0	1	0	50
20:15	43	3	2	0	0	0	0	48
20:30	41	3	3	0	1	3	0	51
20:45	41	3	1	1	0	1	0	47
1 Hr	168	12	6	4	1	5	0	196

21:00	52	4	0	0	1	3	0	60
21:15	63	3	1	0	0	4	0	71
21:30	41	0	1	1	0	0	0	43
21:45	38	1	2	0	0	1	0	42
1 Hr	194	8	4	1	1	8	0	216

21:00	28	3	0	1	0	0	0	32
21:15	38	1	1	1	0	0	0	41
21:30	18	2	2	2	0	1	0	25
21:45	12	0	0	0	0	0	0	12
1 Hr	96	6	3	4	0	1	0	110

22:00	42	1	0	1	0	0	0	44
22:15	34	3	1	0	0	0	0	38
22:30	19	1	0	1	0	0	0	21
22:45	20	2	0	0	0	1	0	23
1 Hr	115	7	1	2	0	1	0	126

22:00	19	3	1	0	0	0	0	23
22:15	25	0	2	2	0	0	0	29
22:30	20	0	1	1	0	0	0	22
22:45	12	0	0	0	0	0	0	12
1 Hr	76	3	4	3	0	0	0	86

23:00	12	0	0	1	0	0	0	13
23:15	10	1	1	0	0	0	0	12
23:30	11	0	1	1	0	0	0	13
23:45	13	2	1	0	0	0	0	16
1 Hr	46	3	3	2	0	0	0	54

23:00	17	1	0	0	0	0	0	18
23:15	7	1	1	0	0	0	0	9
23:30	12	0	0	0	0	0	0	12
23:45	5	0	0	0	0	0	0	5
1 Hr	41	2	1	0	0	0	0	44

6 Hrs	1406	88	20	22	5	22	5	1568
-------	------	----	----	----	---	----	---	------

6 Hrs	986	82	33	24	11	19	7	1162
-------	-----	----	----	----	----	----	---	------

12 Hrs	4512	460	130	110	26	58	12	5308
--------	------	-----	-----	-----	----	----	----	------

12 Hrs	3392	543	204	112	32	37	11	4331
--------	------	-----	-----	-----	----	----	----	------

Total	6350	926	322	273	52	76	13	8012
-------	------	-----	-----	-----	----	----	----	------

Total	6274	923	360	266	54	65	13	7955
-------	------	-----	-----	-----	----	----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Wednesday 4th June 2014

AM Weather: Mild & Heavy Rain
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	8	1	0	0	0	0	0	9
00:15	6	1	0	1	0	0	0	8
00:30	7	0	1	0	0	0	0	8
00:45	5	0	0	2	0	0	0	7
1 Hr	26	2	1	3	0	0	0	32
01:00	1	2	1	2	0	0	0	6
01:15	1	1	0	2	0	0	0	4
01:30	2	2	0	0	0	0	0	4
01:45	3	0	2	0	0	0	0	5
1 Hr	7	5	3	4	0	0	0	19
02:00	3	0	0	0	0	0	0	3
02:15	5	0	0	1	0	0	0	6
02:30	3	1	1	0	0	0	0	5
02:45	4	0	1	0	0	0	0	5
1 Hr	15	1	2	1	0	0	0	19
03:00	2	0	0	2	0	0	0	4
03:15	3	1	0	0	0	0	0	4
03:30	1	0	0	0	0	0	0	1
03:45	2	0	0	1	0	0	0	3
1 Hr	8	1	0	3	0	0	0	12
04:00	2	2	2	2	0	0	0	8
04:15	6	3	0	0	0	0	0	9
04:30	4	1	0	3	0	0	0	8
04:45	6	0	1	4	0	0	0	11
1 Hr	18	6	3	9	0	0	0	36
05:00	8	1	0	2	0	0	1	12
05:15	5	2	4	2	0	0	0	13
05:30	10	2	3	4	0	0	0	19
05:45	10	4	3	7	0	0	0	24
1 Hr	33	9	10	15	0	0	1	68
6 Hrs	107	24	19	35	0	0	1	186

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	3	0	0	2	0	0	0	5
00:15	3	2	0	1	0	0	0	6
00:30	1	0	2	0	0	0	0	3
00:45	3	0	2	0	0	0	0	5
1 Hr	10	2	4	3	0	0	0	19
01:00	2	1	0	0	0	0	0	3
01:15	1	1	0	0	0	0	0	2
01:30	4	2	1	1	0	0	0	8
01:45	1	2	0	1	0	0	0	4
1 Hr	8	6	1	2	0	0	0	17
02:00	3	1	0	0	0	0	0	4
02:15	0	1	0	3	0	0	0	4
02:30	2	1	0	1	0	0	0	4
02:45	2	0	0	0	0	0	0	2
1 Hr	7	3	0	4	0	0	0	14
03:00	3	1	0	0	0	0	0	4
03:15	1	2	0	1	0	0	0	4
03:30	1	1	0	0	0	0	0	2
03:45	1	1	0	3	0	0	0	5
1 Hr	6	5	0	4	0	0	0	15
04:00	1	0	1	0	0	0	0	2
04:15	1	2	0	0	0	0	0	3
04:30	7	1	0	4	0	0	0	12
04:45	4	4	0	1	0	0	0	9
1 Hr	13	7	1	5	0	0	0	26
05:00	9	1	2	3	0	0	0	15
05:15	11	2	0	6	0	0	0	19
05:30	34	9	0	9	0	0	0	52
05:45	26	6	0	3	0	0	0	35
1 Hr	80	18	2	21	0	0	0	121
6 Hrs	124	41	8	39	0	0	0	212

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	0	0	0	0
18:00	0	0	0	0
18:15	0	0	0	0
18:30	1	0	0	1
18:45	0	0	0	0
1 Hr	1	0	0	1
3 Hrs	1	0	0	1
6 Hrs	1	0	0	1

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	0	0	0
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	0	0	0
1 Hr	0	0	0
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	0	0	0
3 Hrs	0	0	0
6 Hrs	0	0	0

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	12	5	8	4	2	0	0	31
06:15	18	7	19	4	1	1	0	50
06:30	26	14	11	2	0	0	0	53
06:45	43	17	5	5	0	0	0	70
1 Hr	99	43	43	15	3	1	0	204

37	10	3	5	0	0	0	0	55
55	12	6	6	0	2	0	0	81
55	18	0	3	0	0	1	0	77
90	24	3	6	1	0	0	0	124
237	64	12	20	1	2	1	0	337

07:00	59	19	13	11	2	1	0	105
07:15	73	18	15	8	1	0	0	115
07:30	92	15	11	8	0	0	0	126
07:45	77	33	12	4	1	2	0	129
1 Hr	301	85	51	31	4	3	0	475

100	20	3	4	0	1	0	0	128
129	23	1	2	1	0	0	0	156
159	28	7	6	0	0	0	0	200
154	18	4	4	2	3	0	0	185
542	89	15	16	3	4	0	0	669

08:00	76	22	11	5	0	0	0	114
08:15	85	19	14	3	0	0	0	121
08:30	81	22	6	5	0	0	0	114
08:45	84	28	10	6	1	0	0	129
1 Hr	326	91	41	19	1	0	0	478

185	16	8	4	1	3	0	0	217
150	17	8	5	2	1	0	0	183
140	11	6	6	0	1	0	0	164
156	11	7	6	0	0	0	0	180
631	55	29	21	3	5	0	0	744

09:00	73	19	10	6	1	1	0	110
09:15	72	11	8	6	2	0	0	99
09:30	89	23	5	4	0	1	0	122
09:45	88	17	5	6	2	0	0	118
1 Hr	322	70	28	22	5	2	0	449

128	7	7	4	0	1	0	0	147
114	13	7	8	1	0	0	0	143
135	9	4	6	4	1	0	0	159
90	16	6	5	1	0	0	0	118
467	45	24	23	6	2	0	0	567

10:00	91	28	7	4	0	0	0	130
10:15	82	15	8	4	1	0	0	110
10:30	95	14	6	4	0	0	0	119
10:45	99	20	5	7	1	0	0	132
1 Hr	367	77	26	19	2	0	0	491

106	12	6	4	1	0	0	0	129
108	19	7	3	1	0	0	0	138
128	18	6	6	3	0	0	0	161
134	20	10	5	0	0	0	0	169
476	69	29	18	5	0	0	0	597

11:00	88	16	4	2	3	0	0	113
11:15	92	15	9	4	1	1	0	122
11:30	93	18	5	3	0	0	0	119
11:45	97	13	5	8	1	1	0	125
1 Hr	370	62	23	17	5	2	0	479

109	14	3	2	0	0	0	0	128
101	8	4	6	0	0	1	0	120
91	12	4	1	1	1	0	0	110
133	19	5	8	3	0	0	0	168
434	53	16	17	4	1	1	0	526

6 Hrs	1785	428	212	123	20	8	0	2576
-------	------	-----	-----	-----	----	---	---	------

2787	375	125	115	22	14	2	0	3440
------	-----	-----	-----	----	----	---	---	------

12 Hrs	1892	452	231	158	20	8	1	2762
--------	------	-----	-----	-----	----	---	---	------

2911	416	133	154	22	14	2	0	3652
------	-----	-----	-----	----	----	---	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Wednesday 4th June 2014

AM Weather: Mild & Heavy Rain
 PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	96	11	5	3	0	0	0	115
12:15	106	12	5	2	1	0	0	126
12:30	95	9	6	6	0	0	0	116
12:45	112	17	0	6	0	0	0	135
1 Hr	409	49	16	17	1	0	0	492

12:00	92	16	6	2	0	0	0	116
12:15	106	15	5	5	0	2	0	133
12:30	99	19	8	2	2	1	0	131
12:45	85	26	5	8	0	0	0	124
1 Hr	382	76	24	17	2	3	0	504

13:00	94	16	7	3	1	1	0	122
13:15	100	14	6	7	2	1	0	130
13:30	90	12	5	9	0	0	0	116
13:45	115	13	10	3	0	0	0	141
1 Hr	399	55	28	22	3	2	0	509

13:00	105	17	9	8	0	0	0	139
13:15	119	17	4	5	0	0	0	145
13:30	127	20	6	3	1	0	0	157
13:45	111	19	6	8	0	0	0	144
1 Hr	462	73	25	24	1	0	0	585

14:00	114	13	4	8	0	0	0	139
14:15	101	20	1	10	2	1	0	135
14:30	109	16	6	7	2	1	0	141
14:45	110	22	6	7	0	0	0	145
1 Hr	434	71	17	32	4	2	0	560

14:00	101	17	8	7	1	0	0	134
14:15	85	20	11	4	2	1	0	123
14:30	100	18	8	4	2	0	0	132
14:45	104	24	9	9	1	0	0	147
1 Hr	390	79	36	24	6	1	0	536

15:00	132	10	2	8	0	1	0	153
15:15	161	14	8	8	1	1	0	193
15:30	151	11	4	2	0	1	0	169
15:45	122	17	2	2	0	1	0	144
1 Hr	566	52	16	20	1	4	0	659

15:00	84	16	9	3	0	0	0	112
15:15	87	17	8	9	1	0	0	122
15:30	105	20	3	3	1	2	0	134
15:45	100	26	8	3	0	0	0	137
1 Hr	376	79	28	18	2	2	0	505

16:00	134	17	4	3	0	0	1	159
16:15	140	21	5	6	3	0	0	175
16:30	174	18	7	4	0	0	0	203
16:45	181	18	5	3	0	0	1	208
1 Hr	629	74	21	16	3	0	2	745

16:00	98	21	10	3	0	1	1	134
16:15	104	20	5	3	1	1	0	134
16:30	126	29	8	4	1	1	0	169
16:45	100	21	7	5	2	0	0	135
1 Hr	428	91	30	15	4	3	1	572

17:00	147	15	1	2	1	0	0	166
17:15	144	13	4	4	1	0	0	166
17:30	147	10	3	1	1	3	0	165
17:45	155	20	0	4	1	1	0	181
1 Hr	593	58	8	11	4	4	0	678

17:00	149	21	6	4	0	0	0	180
17:15	87	14	3	2	2	2	1	111
17:30	87	14	5	2	1	0	0	109
17:45	138	27	5	1	1	0	0	172
1 Hr	461	76	19	9	4	2	1	572

6 Hrs	3030	359	106	118	16	12	2	3643
-------	------	-----	-----	-----	----	----	---	------

6 Hrs	2499	474	162	107	19	11	2	3274
-------	------	-----	-----	-----	----	----	---	------

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	168	16	2	1	0	1	0	188
18:15	148	9	1	4	1	0	0	163
18:30	121	6	0	1	0	3	0	131
18:45	119	21	1	0	1	3	1	146
1 Hr	556	52	4	6	2	7	1	628

18:00	104	16	2	1	1	0	0	124
18:15	114	12	2	3	1	1	0	133
18:30	97	10	0	0	0	0	0	107
18:45	89	8	2	2	0	0	0	101
1 Hr	404	46	6	6	2	1	0	465

19:00	114	16	0	0	1	0	0	131
19:15	102	13	2	0	0	0	0	117
19:30	92	5	2	1	0	0	0	100
19:45	83	4	1	1	1	0	0	90
1 Hr	391	38	5	2	2	0	0	438

19:00	66	7	4	4	1	0	0	82
19:15	70	9	2	5	2	2	0	90
19:30	66	6	3	2	1	0	0	78
19:45	50	9	2	1	0	0	0	62
1 Hr	252	31	11	12	4	2	0	312

20:00	78	3	0	1	1	1	0	84
20:15	81	1	1	2	0	1	0	86
20:30	54	6	3	1	0	0	0	64
20:45	50	2	0	2	0	0	0	54
1 Hr	263	12	4	6	1	2	0	288

20:00	57	9	0	0	0	0	0	66
20:15	42	2	0	0	0	0	1	45
20:30	36	5	0	0	1	1	0	43
20:45	48	6	1	0	0	1	0	56
1 Hr	183	22	1	0	1	2	1	210

21:00	70	3	0	0	1	1	0	75
21:15	51	2	1	1	0	0	0	55
21:30	56	1	2	1	0	0	0	60
21:45	51	1	1	1	0	0	0	54
1 Hr	228	7	4	3	1	1	0	244

21:00	32	3	0	1	0	0	0	36
21:15	30	11	1	1	0	1	0	44
21:30	24	8	1	2	1	0	0	36
21:45	27	6	1	3	0	0	0	37
1 Hr	113	28	3	7	1	1	0	153

22:00	40	1	1	0	0	1	0	43
22:15	42	3	0	0	0	0	0	45
22:30	34	2	0	1	0	0	0	37
22:45	21	0	0	0	0	0	0	21
1 Hr	137	6	1	1	0	1	0	146

22:00	15	7	1	2	0	0	0	25
22:15	16	2	1	0	0	0	0	19
22:30	20	1	1	1	0	0	0	23
22:45	15	2	0	0	0	0	0	17
1 Hr	66	12	3	3	0	0	0	84

23:00	26	2	0	2	0	0	0	30
23:15	17	0	0	0	0	0	0	17
23:30	15	0	1	3	0	0	0	19
23:45	9	1	0	0	0	0	0	10
1 Hr	67	3	1	5	0	0	0	76

23:00	6	4	0	0	0	0	0	10
23:15	10	2	0	0	0	0	0	12
23:30	8	3	1	1	0	0	0	13
23:45	3	1	1	0	0	0	0	5
1 Hr	27	10	2	1	0	0	0	40

6 Hrs	1642	118	19	23	6	11	1	1820
-------	------	-----	----	----	---	----	---	------

6 Hrs	1045	149	26	29	8	6	1	1264
-------	------	-----	----	----	---	---	---	------

12 Hrs	4672	477	125	141	22	23	3	5463
--------	------	-----	-----	-----	----	----	---	------

12 Hrs	3544	623	188	136	27	17	3	4538
--------	------	-----	-----	-----	----	----	---	------

Total	6564	929	356	299	42	31	4	8225
-------	------	-----	-----	-----	----	----	---	------

Total	6455	1039	321	290	49	31	5	8190
-------	------	------	-----	-----	----	----	---	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Thursday 5th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	6	1	0	1	0	0	0	8
00:15	8	2	1	2	0	0	0	13
00:30	7	1	0	1	0	0	0	9
00:45	4	0	0	0	0	0	0	4
1 Hr	25	4	1	4	0	0	0	34
01:00	3	0	0	1	0	0	0	4
01:15	2	0	0	2	0	0	0	4
01:30	4	1	1	2	0	0	0	8
01:45	1	0	2	0	0	0	0	3
1 Hr	10	1	3	5	0	0	0	19
02:00	3	0	0	2	0	0	0	5
02:15	3	0	0	0	0	0	0	3
02:30	4	2	0	0	0	0	0	6
02:45	1	1	0	1	0	0	0	3
1 Hr	11	3	0	3	0	0	0	17
03:00	1	0	0	2	0	0	0	3
03:15	2	0	1	0	0	0	0	3
03:30	3	0	0	0	0	0	0	3
03:45	0	0	1	3	0	0	0	4
1 Hr	6	0	2	5	0	0	0	13
04:00	2	1	3	2	0	0	0	8
04:15	1	3	1	0	0	0	0	5
04:30	4	5	1	2	0	0	0	12
04:45	3	1	2	2	0	0	0	8
1 Hr	10	10	7	6	0	0	0	33
05:00	3	0	2	2	0	1	1	9
05:15	4	2	2	2	0	0	0	10
05:30	7	2	3	1	0	0	0	13
05:45	13	3	3	6	0	0	0	25
1 Hr	27	7	10	11	0	1	1	57
6 Hrs	89	25	23	34	0	1	1	173

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	3	0	0	1	0	0	0	4
00:15	3	1	0	0	0	0	0	4
00:30	3	1	1	1	0	0	0	6
00:45	3	1	2	1	0	0	0	7
1 Hr	12	3	3	3	0	0	0	21
01:00	2	1	0	2	0	0	0	5
01:15	1	1	0	1	0	0	0	3
01:30	4	0	1	0	0	0	0	5
01:45	2	0	0	1	0	0	0	3
1 Hr	9	2	1	4	0	0	0	16
02:00	3	0	0	0	0	0	0	3
02:15	2	0	0	1	0	0	0	3
02:30	3	1	1	0	0	0	0	5
02:45	2	0	0	0	0	0	0	2
1 Hr	10	1	1	1	0	0	0	13
03:00	1	0	0	0	0	0	0	1
03:15	0	0	1	2	0	0	0	3
03:30	3	1	1	1	0	0	0	6
03:45	0	1	0	1	0	0	0	2
1 Hr	4	2	2	4	0	0	0	12
04:00	4	0	0	1	0	0	0	5
04:15	5	2	0	1	0	0	0	8
04:30	4	0	1	3	0	0	0	8
04:45	4	1	0	2	0	0	0	7
1 Hr	17	3	1	7	0	0	0	28
05:00	17	3	2	2	0	0	0	24
05:15	10	3	0	8	0	1	0	22
05:30	29	6	1	2	0	0	0	38
05:45	22	6	0	5	0	0	0	33
1 Hr	78	18	3	17	0	1	0	117
6 Hrs	130	29	11	36	0	1	0	207

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	0	0	0	0
17:30	1	0	0	1
17:45	0	0	0	0
1 Hr	1	0	0	1
18:00	0	0	0	0
18:15	1	0	1	2
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	1	0	1	2
3 Hrs	2	0	1	3
6 Hrs	2	0	1	3

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	0	0	0
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	0	0	0
1 Hr	0	0	0
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	0	0	0
3 Hrs	0	0	0
6 Hrs	0	0	0



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Thursday 5th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	19	5	3	4	2	0	0	33
06:15	14	9	4	3	5	2	1	38
06:30	23	15	8	5	1	1	0	53
06:45	51	23	10	4	0	0	0	88
1 Hr	107	52	25	16	8	3	1	212

51	7	1	2	0	1	0	62
60	10	2	7	0	1	0	80
51	15	3	0	0	0	0	69
73	22	3	5	1	0	0	104
235	54	9	14	1	2	0	315

07:00	49	17	4	2	2	0	0	74
07:15	91	28	11	2	1	0	0	133
07:30	77	30	12	6	2	2	0	129
07:45	102	24	8	5	1	1	1	142
1 Hr	319	99	35	15	6	3	1	478

76	25	5	1	0	1	0	108
116	28	3	1	1	1	0	150
153	31	7	5	0	2	0	198
152	17	3	3	0	3	0	178
497	101	18	10	1	7	0	634

08:00	86	32	15	10	0	0	0	143
08:15	76	22	8	5	0	0	0	111
08:30	87	33	4	2	0	0	0	126
08:45	82	30	7	6	2	0	0	127
1 Hr	331	117	34	23	2	0	0	507

160	13	4	4	3	2	0	186
118	13	5	5	2	0	0	143
168	23	5	5	1	4	0	206
142	11	8	5	0	0	0	166
588	60	22	19	6	6	0	701

09:00	86	18	4	9	3	0	1	121
09:15	89	19	6	4	2	0	0	120
09:30	80	23	9	6	0	0	0	118
09:45	89	29	10	9	1	0	0	138
1 Hr	344	89	29	28	6	0	1	497

134	14	9	6	0	2	0	165
150	9	8	8	0	0	0	175
127	13	7	3	3	3	0	156
123	14	4	7	1	1	0	150
534	50	28	24	4	6	0	646

10:00	69	12	11	7	2	0	0	101
10:15	99	20	4	4	0	0	0	127
10:30	115	15	11	5	0	1	0	147
10:45	91	14	7	4	2	0	0	118
1 Hr	374	61	33	20	4	1	0	493

129	10	9	8	0	5	0	161
120	12	10	8	1	1	0	152
116	13	7	3	5	0	0	144
106	13	7	7	1	0	0	134
471	48	33	26	7	6	0	591

11:00	117	11	3	6	1	0	0	138
11:15	124	21	10	5	1	0	0	161
11:30	134	17	7	9	0	0	0	167
11:45	100	13	5	6	0	0	0	124
1 Hr	475	62	25	26	2	0	0	590

103	15	10	1	0	0	0	129
120	20	11	2	0	0	0	153
92	11	5	3	1	0	0	112
115	16	10	6	0	2	0	149
430	62	36	12	1	2	0	543

6 Hrs	1950	480	181	128	28	7	3	2777
-------	------	-----	-----	-----	----	---	---	------

2755	375	146	105	20	29	0	3430
------	-----	-----	-----	----	----	---	------

12 Hrs	2039	505	204	162	28	8	4	2950
--------	------	-----	-----	-----	----	---	---	------

2885	404	157	141	20	30	0	3637
------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Thursday 5th June 2014

AM Weather: Mild & Cloudy
 PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	105	11	4	4	0	1	0	125
12:15	126	13	10	6	1	0	0	156
12:30	130	14	9	4	0	0	0	157
12:45	122	19	6	2	0	1	0	150
1 Hr	483	57	29	16	1	2	0	588

12:00	105	19	12	5	1	1	0	143
12:15	102	18	9	5	0	0	0	134
12:30	105	16	4	8	2	0	0	135
12:45	123	16	6	8	0	0	0	153
1 Hr	435	69	31	26	3	1	0	565

13:00	126	16	7	7	1	1	0	158
13:15	128	12	4	7	3	0	0	154
13:30	118	17	5	8	0	1	0	149
13:45	102	19	6	8	0	0	0	135
1 Hr	474	64	22	30	4	2	0	596

13:00	110	19	6	8	0	1	0	144
13:15	106	14	10	8	0	1	1	140
13:30	117	18	6	4	1	0	0	146
13:45	76	20	8	7	0	1	0	112
1 Hr	409	71	30	27	1	3	1	542

14:00	99	11	4	6	1	1	0	122
14:15	123	15	3	3	1	0	0	145
14:30	104	14	5	6	2	0	0	131
14:45	128	11	4	4	1	1	0	149
1 Hr	454	51	16	19	5	2	0	547

14:00	107	25	2	5	0	1	1	141
14:15	90	18	2	2	1	1	0	114
14:30	67	20	7	3	2	2	0	101
14:45	129	24	7	2	0	0	0	162
1 Hr	393	87	18	12	3	4	1	518

15:00	142	15	5	4	0	1	1	168
15:15	137	15	7	7	2	1	1	170
15:30	146	22	1	3	0	2	0	174
15:45	135	21	8	2	2	3	1	172
1 Hr	560	73	21	16	4	7	3	684

15:00	100	19	8	3	1	0	0	131
15:15	89	18	2	1	0	1	1	112
15:30	127	23	7	5	1	1	0	164
15:45	116	22	6	7	2	0	1	154
1 Hr	432	82	23	16	4	2	2	561

16:00	164	22	3	2	0	7	0	198
16:15	170	17	6	4	3	3	0	203
16:30	154	14	6	3	0	3	2	182
16:45	171	25	4	2	0	1	1	204
1 Hr	659	78	19	11	3	14	3	787

16:00	116	26	5	3	1	3	0	154
16:15	109	29	4	3	0	0	0	145
16:30	119	30	3	4	1	1	0	158
16:45	122	23	8	2	3	0	1	159
1 Hr	466	108	20	12	5	4	1	616

17:00	174	15	5	1	1	7	0	203
17:15	181	17	0	1	1	3	0	203
17:30	139	21	4	2	2	8	1	177
17:45	169	17	5	2	0	6	0	199
1 Hr	663	70	14	6	4	24	1	782

17:00	123	21	9	3	1	0	0	157
17:15	102	17	4	3	0	3	0	129
17:30	84	14	5	0	3	2	2	110
17:45	125	18	5	3	0	0	2	153
1 Hr	434	70	23	9	4	5	4	549

6 Hrs	3293	393	121	98	21	51	7	3984
-------	------	-----	-----	----	----	----	---	------

6 Hrs	2569	487	145	102	20	19	9	3351
-------	------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Thursday 5th June 2014

AM Weather: Mild & Cloudy
 PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	135	15	3	2	0	6	1	162
18:15	128	15	3	1	1	4	0	152
18:30	124	8	3	5	0	9	0	149
18:45	120	9	3	1	0	8	0	141
1 Hr	507	47	12	9	1	27	1	604

18:00	100	20	0	2	1	0	1	124
18:15	98	10	2	4	0	0	1	115
18:30	93	16	7	8	1	0	1	126
18:45	102	10	6	3	0	1	0	122
1 Hr	393	56	15	17	2	1	3	487

19:00	100	10	0	2	0	4	0	116
19:15	111	11	1	3	1	1	0	128
19:30	99	7	1	1	1	5	1	115
19:45	87	5	1	4	0	6	0	103
1 Hr	397	33	3	10	2	16	1	462

19:00	80	3	2	2	0	1	0	88
19:15	77	8	1	0	3	2	0	91
19:30	48	8	1	2	1	3	0	63
19:45	43	7	2	1	0	6	1	60
1 Hr	248	26	6	5	4	12	1	302

20:00	69	7	0	1	1	0	1	79
20:15	69	3	2	1	0	2	0	77
20:30	53	5	3	0	0	0	0	61
20:45	60	4	2	0	0	0	0	66
1 Hr	251	19	7	2	1	2	1	283

20:00	41	6	0	0	0	1	0	48
20:15	40	3	1	5	0	2	0	51
20:30	26	4	0	0	1	6	0	37
20:45	32	2	1	3	0	3	2	43
1 Hr	139	15	2	8	1	12	2	179

21:00	58	3	1	0	1	3	0	66
21:15	42	4	0	1	0	2	2	51
21:30	57	2	0	0	0	0	0	59
21:45	48	2	1	1	0	0	0	52
1 Hr	205	11	2	2	1	5	2	228

21:00	27	3	1	2	1	15	0	49
21:15	19	2	0	0	0	7	0	28
21:30	30	3	0	0	0	15	0	48
21:45	30	3	1	1	0	4	0	39
1 Hr	106	11	2	3	1	41	0	164

22:00	35	4	0	0	0	3	0	42
22:15	42	4	0	0	0	0	0	46
22:30	35	2	0	1	0	0	0	38
22:45	22	2	0	3	0	0	0	27
1 Hr	134	12	0	4	0	3	0	153

22:00	22	2	3	1	0	0	0	28
22:15	23	4	0	0	0	0	0	27
22:30	23	3	1	0	0	0	0	27
22:45	13	1	0	1	0	0	0	15
1 Hr	81	10	4	2	0	0	0	97

23:00	19	4	0	0	0	1	0	24
23:15	22	1	0	2	0	0	0	25
23:30	12	0	1	1	0	0	0	14
23:45	11	1	0	0	0	0	0	12
1 Hr	64	6	1	3	0	1	0	75

23:00	20	1	0	0	0	1	0	22
23:15	10	1	0	0	0	0	0	11
23:30	12	1	0	0	0	0	0	13
23:45	7	1	0	0	0	0	0	8
1 Hr	49	4	0	0	0	1	0	54

6 Hrs	1558	128	25	30	5	54	5	1805
-------	------	-----	----	----	---	----	---	------

6 Hrs	1016	122	29	35	8	67	6	1283
-------	------	-----	----	----	---	----	---	------

12 Hrs	4851	521	146	128	26	105	12	5789
--------	------	-----	-----	-----	----	-----	----	------

12 Hrs	3585	609	174	137	28	86	15	4634
--------	------	-----	-----	-----	----	----	----	------

Total	6890	1026	350	290	54	113	16	8739
-------	------	------	-----	-----	----	-----	----	------

Total	6470	1013	331	278	48	116	15	8271
-------	------	------	-----	-----	----	-----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Friday 6th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	9	0	1	0	0	0	0	10
00:15	5	1	0	1	0	0	0	7
00:30	3	3	0	0	0	0	0	6
00:45	7	1	1	3	0	0	0	12
1 Hr	24	5	2	4	0	0	0	35
01:00	4	0	0	0	0	0	0	4
01:15	2	0	0	3	0	0	0	5
01:30	2	1	4	1	0	0	0	8
01:45	6	0	0	0	0	0	0	6
1 Hr	14	1	4	4	0	0	0	23
02:00	1	1	0	1	0	0	0	3
02:15	2	0	0	1	0	0	0	3
02:30	0	0	0	1	0	0	0	1
02:45	1	0	2	0	0	0	0	3
1 Hr	4	1	2	3	0	0	0	10
03:00	4	0	1	2	0	0	0	7
03:15	2	0	0	0	0	0	0	2
03:30	5	0	0	1	0	0	0	6
03:45	4	0	1	0	0	0	0	5
1 Hr	15	0	2	3	0	0	0	20
04:00	1	0	1	2	0	0	0	4
04:15	5	0	1	1	0	0	0	7
04:30	5	2	2	1	0	0	0	10
04:45	2	3	0	2	0	0	0	7
1 Hr	13	5	4	6	0	0	0	28
05:00	7	4	0	2	0	1	1	15
05:15	9	1	2	2	0	0	0	14
05:30	8	2	2	3	0	0	0	15
05:45	31	6	1	4	0	0	0	42
1 Hr	55	13	5	11	0	1	1	86
6 Hrs	125	25	19	31	0	1	1	202

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	6	1	0	0	0	0	0	7
00:15	2	0	0	1	0	0	0	3
00:30	7	0	1	0	0	0	0	8
00:45	2	2	1	0	0	0	0	5
1 Hr	17	3	2	1	0	0	0	23
01:00	6	0	0	0	0	0	0	6
01:15	3	0	0	1	0	0	0	4
01:30	2	0	0	0	0	0	0	2
01:45	5	0	0	3	0	0	0	8
1 Hr	16	0	0	4	0	0	0	20
02:00	3	1	1	0	0	0	0	5
02:15	1	2	0	1	0	0	0	4
02:30	2	0	0	0	0	0	0	2
02:45	0	0	0	1	0	0	0	1
1 Hr	6	3	1	2	0	0	0	12
03:00	4	0	1	0	0	0	0	5
03:15	1	0	0	0	0	0	0	1
03:30	4	0	0	3	0	0	0	7
03:45	6	0	1	0	0	0	0	7
1 Hr	15	0	2	3	0	0	0	20
04:00	5	0	0	0	0	0	0	5
04:15	3	0	0	2	0	0	0	5
04:30	7	1	0	3	0	0	0	11
04:45	3	1	2	2	0	0	0	8
1 Hr	18	2	2	7	0	0	0	29
05:00	16	4	0	2	0	0	0	22
05:15	16	0	0	6	0	0	0	22
05:30	20	4	1	3	0	1	0	29
05:45	13	3	8	3	0	1	0	28
1 Hr	65	11	9	14	0	2	0	101
6 Hrs	137	19	16	31	0	2	0	205

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	0	0	0	0
17:30	1	0	0	1
17:45	0	0	0	0
1 Hr	1	0	0	1
18:00	0	0	0	0
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	0	0	0	0
3 Hrs	1	0	0	1
6 Hrs	1	0	0	1

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	0	0	0
16:00	0	0	0
16:15	0	0	0
16:30	1	0	1
16:45	0	0	0
1 Hr	1	0	1
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	0	0	0
3 Hrs	1	0	1
6 Hrs	1	0	1



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Friday 6th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	21	2	3	0	2	0	0	28
06:15	25	3	3	7	1	1	0	40
06:30	31	6	9	1	1	0	0	48
06:45	37	18	4	3	0	0	0	62
1 Hr	114	29	19	11	4	1	0	178

25	7	3	6	0	0	0	41
50	10	0	4	0	3	0	67
58	18	3	4	0	2	1	86
74	22	7	1	1	0	0	105
207	57	13	15	1	5	1	299

07:00	59	21	12	0	2	1	0	95
07:15	68	28	13	6	1	1	0	117
07:30	90	26	11	6	1	1	0	135
07:45	102	33	8	7	0	2	1	153
1 Hr	319	108	44	19	4	5	1	500

91	20	2	6	0	0	0	119
128	19	3	4	1	3	0	158
146	28	3	7	0	4	0	188
159	15	6	7	0	4	0	191
524	82	14	24	1	11	0	656

08:00	73	30	14	3	0	0	0	120
08:15	86	29	15	1	0	0	0	131
08:30	97	22	11	4	0	0	0	134
08:45	104	24	7	6	1	0	0	142
1 Hr	360	105	47	14	1	0	0	527

158	21	7	7	4	1	1	199
155	25	6	6	2	0	0	194
136	20	9	7	0	3	0	175
121	9	10	2	1	1	0	144
570	75	32	22	7	5	1	712

09:00	100	18	6	12	3	0	0	139
09:15	94	18	5	3	2	4	0	126
09:30	102	22	8	5	0	2	0	139
09:45	116	11	11	6	1	4	0	149
1 Hr	412	69	30	26	6	10	0	553

154	10	11	6	0	1	0	182
155	14	8	3	0	0	0	180
139	18	10	3	1	0	0	171
124	15	4	5	3	2	0	153
572	57	33	17	4	3	0	686

10:00	125	18	14	3	1	3	0	164
10:15	145	15	8	4	2	1	0	175
10:30	172	13	7	4	0	3	0	199
10:45	153	16	9	2	0	1	0	181
1 Hr	595	62	38	13	3	8	0	719

149	10	7	7	0	1	0	174
141	19	1	1	2	0	0	164
166	10	4	3	2	0	0	185
154	10	6	2	1	1	0	174
610	49	18	13	5	2	0	697

11:00	163	20	12	5	2	2	1	205
11:15	171	18	8	3	2	1	0	203
11:30	175	21	4	6	2	2	0	210
11:45	190	14	8	3	0	6	0	221
1 Hr	699	73	32	17	6	11	1	839

152	18	11	4	0	2	0	187
138	12	8	5	0	1	0	164
127	18	11	4	2	1	0	163
133	13	6	9	1	1	0	163
550	61	36	22	3	5	0	677

6 Hrs	2499	446	210	100	24	35	2	3316
-------	------	-----	-----	-----	----	----	---	------

3033	381	146	113	21	31	2	3727
------	-----	-----	-----	----	----	---	------

12 Hrs	2624	471	229	131	24	36	3	3518
--------	------	-----	-----	-----	----	----	---	------

3170	400	162	144	21	33	2	3932
------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Friday 6th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	179	25	2	6	0	3	0	215
12:15	166	19	10	5	2	6	0	208
12:30	174	20	4	7	0	4	0	209
12:45	168	13	3	11	1	1	0	197
1 Hr	687	77	19	29	3	14	0	829

12:00	104	22	6	6	0	1	0	139
12:15	123	20	8	4	0	1	0	156
12:30	113	17	8	2	1	7	0	148
12:45	157	13	9	2	1	4	0	186
1 Hr	497	72	31	14	2	13	0	629

13:00	165	16	3	7	1	1	0	193
13:15	158	10	4	8	3	4	0	187
13:30	163	15	6	7	1	2	0	194
13:45	147	9	5	3	0	3	0	167
1 Hr	633	50	18	25	5	10	0	741

13:00	135	26	8	2	0	2	0	173
13:15	107	24	12	2	0	2	0	147
13:30	94	9	5	2	1	4	0	115
13:45	124	17	6	6	0	1	0	154
1 Hr	460	76	31	12	1	9	0	589

14:00	144	15	5	3	1	1	0	169
14:15	143	13	8	4	2	1	0	171
14:30	158	22	2	2	1	1	0	186
14:45	162	18	4	3	1	0	0	188
1 Hr	607	68	19	12	5	3	0	714

14:00	120	21	16	2	0	2	0	161
14:15	107	27	6	3	1	3	0	147
14:30	143	7	1	1	2	5	0	159
14:45	129	18	4	2	2	0	0	155
1 Hr	499	73	27	8	5	10	0	622

15:00	174	20	2	4	0	2	0	202
15:15	195	17	2	3	2	2	0	221
15:30	174	24	5	5	0	1	2	211
15:45	194	24	10	4	1	4	0	237
1 Hr	737	85	19	16	3	9	2	871

15:00	107	24	6	2	2	5	0	146
15:15	107	16	10	3	1	1	1	139
15:30	108	22	2	2	1	2	0	137
15:45	131	25	6	5	1	4	0	172
1 Hr	453	87	24	12	5	12	1	594

16:00	189	33	2	1	3	4	0	232
16:15	190	13	2	3	2	2	1	213
16:30	188	12	1	1	0	5	0	207
16:45	202	26	4	3	0	3	0	238
1 Hr	769	84	9	8	5	14	1	890

16:00	115	33	4	3	0	4	0	159
16:15	105	27	9	2	1	1	0	145
16:30	121	20	4	3	1	3	0	152
16:45	120	15	4	1	1	1	0	142
1 Hr	461	95	21	9	3	9	0	598

17:00	207	21	3	2	0	3	0	236
17:15	175	14	6	2	3	5	0	205
17:30	232	17	5	0	1	4	0	259
17:45	206	10	1	0	0	6	0	223
1 Hr	820	62	15	4	4	18	0	923

17:00	124	10	6	2	2	1	0	145
17:15	141	20	0	5	4	5	0	175
17:30	128	14	4	2	1	6	2	157
17:45	145	12	4	4	2	2	0	169
1 Hr	538	56	14	13	9	14	2	646

6 Hrs	4253	426	99	94	25	68	3	4968
-------	------	-----	----	----	----	----	---	------

6 Hrs	2908	459	148	68	25	67	3	3678
-------	------	-----	-----	----	----	----	---	------

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	213	9	0	2	1	3	1	229
18:15	222	14	0	1	1	8	1	247
18:30	189	15	5	0	0	2	0	211
18:45	165	10	0	2	0	3	2	182
1 Hr	789	48	5	5	2	16	4	869

18:00	135	6	4	3	1	1	1	151
18:15	121	16	0	1	0	2	0	140
18:30	127	11	1	1	1	3	0	144
18:45	142	11	2	2	0	5	2	164
1 Hr	525	44	7	7	2	11	3	599

19:00	166	6	2	0	0	2	0	176
19:15	149	12	1	0	1	4	0	167
19:30	147	8	2	0	1	2	2	162
19:45	125	3	0	0	0	2	0	130
1 Hr	587	29	5	0	2	10	2	635

19:00	99	7	2	5	1	1	0	115
19:15	87	10	1	2	1	0	0	101
19:30	82	6	1	0	1	5	0	95
19:45	60	4	2	1	0	0	0	67
1 Hr	328	27	6	8	3	6	0	378

20:00	132	6	2	1	0	0	0	141
20:15	104	2	2	0	1	1	0	110
20:30	101	1	0	2	0	0	0	104
20:45	85	7	1	0	1	2	0	96
1 Hr	422	16	5	3	2	3	0	451

20:00	66	5	0	0	0	0	0	71
20:15	56	4	1	2	1	2	0	66
20:30	54	5	1	0	1	1	0	62
20:45	39	4	0	2	0	2	0	47
1 Hr	215	18	2	4	2	5	0	246

21:00	90	5	0	0	1	1	0	97
21:15	75	5	0	0	0	0	0	80
21:30	88	5	1	0	0	0	0	94
21:45	60	5	1	0	0	0	0	66
1 Hr	313	20	2	0	1	1	0	337

21:00	28	5	0	0	0	2	0	35
21:15	34	0	1	0	0	0	0	35
21:30	32	2	0	0	0	0	0	34
21:45	27	1	0	0	0	0	0	28
1 Hr	121	8	1	0	0	2	0	132

22:00	54	3	0	0	0	0	0	57
22:15	65	4	1	2	0	0	0	72
22:30	48	1	0	1	0	1	0	51
22:45	39	1	1	2	0	0	0	43
1 Hr	206	9	2	5	0	1	0	223

22:00	25	0	0	0	0	1	0	26
22:15	23	1	2	0	0	0	0	26
22:30	19	0	1	1	0	0	0	21
22:45	24	2	0	0	0	0	0	26
1 Hr	91	3	3	1	0	1	0	99

23:00	38	1	0	1	0	0	0	40
23:15	27	2	1	0	0	0	0	30
23:30	29	3	2	1	0	0	0	35
23:45	19	3	1	0	0	0	0	23
1 Hr	113	9	4	2	0	0	0	128

23:00	36	2	0	0	0	0	0	38
23:15	23	2	0	0	0	0	0	25
23:30	20	2	0	0	0	0	0	22
23:45	20	1	0	0	0	0	0	21
1 Hr	99	7	0	0	0	0	0	106

6 Hrs	2430	131	23	15	7	31	6	2643
-------	------	-----	----	----	---	----	---	------

6 Hrs	1379	107	19	20	7	25	3	1560
-------	------	-----	----	----	---	----	---	------

12 Hrs	6683	557	122	109	32	99	9	7611
--------	------	-----	-----	-----	----	----	---	------

12 Hrs	4287	566	167	88	32	92	6	5238
--------	------	-----	-----	----	----	----	---	------

Total	9307	1028	351	240	56	135	12	11129
-------	------	------	-----	-----	----	-----	----	-------

Total	7457	966	329	232	53	125	8	9170
-------	------	-----	-----	-----	----	-----	---	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 7th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Heavy Rain

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	17	0	0	0	0	0	0	17
00:15	23	1	0	1	0	0	0	25
00:30	12	2	1	2	0	0	0	17
00:45	12	1	1	0	0	0	0	14
1 Hr	64	4	2	3	0	0	0	73
01:00	7	0	0	0	0	0	0	7
01:15	9	0	1	0	0	0	0	10
01:30	6	0	0	1	0	0	0	7
01:45	8	2	0	0	0	0	0	10
1 Hr	30	2	1	1	0	0	0	34
02:00	1	0	1	0	0	0	0	2
02:15	6	1	1	0	0	0	0	8
02:30	7	0	1	0	0	0	0	8
02:45	5	0	0	2	0	0	0	7
1 Hr	19	1	3	2	0	0	0	25
03:00	4	1	0	2	0	0	0	7
03:15	3	1	0	0	0	0	0	4
03:30	6	0	1	0	0	1	0	8
03:45	1	0	1	3	0	0	0	5
1 Hr	14	2	2	5	0	1	0	24
04:00	9	0	2	1	0	0	0	12
04:15	2	3	1	2	0	0	0	8
04:30	3	5	0	1	0	0	0	9
04:45	4	3	2	2	1	0	0	12
1 Hr	18	11	5	6	1	0	0	41
05:00	7	0	0	0	0	0	0	7
05:15	9	0	2	1	0	0	0	12
05:30	6	0	0	5	0	0	0	11
05:45	11	1	2	1	0	0	0	15
1 Hr	33	1	4	7	0	0	0	45
6 Hrs	178	21	17	24	1	1	0	242

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	8	2	0	0	0	0	0	10
00:15	3	1	0	1	0	0	0	5
00:30	10	2	1	1	0	0	0	14
00:45	2	0	0	1	0	0	0	3
1 Hr	23	5	1	3	0	0	0	32
01:00	7	1	0	0	0	1	0	9
01:15	9	1	0	1	0	0	0	11
01:30	9	1	0	0	0	0	0	10
01:45	3	2	1	0	0	0	0	6
1 Hr	28	5	1	1	0	1	0	36
02:00	4	0	0	0	0	0	0	4
02:15	5	1	0	0	0	0	0	6
02:30	4	0	1	0	0	0	0	5
02:45	1	0	0	0	0	0	0	1
1 Hr	14	1	1	0	0	0	0	16
03:00	0	1	0	1	0	0	0	2
03:15	3	0	1	0	0	0	0	4
03:30	1	0	0	0	0	0	0	1
03:45	1	0	0	0	0	0	0	1
1 Hr	5	1	1	1	0	0	0	8
04:00	9	1	0	0	0	0	0	10
04:15	4	0	1	0	0	0	0	5
04:30	6	0	0	1	0	0	0	7
04:45	3	2	1	0	0	0	0	6
1 Hr	22	3	2	1	0	0	0	28
05:00	12	0	0	0	0	0	0	12
05:15	10	0	0	3	0	1	0	14
05:30	15	2	1	3	0	0	0	21
05:45	17	1	0	2	0	0	0	20
1 Hr	54	3	1	8	0	1	0	67
6 Hrs	146	18	7	14	0	2	0	187

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	2	0	0	2
1 Hr	2	0	0	2
18:00	0	0	0	0
18:15	0	0	1	1
18:30	0	0	2	2
18:45	0	0	0	0
1 Hr	0	0	3	3
3 Hrs	2	0	3	5
6 Hrs	2	0	3	5

	Direction : Westbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	1	0	0	1
16:45	0	0	0	0
1 Hr	1	0	0	1
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	0	0	0	0
18:00	0	0	0	0
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	0	0	0	0
3 Hrs	1	0	0	1
6 Hrs	1	0	0	1



Sky High

Count On Us

Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Saturday 7th June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Heavy Rain

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	14	6	2	0	0	1	1	24
06:15	20	0	5	0	0	0	0	25
06:30	29	4	4	1	2	0	0	40
06:45	25	6	7	2	0	0	0	40
1 Hr	88	16	18	3	2	1	1	129

16	2	1	1	0	1	0	21
25	2	0	1	0	0	0	28
27	13	1	0	0	0	0	41
35	8	1	4	0	0	0	48
103	25	3	6	0	1	0	138

07:00	31	4	4	2	0	0	0	41
07:15	42	7	2	1	0	0	0	52
07:30	51	10	3	0	0	1	0	65
07:45	64	8	3	2	0	0	0	77
1 Hr	188	29	12	5	0	1	0	235

41	13	4	0	0	1	0	59
53	8	2	3	1	1	0	68
61	10	1	0	0	0	0	72
69	11	1	3	2	1	0	87
224	42	8	6	3	3	0	286

08:00	66	15	1	0	0	0	0	82
08:15	91	9	4	2	1	0	0	107
08:30	75	12	2	0	0	0	0	89
08:45	88	14	3	4	2	0	0	111
1 Hr	320	50	10	6	3	0	0	389

83	9	1	1	0	1	0	95
62	8	1	0	1	0	0	72
123	11	2	3	0	0	0	139
116	8	2	1	1	3	0	131
384	36	6	5	2	4	0	437

09:00	108	9	3	0	2	0	0	122
09:15	109	9	3	1	4	0	0	126
09:30	147	11	3	0	3	2	0	166
09:45	108	12	2	2	0	0	0	124
1 Hr	472	41	11	3	9	2	0	538

111	9	4	0	1	0	0	125
132	11	5	0	1	0	0	149
123	13	0	0	0	0	0	136
142	7	1	1	2	0	0	153
508	40	10	1	4	0	0	563

10:00	135	10	4	0	0	0	0	149
10:15	155	9	2	2	1	0	0	169
10:30	172	6	2	0	0	0	0	180
10:45	163	8	2	0	7	0	0	180
1 Hr	625	33	10	2	8	0	0	678

160	4	2	1	0	3	0	170
160	10	7	2	0	0	0	179
177	10	2	2	1	0	0	192
153	7	4	1	0	0	0	165
650	31	15	6	1	3	0	706

11:00	194	10	1	3	2	1	0	211
11:15	158	15	1	2	1	1	0	178
11:30	148	9	1	5	0	0	0	163
11:45	162	9	1	1	0	1	0	174
1 Hr	662	43	4	11	3	3	0	726

167	10	3	0	2	0	0	182
141	10	2	1	0	0	7	161
157	10	2	0	1	1	0	171
145	11	3	0	0	1	0	160
610	41	10	1	3	2	7	674

6 Hrs	2355	212	65	30	25	7	1	2695
-------	------	-----	----	----	----	---	---	------

2479	215	52	25	13	13	7	2804
------	-----	----	----	----	----	---	------

12 Hrs	2533	233	82	54	26	8	1	2937
--------	------	-----	----	----	----	---	---	------

2625	233	59	39	13	15	7	2991
------	-----	----	----	----	----	---	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 7th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Heavy Rain

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	128	13	1	2	0	0	0	144
12:15	151	8	1	2	1	1	0	164
12:30	135	6	6	2	0	1	0	150
12:45	157	3	1	0	0	0	0	161
1 Hr	571	30	9	6	1	2	0	619

12:00	120	12	0	1	0	1	0	134
12:15	142	11	1	0	0	0	0	154
12:30	149	8	5	1	2	0	0	165
12:45	139	11	2	1	2	0	0	155
1 Hr	550	42	8	3	4	1	0	608

13:00	136	9	3	2	1	4	0	155
13:15	136	11	3	2	2	0	0	154
13:30	145	8	1	0	0	0	0	154
13:45	147	14	0	1	0	0	0	162
1 Hr	564	42	7	5	3	4	0	625

13:00	147	6	3	0	0	0	0	156
13:15	152	6	5	1	0	0	0	164
13:30	129	6	1	0	1	0	0	137
13:45	146	9	2	2	0	0	0	159
1 Hr	574	27	11	3	1	0	0	616

14:00	129	4	3	0	0	0	0	136
14:15	152	14	1	0	1	0	0	168
14:30	125	9	2	0	1	0	0	137
14:45	139	6	1	0	0	0	0	146
1 Hr	545	33	7	0	2	0	0	587

14:00	111	6	1	0	0	0	0	118
14:15	111	13	2	0	0	0	0	126
14:30	138	7	1	0	2	1	0	149
14:45	135	11	1	0	0	0	0	147
1 Hr	495	37	5	0	2	1	0	540

15:00	146	8	1	0	0	0	0	155
15:15	162	10	0	0	1	0	0	173
15:30	141	10	3	0	0	0	0	154
15:45	148	11	0	0	0	1	1	161
1 Hr	597	39	4	0	1	1	1	643

15:00	93	6	3	0	0	0	0	102
15:15	79	9	5	1	1	0	0	95
15:30	105	12	2	0	0	1	0	120
15:45	123	9	0	0	0	3	0	135
1 Hr	400	36	10	1	1	4	0	452

16:00	127	10	0	0	0	0	0	137
16:15	141	10	0	0	2	0	0	153
16:30	137	6	0	1	1	1	0	146
16:45	135	8	2	0	1	1	0	147
1 Hr	540	34	2	1	4	2	0	583

16:00	81	10	1	0	0	0	0	92
16:15	94	3	2	0	1	1	1	102
16:30	112	8	1	2	1	0	0	124
16:45	118	6	1	0	0	0	0	125
1 Hr	405	27	5	2	2	1	1	443

17:00	135	8	0	0	0	1	0	144
17:15	150	5	0	1	2	0	0	158
17:30	133	5	2	0	0	0	0	140
17:45	142	4	0	0	0	2	0	148
1 Hr	560	22	2	1	2	3	0	590

17:00	92	5	0	0	0	1	0	98
17:15	91	6	0	0	0	0	0	97
17:30	113	1	2	0	2	2	0	120
17:45	108	6	0	0	1	1	0	116
1 Hr	404	18	2	0	3	4	0	431

6 Hrs	3377	200	31	13	13	12	1	3647
-------	------	-----	----	----	----	----	---	------

6 Hrs	2828	187	41	9	13	11	1	3090
-------	------	-----	----	---	----	----	---	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 7th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Heavy Rain

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	127	8	1	0	0	0	0	136
18:15	129	3	0	1	1	0	0	134
18:30	94	3	2	1	0	0	0	100
18:45	110	12	1	0	0	1	0	124
1 Hr	460	26	4	2	1	1	0	494

18:00	104	6	4	1	5	0	0	120
18:15	102	6	2	0	1	0	0	111
18:30	107	11	0	1	1	2	0	122
18:45	87	4	3	0	1	0	0	95
1 Hr	400	27	9	2	8	2	0	448

19:00	99	8	0	0	2	0	0	109
19:15	78	3	0	0	1	1	0	83
19:30	67	3	0	0	0	1	0	71
19:45	60	4	2	0	1	0	0	67
1 Hr	304	18	2	0	4	2	0	330

19:00	108	5	2	0	6	2	0	123
19:15	82	7	0	0	1	1	0	91
19:30	69	4	0	1	1	2	0	77
19:45	65	3	0	0	0	3	0	71
1 Hr	324	19	2	1	8	8	0	362

20:00	71	3	0	0	3	0	0	77
20:15	53	4	0	0	0	0	0	57
20:30	52	4	0	0	0	1	0	57
20:45	49	2	1	0	0	0	0	52
1 Hr	225	13	1	0	3	1	0	243

20:00	57	3	0	0	0	0	1	61
20:15	39	2	0	0	0	0	0	41
20:30	46	5	1	0	1	1	0	54
20:45	34	0	1	1	1	0	0	37
1 Hr	176	10	2	1	2	1	1	193

21:00	50	4	0	0	1	1	0	56
21:15	37	0	0	0	0	0	0	37
21:30	48	2	0	1	0	0	0	51
21:45	40	4	1	0	1	1	0	47
1 Hr	175	10	1	1	2	2	0	191

21:00	41	1	1	0	0	0	0	43
21:15	26	0	1	1	0	1	0	29
21:30	36	1	1	0	0	0	0	38
21:45	42	1	0	0	0	0	0	43
1 Hr	145	3	3	1	0	1	0	153

22:00	29	2	0	0	0	1	0	32
22:15	40	1	0	0	0	0	0	41
22:30	42	0	0	0	0	1	0	43
22:45	36	0	0	0	0	0	0	36
1 Hr	147	3	0	0	0	2	0	152

22:00	32	4	0	1	0	0	0	37
22:15	23	0	0	0	0	1	0	24
22:30	30	3	2	0	0	0	0	35
22:45	20	3	0	0	0	0	0	23
1 Hr	105	10	2	1	0	1	0	119

23:00	26	1	0	0	0	0	0	27
23:15	39	1	0	0	0	0	0	40
23:30	33	1	0	0	0	0	0	34
23:45	22	1	0	0	0	0	0	23
1 Hr	120	4	0	0	0	0	0	124

23:00	20	4	1	0	0	0	0	25
23:15	29	1	0	0	0	0	0	30
23:30	24	1	0	0	0	0	0	25
23:45	29	1	0	0	0	0	0	30
1 Hr	102	7	1	0	0	0	0	110

6 Hrs	1431	74	8	3	10	8	0	1534
-------	------	----	---	---	----	---	---	------

6 Hrs	1252	76	19	6	18	13	1	1385
-------	------	----	----	---	----	----	---	------

12 Hrs	4808	274	39	16	23	20	1	5181
--------	------	-----	----	----	----	----	---	------

12 Hrs	4080	263	60	15	31	24	2	4475
--------	------	-----	----	----	----	----	---	------

Total	7341	507	121	70	49	28	2	8118
-------	------	-----	-----	----	----	----	---	------

Total	6705	496	119	54	44	39	9	7466
-------	------	-----	-----	----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Monday 2nd June - Saturday 7th June 2014

Summary of Counts

Direction :		Eastbound							Total	
Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C				
Day 1	Monday	02/06/2014	7017	948	332	249	47	51	8	8652
Day 2	Tuesday	03/06/2014	6350	926	322	273	52	76	13	8012
Day 3	Wednesday	04/06/2014	6564	929	356	299	42	31	4	8225
Day 4	Thursday	05/06/2014	6890	1026	350	290	54	113	16	8739
Day 5	Friday	06/06/2014	9307	1028	351	240	56	135	12	11129
Day 6	Saturday	07/06/2014	7341	507	121	70	49	28	2	8118
			43469	5364	1832	1421	300	434	55	52875

Direction :		Westbound							Total	
Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C				
Day 1	Monday	02/06/2014	7155	1011	293	262	48	61	9	8839
Day 2	Tuesday	03/06/2014	6274	923	390	266	54	65	13	7955
Day 3	Wednesday	04/06/2014	6455	1039	321	280	49	31	5	8190
Day 4	Thursday	05/06/2014	6470	1013	331	278	48	116	15	8271
Day 5	Friday	06/06/2014	7457	966	329	232	53	125	8	9170
Day 6	Saturday	07/06/2014	6705	496	119	54	44	39	9	7466
			40516	5448	1753	1382	296	437	59	49891

Direction :		Eastbound				Total
Adult	Child	Accompanied Child	Unaccompanied Child			
4	0	0	0		4	
0	0	0	0		0	
1	0	0	0		1	
2	0	1	3		6	
1	0	0	1		2	
2	0	0	3		5	
10	0	4	14		28	

Direction :		Westbound				Total
Adult	Child	Accompanied Child	Unaccompanied Child			
1	0	0	0		1	
1	0	0	0		1	
0	0	0	0		0	
0	0	0	0		0	
1	0	0	1		2	
1	0	0	1		2	
4	0	0	4		8	

Direction :		Combined Counts							Total	
Car	Lgv	Ogv1	Ogv2	Psv	MC	PC				
Day 1	Monday	02/06/2014	14172	1959	625	511	95	112	17	17491
Day 2	Tuesday	03/06/2014	12624	1849	682	539	106	141	26	15987
Day 3	Wednesday	04/06/2014	13019	1968	677	589	91	82	9	16415
Day 4	Thursday	05/06/2014	13360	2039	681	568	102	229	31	17010
Day 5	Friday	06/06/2014	16764	1994	680	472	109	260	20	20299
Day 6	Saturday	07/06/2014	14046	1003	240	124	93	67	11	15584
			83985	10812	3585	2803	596	871	114	102766

Direction :		Combined Counts				Total
Adult	Child	Accompanied Child	Unaccompanied Child			
5	0	0	0		5	
1	0	0	0		1	
1	0	0	0		1	
2	0	1	3		6	
2	0	0	2		4	
3	0	0	3		6	
14	0	4	18		36	

Averages Vehicles

Day 1		Direction :		Eastbound							Total
AM	PM	Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C			
AM		78.00	23.33	10.08	3.67	0.67	0.33	0.00		116.08	
PM		149.33	15.67	2.83	2.92	0.58	1.67	0.33		173.33	
00:00-12:00		44.79	9.83	4.19	2.33	0.40	0.17	0.00		61.71	
12:00-24:00		101.40	9.92	2.73	2.85	0.58	0.90	0.17		118.54	
24 Hrs		73.09	9.88	3.46	2.59	0.49	0.53	0.08		90.13	

Day 1		Direction :		Westbound							Total
AM	PM	Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C			
AM		146.00	17.92	5.42	4.58	1.00	1.08	0.00		176.00	
PM		111.00	17.17	3.67	3.08	0.92	0.58	0.17		136.58	
00:00-12:00		69.46	10.31	2.67	3.02	0.44	0.48	0.00		86.38	
12:00-24:00		79.60	10.75	3.44	2.44	0.56	0.79	0.19		97.77	
24 Hrs		74.53	10.53	3.05	2.73	0.50	0.64	0.09		92.07	

Pedestrians

Day 1		Direction :		Eastbound				Total
AM	PM	Adult	Ac Child	Un Child				
AM		0.00	0.00	0.00	0.00		0.00	
PM		0.33	0.00	0.00	0.33		0.33	
6 Hrs		0.17	0.00	0.00	0.17		0.17	

Day 1		Direction :		Westbound				Total
AM	PM	Adult	Ac Child	Un Child				
AM		0.00	0.00	0.00	0.00		0.00	
PM		0.08	0.00	0.00	0.08		0.08	
6 Hrs		0.04	0.00	0.00	0.04		0.04	

Day 2

AM		75.67	22.00	7.92	5.67	1.08	0.58	0.00		112.92
PM		146.00	15.58	2.58	2.42	0.67	1.83	0.50		169.58
00:00-12:00		38.29	9.71	4.00	3.40	0.54	0.38	0.02		56.33
12:00-24:00		94.00	9.58	2.71	2.29	0.54	1.21	0.25		110.58
24 Hrs		66.15	9.65	3.35	2.64	0.54	0.79	0.14		83.46

AM		138.50	16.92	5.58	4.67	0.92	1.08	0.00		167.67
PM		104.67	17.33	6.17	2.25	1.25	1.50	0.50		133.67
00:00-12:00		60.04	7.92	3.25	3.21	0.46	0.58	0.04		75.50
12:00-24:00		70.67	11.31	4.25	2.33	0.67	0.77	0.23		90.23
24 Hrs		65.35	9.61	3.75	2.77	0.56	0.68	0.14		82.86

AM		0.00	0.00	0.00	0.00		0.00			0.00
PM		0.00	0.00	0.00	0.00		0.00			0.00
6 Hrs		0.00	0.00	0.00	0.00		0.00			0.00

AM		0.00	0.00	0.00	0.00		0.00			0.00
PM		0.08	0.00	0.00	0.08		0.08			0.08
6 Hrs		0.04	0.00	0.00	0.04		0.04			0.04

Day 3

AM		79.08	20.50	10.00	6.00	0.83	0.42	0.00		116.83
PM		148.17	15.33	2.75	2.75	0.75	0.92	0.25		170.92
00:00-12:00		39.42	9.42	4.81	3.29	0.42	0.17	0.02		57.54
12:00-24:00		97.33	9.94	2.60	2.94	0.46	0.48	0.06		113.81
24 Hrs		68.38	9.68	3.71	3.11	0.44	0.32	0.04		85.68

AM		136.67	15.75	5.67	5.00	1.00	0.92	0.00		165.00
PM		107.75	17.75	4.58	2.50	0.83	0.50	0.17		134.08
00:00-12:00		60.65	8.67	2.77	3.21	0.46	0.29	0.04		76.08
12:00-24:00		73.83	12.98	3.92	2.83	0.56	0.35	0.06		94.54
24 Hrs		67.24	10.82	3.34	3.02	0.51	0.32	0.05		85.31

AM		0.00	0.00	0.00	0.00		0.00			0.00
PM		0.08	0.00	0.00	0.08		0.08			0.08
6 Hrs		0.04	0.00	0.00	0.04		0.04			0.04

AM		0.00	0.00	0.00	0.00		0.00			0.00
PM		0.08	0.00	0.00	0.08		0.08			0.08
6 Hrs		0.04	0.00	0.00	0.04		0.04			0.04

Day 4

AM		82.83	25.42	8.17	5.50	1.17	0.25	0.17		123.50
PM		152.42	16.25	3.75	2.17	0.67	5.42	0.42		181.08
00:00-12:00		42.48	10.52	4.25	3.38	0.58	0.17	0.08		61.46
12:00-24:00		101.06	10.85	3.04	2.67	0.54	2.19	0.25		120.60
24 Hrs		71.77	10.69	3.65	3.02	0.56	1.18	0.17		91.03

AM		134.92	17.58	5.67	4.42	0.92	1.58	0.00		165.08
PM		107.75	19.50	4.83	3.17	0.92	0.83	0.67		137.67
00:00-12:00		60.10	8.42	3.27	2.94	0.42	0.63	0.00		75.77
12:00-24:00		74.69	12.69	3.63	2.85	0.58	1.79	0.31		96.54
24 Hrs		67.40	10.55	3.45	2.90	0.50	1.21	0.16		86.16

AM		0.00	0.00	0.00	0.00		0.00			0.00
PM		0.17	0.00	0.08	0.25		0.25			0.25
6 Hrs		0.08	0.00	0.04	0.13		0.13			0.13


AM		0.00	0.00	0.00	0.00		0.00			0.00
PM		0.17	0.00	0.08	0.25		0.25			0.25
6 Hrs										




Sky High

Count On Us

Client : Lincolnshire County Council	Site plan for : EW1 - A158 Wragby Road East
Project : 9320 / Lincoln By Pass	Date : Monday 2nd June - Saturday 7th June 2014



Unnamed Road



A518 Wragby Road



Sky High

Count On Us

Client:	Lincolnshire County Council
Project:	9320 / Lincoln By Pass
Site:	EW1 - A158 Wragby Road East
Survey Date:	Monday 9th June - Saturday 14th June 2014
Survey Period:	07:00 - 19:00
Method:	Video Observation

Incidents / Observations:

There were no incidents reported over the survey period.



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Monday 9th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	7	1	0	0	0	0	0	8
00:15	7	1	1	1	0	0	1	11
00:30	7	0	0	1	0	0	0	8
00:45	4	1	1	1	0	0	0	7
1 Hr	25	3	2	3	0	0	1	34
01:00	9	0	0	0	0	0	0	9
01:15	4	0	1	1	0	0	0	6
01:30	4	0	0	1	0	0	0	5
01:45	0	0	1	0	0	0	0	1
1 Hr	17	0	2	2	0	0	0	21
02:00	2	0	0	1	0	0	0	3
02:15	0	0	0	1	0	0	0	1
02:30	8	0	0	0	0	0	0	8
02:45	2	0	0	1	0	0	0	3
1 Hr	12	0	0	3	0	0	0	15
03:00	0	1	0	0	0	0	0	1
03:15	1	0	0	0	0	0	0	1
03:30	3	1	0	1	0	0	0	5
03:45	1	1	0	1	0	0	0	3
1 Hr	5	3	0	2	0	0	0	10
04:00	2	1	1	1	0	0	0	5
04:15	4	0	1	3	0	0	0	8
04:30	9	5	1	0	0	0	0	15
04:45	4	2	0	1	0	0	0	7
1 Hr	19	8	3	5	0	0	0	35
05:00	2	3	1	1	0	0	0	7
05:15	4	0	3	0	0	0	0	7
05:30	7	3	1	2	0	0	0	13
05:45	8	3	2	3	0	0	0	16
1 Hr	21	9	7	6	0	0	0	43
6 Hrs	99	23	14	21	0	0	1	158

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	6	1	0	1	0	0	0	8
00:15	4	0	0	1	0	1	0	6
00:30	6	1	2	0	0	0	0	9
00:45	4	0	0	0	0	0	0	4
1 Hr	20	2	2	2	0	1	0	27
01:00	9	0	0	0	0	0	0	9
01:15	2	0	0	0	0	0	0	2
01:30	5	0	0	2	0	0	0	7
01:45	1	1	0	0	0	0	0	2
1 Hr	17	1	0	2	0	0	0	20
02:00	1	0	2	0	0	0	0	3
02:15	0	1	0	1	0	0	0	2
02:30	2	1	0	1	0	0	0	4
02:45	1	3	0	0	0	0	0	4
1 Hr	4	5	2	2	0	0	0	13
03:00	3	1	0	1	0	0	0	5
03:15	3	2	0	0	0	0	0	5
03:30	1	2	0	1	0	0	0	4
03:45	6	0	0	2	0	0	0	8
1 Hr	13	5	0	4	0	0	0	22
04:00	9	2	0	1	0	0	0	12
04:15	9	2	0	4	0	0	0	15
04:30	10	0	2	5	0	0	0	17
04:45	14	3	0	2	0	0	0	19
1 Hr	42	7	2	12	0	0	0	63
05:00	15	8	1	4	0	1	0	29
05:15	16	5	1	6	0	0	0	28
05:30	32	1	1	6	0	0	0	40
05:45	46	9	2	4	0	0	0	61
1 Hr	109	23	5	20	0	1	0	158
6 Hrs	205	43	11	42	0	2	0	303

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	1	0	0	1
1 Hr	1	0	0	1
17:00	1	0	0	1
17:15	1	0	0	1
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	2	0	0	2
18:00	0	0	0	0
18:15	0	0	0	0
18:30	1	0	0	1
18:45	1	0	0	1
1 Hr	2	0	0	2
3 Hrs	5	0	0	5
6 Hrs	5	0	0	5

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	3	0	3
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	3	0	3
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	3	0	3
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	1	0	1
1 Hr	1	0	1
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	2	0	2
18:45	0	0	0
1 Hr	2	0	2
3 Hrs	3	0	3
6 Hrs	6	0	6



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Monday 9th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	12	8	5	1	2	0	0	28
06:15	18	8	4	6	2	0	0	38
06:30	33	16	5	5	1	1	0	61
06:45	49	26	9	4	0	0	0	88
1 Hr	112	58	23	16	5	1	0	215

39	6	2	8	0	2	0	57
60	9	3	5	0	2	0	79
66	13	4	4	0	0	1	88
105	34	4	7	1	1	1	153
270	62	13	24	1	5	2	377

07:00	61	16	8	8	2	0	0	95
07:15	84	21	8	5	2	0	0	120
07:30	86	27	6	6	1	1	0	127
07:45	91	26	6	1	0	1	0	125
1 Hr	322	90	28	20	5	2	0	467

108	24	4	6	0	0	0	142
135	24	4	4	1	3	1	172
148	23	8	3	0	1	1	184
183	18	5	5	3	4	2	220
574	89	21	18	4	8	4	718

08:00	66	21	15	1	0	0	0	103
08:15	77	17	8	7	0	0	0	109
08:30	75	18	4	5	0	0	0	102
08:45	99	22	14	5	2	0	0	142
1 Hr	317	78	41	18	2	0	0	456

144	16	4	5	1	1	0	171
153	17	4	4	3	1	0	182
163	20	3	4	2	2	0	194
128	12	3	6	0	1	0	150
588	65	14	19	6	5	0	697

09:00	80	20	9	1	1	0	0	111
09:15	84	33	8	5	1	0	0	131
09:30	105	19	9	4	2	2	0	141
09:45	99	19	7	7	2	0	0	134
1 Hr	368	91	33	17	6	2	0	517

159	14	8	4	0	0	0	185
138	15	8	2	0	0	0	163
136	16	9	8	1	1	1	172
134	11	8	3	2	1	0	159
567	56	33	17	3	2	1	679

10:00	107	16	5	6	0	0	0	134
10:15	125	16	0	4	1	0	0	146
10:30	111	13	6	3	0	0	0	133
10:45	130	17	6	3	1	0	0	157
1 Hr	473	62	17	16	2	0	0	570

136	15	3	8	2	1	0	165
154	13	7	6	2	1	0	183
143	15	10	4	1	1	0	174
169	15	8	5	1	1	0	199
602	58	28	23	6	4	0	721

11:00	138	19	8	5	2	0	0	172
11:15	140	12	3	3	2	2	0	162
11:30	148	8	0	4	0	1	0	161
11:45	144	17	9	3	0	1	1	175
1 Hr	570	56	20	15	4	4	1	670

135	13	2	4	1	1	0	156
146	15	8	8	2	1	0	180
134	18	6	6	1	0	0	165
138	16	7	3	0	1	0	165
553	62	23	21	4	3	0	666

6 Hrs	2162	435	162	102	24	9	1	2895
-------	------	-----	-----	-----	----	---	---	------

3154	392	132	122	24	27	7	3858
------	-----	-----	-----	----	----	---	------

12 Hrs	2261	458	176	123	24	9	2	3053
--------	------	-----	-----	-----	----	---	---	------

3359	435	143	164	24	29	7	4161
------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Monday 9th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	135	14	6	6	1	1	0	163
12:15	123	22	3	3	1	1	0	153
12:30	132	10	6	6	0	0	0	154
12:45	147	16	3	4	2	0	0	172
1 Hr	537	62	18	19	4	2	0	642

12:00	131	11	6	3	0	0	0	151
12:15	143	22	10	8	1	0	0	184
12:30	102	16	7	3	2	0	0	130
12:45	121	17	4	7	0	1	0	150
1 Hr	497	66	27	21	3	1	0	615

13:00	124	14	6	10	1	2	0	157
13:15	114	16	9	7	1	3	0	150
13:30	98	12	3	6	0	0	0	119
13:45	107	18	5	5	1	3	0	139
1 Hr	443	60	23	28	3	8	0	565

13:00	128	14	6	2	0	2	0	152
13:15	80	8	7	10	0	2	0	107
13:30	92	9	4	4	1	2	0	112
13:45	91	12	8	5	0	0	0	116
1 Hr	391	43	25	21	1	6	0	487

14:00	104	15	5	6	0	1	0	131
14:15	116	17	1	1	1	0	0	136
14:30	110	13	3	5	1	0	1	133
14:45	130	15	5	4	1	1	1	157
1 Hr	460	60	14	16	3	2	2	557

14:00	135	16	4	5	0	1	0	161
14:15	106	23	6	7	1	0	0	143
14:30	109	15	9	4	2	1	0	140
14:45	118	24	9	2	2	1	0	156
1 Hr	468	78	28	18	5	3	0	600

15:00	133	13	5	4	1	2	0	158
15:15	151	8	5	10	2	0	0	176
15:30	113	14	3	4	0	2	0	136
15:45	130	14	6	0	0	1	0	151
1 Hr	527	49	19	18	3	5	0	621

15:00	98	19	4	2	1	2	0	126
15:15	90	23	5	1	2	0	0	121
15:30	116	18	6	2	0	0	0	142
15:45	86	21	4	5	0	1	0	117
1 Hr	390	81	19	10	3	3	0	506

16:00	112	23	6	5	1	3	1	151
16:15	159	23	5	3	3	1	1	195
16:30	150	16	3	2	0	3	2	176
16:45	146	21	5	2	0	2	0	176
1 Hr	567	83	19	12	4	9	4	698

16:00	119	22	8	3	0	0	0	152
16:15	98	21	5	2	0	1	0	127
16:30	116	30	10	1	1	0	0	158
16:45	120	17	1	4	2	1	0	145
1 Hr	453	90	24	10	3	2	0	582

17:00	138	19	4	4	2	0	0	167
17:15	179	18	2	2	0	1	0	202
17:30	141	10	7	2	3	2	1	166
17:45	173	19	3	1	0	1	0	197
1 Hr	631	66	16	9	5	4	1	732

17:00	109	33	7	3	3	0	0	155
17:15	112	19	4	3	0	1	0	139
17:30	107	16	9	4	2	0	0	138
17:45	130	19	3	2	1	1	0	156
1 Hr	458	87	23	12	6	2	0	588

6 Hrs	3165	380	109	102	22	30	7	3815
-------	------	-----	-----	-----	----	----	---	------

6 Hrs	2657	445	146	92	21	17	0	3378
-------	------	-----	-----	----	----	----	---	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Monday 9th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	148	7	1	2	0	1	0	159
18:15	124	15	1	1	1	1	0	143
18:30	105	4	0	0	1	1	2	113
18:45	83	6	1	0	0	3	0	93
1 Hr	460	32	3	3	2	6	2	508

18:00	129	20	2	3	3	0	0	157
18:15	101	14	4	1	0	0	0	120
18:30	103	5	1	2	1	2	0	114
18:45	79	5	3	5	0	0	0	92
1 Hr	412	44	10	11	4	2	0	483

19:00	70	11	1	1	0	0	0	83
19:15	74	2	1	2	1	0	0	80
19:30	89	4	1	1	0	0	0	95
19:45	80	3	2	2	0	0	0	87
1 Hr	313	20	5	6	1	0	0	345

19:00	76	4	3	2	2	0	0	87
19:15	59	4	2	1	1	1	0	68
19:30	64	6	1	1	1	2	0	75
19:45	49	2	0	1	0	0	2	54
1 Hr	248	16	6	5	4	3	2	284

20:00	59	2	0	1	2	0	0	64
20:15	66	2	0	1	0	0	0	69
20:30	55	2	3	1	0	2	1	64
20:45	64	3	0	0	0	1	0	68
1 Hr	244	9	3	3	2	3	1	265

20:00	49	9	2	0	0	0	2	62
20:15	46	5	1	0	0	2	0	54
20:30	31	2	0	1	1	0	0	35
20:45	35	6	1	1	0	0	0	43
1 Hr	161	22	4	2	1	2	2	194

21:00	60	2	1	0	1	1	0	65
21:15	42	2	0	1	0	0	0	45
21:30	41	1	0	0	0	0	0	42
21:45	31	2	2	0	0	0	0	35
1 Hr	174	7	3	1	1	1	0	187

21:00	17	2	0	0	0	1	0	20
21:15	30	1	1	0	0	0	0	32
21:30	16	1	0	2	0	1	0	20
21:45	11	0	0	0	0	0	0	11
1 Hr	74	4	1	2	0	2	0	83

22:00	27	0	0	0	0	0	0	27
22:15	38	2	0	0	0	1	0	41
22:30	24	4	0	0	0	0	0	28
22:45	13	2	0	2	0	0	0	17
1 Hr	102	8	0	2	0	1	0	113

22:00	15	0	1	0	0	1	0	17
22:15	16	0	0	0	0	0	0	16
22:30	10	0	0	0	0	0	0	10
22:45	12	0	0	0	0	0	0	12
1 Hr	53	0	1	0	0	1	0	55

23:00	12	0	1	1	0	0	0	14
23:15	12	1	1	1	0	0	0	15
23:30	8	1	1	1	0	0	0	11
23:45	5	0	0	2	0	0	0	7
1 Hr	37	2	3	5	0	0	0	47

23:00	6	1	0	0	0	0	0	7
23:15	6	0	0	0	0	0	0	6
23:30	5	2	0	1	0	0	0	8
23:45	3	3	0	1	0	0	0	7
1 Hr	20	6	0	2	0	0	0	28

6 Hrs	1330	78	17	20	6	11	3	1465
-------	------	----	----	----	---	----	---	------

6 Hrs	968	92	22	22	9	10	4	1127
-------	-----	----	----	----	---	----	---	------

12 Hrs	4495	458	126	122	28	41	10	5280
--------	------	-----	-----	-----	----	----	----	------

12 Hrs	3625	537	168	114	30	27	4	4505
--------	------	-----	-----	-----	----	----	---	------

Total	6756	916	302	245	52	50	12	8333
-------	------	-----	-----	-----	----	----	----	------

Total	6984	972	311	278	54	56	11	8666
-------	------	-----	-----	-----	----	----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Tuesday 10th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	8	0	0	0	0	0	0	8
00:15	7	0	0	1	0	0	0	8
00:30	6	1	1	0	0	0	0	8
00:45	0	1	1	0	0	0	0	2
1 Hr	21	2	2	1	0	0	0	26
01:00	3	2	0	0	0	0	0	5
01:15	4	0	1	0	0	0	0	5
01:30	3	0	0	3	0	0	0	6
01:45	1	0	1	0	0	0	0	2
1 Hr	11	2	2	3	0	0	0	18
02:00	4	1	2	1	0	0	0	8
02:15	6	1	0	1	0	0	0	8
02:30	2	0	0	1	0	0	0	3
02:45	3	1	0	1	0	0	0	5
1 Hr	15	3	2	4	0	0	0	24
03:00	1	1	0	0	0	0	0	2
03:15	2	0	0	1	0	0	0	3
03:30	1	0	0	1	0	0	0	2
03:45	1	1	1	2	0	0	0	5
1 Hr	5	2	1	4	0	0	0	12
04:00	2	1	0	1	0	0	0	4
04:15	4	0	2	1	0	0	0	7
04:30	6	7	0	2	0	0	0	15
04:45	4	3	0	2	0	0	0	9
1 Hr	16	11	2	6	0	0	0	35
05:00	3	1	1	2	0	0	0	7
05:15	5	1	2	2	0	0	0	10
05:30	10	4	8	4	0	0	0	26
05:45	11	8	2	5	0	0	0	26
1 Hr	29	14	13	13	0	0	0	69
6 Hrs	97	34	22	31	0	0	0	184

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	8	0	0	0	0	0	0	8
00:15	2	0	0	1	0	0	0	3
00:30	2	0	1	1	0	0	0	4
00:45	5	2	0	1	0	0	0	8
1 Hr	17	2	1	3	0	0	0	23
01:00	0	2	0	1	0	0	0	3
01:15	2	0	0	0	0	0	0	2
01:30	1	1	0	0	0	0	0	2
01:45	2	0	1	2	0	0	0	5
1 Hr	5	3	1	3	0	0	0	12
02:00	3	0	0	0	0	0	0	3
02:15	2	0	0	1	0	0	0	3
02:30	1	0	1	2	0	0	0	4
02:45	2	2	0	0	0	0	0	4
1 Hr	8	2	1	3	0	0	0	14
03:00	2	1	0	2	0	0	0	5
03:15	2	0	1	0	0	0	0	3
03:30	4	1	0	0	0	0	0	5
03:45	0	0	0	0	0	0	0	0
1 Hr	8	2	1	2	0	0	0	13
04:00	4	1	0	0	0	0	0	5
04:15	7	1	0	1	0	0	0	9
04:30	4	0	1	4	0	0	0	9
04:45	10	1	1	4	0	0	0	16
1 Hr	25	3	2	9	0	0	0	39
05:00	7	2	2	4	0	0	0	15
05:15	14	6	2	5	0	0	0	27
05:30	22	0	1	2	0	1	0	26
05:45	22	8	2	7	0	0	0	39
1 Hr	65	16	7	18	0	1	0	107
6 Hrs	128	28	13	38	0	1	0	208

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	2	0	0	2
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	2	0	0	2
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	0	0	0	0
18:00	0	0	0	0
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	0	0	0	0
3 Hrs	2	0	0	2
6 Hrs	2	0	0	2

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	2	0	2
1 Hr	2	0	2
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	2	0	2
1 Hr	2	0	2
4	4	0	4
16:00	1	0	1
16:15	0	0	0
16:30	0	0	0
16:45	0	0	0
1 Hr	1	0	1
17:00	0	0	0
17:15	4	0	4
17:30	0	0	0
17:45	0	0	0
1 Hr	4	0	4
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	0	0	0
3 Hrs	5	0	5
6 Hrs	9	0	9

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	19	5	2	5	1	0	0	32
06:15	23	9	7	1	2	1	0	43
06:30	37	13	4	5	0	0	0	59
06:45	43	16	9	5	1	1	0	75
1 Hr	122	43	22	16	4	2	0	209

41	5	0	6	0	0	0	52
49	10	4	5	0	0	0	68
51	11	3	4	0	2	1	72
88	34	5	8	1	1	0	137
229	60	12	23	1	3	1	329

07:00	61	19	9	6	2	0	0	97
07:15	70	25	9	4	1	0	0	109
07:30	80	33	5	5	1	1	0	125
07:45	86	35	11	6	0	2	0	140
1 Hr	297	112	34	21	4	3	0	471

101	23	3	4	0	0	0	131
140	31	2	3	1	2	0	179
161	19	7	3	0	1	2	193
154	23	5	2	1	4	0	189
556	96	17	12	2	7	2	692

08:00	97	36	13	4	0	0	0	150
08:15	64	23	9	6	0	1	0	103
08:30	96	21	5	7	0	0	0	129
08:45	88	25	9	2	2	0	0	126
1 Hr	345	105	36	19	2	1	0	508

166	15	4	1	2	2	0	190
139	17	7	7	3	1	0	174
172	17	1	4	0	2	0	196
129	10	5	6	0	3	0	153
606	59	17	18	5	8	0	713

09:00	62	18	11	5	2	1	0	99
09:15	106	19	6	2	0	1	0	134
09:30	80	18	8	6	1	0	1	114
09:45	109	27	8	1	2	1	0	148
1 Hr	357	82	33	14	5	3	1	495

133	17	8	4	0	1	0	163
116	19	3	11	0	1	0	150
152	16	6	8	1	1	0	184
130	12	10	3	5	2	0	162
531	64	27	26	6	5	0	659

10:00	100	14	12	7	2	1	0	136
10:15	98	19	7	2	2	4	0	132
10:30	109	19	9	3	0	3	0	143
10:45	98	13	8	5	3	1	0	128
1 Hr	405	65	36	17	7	9	0	539

97	12	5	4	1	2	1	122
144	17	6	5	3	1	0	176
99	9	7	7	2	1	0	125
105	14	6	1	2	0	0	128
445	52	24	17	8	4	1	551

11:00	103	8	10	5	0	0	0	126
11:15	110	17	3	2	1	2	0	135
11:30	117	13	4	1	0	1	0	136
11:45	100	13	7	6	0	2	0	128
1 Hr	430	51	24	14	1	5	0	525

91	9	6	6	0	3	0	115
108	11	7	4	0	1	0	131
105	16	6	5	1	2	0	135
91	17	5	5	0	2	0	120
395	53	24	20	1	8	0	501

6 Hrs	1956	458	185	101	23	23	1	2747
-------	------	-----	-----	-----	----	----	---	------

2762	384	121	116	23	35	4	3445
------	-----	-----	-----	----	----	---	------

12 Hrs	2053	492	207	132	23	23	1	2931
--------	------	-----	-----	-----	----	----	---	------

2890	412	134	154	23	36	4	3653
------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Tuesday 10th June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	98	13	3	1	0	0	1	116
12:15	97	15	1	6	1	0	0	120
12:30	110	12	7	10	0	0	0	139
12:45	117	12	7	9	2	0	0	147
1 Hr	422	52	18	26	3	0	1	522

12:00	87	15	9	1	1	1	0	114
12:15	113	17	8	5	0	1	0	144
12:30	85	12	3	3	2	1	1	107
12:45	104	14	6	4	0	2	0	130
1 Hr	389	58	26	13	3	5	1	495

13:00	106	18	4	3	0	1	0	132
13:15	119	13	6	7	3	2	0	150
13:30	90	11	6	6	0	1	0	114
13:45	102	14	10	6	2	1	0	135
1 Hr	417	56	26	22	5	5	0	531

13:00	82	13	8	1	0	1	0	105
13:15	97	8	8	6	0	2	0	121
13:30	98	12	9	4	1	1	2	127
13:45	92	16	9	5	0	3	0	125
1 Hr	369	49	34	16	1	7	2	478

14:00	115	21	7	2	4	2	0	151
14:15	127	7	3	8	2	5	0	152
14:30	112	14	8	9	1	3	0	147
14:45	125	11	7	7	0	3	0	153
1 Hr	479	53	25	26	7	13	0	603

14:00	96	19	7	1	1	0	0	124
14:15	112	24	9	2	1	4	0	152
14:30	97	20	3	4	2	2	0	128
14:45	94	11	8	3	0	1	0	117
1 Hr	399	74	27	10	4	7	0	521

15:00	123	20	3	3	0	1	0	150
15:15	128	12	1	2	1	1	1	146
15:30	116	15	3	5	0	5	0	144
15:45	127	15	4	6	0	1	0	153
1 Hr	494	62	11	16	1	8	1	593

15:00	100	20	5	3	0	2	0	130
15:15	112	20	10	4	1	0	0	147
15:30	99	23	11	4	0	0	0	137
15:45	124	22	7	5	0	0	0	158
1 Hr	435	85	33	16	1	2	0	572

16:00	172	26	7	2	1	5	1	214
16:15	154	19	7	1	1	1	2	185
16:30	126	16	5	5	1	1	2	156
16:45	150	18	6	2	0	1	1	178
1 Hr	602	79	25	10	3	8	6	733

16:00	93	28	5	4	0	3	0	133
16:15	92	35	11	2	3	3	1	147
16:30	121	29	6	4	3	3	0	166
16:45	94	25	6	1	1	0	0	127
1 Hr	400	117	28	11	7	9	1	573

17:00	169	21	3	0	1	4	0	198
17:15	163	15	3	0	1	1	0	183
17:30	168	16	5	5	2	1	1	198
17:45	162	20	3	2	0	0	0	187
1 Hr	662	72	14	7	4	6	1	766

17:00	118	16	4	5	3	3	0	149
17:15	100	22	5	2	1	6	1	137
17:30	105	17	4	0	1	2	0	129
17:45	120	16	5	2	1	0	0	144
1 Hr	443	71	18	9	6	11	1	559

6 Hrs	3076	374	119	107	23	40	9	3748
-------	------	-----	-----	-----	----	----	---	------

6 Hrs	2435	454	166	75	22	41	5	3198
-------	------	-----	-----	----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Tuesday 10th June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	123	13	3	2	0	0	1	142
18:15	118	6	2	0	2	0	1	129
18:30	87	6	1	0	0	2	0	96
18:45	78	6	1	0	0	1	0	86
1 Hr	406	31	7	2	2	3	2	453

18:00	124	20	7	3	2	0	3	159
18:15	137	14	0	2	0	1	1	155
18:30	108	10	2	4	1	2	1	128
18:45	82	5	1	1	0	1	0	90
1 Hr	451	49	10	10	3	4	5	532

19:00	89	5	0	2	0	0	0	96
19:15	81	6	2	1	1	0	0	91
19:30	69	8	1	1	0	0	0	79
19:45	71	4	2	1	1	1	0	80
1 Hr	310	23	5	5	2	1	0	346

19:00	86	6	2	3	1	3	1	102
19:15	78	8	3	1	0	2	0	92
19:30	54	3	1	1	1	3	0	63
19:45	58	8	2	0	0	2	0	70
1 Hr	276	25	8	5	2	10	1	327

20:00	83	4	1	1	0	0	0	89
20:15	59	6	1	0	1	0	1	68
20:30	62	5	1	0	0	1	0	69
20:45	53	3	2	1	0	0	0	59
1 Hr	257	18	5	2	1	1	1	285

20:00	49	4	0	0	0	0	0	53
20:15	38	1	0	0	0	2	1	42
20:30	39	3	1	2	1	1	0	47
20:45	32	4	0	0	0	3	0	39
1 Hr	158	12	1	2	1	6	1	181

21:00	60	4	0	0	1	1	0	66
21:15	54	4	1	0	0	2	0	61
21:30	50	1	1	3	0	2	0	57
21:45	34	5	1	0	0	1	0	41
1 Hr	198	14	3	3	1	6	0	225

21:00	31	3	2	1	0	0	0	37
21:15	30	5	0	0	0	1	0	36
21:30	22	1	2	0	0	3	0	28
21:45	34	2	1	1	0	0	0	38
1 Hr	117	11	5	2	0	4	0	139

22:00	49	0	1	0	0	2	0	52
22:15	57	3	1	0	0	1	0	62
22:30	30	1	0	0	0	0	0	31
22:45	21	2	0	0	0	0	0	23
1 Hr	157	6	2	0	0	3	0	168

22:00	22	0	1	1	0	0	0	24
22:15	20	3	0	1	0	0	0	24
22:30	22	1	0	2	0	3	0	28
22:45	11	0	1	0	0	0	0	12
1 Hr	75	4	2	4	0	3	0	88

23:00	27	4	0	5	0	0	0	36
23:15	22	2	1	0	0	0	0	25
23:30	17	0	1	0	0	0	0	18
23:45	9	0	0	0	0	0	1	10
1 Hr	75	6	2	5	0	0	1	89

23:00	19	0	0	2	0	0	0	21
23:15	7	1	0	2	0	0	0	10
23:30	2	1	0	0	0	0	0	3
23:45	9	1	0	1	0	0	0	11
1 Hr	37	3	0	5	0	0	0	45

6 Hrs	1403	98	24	17	6	14	4	1566
-------	------	----	----	----	---	----	---	------

6 Hrs	1114	104	26	28	6	27	7	1312
-------	------	-----	----	----	---	----	---	------

12 Hrs	4479	472	143	124	29	54	13	5314
--------	------	-----	-----	-----	----	----	----	------

12 Hrs	3549	558	192	103	28	68	12	4510
--------	------	-----	-----	-----	----	----	----	------

Total	6532	964	350	256	52	77	14	8245
-------	------	-----	-----	-----	----	----	----	------

Total	6439	970	326	257	51	104	16	8163
-------	------	-----	-----	-----	----	-----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Wednesday 11th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	7	1	1	0	0	0	0	9
00:15	11	0	0	1	0	0	0	12
00:30	10	0	0	0	0	0	0	10
00:45	5	0	0	0	0	0	0	5
1 Hr	33	1	1	1	0	0	0	36
01:00	4	0	0	0	0	0	0	4
01:15	2	0	0	0	3	0	0	5
01:30	1	3	1	0	0	0	0	5
01:45	3	1	0	1	0	0	0	5
1 Hr	10	4	1	1	3	0	0	19
02:00	3	1	0	0	0	0	0	4
02:15	4	1	1	1	0	0	0	7
02:30	0	0	0	1	0	0	0	1
02:45	2	0	1	1	0	0	0	4
1 Hr	9	2	2	3	0	0	0	16
03:00	1	3	2	1	0	0	0	7
03:15	2	0	0	1	0	0	0	3
03:30	3	2	0	1	0	0	0	6
03:45	1	1	2	2	0	0	0	6
1 Hr	7	6	4	5	0	0	0	22
04:00	2	0	1	0	0	0	0	3
04:15	2	0	1	0	0	0	0	3
04:30	5	0	0	1	0	0	0	6
04:45	9	7	0	1	0	0	1	18
1 Hr	18	7	2	2	0	0	1	30
05:00	1	2	0	1	0	1	0	5
05:15	7	5	2	2	0	1	0	17
05:30	7	1	3	4	0	0	0	15
05:45	11	6	2	0	0	0	0	19
1 Hr	26	14	7	7	0	2	0	56
6 Hrs	103	34	17	19	3	2	1	179

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	3	0	0	0	0	0	0	3
00:15	2	0	0	2	0	0	0	4
00:30	3	3	1	1	0	0	0	8
00:45	1	0	0	1	0	0	0	2
1 Hr	9	3	1	4	0	0	0	17
01:00	3	1	0	2	0	0	0	6
01:15	3	0	0	1	0	0	0	4
01:30	6	2	0	0	0	0	0	8
01:45	3	2	1	1	0	0	0	7
1 Hr	15	5	1	4	0	0	0	25
02:00	5	1	2	1	0	0	0	9
02:15	3	1	0	1	0	0	0	5
02:30	0	1	0	0	0	0	0	1
02:45	4	0	1	0	0	0	0	5
1 Hr	12	3	3	2	0	0	0	20
03:00	2	0	0	1	0	0	0	3
03:15	2	1	1	1	0	0	0	5
03:30	1	0	0	1	0	0	0	2
03:45	1	0	0	0	0	0	0	1
1 Hr	6	1	1	3	0	0	0	11
04:00	4	2	0	0	0	0	0	6
04:15	10	1	1	2	0	0	0	14
04:30	7	2	1	5	0	0	0	15
04:45	7	3	2	4	0	0	0	16
1 Hr	28	8	4	11	0	0	0	51
05:00	7	3	0	6	0	0	0	16
05:15	16	6	1	6	0	0	0	29
05:30	15	4	1	2	0	1	0	23
05:45	39	7	4	9	0	1	0	60
1 Hr	77	20	6	23	0	2	0	128
6 Hrs	147	40	16	47	0	2	0	252

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	1	0	0	1
09:15	0	0	0	0
09:30	1	0	0	1
09:45	0	0	0	0
1 Hr	2	0	0	2
3 Hr	2	0	0	2
16:00	1	0	0	1
16:15	0	0	0	0
16:30	1	0	0	1
16:45	0	0	0	0
1 Hr	2	0	0	2
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	1	0	0	1
1 Hr	1	0	0	1
18:00	1	0	0	1
18:15	1	0	0	1
18:30	1	0	0	1
18:45	0	0	0	0
1 Hr	3	0	0	3
3 Hrs	6	0	0	6
6 Hrs	8	0	0	8

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	2	0	2
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	2	0	2
3 Hr	2	0	2
16:00	0	0	0
16:15	0	0	0
16:30	1	0	1
16:45	0	0	0
1 Hr	1	0	1
17:00	2	0	2
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	2	0	2
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	0	0	0
3 Hrs	3	0	3
6 Hrs	5	0	5



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Wednesday 11th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	15	4	6	4	0	0	0	29
06:15	23	5	6	4	2	1	0	41
06:30	28	14	10	4	0	1	0	57
06:45	42	16	7	4	0	0	0	69
1 Hr	108	39	29	16	2	2	0	196

06:00	39	5	3	4	0	1	0	52
06:15	66	16	4	3	0	1	0	90
06:30	57	17	2	5	1	1	3	86
06:45	73	12	3	6	0	0	0	94
1 Hr	235	50	12	18	1	3	3	322

07:00	60	18	11	9	1	0	0	99
07:15	72	22	13	5	1	2	0	115
07:30	87	34	14	4	0	1	0	140
07:45	98	23	11	8	1	1	0	142
1 Hr	317	97	49	26	3	4	0	496

07:00	113	23	2	1	0	0	0	139
07:15	114	20	6	2	1	1	0	144
07:30	152	31	8	7	0	2	1	201
07:45	156	20	4	4	0	6	1	191
1 Hr	535	94	20	14	1	9	2	675

08:00	73	23	10	6	0	0	0	112
08:15	73	13	14	7	0	0	0	107
08:30	93	24	10	3	0	1	0	131
08:45	107	18	4	7	1	0	0	137
1 Hr	346	78	38	23	1	1	0	487

08:00	133	19	3	5	3	2	1	166
08:15	156	17	5	3	3	4	0	188
08:30	164	9	3	2	0	3	0	181
08:45	140	9	3	4	0	1	0	157
1 Hr	593	54	14	14	6	10	1	692

09:00	100	24	5	4	2	0	0	135
09:15	103	23	7	4	1	1	0	139
09:30	109	26	13	4	3	1	1	157
09:45	100	10	4	5	2	0	0	121
1 Hr	412	83	29	17	8	2	1	552

09:00	146	17	5	10	1	1	0	180
09:15	152	10	7	5	1	0	0	175
09:30	132	12	3	3	2	1	1	154
09:45	93	10	2	2	2	1	0	110
1 Hr	523	49	17	20	6	3	1	619

10:00	114	22	6	2	2	1	1	148
10:15	136	21	8	7	4	5	0	181
10:30	125	22	8	4	2	1	0	162
10:45	84	16	4	4	0	2	0	110
1 Hr	459	81	26	17	8	9	1	601

10:00	135	26	11	6	2	0	0	180
10:15	115	9	10	6	2	0	0	142
10:30	134	12	19	3	3	1	0	172
10:45	107	12	7	6	1	1	0	134
1 Hr	491	59	47	21	8	2	0	628

11:00	116	21	5	10	4	0	0	156
11:15	113	22	5	1	1	1	0	143
11:30	137	17	8	7	0	0	0	169
11:45	119	17	2	5	0	0	0	143
1 Hr	485	77	20	23	5	1	0	611

11:00	111	15	3	7	0	3	0	139
11:15	102	18	6	2	0	2	0	130
11:30	89	18	5	4	1	1	0	118
11:45	112	11	7	1	1	1	0	133
1 Hr	414	62	21	14	2	7	0	520

6 Hrs	2127	455	191	122	27	19	2	2943
-------	------	-----	-----	-----	----	----	---	------

6 Hrs	2791	368	131	101	24	34	7	3456
-------	------	-----	-----	-----	----	----	---	------

12 Hrs	2230	489	208	141	30	21	3	3122
--------	------	-----	-----	-----	----	----	---	------

12 Hrs	2938	408	147	148	24	36	7	3708
--------	------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Wednesday 11th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	123	10	6	3	0	2	0	144
12:15	102	16	7	7	1	0	0	133
12:30	118	16	3	7	0	0	0	144
12:45	105	16	4	9	1	2	0	137
1 Hr	448	58	20	26	2	4	0	558

12:00	98	18	6	5	0	0	1	128
12:15	72	14	7	4	0	2	0	99
12:30	97	15	6	4	0	2	0	124
12:45	97	13	6	2	1	1	0	120
1 Hr	364	60	25	15	1	5	1	471

13:00	93	8	6	5	1	1	0	114
13:15	106	19	4	3	1	1	0	134
13:30	109	6	4	6	0	0	0	125
13:45	82	8	7	5	0	0	0	102
1 Hr	390	41	21	19	2	2	0	475

13:00	116	25	6	9	0	0	0	156
13:15	124	17	10	3	0	1	0	155
13:30	87	11	4	3	1	1	0	107
13:45	114	15	9	8	1	0	0	147
1 Hr	441	68	29	23	2	2	0	565

14:00	119	16	3	7	0	4	1	150
14:15	119	15	6	2	1	3	2	148
14:30	106	19	6	1	1	0	0	133
14:45	117	12	5	2	1	1	0	138
1 Hr	461	62	20	12	3	8	3	569

14:00	112	17	5	5	3	1	0	143
14:15	96	18	8	4	0	1	0	127
14:30	115	18	8	11	3	1	0	156
14:45	93	12	3	6	0	1	1	116
1 Hr	416	65	24	26	6	4	1	542

15:00	115	10	5	0	0	1	1	132
15:15	133	16	9	8	1	2	2	171
15:30	136	15	6	4	0	2	0	163
15:45	142	22	5	6	1	1	0	177
1 Hr	526	63	25	18	2	6	3	643

15:00	92	16	13	3	0	0	2	126
15:15	144	22	9	10	1	1	1	188
15:30	112	16	5	2	1	1	0	137
15:45	106	14	4	4	1	3	1	133
1 Hr	454	68	31	19	3	5	4	584

16:00	134	19	7	6	0	1	0	167
16:15	152	21	7	3	3	3	1	190
16:30	157	17	5	4	0	2	2	187
16:45	137	14	3	7	0	4	3	168
1 Hr	580	71	22	20	3	10	6	712

16:00	100	31	6	3	2	16	0	158
16:15	101	25	8	4	1	0	0	139
16:30	140	26	4	3	1	3	0	177
16:45	126	25	4	2	4	1	0	162
1 Hr	467	107	22	12	8	20	0	636

17:00	194	18	5	5	1	3	1	227
17:15	164	9	3	1	1	3	0	181
17:30	167	16	3	4	1	1	1	193
17:45	179	18	4	2	0	4	1	208
1 Hr	704	61	15	12	3	11	3	809

17:00	100	20	5	7	2	2	1	137
17:15	120	27	3	3	1	2	1	157
17:30	121	21	4	0	2	2	0	150
17:45	116	12	3	4	4	2	1	142
1 Hr	457	80	15	14	9	8	3	586

6 Hrs	3109	356	123	107	15	41	15	3766
-------	------	-----	-----	-----	----	----	----	------

6 Hrs	2599	448	146	109	29	44	9	3384
-------	------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Wednesday 11th June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	144	10	4	3	1	5	4	171
18:15	129	15	2	1	0	1	1	149
18:30	122	12	1	0	0	1	2	138
18:45	105	11	3	1	0	4	1	125
1 Hr	500	48	10	5	1	11	8	583

18:00	108	10	5	1	1	2	0	127
18:15	81	6	1	0	2	1	0	91
18:30	118	9	2	2	1	3	0	135
18:45	140	11	0	5	0	7	1	164
1 Hr	447	36	8	8	4	13	1	517

19:00	89	7	0	0	1	1	0	98
19:15	83	11	1	1	0	5	0	101
19:30	91	4	0	3	0	0	0	98
19:45	88	3	2	1	0	5	0	99
1 Hr	351	25	3	5	1	11	0	396

19:00	92	9	3	3	1	3	0	111
19:15	74	12	1	2	1	1	0	91
19:30	58	8	0	1	1	0	0	68
19:45	57	9	1	1	0	2	0	70
1 Hr	281	38	5	7	3	6	0	340

20:00	92	5	1	0	1	5	1	105
20:15	85	7	1	0	1	3	1	98
20:30	73	0	0	0	0	1	0	74
20:45	62	5	0	0	0	0	0	67
1 Hr	312	17	2	0	2	9	2	344

20:00	56	7	0	3	0	1	3	70
20:15	61	3	0	0	0	3	0	67
20:30	36	3	2	2	2	6	1	52
20:45	68	6	4	1	0	1	1	81
1 Hr	221	19	6	6	2	11	5	270

21:00	74	5	0	0	1	1	0	81
21:15	47	3	1	1	0	0	0	52
21:30	53	3	0	1	0	1	0	58
21:45	47	2	1	0	0	1	2	53
1 Hr	221	13	2	2	1	3	2	244

21:00	39	3	0	0	0	1	0	43
21:15	35	3	0	1	0	5	0	44
21:30	32	3	2	0	0	5	0	42
21:45	28	2	0	0	0	2	0	32
1 Hr	134	11	2	1	0	13	0	161

22:00	45	1	1	1	0	0	0	48
22:15	38	1	1	0	0	2	0	42
22:30	36	0	0	0	0	0	0	36
22:45	20	2	0	0	0	0	0	22
1 Hr	139	4	2	1	0	2	0	148

22:00	15	1	1	0	0	1	0	18
22:15	16	1	1	0	0	1	0	19
22:30	6	3	1	0	0	0	0	10
22:45	16	1	1	2	0	0	0	20
1 Hr	53	6	4	2	0	2	0	67

23:00	29	1	1	3	0	0	0	34
23:15	14	3	0	2	0	0	0	19
23:30	11	0	0	0	0	0	0	11
23:45	8	1	0	2	0	0	0	11
1 Hr	62	5	1	7	0	0	0	75

23:00	11	1	0	0	0	0	0	12
23:15	16	2	0	0	0	0	0	18
23:30	7	1	0	0	0	0	0	8
23:45	4	0	0	1	0	0	0	5
1 Hr	38	4	0	1	0	0	0	43

6 Hrs	1585	112	20	20	5	36	12	1790
-------	------	-----	----	----	---	----	----	------

6 Hrs	1174	114	25	25	9	45	6	1398
-------	------	-----	----	----	---	----	---	------

12 Hrs	4694	468	143	127	20	77	27	5556
--------	------	-----	-----	-----	----	----	----	------

12 Hrs	3773	562	171	134	38	89	15	4782
--------	------	-----	-----	-----	----	----	----	------

Total	6924	957	351	268	50	98	30	8678
-------	------	-----	-----	-----	----	----	----	------

Total	6711	970	318	282	62	125	22	8490
-------	------	-----	-----	-----	----	-----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Thursday 12th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	11	3	2	0	0	0	0	16
00:15	7	0	0	0	0	0	0	7
00:30	7	0	0	2	0	0	0	9
00:45	3	1	0	0	0	0	0	4
1 Hr	28	4	2	2	0	0	0	36
01:00	5	1	1	1	0	0	0	8
01:15	6	2	1	1	0	0	0	10
01:30	3	0	0	0	0	0	0	3
01:45	2	1	0	1	0	0	0	4
1 Hr	16	4	2	3	0	0	0	25
02:00	2	0	1	0	0	0	0	3
02:15	1	1	0	1	0	0	0	3
02:30	2	2	0	3	0	0	0	7
02:45	3	1	0	1	0	0	0	5
1 Hr	8	4	1	5	0	0	0	18
03:00	0	0	2	0	0	0	0	2
03:15	4	0	0	1	0	0	0	5
03:30	4	0	0	0	0	0	0	4
03:45	2	1	1	0	0	0	0	4
1 Hr	10	1	3	1	0	0	0	15
04:00	3	0	0	4	0	0	0	7
04:15	3	0	3	0	0	0	0	6
04:30	7	2	1	2	0	0	0	12
04:45	4	6	0	4	0	0	0	14
1 Hr	17	8	4	10	0	0	0	39
05:00	3	4	1	1	0	0	0	9
05:15	7	1	3	3	0	0	0	14
05:30	8	1	2	4	0	0	0	15
05:45	9	4	1	5	0	0	0	19
1 Hr	27	10	7	13	0	0	0	57
6 Hrs	106	31	19	34	0	0	0	190

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	9	1	0	0	0	0	0	10
00:15	2	0	1	1	0	0	0	4
00:30	3	0	0	0	0	0	0	3
00:45	2	1	0	4	0	0	0	7
1 Hr	16	2	1	5	0	0	0	24
01:00	0	1	0	0	0	0	0	1
01:15	7	0	0	1	0	0	0	8
01:30	2	0	0	0	0	0	0	2
01:45	4	1	0	1	0	0	0	6
1 Hr	13	2	0	2	0	0	0	17
02:00	1	0	0	0	0	0	0	1
02:15	0	1	0	0	0	0	0	1
02:30	1	0	2	0	0	0	0	3
02:45	1	0	0	0	0	0	0	1
1 Hr	3	1	2	0	0	0	0	6
03:00	1	0	0	0	0	0	0	1
03:15	6	0	0	0	0	0	0	6
03:30	2	0	0	1	0	0	0	3
03:45	3	0	0	1	0	0	0	4
1 Hr	12	0	0	2	0	0	0	14
04:00	4	0	0	3	0	0	0	7
04:15	5	0	2	2	0	0	0	9
04:30	8	3	0	3	0	0	0	14
04:45	7	2	1	3	0	0	0	13
1 Hr	24	5	3	11	0	0	0	43
05:00	8	3	1	1	0	0	0	13
05:15	12	7	3	6	0	0	0	28
05:30	22	6	1	3	0	0	0	32
05:45	24	5	1	6	0	1	0	37
1 Hr	66	21	6	16	0	1	0	110
6 Hrs	134	31	12	36	0	1	0	214

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	1	0	0	1
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	1	0	0	1
18:00	0	0	0	0
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	0	0	0	0
3 Hrs	1	0	0	1
6 Hrs	1	0	0	1

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	0	0	0
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	0	0	0
1 Hr	0	0	0
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	0	0	0
3 Hrs	0	0	0
6 Hrs	0	0	0



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Thursday 12th June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	18	7	6	6	2	0	0	39
06:15	13	6	5	3	0	1	0	28
06:30	41	22	5	3	0	0	0	71
06:45	40	17	6	6	0	0	0	69
1 Hr	112	52	22	18	2	1	0	207

06:00	33	6	2	5	0	1	1	48
06:15	45	13	2	6	0	1	0	67
06:30	67	19	3	3	2	0	0	94
06:45	82	20	3	6	1	2	0	114
1 Hr	227	58	10	20	3	4	1	323

07:00	56	22	8	3	1	0	0	90
07:15	81	28	13	5	2	3	0	132
07:30	87	31	13	7	1	0	0	139
07:45	96	29	8	9	0	1	1	144
1 Hr	320	110	42	24	4	4	1	505

07:00	94	24	6	6	0	1	0	131
07:15	145	28	3	1	1	4	0	182
07:30	138	22	4	5	0	0	0	169
07:45	132	10	1	3	1	4	0	151
1 Hr	509	84	14	15	2	9	0	633

08:00	65	21	9	4	0	0	0	99
08:15	87	23	13	3	0	1	0	127
08:30	102	27	11	8	0	1	0	149
08:45	91	33	8	7	1	1	0	141
1 Hr	345	104	41	22	1	3	0	516

08:00	151	16	4	2	0	4	2	179
08:15	123	14	3	5	2	2	1	150
08:30	191	22	8	3	0	3	1	228
08:45	109	6	9	7	0	1	0	132
1 Hr	574	58	24	17	2	10	4	689

09:00	96	19	11	2	2	3	0	133
09:15	104	30	4	4	1	2	1	146
09:30	90	21	6	5	0	2	0	124
09:45	134	23	6	6	1	1	0	171
1 Hr	424	93	27	17	4	8	1	574

09:00	143	14	5	2	0	0	0	164
09:15	143	10	6	6	0	2	0	167
09:30	119	9	7	3	2	1	0	141
09:45	128	13	6	4	1	0	0	152
1 Hr	533	46	24	15	3	3	0	624

10:00	127	15	11	6	5	1	0	165
10:15	104	15	9	4	1	1	0	134
10:30	142	14	10	7	1	2	0	176
10:45	117	9	7	5	1	0	0	139
1 Hr	490	53	37	22	8	4	0	614

10:00	143	17	7	1	1	0	0	169
10:15	103	9	4	8	1	1	0	126
10:30	132	14	5	7	3	1	0	162
10:45	108	6	7	8	0	1	1	131
1 Hr	486	46	23	24	5	3	1	588

11:00	150	13	8	0	1	1	1	174
11:15	141	11	4	10	1	3	0	170
11:30	145	15	5	11	0	3	0	179
11:45	139	16	5	8	0	0	0	168
1 Hr	575	55	22	29	2	7	1	691

11:00	128	15	10	5	0	4	0	162
11:15	113	21	8	4	0	3	0	149
11:30	96	19	3	0	2	4	0	124
11:45	95	14	4	7	0	1	0	121
1 Hr	432	69	25	16	2	12	0	556

6 Hrs	2266	467	191	132	21	27	3	3107
-------	------	-----	-----	-----	----	----	---	------

6 Hrs	2761	361	120	107	17	41	6	3413
-------	------	-----	-----	-----	----	----	---	------

12 Hrs	2372	498	210	166	21	27	3	3297
--------	------	-----	-----	-----	----	----	---	------

12 Hrs	2895	392	132	143	17	42	6	3627
--------	------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Thursday 12th June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	118	21	2	3	0	2	0	146
12:15	119	13	5	3	1	4	0	145
12:30	125	14	1	7	0	3	0	150
12:45	115	17	6	7	1	1	0	147
1 Hr	477	65	14	20	2	10	0	588

12:00	129	12	9	1	2	1	0	154
12:15	92	14	4	2	0	0	0	112
12:30	109	22	8	6	2	4	0	151
12:45	104	17	8	7	0	1	0	137
1 Hr	434	65	29	16	4	6	0	554

13:00	110	14	8	6	0	3	0	141
13:15	103	12	7	3	2	2	0	129
13:30	104	12	3	5	0	5	0	129
13:45	92	13	8	1	0	3	0	117
1 Hr	409	51	26	15	2	13	0	516

13:00	116	17	9	5	0	2	0	149
13:15	105	10	8	7	0	5	0	135
13:30	111	18	10	7	1	5	2	154
13:45	106	20	3	4	1	0	0	134
1 Hr	438	65	30	23	2	12	2	572

14:00	115	15	4	7	0	1	0	142
14:15	102	18	9	4	1	1	0	135
14:30	112	15	6	5	1	0	0	139
14:45	134	15	6	8	1	3	2	169
1 Hr	463	63	25	24	3	5	2	585

14:00	96	18	8	6	1	1	1	131
14:15	90	28	11	5	1	4	1	140
14:30	101	23	9	3	2	5	0	143
14:45	83	13	8	6	1	0	0	111
1 Hr	370	82	36	20	5	10	2	525

15:00	139	17	7	6	0	1	0	170
15:15	147	18	2	5	2	1	1	176
15:30	127	14	6	1	0	3	0	151
15:45	160	15	5	3	1	2	1	187
1 Hr	573	64	20	15	3	7	2	684

15:00	117	19	7	6	0	1	0	150
15:15	98	24	3	3	0	1	0	129
15:30	109	18	6	6	1	0	0	140
15:45	123	30	6	4	0	4	1	168
1 Hr	447	91	22	19	1	6	1	587

16:00	152	17	6	7	0	5	1	188
16:15	152	14	6	2	4	7	1	186
16:30	157	19	5	3	0	4	2	190
16:45	171	25	3	4	0	3	0	206
1 Hr	632	75	20	16	4	19	4	770

16:00	84	30	6	4	1	3	0	128
16:15	151	27	7	1	0	1	0	187
16:30	119	24	7	3	1	2	1	157
16:45	114	27	3	3	3	0	0	150
1 Hr	468	108	23	11	5	6	1	622

17:00	155	13	2	5	1	3	1	180
17:15	174	16	3	3	2	1	1	200
17:30	172	22	1	3	1	1	0	200
17:45	189	8	1	2	0	2	0	202
1 Hr	690	59	7	13	4	7	2	782

17:00	124	24	7	2	1	1	0	159
17:15	123	19	5	2	3	6	0	158
17:30	133	20	1	2	2	3	0	161
17:45	149	21	2	4	0	3	0	179
1 Hr	529	84	15	10	6	13	0	657

6 Hrs	3244	377	112	103	18	61	10	3925
-------	------	-----	-----	-----	----	----	----	------

6 Hrs	2686	495	155	99	23	53	6	3517
-------	------	-----	-----	----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Thursday 12th June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	145	6	0	2	0	2	4	159
18:15	145	13	0	1	2	1	1	163
18:30	145	10	1	0	1	0	0	157
18:45	112	10	2	4	0	6	0	134
1 Hr	547	39	3	7	3	9	5	613

18:00	132	16	6	1	1	3	0	159
18:15	125	9	1	3	1	4	0	143
18:30	92	16	2	5	1	1	0	117
18:45	123	8	5	1	1	0	0	138
1 Hr	472	49	14	10	4	8	0	557

19:00	112	10	2	0	1	1	0	126
19:15	101	3	1	4	0	1	1	111
19:30	101	6	2	0	0	5	0	114
19:45	84	6	0	1	1	3	0	95
1 Hr	398	25	5	5	2	10	1	446

19:00	92	7	3	2	1	2	0	107
19:15	81	5	2	1	1	3	0	93
19:30	85	9	1	1	0	2	1	99
19:45	58	5	1	0	0	1	0	65
1 Hr	316	26	7	4	2	8	1	364

20:00	88	6	3	2	2	0	2	103
20:15	80	3	3	1	1	0	1	89
20:30	76	7	3	1	0	2	0	89
20:45	60	8	2	2	0	1	0	73
1 Hr	304	24	11	6	3	3	3	354

20:00	52	8	2	1	0	1	0	64
20:15	52	5	2	0	0	1	0	60
20:30	60	6	1	1	0	2	1	71
20:45	40	6	2	1	0	2	0	51
1 Hr	204	25	7	3	0	6	1	246

21:00	63	8	3	0	1	1	0	76
21:15	65	8	0	1	0	2	0	76
21:30	58	5	1	0	0	0	0	64
21:45	56	2	0	1	0	0	0	59
1 Hr	242	23	4	2	1	3	0	275

21:00	38	4	1	0	0	1	0	44
21:15	25	1	1	0	0	1	0	28
21:30	36	0	0	0	0	2	0	38
21:45	25	3	0	0	0	2	0	30
1 Hr	124	8	2	0	0	6	0	140

22:00	49	2	1	1	0	1	0	54
22:15	37	0	1	0	0	2	0	40
22:30	36	4	1	0	0	0	0	41
22:45	33	3	0	1	0	0	0	37
1 Hr	155	9	3	2	0	3	0	172

22:00	21	2	1	0	0	0	0	24
22:15	16	3	0	1	0	0	0	20
22:30	28	1	0	0	0	0	0	29
22:45	9	1	0	0	0	2	0	12
1 Hr	74	7	1	1	0	2	0	85

23:00	12	2	0	0	0	0	0	14
23:15	19	1	0	1	0	0	0	21
23:30	17	1	0	0	0	0	0	18
23:45	8	4	0	1	0	0	0	13
1 Hr	56	8	0	2	0	0	0	66

23:00	9	0	0	0	0	0	0	9
23:15	7	3	0	0	0	0	0	10
23:30	7	0	0	0	0	0	0	7
23:45	12	0	0	0	0	0	0	12
1 Hr	35	3	0	0	0	0	0	38

6 Hrs	1702	128	26	24	9	28	9	1926
-------	------	-----	----	----	---	----	---	------

6 Hrs	1225	118	31	18	6	30	2	1430
-------	------	-----	----	----	---	----	---	------

12 Hrs	4946	505	138	127	27	89	19	5851
--------	------	-----	-----	-----	----	----	----	------

12 Hrs	3911	613	186	117	29	83	8	4947
--------	------	-----	-----	-----	----	----	---	------

Total	7318	1003	348	293	48	116	22	9148
-------	------	------	-----	-----	----	-----	----	------

Total	6806	1005	318	260	46	125	14	8574
-------	------	------	-----	-----	----	-----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Friday 13th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	15	1	0	0	0	0	0	16
00:15	13	0	0	2	0	0	0	15
00:30	9	0	1	0	0	0	0	10
00:45	9	0	0	2	0	0	0	11
1 Hr	46	1	1	4	0	0	0	52
01:00	5	0	1	1	0	0	0	7
01:15	4	1	1	0	0	0	0	6
01:30	3	0	1	0	0	0	0	4
01:45	2	0	1	1	0	0	0	4
1 Hr	14	1	4	2	0	0	0	21
02:00	3	1	1	2	0	0	0	7
02:15	0	1	2	1	0	0	0	4
02:30	3	1	0	0	0	0	0	4
02:45	5	2	0	1	0	0	0	8
1 Hr	11	5	3	4	0	0	0	23
03:00	1	0	1	0	0	0	0	2
03:15	3	0	0	0	0	0	0	3
03:30	5	0	1	0	0	0	0	6
03:45	3	0	1	0	0	0	0	4
1 Hr	12	0	3	0	0	0	0	15
04:00	5	0	2	0	0	0	0	7
04:15	2	1	1	1	0	0	0	5
04:30	1	5	0	3	0	0	0	9
04:45	5	1	0	0	0	0	0	6
1 Hr	13	7	3	4	0	0	0	27
05:00	4	1	1	3	0	0	1	10
05:15	6	2	2	1	0	1	0	12
05:30	12	0	4	3	0	0	0	19
05:45	11	5	4	7	0	0	0	27
1 Hr	33	8	11	14	0	1	1	68
6 Hrs	129	22	25	28	0	1	1	206

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	8	0	0	1	0	0	0	9
00:15	5	0	0	1	0	0	0	6
00:30	4	0	1	0	0	0	0	5
00:45	1	1	0	1	0	0	0	3
1 Hr	18	1	1	3	0	0	0	23
01:00	4	0	0	0	0	0	0	4
01:15	3	1	0	0	0	0	0	4
01:30	1	0	0	0	0	0	0	1
01:45	3	0	0	1	0	0	0	4
1 Hr	11	1	0	1	0	0	0	13
02:00	3	0	0	1	0	0	0	4
02:15	2	1	0	0	0	0	0	3
02:30	0	0	0	0	0	0	0	0
02:45	1	1	1	1	0	0	0	4
1 Hr	6	2	1	2	0	0	0	11
03:00	1	0	0	0	0	0	0	1
03:15	6	0	0	0	0	0	0	6
03:30	0	1	0	0	0	0	0	1
03:45	3	1	1	1	0	0	0	6
1 Hr	10	2	1	1	0	0	0	14
04:00	5	1	1	1	0	0	0	8
04:15	3	0	0	3	0	0	0	6
04:30	5	3	0	4	0	0	0	12
04:45	5	2	0	4	0	0	0	11
1 Hr	18	6	1	12	0	0	0	37
05:00	7	4	1	2	0	0	0	14
05:15	26	1	3	5	0	1	0	36
05:30	24	5	3	4	0	1	0	37
05:45	37	4	3	8	0	0	0	52
1 Hr	94	14	10	19	0	2	0	139
6 Hrs	157	26	14	38	0	2	0	237

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	1	0	0	1
09:45	0	0	0	0
1 Hr	1	0	0	1
3 Hr	1	0	0	1
16:00	1	0	0	1
16:15	0	0	0	0
16:30	0	0	0	0
16:45	1	0	0	1
1 Hr	2	0	0	2
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	1	0	0	1
1 Hr	1	0	0	1
18:00	0	0	0	0
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	0	0	0	0
3 Hrs	3	0	0	3
6 Hrs	4	0	0	4

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	0	0	0
16:00	0	0	0
16:15	1	0	1
16:30	0	0	0
16:45	2	0	2
1 Hr	3	0	3
17:00	1	0	1
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	1	0	1
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	1	0	1
1 Hr	1	0	1
3 Hrs	5	0	5
6 Hrs	5	0	5



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Friday 13th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	25	5	3	0	2	0	0	35
06:15	25	7	7	2	0	2	0	43
06:30	35	15	7	5	2	1	0	65
06:45	43	17	10	5	0	0	0	75
1 Hr	128	44	27	12	4	3	0	218

34	6	1	3	0	1	0	45
41	10	0	6	0	1	0	58
59	10	2	2	0	2	2	77
76	24	3	3	1	1	0	108
210	50	6	14	1	5	2	288

07:00	59	20	6	4	2	0	0	91
07:15	64	30	13	6	1	1	0	115
07:30	92	23	8	8	1	1	0	133
07:45	98	30	9	11	0	1	1	150
1 Hr	313	103	36	29	4	3	1	489

91	21	4	4	0	0	0	120
130	18	2	7	1	3	1	162
127	16	6	0	0	2	1	152
177	17	4	3	2	1	0	204
525	72	16	14	3	6	2	638

08:00	86	20	7	8	1	1	0	123
08:15	88	31	11	7	0	2	0	139
08:30	101	22	12	6	1	0	0	142
08:45	105	18	6	6	2	2	0	139
1 Hr	380	91	36	27	4	5	0	543

164	15	9	4	2	4	0	198
149	11	8	4	2	2	2	178
144	9	3	5	1	3	0	165
140	14	12	3	1	4	0	174
597	49	32	16	6	13	2	715

09:00	75	26	5	3	1	0	0	110
09:15	107	24	8	6	2	1	1	149
09:30	101	29	7	4	0	0	0	141
09:45	126	19	12	4	1	1	0	163
1 Hr	409	98	32	17	4	2	1	563

127	16	8	4	0	0	0	155
109	12	5	10	0	0	1	137
141	13	6	7	1	1	0	169
176	22	7	6	2	2	0	215
553	63	26	27	3	3	1	676

10:00	125	14	2	2	0	2	0	145
10:15	132	20	3	3	2	3	0	163
10:30	159	10	9	6	0	2	1	187
10:45	157	17	5	4	0	1	1	185
1 Hr	573	61	19	15	2	8	2	680

136	14	5	4	2	2	0	163
161	15	6	11	1	3	0	197
143	12	6	5	2	0	0	168
145	17	7	4	1	0	0	174
585	58	24	24	6	5	0	702

11:00	163	19	4	5	2	5	0	198
11:15	155	20	2	5	1	2	0	185
11:30	175	14	7	5	1	0	0	202
11:45	168	17	6	4	0	2	0	197
1 Hr	661	70	19	19	4	9	0	782

169	13	9	2	1	1	0	195
127	18	4	7	1	1	0	158
123	12	8	4	1	3	0	151
143	14	12	3	1	0	0	173
562	57	33	16	4	5	0	677

6 Hrs	2464	467	169	119	22	30	4	3275
-------	------	-----	-----	-----	----	----	---	------

3032	349	137	111	23	37	7	3696
------	-----	-----	-----	----	----	---	------

12 Hrs	2593	489	194	147	22	31	5	3481
--------	------	-----	-----	-----	----	----	---	------

3189	375	151	149	23	39	7	3933
------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Friday 13th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	176	13	4	5	0	5	0	203
12:15	181	15	6	4	2	1	0	209
12:30	158	14	7	7	0	2	1	189
12:45	159	25	5	0	1	2	0	192
1 Hr	674	67	22	16	3	10	1	793

12:00	105	11	2	4	0	1	0	123
12:15	145	19	7	5	1	1	0	178
12:30	93	14	3	4	0	0	0	114
12:45	124	17	10	6	2	3	0	162
1 Hr	467	61	22	19	3	5	0	577

13:00	180	11	5	4	2	0	0	202
13:15	156	16	2	4	2	3	0	183
13:30	144	22	4	4	0	3	0	177
13:45	148	11	4	2	0	1	0	166
1 Hr	628	60	15	14	4	7	0	728

13:00	129	19	9	4	0	2	0	163
13:15	85	19	10	1	0	3	0	118
13:30	139	24	13	2	1	3	2	184
13:45	145	17	10	5	0	1	0	178
1 Hr	498	79	42	12	1	9	2	643

14:00	163	24	3	6	0	4	0	200
14:15	170	21	5	3	1	2	1	203
14:30	157	14	5	5	1	1	0	183
14:45	197	22	4	9	1	0	0	233
1 Hr	687	81	17	23	3	7	1	819

14:00	116	21	6	5	0	2	0	150
14:15	110	19	8	4	1	3	0	145
14:30	126	25	6	5	3	1	0	166
14:45	112	12	7	2	1	4	0	138
1 Hr	464	77	27	16	5	10	0	599

15:00	186	19	6	6	1	3	0	221
15:15	201	17	4	4	3	1	0	230
15:30	164	18	5	5	0	2	1	195
15:45	189	12	1	7	0	1	0	210
1 Hr	740	66	16	22	4	7	1	856

15:00	107	23	8	1	0	1	3	143
15:15	95	25	7	2	0	2	0	131
15:30	155	26	6	7	2	5	1	202
15:45	109	16	3	4	1	2	0	135
1 Hr	466	90	24	14	3	10	4	611

16:00	195	12	6	4	1	4	0	222
16:15	187	18	2	2	3	1	1	214
16:30	222	12	5	6	0	2	0	247
16:45	214	14	3	4	0	2	0	237
1 Hr	818	56	16	16	4	9	1	920

16:00	137	30	7	2	2	1	0	179
16:15	107	15	4	3	0	2	0	131
16:30	139	23	3	1	0	5	0	171
16:45	133	21	6	2	1	0	2	165
1 Hr	516	89	20	8	3	8	2	646

17:00	226	15	2	3	0	6	0	252
17:15	231	19	1	1	1	2	3	258
17:30	207	22	4	2	3	2	0	240
17:45	243	18	7	3	0	3	0	274
1 Hr	907	74	14	9	4	13	3	1024

17:00	120	14	4	1	2	6	0	147
17:15	97	15	2	1	2	2	0	119
17:30	125	17	2	2	0	4	0	150
17:45	148	17	8	1	1	0	0	175
1 Hr	490	63	16	5	5	12	0	591

6 Hrs	4454	404	100	100	22	53	7	5140
-------	------	-----	-----	-----	----	----	---	------

6 Hrs	2901	459	151	74	20	54	8	3667
-------	------	-----	-----	----	----	----	---	------

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	248	20	2	5	0	1	2	278
18:15	237	17	5	0	1	3	0	263
18:30	244	18	3	4	1	2	0	272
18:45	213	16	3	1	0	5	1	239
1 Hr	942	71	13	10	2	11	3	1052

18:00	114	12	2	1	1	2	0	132
18:15	157	13	4	2	0	1	0	177
18:30	113	6	3	2	2	1	0	127
18:45	113	12	1	2	0	2	0	130
1 Hr	497	43	10	7	3	6	0	566

19:00	222	18	1	0	1	3	1	246
19:15	157	13	2	2	0	1	0	175
19:30	195	13	4	0	0	1	0	213
19:45	159	10	2	0	0	4	0	175
1 Hr	733	54	9	2	1	9	1	809

19:00	97	10	3	3	1	2	0	116
19:15	80	5	1	0	1	0	0	87
19:30	71	7	2	0	1	0	0	81
19:45	75	3	1	0	1	1	0	81
1 Hr	323	25	7	3	4	3	0	365

20:00	130	11	1	0	2	0	0	144
20:15	126	5	1	0	0	3	0	135
20:30	116	7	1	1	0	1	0	126
20:45	102	6	1	0	0	0	0	109
1 Hr	474	29	4	1	2	4	0	514

20:00	62	4	1	1	0	1	0	69
20:15	62	0	1	0	0	0	0	63
20:30	44	1	0	1	1	0	0	47
20:45	49	3	2	1	0	1	0	56
1 Hr	217	8	4	3	1	2	0	235

21:00	86	4	0	1	1	1	0	93
21:15	68	2	0	0	0	0	0	70
21:30	73	2	1	0	0	0	0	76
21:45	60	6	1	0	1	0	0	68
1 Hr	287	14	2	1	2	1	0	307

21:00	34	1	1	0	0	0	0	36
21:15	38	1	0	1	0	0	0	40
21:30	29	1	0	1	0	0	0	31
21:45	35	1	0	0	0	2	0	38
1 Hr	136	4	1	2	0	2	0	145

22:00	64	3	2	0	0	2	0	71
22:15	62	6	0	1	0	0	1	70
22:30	41	0	0	0	0	0	0	41
22:45	32	2	0	0	0	2	0	36
1 Hr	199	11	2	1	0	4	1	218

22:00	27	2	0	1	0	1	0	31
22:15	16	2	1	1	0	0	0	20
22:30	22	1	0	0	1	1	0	25
22:45	27	1	0	2	0	1	0	31
1 Hr	92	6	1	4	1	3	0	107

23:00	34	0	1	0	0	1	0	36
23:15	31	2	0	0	0	0	0	33
23:30	17	0	1	1	0	0	0	19
23:45	18	3	0	1	0	0	0	22
1 Hr	100	5	2	2	0	1	0	110

23:00	33	2	0	0	0	1	0	36
23:15	13	0	1	0	0	0	0	14
23:30	19	2	1	0	0	0	0	22
23:45	13	1	0	0	0	0	0	14
1 Hr	78	5	2	0	0	1	0	86

6 Hrs	2735	184	32	17	7	30	5	3010
-------	------	-----	----	----	---	----	---	------

6 Hrs	1343	91	25	19	9	17	0	1504
-------	------	----	----	----	---	----	---	------

12 Hrs	7189	588	132	117	29	83	12	8150
--------	------	-----	-----	-----	----	----	----	------

12 Hrs	4244	550	176	93	29	71	8	5171
--------	------	-----	-----	----	----	----	---	------

Total	9782	1077	326	264	51	114	17	11631
-------	------	------	-----	-----	----	-----	----	-------

Total	7433	925	327	242	52	110	15	9104
-------	------	-----	-----	-----	----	-----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 14th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	21	0	1	1	0	0	0	23
00:15	9	1	0	0	0	0	1	11
00:30	33	2	1	1	0	0	0	37
00:45	7	1	0	0	0	0	0	8
1 Hr	70	4	2	2	0	0	1	79
01:00	8	1	0	0	0	0	0	9
01:15	7	1	1	0	0	0	0	9
01:30	8	0	0	0	0	0	0	8
01:45	9	0	0	0	0	0	0	9
1 Hr	32	2	1	0	0	0	0	35
02:00	2	0	1	0	0	0	0	3
02:15	4	0	0	1	0	0	0	5
02:30	5	1	1	2	0	0	0	9
02:45	5	0	0	2	0	0	0	7
1 Hr	16	1	2	5	0	0	0	24
03:00	2	1	0	0	0	0	0	3
03:15	4	1	1	1	0	0	0	7
03:30	3	0	0	3	0	0	0	6
03:45	2	0	0	0	0	0	0	2
1 Hr	11	2	1	4	0	0	0	18
04:00	4	0	3	1	0	0	0	8
04:15	4	1	0	1	0	0	0	6
04:30	4	6	0	2	0	0	0	12
04:45	3	4	2	1	0	0	0	10
1 Hr	15	11	5	5	0	0	0	36
05:00	9	3	1	1	0	0	0	14
05:15	8	0	0	5	0	0	0	13
05:30	8	4	0	3	0	0	0	15
05:45	11	2	1	1	0	2	0	17
1 Hr	36	9	2	10	0	2	0	59
6 Hrs	180	29	13	26	0	2	1	251

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	10	1	0	2	0	0	0	13
00:15	12	0	0	1	0	0	0	13
00:30	22	1	1	0	0	0	0	24
00:45	6	0	0	1	0	0	0	7
1 Hr	50	2	1	4	0	0	0	57
01:00	10	0	0	1	0	0	0	11
01:15	8	0	0	0	0	0	0	8
01:30	6	0	0	0	0	0	0	6
01:45	6	0	1	1	0	1	0	9
1 Hr	30	0	1	2	0	1	0	34
02:00	4	0	0	1	0	0	0	5
02:15	3	0	0	0	0	0	0	3
02:30	5	1	2	0	0	0	0	8
02:45	1	1	0	0	0	0	0	2
1 Hr	13	2	2	1	0	0	0	18
03:00	2	1	1	1	0	0	0	5
03:15	4	0	1	0	0	0	0	5
03:30	4	0	0	0	0	0	0	4
03:45	2	0	0	0	0	0	0	2
1 Hr	12	1	2	1	0	0	0	16
04:00	1	0	1	0	0	0	0	2
04:15	3	2	1	2	0	0	0	8
04:30	3	0	1	1	0	0	0	5
04:45	6	3	0	1	0	0	0	10
1 Hr	13	5	3	4	0	0	0	25
05:00	5	0	0	3	0	1	0	9
05:15	18	2	0	2	0	1	0	23
05:30	13	4	1	1	0	1	0	20
05:45	19	4	3	0	0	0	0	26
1 Hr	55	10	4	6	0	3	0	78
6 Hrs	173	20	13	18	0	4	0	228

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	1	0	0	1
08:30	0	0	0	0
08:45	1	0	0	1
1 Hr	2	0	0	2
09:00	1	0	0	1
09:15	0	0	0	0
09:30	3	0	0	3
09:45	0	0	0	0
1 Hr	4	0	0	4
3 Hr	6	0	0	6
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	1	0	0	1
17:15	0	0	0	0
17:30	4	0	0	4
17:45	0	0	0	0
1 Hr	5	0	0	5
18:00	0	0	0	0
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	0	0	0	0
3 Hrs	5	0	0	5
6 Hrs	11	0	0	11

	Direction : Westbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	1	0	0	1
07:45	0	0	0	0
1 Hr	1	0	0	1
08:00	0	0	0	0
08:15	0	0	0	0
08:30	1	0	0	1
08:45	1	0	0	1
1 Hr	2	0	0	2
09:00	2	0	0	2
09:15	1	0	0	1
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	3	0	0	3
6 Hrs	6	0	0	6
16:00	0	0	0	0
16:15	2	0	0	2
16:30	0	0	0	0
16:45	2	0	0	2
1 Hr	4	0	0	4
17:00	0	0	0	0
17:15	0	0	0	0
17:30	1	0	0	1
17:45	0	0	0	0
1 Hr	1	0	0	1
18:00	1	0	0	1
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	1	0	0	1
6 Hrs	6	0	0	6
6 Hrs	12	0	0	12



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 14th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	16	1	4	1	1	0	0	23
06:15	30	5	2	0	1	1	0	39
06:30	27	5	1	4	0	0	0	37
06:45	49	4	5	2	0	1	0	61
1 Hr	122	15	12	7	2	2	0	160

21	1	0	0	0	0	0	0	22
29	2	1	0	0	1	0	0	33
40	9	1	3	0	1	0	0	54
47	11	0	2	0	0	0	0	60
137	23	2	5	0	2	0	0	169

07:00	43	10	6	0	0	0	1	60
07:15	50	9	4	1	0	1	0	65
07:30	75	8	4	7	0	1	0	95
07:45	90	7	2	0	0	0	0	99
1 Hr	258	34	16	8	0	2	1	319

52	8	2	1	1	2	0	0	66
49	10	1	0	0	0	0	0	60
87	10	3	0	2	1	1	0	104
89	11	0	0	0	1	0	0	101
277	39	6	1	3	4	1	0	331

08:00	83	15	8	1	1	1	0	109
08:15	92	12	0	2	0	2	4	112
08:30	116	8	3	2	3	2	0	134
08:45	126	9	3	0	2	5	0	145
1 Hr	417	44	14	5	6	10	4	500

88	8	5	2	2	2	0	0	107
109	8	1	1	0	1	0	0	120
116	10	2	1	0	0	0	0	129
124	10	2	3	0	0	0	0	139
437	36	10	7	2	3	0	0	495

09:00	162	4	2	1	2	0	0	171
09:15	151	15	5	1	4	1	3	180
09:30	176	10	2	0	3	4	0	195
09:45	174	7	2	2	1	4	0	190
1 Hr	663	36	11	4	10	9	3	736

136	5	6	0	0	1	0	0	148
134	9	1	1	1	2	0	0	148
158	13	5	1	1	1	0	0	179
168	12	3	3	1	0	0	0	187
596	39	15	5	3	4	0	0	662

10:00	199	8	1	2	3	4	0	217
10:15	187	7	2	2	2	3	0	203
10:30	220	9	6	0	1	1	0	237
10:45	198	7	2	0	1	3	1	212
1 Hr	804	31	11	4	7	11	1	869

174	9	2	0	0	0	0	0	185
158	8	9	3	2	0	0	0	180
180	7	1	2	0	2	0	0	192
162	12	0	1	0	3	1	0	179
674	36	12	6	2	5	1	0	736

11:00	195	10	0	2	0	3	0	210
11:15	190	9	0	2	0	3	0	204
11:30	190	14	3	0	0	1	0	208
11:45	210	12	0	0	0	3	0	225
1 Hr	785	45	3	4	0	10	0	847

164	10	2	0	0	3	0	0	179
194	10	2	1	0	3	0	0	210
143	10	2	0	1	0	0	0	156
150	14	2	3	0	7	0	0	176
651	44	8	4	1	13	0	0	721

6 Hrs	3049	205	67	32	25	44	9	3431
-------	------	-----	----	----	----	----	---	------

2772	217	53	28	11	31	2	0	3114
------	-----	----	----	----	----	---	---	------

12 Hrs	3229	234	80	58	25	46	10	3682
--------	------	-----	----	----	----	----	----	------

2945	237	66	46	11	35	2	0	3342
------	-----	----	----	----	----	---	---	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 14th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	189	16	2	2	1	2	0	212
12:15	202	11	3	2	1	3	0	222
12:30	166	11	2	0	0	2	1	182
12:45	151	10	1	1	1	3	1	168
1 Hr	708	48	8	5	3	10	2	784

116	9	2	1	0	3	0	131
146	8	1	1	0	3	0	159
125	10	3	0	3	1	0	142
161	12	0	0	0	0	0	173
548	39	6	2	3	7	0	605

13:00	187	18	0	2	0	5	0	212
13:15	171	7	1	1	1	1	0	182
13:30	163	10	2	0	0	0	0	175
13:45	124	9	2	1	0	0	0	136
1 Hr	645	44	5	4	1	6	0	705

147	8	2	0	0	0	0	157
145	6	2	0	0	2	1	156
120	14	0	2	1	0	0	137
130	9	0	0	0	3	0	142
542	37	4	2	1	5	1	592

14:00	140	5	0	1	1	1	0	148
14:15	151	9	2	0	1	3	0	166
14:30	151	14	4	0	0	1	0	170
14:45	140	12	2	0	0	5	0	159
1 Hr	582	40	8	1	2	10	0	643

152	9	6	0	0	7	0	174
115	3	2	1	0	3	0	124
136	17	1	1	3	6	0	164
108	9	3	1	1	2	0	124
511	38	12	3	4	18	0	586

15:00	152	6	1	0	1	3	0	163
15:15	168	10	0	3	0	3	0	184
15:30	130	10	1	1	0	3	0	145
15:45	148	9	4	2	0	4	0	167
1 Hr	598	35	6	6	1	13	0	659

106	6	0	0	0	5	1	118
111	5	2	2	0	0	0	120
109	7	0	3	0	3	0	122
135	8	2	4	1	4	1	155
461	26	4	9	1	12	2	515

16:00	156	7	3	0	0	2	0	168
16:15	171	3	1	0	2	3	0	180
16:30	177	10	2	2	0	1	2	194
16:45	139	9	1	1	1	4	0	155
1 Hr	643	29	7	3	3	10	2	697

119	12	0	0	0	1	0	132
114	11	0	0	0	1	0	126
154	6	3	0	1	2	0	166
123	7	0	0	0	5	0	135
510	36	3	0	1	9	0	559

17:00	151	6	0	0	0	0	0	157
17:15	142	6	1	1	1	1	0	152
17:30	150	8	2	0	0	0	0	160
17:45	160	6	3	1	0	0	0	170
1 Hr	603	26	6	2	1	1	0	639

132	7	3	0	0	2	0	144
130	5	2	0	0	3	0	140
135	6	3	0	0	2	0	146
140	7	2	0	0	1	0	150
537	25	10	0	0	8	0	580

6 Hrs	3779	222	40	21	11	50	4	4127
-------	------	-----	----	----	----	----	---	------

3109	201	39	16	10	59	3	3437
------	-----	----	----	----	----	---	------

Flowcount

Direction : **Eastbound**

Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total
-----	-----	------	------	-----	-----	-----	-------

Direction : **Westbound**

Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total
-----	-----	------	------	-----	-----	-----	-------

18:00	136	5	1	0	0	3	0	145
18:15	120	8	0	0	1	1	0	130
18:30	126	4	2	0	1	1	0	134
18:45	89	4	0	0	0	0	0	93
1 Hr	471	21	3	0	2	5	0	502

18:00	101	5	1	1	8	2	0	118
18:15	118	6	0	3	2	3	0	132
18:30	145	4	2	0	1	3	0	155
18:45	140	8	0	1	3	3	0	155
1 Hr	504	23	3	5	14	11	0	560

19:00	102	4	3	1	1	3	0	114
19:15	87	2	1	0	0	0	0	90
19:30	88	7	2	0	0	0	1	98
19:45	85	2	0	0	2	1	0	90
1 Hr	362	15	6	1	3	4	1	392

19:00	99	9	0	0	4	4	0	116
19:15	130	2	1	0	2	3	0	138
19:30	120	6	1	1	2	0	0	130
19:45	87	3	0	0	0	2	0	92
1 Hr	436	20	2	1	8	9	0	476

20:00	75	2	0	0	1	2	0	80
20:15	74	6	0	0	0	1	0	81
20:30	54	2	0	0	0	2	0	58
20:45	61	4	1	0	0	0	0	66
1 Hr	264	14	1	0	1	5	0	285

20:00	107	2	0	0	0	1	0	110
20:15	62	4	0	0	0	5	0	71
20:30	45	1	0	2	1	1	0	50
20:45	59	4	1	0	0	1	0	65
1 Hr	273	11	1	2	1	8	0	296

21:00	52	3	1	0	1	1	0	58
21:15	38	3	0	0	0	0	0	41
21:30	47	0	3	0	0	1	0	51
21:45	43	1	0	0	0	0	0	44
1 Hr	180	7	4	0	1	2	0	194

21:00	52	1	0	1	0	0	0	54
21:15	50	4	0	0	0	2	0	56
21:30	40	2	0	0	0	0	0	42
21:45	54	3	0	0	0	0	0	57
1 Hr	196	10	0	1	0	2	0	209

22:00	32	1	0	0	0	0	1	34
22:15	34	1	0	0	0	0	0	35
22:30	40	2	0	0	0	0	0	42
22:45	49	1	0	0	0	2	0	52
1 Hr	155	5	0	0	0	2	1	163

22:00	36	2	0	0	0	1	0	39
22:15	33	2	0	0	0	0	0	35
22:30	31	0	0	0	0	0	0	31
22:45	31	3	0	0	0	0	0	34
1 Hr	131	7	0	0	0	1	0	139

23:00	24	1	0	0	0	0	0	25
23:15	27	0	0	0	0	0	0	27
23:30	21	2	0	0	0	0	0	23
23:45	14	2	0	0	0	1	0	17
1 Hr	86	5	0	0	0	1	0	92

23:00	25	1	0	0	0	0	0	26
23:15	20	1	0	0	0	0	0	21
23:30	19	2	0	0	0	0	0	21
23:45	17	0	0	0	0	0	0	17
1 Hr	81	4	0	0	0	0	0	85

6 Hrs	1518	67	14	1	7	19	2	1628
-------	------	----	----	---	---	----	---	------

6 Hrs	1621	75	6	9	23	31	0	1765
-------	------	----	---	---	----	----	---	------

12 Hrs	5297	289	54	22	18	69	6	5755
--------	------	-----	----	----	----	----	---	------

12 Hrs	4730	276	45	25	33	90	3	5202
--------	------	-----	----	----	----	----	---	------

Total	8526	523	134	80	43	115	16	9437
-------	------	-----	-----	----	----	-----	----	------

Total	7675	513	111	71	44	125	5	8544
-------	------	-----	-----	----	----	-----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Monday 9th June - Saturday 14th June 2014

Summary of Counts

		Direction : Eastbound							Total	
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total	
Day 1	Monday	09/06/2014	6756	916	302	245	52	50	12	8333
Day 2	Tuesday	10/06/2014	6532	964	350	256	52	77	14	8245
Day 3	Wednesday	11/06/2014	6924	957	351	268	50	98	30	8678
Day 4	Thursday	12/06/2014	7318	1003	348	293	49	116	22	9148
Day 5	Friday	13/06/2014	9782	1077	326	264	51	114	17	11631
Day 6	Saturday	14/06/2014	8526	523	134	80	43	115	16	9437
			45838	5440	1811	1406	296	570	111	56472

		Direction : Westbound							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total
		6984	972	311	278	54	56	11	8666
		6439	970	326	257	51	104	16	8163
		6711	970	318	262	62	125	22	8490
		6806	1005	318	260	46	125	14	8574
		7433	925	327	242	52	110	15	9104
		7675	513	111	71	44	125	5	8544
		42048	5355	1711	1390	309	645	83	51541

		Direction Eastbound					Total
		Adult	Unaccompanied Child	Accompanied Child	Unaccompanied Adult	Accompanied Adult	Total
		5	0	0	0	0	5
		2	0	0	0	0	2
		8	0	0	0	0	8
		1	0	0	0	0	1
		4	0	0	0	0	4
		11	0	0	0	0	11
		31	0	0	0	0	31

		Direction Westbound					Total
		Adult	Unaccompanied Child	Accompanied Child	Unaccompanied Adult	Accompanied Adult	Total
		6	0	0	0	0	6
		9	0	0	0	0	9
		5	0	0	0	0	5
		0	0	0	0	0	0
		5	0	0	0	0	5
		12	0	0	0	0	12
		37	0	0	0	0	37

		Direction : Combined Counts							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	PC	Total

Day 1	Monday	09/06/2014	13740	1888	613	523	106	106	23	16999
Day 2	Tuesday	10/06/2014	12971	1934	676	513	103	181	30	16408
Day 3	Wednesday	11/06/2014	13635	1927	669	550	112	223	52	17168
Day 4	Thursday	12/06/2014	14124	2008	666	553	94	241	36	17722
Day 5	Friday	13/06/2014	17215	2002	653	506	103	224	32	20735
Day 6	Saturday	14/06/2014	16201	1036	245	151	87	240	21	17981
			87886	10795	3522	2796	605	1215	194	107013

		Direction : Combined Counts					Total
		Adult	Unaccompanied Child	Accompanied Child	Unaccompanied Adult	Accompanied Adult	Total

		11	0	0	0	0	11
		11	0	0	0	0	11
		13	0	0	0	0	13
		1	0	0	0	0	1
		9	0	0	0	0	9
		23	0	0	0	0	23
		68	0	0	0	0	68

Averages Vehicles

		Direction : Eastbound							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total
Day 1	AM	83.92	21.58	8.50	4.58	1.08	0.33	0.00	120.00
	PM	138.17	15.08	3.17	2.00	0.92	1.58	0.58	161.50
	00:00-12:00	47.10	9.54	3.67	2.56	0.50	0.19	0.04	63.60
	12:00-24:00	93.65	9.54	2.63	2.54	0.58	0.85	0.21	110.00
	24 Hrs	70.38	9.54	3.15	2.55	0.54	0.52	0.13	86.80

		Direction : Westbound							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total
		144.08	17.50	5.67	4.50	1.08	1.25	0.42	174.50
		110.25	18.42	4.75	2.75	1.08	0.50	0.00	137.75
		69.98	9.06	2.98	3.42	0.50	0.60	0.15	86.69
		75.52	11.19	3.50	2.38	0.63	0.56	0.08	93.85
		72.75	10.13	3.24	2.90	0.56	0.58	0.11	90.27

Pedestrians

		Direction Eastbound				Total
		Adult	Ac Child	Un Child	Total	Total
AM		0.00	0.00	0.00	0.00	0.00
PM		0.42	0.00	0.00	0.42	0.42
6 Hrs		0.21	0.00	0.00	0.21	0.21

		Direction Westbound				Total
		Adult	Ac Child	Un Child	Total	Total
AM		0.25	0.00	0.00	0.25	0.25
PM		0.25	0.00	0.00	0.25	0.25
6 Hrs		0.25	0.00	0.00	0.25	0.25

Day 2

AM	83.25	24.92	8.58	4.50	0.92	0.58	0.08	122.83
PM	139.17	15.17	3.83	1.58	0.75	1.42	0.75	162.67
00:00-12:00	42.77	10.25	4.31	2.75	0.48	0.48	0.02	61.06
12:00-24:00	93.31	9.83	2.98	2.58	0.60	1.13	0.27	110.71
24 Hrs	68.04	10.04	3.65	2.67	0.54	0.80	0.15	85.89

AM	141.08	18.25	5.08	4.67	1.08	1.67	0.17	172.00
PM	107.83	19.75	4.67	2.50	1.33	2.00	0.58	138.67
00:00-12:00	60.21	8.58	2.79	3.21	0.48	0.75	0.08	76.10
12:00-24:00	73.94	11.63	4.00	2.15	0.58	1.42	0.25	93.96
24 Hrs	67.07	10.10	3.40	2.68	0.53	1.08	0.17	85.03

AM	0.00	0.00	0.00	0.00	0.00
PM	0.17	0.00	0.00	0.17	0.17
6 Hrs	0.08	0.00	0.00	0.08	0.08

AM	0.33	0.00	0.00	0.33
PM	0.42	0.00	0.00	0.42
6 Hrs	0.38	0.00	0.00	0.38

Day 3

AM	89.58	21.50	9.67	5.50	1.00	0.58	0.08	127.92
PM	148.67	15.00	3.92	3.08	0.58	2.67	1.42	175.33
00:00-12:00	46.46	10.19	4.33	2.94	0.63	0.44	0.06	65.04
12:00-24:00	97.79	9.75	2.98	2.65	0.42	1.60	0.56	115.75
24 Hrs	72.13	9.97	3.66	2.79	0.52	1.02	0.31	90.40

AM	137.58	16.42	4.25	4.00	1.08	1.83	0.33	165.50
PM	114.25	18.58	3.75	2.83	1.75	3.42	0.33	144.92
00:00-12:00	61.21	8.50	3.06	3.08	0.50	0.75	0.15	77.25
12:00-24:00	78.60	11.71	3.56	2.79	0.79	1.85	0.31	99.63
24 Hrs	69.91	10.10	3.31	2.94	0.65	1.30	0.23	88.44

AM	0.17	0.00	0.00	0.17
PM	0.50	0.00	0.00	0.50
6 Hrs	0.33	0.00	0.00	0.33

AM	0.17	0.00	0.00	0.17
PM	0.25	0.00	0.00	0.25
6 Hrs	0.21	0.00	0.00	0.21

Day 4

AM	90.75	25.58	9.17	5.25	0.75	1.25	0.17	132.92
PM	155.75	14.42	2.50	3.00	0.92	2.92	0.92	180.42
00:00-12:00	49.42	10.38	4.38	3.46	0.44	0.56	0.06	68.69
12:00-24:00	103.04	10.52	2.88	2.65	0.56	1.85	0.40	121.90
24 Hrs	76.23	10.45	3.63	3.05	0.50	1.21	0.23	95.29

AM	134.67	15.67	5.17	3.92	0.58	1.83	0.33	162.17
PM	122.42	20.08	4.33	2.58	1.25	2.25	0.08	153.00
00:00-12:00	60.31	8.17	2.75	2.98	0.35	0.88	0.13	75.56
12:00-24:00	81.48	12.77	3.88	2.44	0.60	1.73	0.17	103.06
24 Hrs	70.90	10.47	3.31	2.71	0.48	1.30	0.15	89.31

AM	0.00	0.00	0.00	0.00
PM	0.08	0.00	0.00	0.08
6 Hrs	0.04	0.00	0.00	0.04

AM	0.00	0.00	0.00	0.00
PM	0.00	0.00	0.00	0.00
6 Hrs	0.00	0.00	0.00	0.00

Day 5

AM	91.83	24.33	8.67	6.08	1.00	0.83	0.17	132.92
PM	222.25	16.75	3.58	2.92	0.83	2.75	0.58	249.67
00:00-12:00	54.02	10.19	4.04	3.06	0.46	0.65	0.10	72.52
12:00-24:00	149.77	12.25	2.75	2.44	0.60	1.73	0.25	169.79
24 Hrs	101.90	11.22	3.40	2.75	0.53	1.19	0.16	121.16

AM	139.58	15.33	6.17	4.75	1.00	1.83	0.42	169.08
PM	125.25	16.25	3.83	1.67	0.92	2.17	0.17	150.25
00:00-12:00	66.44							




Sky High

Count On Us

Client : Lincolnshire County Council	Site plan for : EW1 - A158 Wragby Road East
Project : 9320 / Lincoln By Pass	Date : Monday 9th June - Saturday 14th June 2014



Unnamed Road



A518 Wragby Road



Sky High

Count On Us

Client:	Lincolnshire County Council
Project:	9320 / Lincoln By Pass
Site:	EW1 - A158 Wragby Road East
Survey Date:	Monday 16th June - Saturday 21st June 2014
Survey Period:	07:00 - 19:00
Method:	Video Observation

Incidents / Observations:

There were no incidents reported over the survey period.



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Monday 16th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Clear

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	8	0	0	0	0	0	0	8
00:15	2	0	1	0	0	0	0	3
00:30	7	0	1	0	0	0	0	8
00:45	3	0	0	0	0	0	0	3
1 Hr	20	0	2	0	0	0	0	22
01:00	3	0	1	0	0	0	0	4
01:15	1	0	0	1	0	0	0	2
01:30	7	0	0	0	0	0	0	7
01:45	5	1	1	1	0	0	0	8
1 Hr	16	1	2	2	0	0	0	21
02:00	2	1	0	0	0	0	0	3
02:15	2	0	0	0	0	0	0	2
02:30	3	0	0	1	0	0	0	4
02:45	3	0	0	1	0	0	0	4
1 Hr	10	1	0	2	0	0	0	13
03:00	1	0	0	0	0	0	0	1
03:15	4	0	0	0	0	0	0	4
03:30	3	0	2	0	0	0	0	5
03:45	1	0	0	2	0	0	0	3
1 Hr	9	0	2	2	0	0	0	13
04:00	0	1	0	0	0	0	0	1
04:15	1	4	0	1	0	0	0	6
04:30	6	3	2	2	0	0	0	13
04:45	3	1	1	1	0	0	0	6
1 Hr	10	9	3	4	0	0	0	26
05:00	7	1	2	1	0	0	0	11
05:15	9	1	1	1	0	0	0	12
05:30	11	1	2	2	0	0	0	16
05:45	17	2	1	1	0	0	0	21
1 Hr	44	5	6	5	0	0	0	60
6 Hrs	109	16	15	15	0	0	0	155

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	7	1	0	1	0	0	0	9
00:15	5	0	1	0	0	0	0	6
00:30	5	0	0	0	0	0	0	5
00:45	2	0	0	0	0	0	0	2
1 Hr	19	1	1	1	0	0	0	22
01:00	2	0	0	0	0	0	0	2
01:15	3	0	0	0	0	0	0	3
01:30	0	1	0	0	0	0	0	1
01:45	2	0	0	0	0	0	0	2
1 Hr	7	1	0	0	0	0	0	8
02:00	3	1	0	1	0	0	0	5
02:15	0	1	0	0	0	0	0	1
02:30	0	0	0	0	0	0	0	0
02:45	1	0	0	0	0	0	0	1
1 Hr	4	2	0	1	0	0	0	7
03:00	2	0	0	2	0	0	0	4
03:15	5	2	0	1	0	0	0	8
03:30	3	1	0	3	0	0	0	7
03:45	3	0	0	0	0	0	0	3
1 Hr	13	3	0	6	0	0	0	22
04:00	8	5	1	0	0	0	0	14
04:15	8	5	1	3	0	0	0	17
04:30	15	3	2	3	0	0	0	23
04:45	8	3	2	5	0	0	0	18
1 Hr	39	16	6	11	0	0	0	72
05:00	14	3	0	8	0	1	0	26
05:15	16	8	1	5	0	0	0	30
05:30	20	12	1	11	0	0	0	44
05:45	22	8	1	6	0	0	0	37
1 Hr	72	31	3	30	0	1	0	137
6 Hrs	154	54	10	49	0	1	0	268

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	1	0	0	1
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	1	0	0	1
18:00	0	0	0	0
18:15	1	0	0	1
18:30	2	0	0	2
18:45	1	0	0	1
1 Hr	4	0	0	4
3 Hrs	5	0	0	5
6 Hrs	5	0	0	5

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	1	0	1
07:30	0	0	0
07:45	0	0	0
1 Hr	1	0	1
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	1	0	1
09:30	0	0	0
09:45	1	0	1
1 Hr	2	0	2
3 Hr	3	0	3
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	2	0	2
1 Hr	2	0	2
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	0	0	0
3 Hrs	2	0	2
6 Hrs	5	0	5



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Monday 16th June 2014

AM Weather: Mild & Cloudy
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	7	13	1	5	3	0	0	29
06:15	33	12	3	0	2	1	0	51
06:30	37	17	3	2	0	1	0	60
06:45	35	14	7	8	1	2	0	67
1 Hr	112	56	14	15	6	4	0	207

50	12	2	10	1	1	0	76
56	14	2	2	0	2	0	76
76	18	1	4	0	2	2	103
78	25	5	5	1	0	0	114
260	69	10	21	2	5	2	369

07:00	68	23	8	2	2	0	0	103
07:15	63	29	3	2	1	0	0	98
07:30	94	27	3	5	1	1	0	131
07:45	101	23	9	1	0	0	0	134
1 Hr	326	102	23	10	4	1	0	466

85	25	2	2	1	0	0	115
146	28	2	4	1	2	1	184
161	33	3	4	0	0	1	202
154	15	5	7	1	6	0	188
546	101	12	17	3	8	2	689

08:00	84	27	10	10	0	0	0	131
08:15	79	23	10	4	0	0	0	116
08:30	92	31	9	3	0	0	0	135
08:45	76	17	6	6	3	0	0	108
1 Hr	331	98	35	23	3	0	0	490

188	18	1	5	2	3	0	217
95	14	6	2	1	1	2	121
172	26	8	3	2	3	1	215
115	11	3	4	1	1	0	135
570	69	18	14	6	8	3	688

09:00	100	20	10	3	0	0	0	133
09:15	90	21	6	5	2	0	0	124
09:30	100	15	3	7	0	1	0	126
09:45	102	17	3	6	5	1	0	134
1 Hr	392	73	22	21	7	2	0	517

138	14	8	4	0	0	0	164
103	13	5	4	0	0	1	126
129	20	5	5	2	1	0	162
125	19	6	8	3	0	1	162
495	66	24	21	5	1	2	614

10:00	107	14	8	5	1	2	0	137
10:15	98	24	5	5	1	1	0	134
10:30	125	11	6	6	0	1	0	149
10:45	126	7	8	6	2	0	0	149
1 Hr	456	56	27	22	4	4	0	569

131	21	4	3	1	1	0	161
148	12	8	4	1	2	0	175
141	16	6	6	3	1	0	173
153	13	3	3	1	2	0	175
573	62	21	16	6	6	0	684

11:00	125	12	4	5	1	0	0	147
11:15	136	17	7	10	2	0	0	172
11:30	162	12	3	5	0	1	0	183
11:45	132	7	3	4	1	1	0	148
1 Hr	555	48	17	24	4	2	0	650

131	14	3	2	3	0	0	153
118	16	5	2	0	0	0	141
131	15	5	2	2	1	0	156
136	12	5	4	0	0	0	157
516	57	18	10	5	1	0	607

6 Hrs	2172	433	138	115	28	13	0	2899
-------	------	-----	-----	-----	----	----	---	------

2960	424	103	99	27	29	9	3651
------	-----	-----	----	----	----	---	------

12 Hrs	2281	449	153	130	28	13	0	3054
--------	------	-----	-----	-----	----	----	---	------

3114	478	113	148	27	30	9	3919
------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Monday 16th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	149	16	5	8	2	1	0	181
12:15	134	10	5	7	0	0	0	156
12:30	134	18	6	9	1	0	1	169
12:45	125	16	5	7	1	1	0	155
1 Hr	542	60	21	31	4	2	1	661

12:00	129	13	3	2	1	0	0	148
12:15	129	19	3	5	1	0	0	157
12:30	140	13	1	7	1	2	0	164
12:45	111	17	4	8	0	2	0	142
1 Hr	509	62	11	22	3	4	0	611

13:00	115	8	3	3	0	1	0	130
13:15	115	11	3	11	1	0	0	141
13:30	130	9	4	11	0	0	0	154
13:45	125	9	2	6	2	0	0	144
1 Hr	485	37	12	31	3	1	0	569

13:00	127	20	6	4	0	0	1	158
13:15	111	16	8	5	1	2	0	143
13:30	120	17	7	6	1	1	0	152
13:45	134	21	8	6	1	0	0	170
1 Hr	492	74	29	21	3	3	1	623

14:00	122	13	4	6	0	0	0	145
14:15	124	17	1	2	1	3	0	148
14:30	126	17	1	2	5	1	1	153
14:45	134	9	4	6	1	2	0	156
1 Hr	506	56	10	16	7	6	1	602

14:00	137	11	8	3	4	1	0	164
14:15	103	20	10	3	1	0	0	137
14:30	143	19	5	5	2	0	0	174
14:45	109	20	9	6	1	2	1	148
1 Hr	492	70	32	17	8	3	1	623

15:00	140	14	2	3	0	1	0	160
15:15	134	8	3	8	1	0	0	154
15:30	131	17	4	4	1	2	1	160
15:45	131	21	3	11	0	1	0	167
1 Hr	536	60	12	26	2	4	1	641

15:00	114	28	14	5	1	3	0	165
15:15	81	13	6	7	0	2	1	110
15:30	106	9	11	4	2	0	1	133
15:45	123	33	6	5	0	0	0	167
1 Hr	424	83	37	21	3	5	2	575

16:00	171	16	5	3	0	1	0	196
16:15	158	20	3	5	3	1	1	191
16:30	142	20	3	11	0	0	1	177
16:45	173	10	4	2	0	2	1	192
1 Hr	644	66	15	21	3	4	3	756

16:00	94	27	5	5	1	0	0	132
16:15	137	26	7	4	0	3	0	177
16:30	117	25	1	3	1	1	0	148
16:45	133	29	5	2	2	0	0	171
1 Hr	481	107	18	14	4	4	0	628

17:00	157	19	2	4	1	2	2	187
17:15	144	7	3	1	2	3	1	161
17:30	160	7	5	3	1	3	1	180
17:45	160	17	0	2	0	3	0	182
1 Hr	621	50	10	10	4	11	4	710

17:00	109	17	2	1	2	0	1	132
17:15	103	12	3	3	0	2	0	123
17:30	117	14	4	3	1	0	0	139
17:45	114	20	3	8	0	3	0	148
1 Hr	443	63	12	15	3	5	1	542

6 Hrs	3334	329	80	135	23	28	10	3939
-------	------	-----	----	-----	----	----	----	------

6 Hrs	2841	459	139	110	24	24	5	3602
-------	------	-----	-----	-----	----	----	---	------

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	158	13	3	2	1	2	0	179
18:15	110	2	1	4	0	3	2	122
18:30	109	8	3	0	1	1	0	122
18:45	82	9	0	1	0	0	0	92
1 Hr	459	32	7	7	2	6	2	515

18:00	87	17	4	2	1	0	0	111
18:15	105	13	5	5	0	1	1	130
18:30	108	11	0	3	1	0	0	123
18:45	71	6	3	2	0	1	0	83
1 Hr	371	47	12	12	2	2	1	447

19:00	96	5	0	2	1	0	0	104
19:15	92	4	3	2	0	3	0	104
19:30	76	6	0	0	0	4	2	88
19:45	81	4	2	5	1	0	0	93
1 Hr	345	19	5	9	2	7	2	389

19:00	75	8	2	3	1	1	0	90
19:15	70	5	0	1	1	0	0	77
19:30	59	4	1	0	1	0	0	65
19:45	49	8	0	0	0	0	0	57
1 Hr	253	25	3	4	3	1	0	289

20:00	68	7	0	3	1	0	1	80
20:15	66	2	0	1	0	1	0	70
20:30	47	4	0	1	0	0	1	53
20:45	54	3	0	0	0	0	0	57
1 Hr	235	16	0	5	1	1	2	260

20:00	45	1	1	4	0	0	1	52
20:15	45	2	1	1	0	1	0	50
20:30	30	2	0	3	0	2	0	37
20:45	24	5	0	2	0	0	0	31
1 Hr	144	10	2	10	0	3	1	170

21:00	49	2	0	0	1	0	0	52
21:15	52	2	0	0	0	0	0	54
21:30	40	0	0	2	0	0	0	42
21:45	29	3	0	1	0	0	0	33
1 Hr	170	7	0	3	1	0	0	181

21:00	40	1	0	1	0	1	0	43
21:15	19	1	0	1	0	0	0	21
21:30	19	1	0	1	0	1	0	22
21:45	26	3	0	0	0	0	0	29
1 Hr	104	6	0	3	0	2	0	115

22:00	26	2	0	0	0	0	0	28
22:15	28	2	0	2	0	0	0	32
22:30	23	0	0	1	0	0	0	24
22:45	11	3	0	0	0	0	0	14
1 Hr	88	7	0	3	0	0	0	98

22:00	22	2	1	0	0	0	0	25
22:15	18	1	0	0	0	0	0	19
22:30	16	4	0	0	0	0	0	20
22:45	8	1	0	0	0	0	0	9
1 Hr	64	8	1	0	0	0	0	73

23:00	32	1	0	0	0	0	0	33
23:15	9	0	0	0	0	0	1	10
23:30	16	0	0	3	0	0	0	19
23:45	4	0	0	0	0	0	0	4
1 Hr	61	1	0	3	0	0	1	66

23:00	8	0	1	0	0	0	1	10
23:15	3	0	0	0	0	0	0	3
23:30	4	0	0	0	0	0	1	5
23:45	6	1	0	0	0	0	0	7
1 Hr	21	1	1	0	0	0	2	25

6 Hrs	1358	82	12	30	6	14	7	1509
-------	------	----	----	----	---	----	---	------

6 Hrs	957	97	19	29	5	8	4	1119
-------	-----	----	----	----	---	---	---	------

12 Hrs	4692	411	92	165	29	42	17	5448
--------	------	-----	----	-----	----	----	----	------

12 Hrs	3798	556	158	139	29	32	9	4721
--------	------	-----	-----	-----	----	----	---	------

Total	6973	860	245	295	57	55	17	8502
-------	------	-----	-----	-----	----	----	----	------

Total	6912	1034	271	287	56	62	18	8640
-------	------	------	-----	-----	----	----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Tuesday 17th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	7	0	0	1	0	0	0	8
00:15	5	2	1	0	0	0	0	8
00:30	3	1	0	1	0	0	0	5
00:45	2	0	0	0	0	0	0	2
1 Hr	17	3	1	2	0	0	0	23
01:00	6	0	0	0	0	0	0	6
01:15	3	0	0	0	0	0	0	3
01:30	5	0	0	2	0	0	0	7
01:45	2	0	0	1	0	0	0	3
1 Hr	16	0	0	3	0	0	0	19
02:00	2	0	1	0	0	0	0	3
02:15	2	0	0	1	0	0	0	3
02:30	1	0	0	1	0	0	0	2
02:45	1	1	1	1	0	0	0	4
1 Hr	6	1	2	3	0	0	0	12
03:00	3	0	1	1	0	0	0	5
03:15	1	0	0	0	0	0	0	1
03:30	2	0	0	0	0	0	0	2
03:45	1	1	2	0	0	0	0	4
1 Hr	7	1	3	1	0	0	0	12
04:00	4	0	3	0	0	0	0	7
04:15	3	4	1	2	0	0	0	10
04:30	4	3	1	2	0	0	0	10
04:45	2	0	1	4	0	0	0	7
1 Hr	13	7	6	8	0	0	0	34
05:00	7	4	2	5	0	1	1	20
05:15	8	2	1	2	0	1	0	14
05:30	6	2	2	2	0	0	0	12
05:45	14	7	2	2	0	0	0	25
1 Hr	35	15	7	11	0	2	1	71
6 Hrs	94	27	19	28	0	2	1	171

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	2	0	0	1	0	0	0	3
00:15	4	0	1	2	0	0	0	7
00:30	4	0	0	2	0	0	0	6
00:45	5	2	0	0	0	0	0	7
1 Hr	15	2	1	5	0	0	0	23
01:00	3	0	0	0	0	0	0	3
01:15	2	1	0	1	0	0	0	4
01:30	4	0	1	0	0	0	0	5
01:45	4	0	1	0	0	1	0	6
1 Hr	13	1	2	1	0	1	0	18
02:00	2	0	2	1	0	0	0	5
02:15	2	0	0	0	0	0	0	2
02:30	0	1	2	0	0	0	0	3
02:45	0	1	0	0	0	0	0	1
1 Hr	4	2	4	1	0	0	0	11
03:00	0	0	0	0	0	0	0	0
03:15	5	0	2	1	0	0	0	8
03:30	4	0	0	2	0	0	0	6
03:45	2	1	0	0	0	0	0	3
1 Hr	11	1	2	3	0	0	0	17
04:00	4	0	0	1	0	0	0	5
04:15	4	2	0	1	0	0	0	7
04:30	8	2	0	5	0	0	0	15
04:45	4	2	0	4	0	0	0	10
1 Hr	20	6	0	11	0	0	0	37
05:00	6	1	3	6	0	0	0	16
05:15	11	3	0	4	0	0	0	18
05:30	25	5	1	2	0	0	0	33
05:45	32	12	0	7	0	1	0	52
1 Hr	74	21	4	19	0	1	0	119
6 Hrs	137	33	13	40	0	2	0	225

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	0	0	0	0
17:30	1	0	0	1
17:45	0	0	0	0
1 Hr	1	0	0	1
18:00	1	0	0	1
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	1	0	0	1
3 Hrs	2	0	0	2
6 Hrs	2	0	0	2

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	0	0	0
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	0	0	0
1 Hr	0	0	0
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	1	0	1
1 Hr	1	0	1
3 Hrs	1	0	1
6 Hrs	1	0	1

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	15	6	5	8	1	0	0	35
06:15	23	7	4	5	2	1	0	42
06:30	36	19	4	5	0	0	1	65
06:45	36	19	6	8	1	0	1	71
1 Hr	110	51	19	26	4	1	2	213

26	7	2	5	0	0	0	40
43	10	3	6	0	1	0	63
60	19	3	7	0	1	0	90
84	21	2	4	1	1	0	113
213	57	10	22	1	3	0	306

07:00	53	22	9	6	2	1	0	93
07:15	82	27	9	3	1	1	0	123
07:30	90	20	14	4	1	1	0	130
07:45	87	30	9	5	0	2	0	133
1 Hr	312	99	41	18	4	5	0	479

89	27	7	5	0	5	0	133
130	37	5	6	1	1	2	182
142	24	5	3	0	4	0	178
140	12	3	3	0	2	1	161
501	100	20	17	1	12	3	654

08:00	89	33	13	4	0	0	0	139
08:15	83	13	3	8	0	0	0	107
08:30	73	32	15	6	0	0	0	126
08:45	104	28	5	6	2	1	0	146
1 Hr	349	106	36	24	2	1	0	518

208	20	6	3	3	3	0	243
136	17	7	5	2	0	0	167
190	16	9	6	1	4	1	227
122	9	10	2	0	0	0	143
656	62	32	16	6	7	1	780

09:00	75	15	5	8	0	0	0	103
09:15	79	16	6	8	2	1	0	112
09:30	77	14	7	4	0	0	1	103
09:45	90	19	2	2	2	0	0	115
1 Hr	321	64	20	22	4	1	1	433

110	12	4	3	0	0	0	129
148	17	4	7	0	3	0	179
129	16	8	4	1	2	0	160
105	18	5	7	1	0	0	136
492	63	21	21	2	5	0	604

10:00	102	15	3	5	2	2	0	129
10:15	104	18	4	6	3	0	0	135
10:30	96	14	6	1	1	1	0	119
10:45	109	15	9	9	3	0	0	145
1 Hr	411	62	22	21	9	3	0	528

115	17	11	2	0	1	0	146
120	15	7	8	1	0	0	151
106	20	10	8	5	0	0	149
116	17	4	11	1	3	0	152
457	69	32	29	7	4	0	598

11:00	132	9	6	9	1	0	0	157
11:15	103	6	3	6	1	1	1	121
11:30	115	14	7	5	0	0	0	141
11:45	118	16	4	5	0	0	0	143
1 Hr	468	45	20	25	2	1	1	562

98	13	1	4	0	0	0	116
116	12	9	6	0	3	0	146
104	18	3	5	1	1	0	132
108	17	5	6	1	0	0	137
426	60	18	21	2	4	0	531

6 Hrs	1971	427	158	136	25	12	4	2733
-------	------	-----	-----	-----	----	----	---	------

2745	411	133	126	19	35	4	3473
------	-----	-----	-----	----	----	---	------

12 Hrs	2065	454	177	164	25	14	5	2904
--------	------	-----	-----	-----	----	----	---	------

2882	444	146	166	19	37	4	3698
------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Tuesday 17th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	113	11	6	5	1	0	0	136
12:15	100	12	4	6	0	1	1	124
12:30	102	9	1	4	0	3	0	119
12:45	104	10	5	3	1	2	0	125
1 Hr	419	42	16	18	2	6	1	504

12:00	67	8	12	6	0	1	0	94
12:15	133	20	7	6	0	1	0	167
12:30	108	13	7	5	2	1	0	136
12:45	98	16	6	3	0	1	1	125
1 Hr	406	57	32	20	2	4	1	522

13:00	105	6	1	6	1	1	0	120
13:15	98	14	4	5	1	1	0	123
13:30	107	13	7	10	0	3	0	140
13:45	99	13	1	12	0	0	0	125
1 Hr	409	46	13	33	2	5	0	508

13:00	85	4	7	6	0	3	1	106
13:15	91	15	12	4	1	2	0	125
13:30	100	18	8	3	1	1	0	131
13:45	90	22	8	3	0	2	0	125
1 Hr	366	59	35	16	2	8	1	487

14:00	94	19	8	9	0	2	0	132
14:15	75	12	3	5	1	1	0	97
14:30	96	13	7	5	1	1	1	124
14:45	116	17	7	6	0	0	0	146
1 Hr	381	61	25	25	2	4	1	499

14:00	118	20	9	4	0	2	0	153
14:15	86	23	8	3	2	1	1	124
14:30	91	14	7	5	5	0	0	122
14:45	111	25	11	6	0	2	0	155
1 Hr	406	82	35	18	7	5	1	554

15:00	130	9	4	6	2	1	0	152
15:15	125	10	6	4	1	2	0	148
15:30	141	7	4	6	0	1	0	159
15:45	148	16	1	8	0	0	0	173
1 Hr	544	42	15	24	3	4	0	632

15:00	99	13	6	4	0	0	0	122
15:15	109	17	11	6	0	6	1	150
15:30	97	22	8	4	1	2	0	134
15:45	97	22	6	7	0	0	0	132
1 Hr	402	74	31	21	1	8	1	538

16:00	153	19	6	9	0	5	1	193
16:15	154	31	1	4	3	6	1	200
16:30	152	15	3	3	0	5	1	179
16:45	157	26	7	2	0	7	0	199
1 Hr	616	91	17	18	3	23	3	771

16:00	132	21	7	4	1	0	2	167
16:15	93	23	7	5	2	4	0	134
16:30	112	24	8	7	1	6	0	158
16:45	129	24	8	3	2	0	0	166
1 Hr	466	92	30	19	6	10	2	625

17:00	159	15	2	5	1	4	1	187
17:15	177	16	3	3	2	4	1	206
17:30	158	15	5	2	1	1	0	182
17:45	167	14	2	4	0	2	0	189
1 Hr	661	60	12	14	4	11	2	764

17:00	101	22	8	4	4	1	0	140
17:15	89	23	4	6	0	1	0	123
17:30	110	17	4	2	1	3	0	137
17:45	123	10	5	6	1	0	0	145
1 Hr	423	72	21	18	6	5	0	545

6 Hrs	3030	342	98	132	16	53	7	3678
-------	------	-----	----	-----	----	----	---	------

6 Hrs	2469	436	184	112	24	40	6	3271
-------	------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Tuesday 17th June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	131	22	2	0	0	4	0	159
18:15	113	14	3	3	2	1	0	136
18:30	110	10	1	2	0	3	1	127
18:45	97	7	1	1	0	1	0	107
1 Hr	451	53	7	6	2	9	1	529

18:00	122	17	0	4	4	1	1	149
18:15	133	6	1	1	0	1	2	144
18:30	126	19	0	2	1	2	0	150
18:45	103	6	1	2	0	2	0	114
1 Hr	484	48	2	9	5	6	3	557

19:00	105	9	1	1	0	4	0	120
19:15	93	9	1	2	1	2	1	109
19:30	67	8	0	0	0	2	0	77
19:45	69	5	0	1	1	0	0	76
1 Hr	334	31	2	4	2	8	1	382

19:00	77	7	2	3	2	3	0	94
19:15	58	5	1	2	0	0	0	66
19:30	84	2	1	1	1	0	0	89
19:45	40	5	1	0	0	0	0	46
1 Hr	259	19	5	6	3	3	0	295

20:00	69	4	1	1	1	0	0	76
20:15	78	3	0	2	0	2	0	85
20:30	58	4	0	0	0	7	0	69
20:45	66	3	0	0	0	1	0	70
1 Hr	271	14	1	3	1	10	0	300

20:00	41	5	1	0	0	1	0	48
20:15	42	2	1	0	0	0	0	45
20:30	40	4	1	0	1	1	0	47
20:45	43	2	1	2	0	0	0	48
1 Hr	166	13	4	2	1	2	0	188

21:00	55	1	1	0	1	0	0	58
21:15	57	4	1	0	0	0	0	62
21:30	44	3	0	1	0	1	0	49
21:45	48	2	0	1	0	0	0	51
1 Hr	204	10	2	2	1	1	0	220

21:00	17	2	0	1	0	1	1	22
21:15	30	2	0	1	1	4	0	38
21:30	25	1	0	1	0	1	0	28
21:45	22	1	1	0	0	0	0	24
1 Hr	94	6	1	3	1	6	1	112

22:00	28	4	0	0	0	2	0	34
22:15	38	0	0	2	0	0	0	40
22:30	24	3	0	0	0	0	0	27
22:45	26	1	0	0	0	1	0	28
1 Hr	116	8	0	2	0	3	0	129

22:00	19	2	1	0	0	2	0	24
22:15	16	1	0	0	2	1	0	20
22:30	21	0	0	1	0	0	0	22
22:45	18	1	0	0	0	0	1	20
1 Hr	74	4	1	1	2	3	1	86

23:00	19	2	0	0	0	0	0	21
23:15	11	0	0	1	0	0	0	12
23:30	25	0	0	0	0	0	0	25
23:45	15	1	1	2	0	0	0	19
1 Hr	70	3	1	3	0	0	0	77

23:00	10	1	0	0	0	0	0	11
23:15	4	0	0	0	0	0	0	4
23:30	5	1	0	0	0	0	0	6
23:45	7	1	0	1	0	0	0	9
1 Hr	26	3	0	1	0	0	0	30

6 Hrs	1446	119	13	20	6	31	2	1637
-------	------	-----	----	----	---	----	---	------

6 Hrs	1103	93	13	22	12	20	5	1268
-------	------	----	----	----	----	----	---	------

12 Hrs	4476	461	111	152	22	84	9	5315
--------	------	-----	-----	-----	----	----	---	------

12 Hrs	3572	529	197	134	36	60	11	4539
--------	------	-----	-----	-----	----	----	----	------

Total	6541	915	288	316	47	98	14	8219
-------	------	-----	-----	-----	----	----	----	------

Total	6454	973	343	300	55	97	15	8237
-------	------	-----	-----	-----	----	----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Wednesday 18th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Clear

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	8	3	0	1	0	0	0	12
00:15	10	1	0	0	0	0	0	11
00:30	8	2	0	2	0	0	0	12
00:45	4	1	0	0	0	0	0	5
1 Hr	30	7	0	3	0	0	0	40
01:00	4	1	1	1	0	0	0	7
01:15	3	2	0	3	0	0	0	8
01:30	1	0	0	3	0	0	0	4
01:45	1	0	2	0	0	0	0	3
1 Hr	9	3	3	7	0	0	0	22
02:00	3	0	0	1	0	0	0	4
02:15	2	1	0	2	0	0	0	5
02:30	0	0	0	2	0	0	0	2
02:45	2	1	0	0	0	0	0	3
1 Hr	7	2	0	5	0	0	0	14
03:00	3	0	1	1	0	0	0	5
03:15	5	1	0	1	0	0	0	7
03:30	5	0	0	1	0	0	0	6
03:45	3	0	2	1	0	0	0	6
1 Hr	16	1	3	4	0	0	0	24
04:00	2	0	2	1	0	0	0	5
04:15	5	3	1	1	0	1	0	11
04:30	7	3	0	1	0	0	0	11
04:45	1	1	0	2	0	0	0	4
1 Hr	15	7	3	5	0	1	0	31
05:00	4	3	1	2	0	1	0	11
05:15	7	2	1	4	0	0	0	14
05:30	5	3	1	5	0	0	0	14
05:45	10	8	2	3	0	0	0	23
1 Hr	26	16	5	14	0	1	0	62
6 Hrs	103	36	14	38	0	2	0	193

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	2	0	1	0	0	0	0	3
00:15	5	1	0	1	0	0	0	7
00:30	3	1	1	0	0	0	0	5
00:45	2	0	0	1	0	0	0	3
1 Hr	12	2	2	2	0	0	0	18
01:00	0	1	1	0	0	0	0	2
01:15	1	0	1	0	0	0	0	2
01:30	4	0	1	0	0	0	0	5
01:45	3	2	0	0	0	0	0	5
1 Hr	8	3	3	0	0	0	0	14
02:00	1	0	0	0	0	0	0	1
02:15	0	2	1	0	0	0	0	3
02:30	0	0	0	2	0	0	0	2
02:45	3	0	0	0	0	0	0	3
1 Hr	4	2	1	2	0	0	0	9
03:00	0	0	0	3	0	0	0	3
03:15	3	1	0	1	1	0	0	6
03:30	3	0	1	0	0	0	0	4
03:45	1	0	0	1	0	0	0	2
1 Hr	7	1	1	5	1	0	0	15
04:00	3	0	0	2	0	0	0	5
04:15	7	2	1	2	0	0	0	12
04:30	7	2	1	4	0	0	0	14
04:45	6	4	2	3	0	0	0	15
1 Hr	23	8	4	11	0	0	0	46
05:00	10	5	0	8	0	0	0	23
05:15	12	2	1	2	0	1	0	18
05:30	19	5	2	1	0	0	0	27
05:45	26	2	0	6	0	1	0	35
1 Hr	67	14	3	17	0	2	0	103
6 Hrs	121	30	14	37	1	2	0	205

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	1	0	0	1
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	1	0	0	1
3 Hr	1	0	0	1
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	1	0	0	1
1 Hr	1	0	0	1
17:00	0	0	0	0
17:15	2	0	0	2
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	2	0	0	2
18:00	0	0	0	0
18:15	3	0	0	3
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	3	0	0	3
3 Hrs	6	0	0	6
6 Hrs	7	0	0	7

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	0	0	0
16:00	1	0	1
16:15	0	0	0
16:30	0	0	0
16:45	0	0	0
1 Hr	1	0	1
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	2	0	2
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	2	0	2
3 Hrs	3	0	3
6 Hrs	3	0	3



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Wednesday 18th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	18	6	3	2	2	1	0	32
06:15	21	9	6	3	1	0	3	43
06:30	36	15	6	1	1	0	0	59
06:45	53	21	12	5	0	0	0	91
1 Hr	128	51	27	11	4	1	3	225

37	8	1	7	0	1	1	55
50	11	1	2	0	1	0	65
75	15	0	8	1	0	2	101
93	30	0	8	0	3	1	135
255	64	2	25	1	5	4	356

07:00	58	25	8	4	3	1	0	99
07:15	66	24	8	3	0	1	0	102
07:30	85	24	9	8	1	0	0	127
07:45	89	20	9	9	0	1	1	129
1 Hr	298	93	34	24	4	3	1	457

114	25	0	5	5	0	0	149
161	29	6	9	1	3	1	210
174	30	5	2	0	3	1	215
208	23	5	4	2	1	0	243
657	107	16	20	8	7	2	817

08:00	79	29	10	5	0	1	0	124
08:15	81	21	5	3	0	0	0	110
08:30	83	14	9	4	0	0	0	110
08:45	72	22	5	6	2	1	0	108
1 Hr	315	86	29	18	2	2	0	452

234	23	4	0	1	4	0	266
164	21	6	2	2	2	4	201
196	10	5	3	1	1	2	218
196	13	8	8	0	1	1	227
790	67	23	13	4	8	7	912

09:00	76	26	5	4	1	1	1	114
09:15	76	19	6	2	1	1	0	105
09:30	68	19	3	2	1	1	0	94
09:45	99	17	10	6	3	0	0	135
1 Hr	319	81	24	14	6	3	1	448

155	9	8	2	0	0	0	174
165	13	6	3	0	0	0	187
139	23	5	2	1	0	0	170
168	26	2	9	2	0	0	207
627	71	21	16	3	0	0	738

10:00	88	18	6	3	5	1	0	121
10:15	110	29	6	4	1	0	0	150
10:30	99	16	9	8	2	0	0	134
10:45	94	17	4	5	1	0	0	121
1 Hr	391	80	25	20	9	1	0	526

146	23	7	8	2	1	0	187
146	13	9	3	1	0	0	172
124	26	6	3	2	4	1	166
111	20	8	3	0	1	0	143
527	82	30	17	5	6	1	668

11:00	90	15	8	2	1	0	0	116
11:15	111	15	5	4	2	2	0	139
11:30	105	8	1	3	0	2	0	119
11:45	88	7	6	1	0	1	0	103
1 Hr	394	45	20	10	3	5	0	477

114	15	8	5	0	0	0	142
110	24	7	1	0	0	0	142
96	25	3	5	2	2	0	133
112	14	10	4	0	0	0	140
432	78	28	15	2	2	0	557

6 Hrs	1845	436	159	97	28	15	5	2585
-------	------	-----	-----	----	----	----	---	------

3288	469	120	106	23	28	14	4048
------	-----	-----	-----	----	----	----	------

12 Hrs	1948	472	173	135	28	17	5	2778
--------	------	-----	-----	-----	----	----	---	------

3409	499	134	143	24	30	14	4253
------	-----	-----	-----	----	----	----	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Wednesday 18th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	104	8	8	2	1	2	0	125
12:15	100	12	5	5	0	0	1	123
12:30	95	8	7	6	0	0	0	116
12:45	122	13	11	9	1	1	0	157
1 Hr	421	41	31	22	2	3	1	521

12:00	81	15	8	4	0	3	0	111
12:15	91	18	1	6	0	0	0	116
12:30	75	18	6	2	2	1	0	104
12:45	93	14	8	7	0	2	1	125
1 Hr	340	65	23	19	2	6	1	456

13:00	99	10	0	4	0	1	0	114
13:15	92	15	4	4	2	1	0	118
13:30	99	12	2	1	0	2	0	116
13:45	117	9	8	2	0	0	0	136
1 Hr	407	46	14	11	2	4	0	484

13:00	80	19	10	1	0	2	0	112
13:15	112	25	8	4	0	0	0	149
13:30	108	15	6	1	1	1	0	132
13:45	87	12	10	0	0	1	0	110
1 Hr	387	71	34	6	1	4	0	503

14:00	116	12	5	3	0	0	1	137
14:15	110	16	2	6	3	0	1	138
14:30	112	9	3	3	3	1	0	131
14:45	131	10	6	4	0	1	0	152
1 Hr	469	47	16	16	6	2	2	558

14:00	88	19	8	1	2	3	0	121
14:15	67	16	4	3	0	3	0	93
14:30	98	18	8	6	4	2	0	136
14:45	98	21	4	4	0	0	0	127
1 Hr	351	74	24	14	6	8	0	477

15:00	125	9	2	3	0	3	0	142
15:15	167	19	5	5	1	3	0	200
15:30	153	14	4	5	0	3	0	179
15:45	154	16	5	2	2	1	0	180
1 Hr	599	58	16	15	3	10	0	701

15:00	97	18	2	4	0	1	0	122
15:15	76	22	6	2	2	1	0	109
15:30	93	17	5	10	0	3	0	128
15:45	103	34	6	2	0	2	0	147
1 Hr	369	91	19	18	2	7	0	506

16:00	159	20	7	2	0	4	1	193
16:15	193	16	5	4	2	0	2	222
16:30	220	17	2	3	0	1	1	244
16:45	189	18	8	4	0	3	1	223
1 Hr	761	71	22	13	2	8	5	882

16:00	80	15	2	2	1	3	0	103
16:15	85	21	5	2	0	0	0	113
16:30	121	25	7	0	3	4	1	161
16:45	104	31	3	3	2	1	0	144
1 Hr	390	92	17	7	6	8	1	521

17:00	211	20	2	4	0	2	0	239
17:15	198	17	4	0	4	9	0	232
17:30	207	16	1	2	1	2	1	230
17:45	218	15	0	1	0	2	2	238
1 Hr	834	68	7	7	5	15	3	939

17:00	90	24	6	1	3	0	0	124
17:15	98	13	7	3	2	2	0	125
17:30	94	22	3	0	1	2	0	122
17:45	104	23	4	1	0	1	0	133
1 Hr	386	82	20	5	6	5	0	504

6 Hrs	3491	331	106	84	20	42	11	4085
-------	------	-----	-----	----	----	----	----	------

6 Hrs	2223	475	137	69	23	38	2	2967
-------	------	-----	-----	----	----	----	---	------

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	192	13	3	2	0	6	2	218
18:15	196	13	2	1	1	9	0	222
18:30	184	9	1	2	0	6	1	203
18:45	153	19	1	1	1	9	0	184
1 Hr	725	54	7	6	2	30	3	827

18:00	97	13	2	0	6	1	1	120
18:15	72	19	3	1	1	0	0	96
18:30	107	7	3	3	0	3	0	123
18:45	89	10	2	4	0	3	1	109
1 Hr	365	49	10	8	7	7	2	448

19:00	144	12	2	2	0	5	1	166
19:15	122	8	4	1	1	5	1	142
19:30	92	11	0	1	0	3	3	110
19:45	97	5	1	0	1	2	0	106
1 Hr	455	36	7	4	2	15	5	524

19:00	98	15	1	0	1	8	0	123
19:15	69	18	2	1	1	3	3	97
19:30	58	9	0	2	1	0	0	70
19:45	50	9	1	1	0	6	2	69
1 Hr	275	51	4	4	3	17	5	359

20:00	87	6	0	1	1	4	0	99
20:15	69	11	0	0	0	1	0	81
20:30	77	3	1	0	0	5	1	87
20:45	66	1	0	2	0	0	0	69
1 Hr	299	21	1	3	1	10	1	336

20:00	46	6	1	2	0	7	0	62
20:15	44	10	0	1	0	1	0	56
20:30	34	4	0	0	1	11	1	51
20:45	69	7	0	0	0	1	0	77
1 Hr	193	27	1	3	1	20	1	246

21:00	52	4	0	0	1	1	4	62
21:15	70	2	0	0	0	1	0	73
21:30	53	4	2	0	0	1	0	60
21:45	39	3	2	0	0	1	0	45
1 Hr	214	13	4	0	1	4	4	240

21:00	41	4	1	1	0	3	0	50
21:15	25	2	2	0	0	4	0	33
21:30	30	3	0	0	0	3	0	36
21:45	17	2	0	3	0	9	0	31
1 Hr	113	11	3	4	0	19	0	150

22:00	36	1	2	0	0	2	0	41
22:15	28	1	0	0	0	1	0	30
22:30	47	2	0	0	0	2	0	51
22:45	31	1	0	1	0	0	0	33
1 Hr	142	5	2	1	0	5	0	155

22:00	32	2	1	0	0	0	0	35
22:15	16	0	2	1	0	0	0	19
22:30	17	0	1	0	0	1	0	19
22:45	20	0	0	1	0	0	0	21
1 Hr	85	2	4	2	0	1	0	94

23:00	25	2	0	1	0	0	1	29
23:15	23	0	0	0	1	0	0	24
23:30	17	2	0	3	0	0	0	22
23:45	16	1	0	0	0	0	0	17
1 Hr	81	5	0	4	1	0	1	92

23:00	11	1	0	0	0	0	0	12
23:15	8	0	0	0	0	0	1	9
23:30	6	0	0	0	0	0	0	6
23:45	16	2	0	0	0	0	0	18
1 Hr	41	3	0	0	0	0	1	45

6 Hrs	1916	134	21	18	7	64	14	2174
-------	------	-----	----	----	---	----	----	------

6 Hrs	1072	143	22	21	11	64	9	1342
-------	------	-----	----	----	----	----	---	------

12 Hrs	5407	465	127	102	27	106	25	6259
--------	------	-----	-----	-----	----	-----	----	------

12 Hrs	3295	618	159	90	34	102	11	4309
--------	------	-----	-----	----	----	-----	----	------

Total	7355	937	300	237	55	123	30	9037
-------	------	-----	-----	-----	----	-----	----	------

Total	6704	1117	293	233	58	132	25	8562
-------	------	------	-----	-----	----	-----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Thursday 19th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	14	0	0	0	0	0	0	14
00:15	10	0	1	2	0	0	0	13
00:30	5	1	1	0	0	0	0	7
00:45	8	0	0	0	0	0	0	8
1 Hr	37	1	2	2	0	0	0	42
01:00	1	1	1	0	0	0	0	3
01:15	4	1	0	0	0	0	0	5
01:30	6	0	1	0	0	0	0	7
01:45	2	0	0	0	0	0	0	2
1 Hr	13	2	2	0	0	0	0	17
02:00	2	0	1	1	0	0	0	4
02:15	3	0	2	0	0	0	0	5
02:30	3	0	0	0	0	0	0	3
02:45	5	1	2	1	0	0	0	9
1 Hr	13	1	5	2	0	0	0	21
03:00	2	0	1	0	0	0	0	3
03:15	2	0	1	1	0	0	0	4
03:30	3	1	0	0	0	0	0	4
03:45	0	3	1	1	0	0	0	5
1 Hr	7	4	3	2	0	0	0	16
04:00	1	0	3	0	0	0	0	4
04:15	4	1	2	0	0	0	0	7
04:30	6	3	0	3	0	0	0	12
04:45	3	4	1	0	0	0	2	10
1 Hr	14	8	6	3	0	0	2	33
05:00	3	2	2	1	0	1	0	9
05:15	5	1	2	0	0	1	0	9
05:30	6	5	4	3	0	0	0	18
05:45	15	10	2	4	0	0	0	31
1 Hr	29	18	10	8	0	2	0	67
6 Hrs	113	34	28	17	0	2	2	196

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	5	1	1	0	0	0	0	7
00:15	3	0	0	0	0	0	0	3
00:30	3	0	1	2	0	0	0	6
00:45	2	1	1	2	0	0	0	6
1 Hr	13	2	3	4	0	0	0	22
01:00	4	0	0	1	0	0	0	5
01:15	5	0	0	1	0	0	0	6
01:30	3	0	0	0	0	0	0	3
01:45	2	1	1	1	0	0	1	6
1 Hr	14	1	1	3	0	0	1	20
02:00	4	0	0	0	0	0	0	4
02:15	1	0	1	0	0	0	0	2
02:30	2	1	0	0	0	0	0	3
02:45	0	0	0	0	0	0	0	0
1 Hr	7	1	1	0	0	0	0	9
03:00	4	0	1	1	0	0	0	6
03:15	2	0	0	0	0	0	0	2
03:30	2	0	1	2	0	0	0	5
03:45	1	0	0	1	0	0	0	2
1 Hr	9	0	2	4	0	0	0	15
04:00	3	0	0	0	0	0	0	3
04:15	2	0	1	0	0	0	0	3
04:30	9	1	1	4	0	0	0	15
04:45	9	2	3	4	0	0	0	18
1 Hr	23	3	5	8	0	0	0	39
05:00	11	1	2	0	0	0	0	14
05:15	7	6	1	4	0	0	0	18
05:30	23	8	3	2	0	0	0	36
05:45	35	7	1	2	0	1	0	46
1 Hr	76	22	7	8	0	1	0	114
6 Hrs	142	29	19	27	0	1	1	219

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	1	0	0	1
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	1	0	0	1
3 Hr	1	0	0	1
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	1	0	0	1
1 Hr	1	0	0	1
18:00	1	0	0	1
18:15	0	0	0	0
18:30	0	0	0	0
18:45	2	0	0	2
1 Hr	3	0	0	3
3 Hrs	4	0	0	4
6 Hrs	5	0	0	5

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	0	0	0
16:00	2	0	2
16:15	0	0	0
16:30	0	0	0
16:45	0	0	0
1 Hr	2	0	2
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	0	0	0
3 Hrs	2	0	2
6 Hrs	2	0	2



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Thursday 19th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	6	9	3	4	1	0	0	23
06:15	19	6	6	3	2	2	0	38
06:30	24	22	10	6	1	1	0	64
06:45	47	14	9	8	0	0	0	78
1 Hr	96	51	28	21	4	3	0	203

26	7	3	5	0	0	0	41
47	12	1	6	0	1	1	68
59	12	0	6	1	4	1	83
107	23	7	9	0	0	0	146
239	54	11	26	1	5	2	338

07:00	59	22	11	4	3	1	0	100
07:15	63	26	13	6	0	2	0	110
07:30	86	21	10	3	1	1	0	122
07:45	81	25	12	6	0	1	0	125
1 Hr	289	94	46	19	4	5	0	457

113	29	4	1	0	2	2	151
149	27	3	2	1	2	0	184
154	32	8	2	0	4	2	202
204	16	6	5	0	3	1	235
620	104	21	10	1	11	5	772

08:00	89	29	11	2	0	0	1	132
08:15	76	23	8	6	0	0	0	113
08:30	81	20	10	4	0	0	0	115
08:45	88	24	10	6	3	1	0	132
1 Hr	334	96	39	18	3	1	1	492

194	18	5	3	3	2	1	226
155	20	3	2	2	2	0	184
193	19	9	2	0	3	0	226
179	13	7	5	0	2	0	206
721	70	24	12	5	9	1	842

09:00	57	18	5	1	0	1	1	83
09:15	70	22	5	1	2	0	0	100
09:30	88	21	8	4	2	0	0	123
09:45	91	14	10	6	3	0	0	124
1 Hr	306	75	28	12	7	1	1	430

180	6	3	1	0	0	1	191
174	14	9	1	0	0	1	199
162	7	6	3	1	1	0	180
167	23	7	4	7	0	0	208
683	50	25	9	8	1	2	778

10:00	109	22	4	3	2	0	0	140
10:15	106	24	4	2	1	3	1	141
10:30	87	21	3	6	0	2	0	119
10:45	109	13	7	7	1	0	1	138
1 Hr	411	80	18	18	4	5	2	538

147	10	8	2	3	2	0	172
168	12	12	2	0	1	0	195
124	13	8	4	3	0	0	152
129	18	6	5	1	0	0	159
568	53	34	13	7	3	0	678

11:00	101	9	10	6	0	0	1	127
11:15	118	18	10	4	2	0	0	152
11:30	116	13	6	3	0	1	0	139
11:45	103	14	5	2	0	0	0	124
1 Hr	438	54	31	15	2	1	1	542

131	11	10	5	0	2	2	161
108	12	9	3	0	2	1	135
82	19	7	5	2	1	0	116
107	14	7	3	0	0	0	131
428	56	33	16	2	5	3	543

6 Hrs	1874	450	190	103	24	16	5	2662
-------	------	-----	-----	-----	----	----	---	------

3259	387	148	86	24	34	13	3951
------	-----	-----	----	----	----	----	------

12 Hrs	1987	484	218	120	24	18	7	2858
--------	------	-----	-----	-----	----	----	---	------

3401	416	167	113	24	35	14	4170
------	-----	-----	-----	----	----	----	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Thursday 19th June 2014

AM Weather: Mild & Cloudy
 PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	98	15	5	3	0	1	0	122
12:15	118	19	8	3	1	3	0	152
12:30	110	18	1	1	0	3	0	133
12:45	118	14	1	5	0	1	0	139
1 Hr	444	66	15	12	1	8	0	546

12:00	113	15	10	3	0	1	0	142
12:15	120	14	12	4	0	0	0	150
12:30	111	17	8	3	0	0	1	140
12:45	116	18	3	4	2	0	0	143
1 Hr	460	64	33	14	2	1	1	575

13:00	96	15	8	6	1	0	0	126
13:15	120	17	7	9	2	1	1	157
13:30	97	17	3	6	0	0	0	123
13:45	86	18	4	4	0	0	0	112
1 Hr	399	67	22	25	3	1	1	518

13:00	82	9	6	2	0	1	0	100
13:15	99	27	8	3	0	1	0	138
13:30	100	21	12	4	1	2	1	141
13:45	104	15	7	6	0	0	0	132
1 Hr	385	72	33	15	1	4	1	511

14:00	115	18	6	5	1	1	0	146
14:15	114	10	11	4	1	2	0	142
14:30	109	10	3	1	1	0	0	124
14:45	134	17	4	6	0	0	0	161
1 Hr	472	55	24	16	3	3	0	573

14:00	92	20	7	6	0	1	0	126
14:15	105	19	3	4	0	0	0	131
14:30	73	14	7	4	5	0	1	104
14:45	90	20	3	9	1	0	0	123
1 Hr	360	73	20	23	6	1	1	484

15:00	149	8	7	5	1	2	0	172
15:15	161	7	1	1	1	1	0	172
15:30	190	10	3	5	0	2	0	210
15:45	161	18	1	3	1	1	0	185
1 Hr	661	43	12	14	3	6	0	739

15:00	88	10	5	5	0	1	0	109
15:15	86	17	4	6	1	2	0	116
15:30	93	16	7	1	0	0	0	117
15:45	98	33	1	3	0	1	1	137
1 Hr	365	76	17	15	1	4	1	479

16:00	193	13	7	3	0	3	0	219
16:15	177	22	5	1	4	4	0	213
16:30	185	19	2	4	1	2	0	213
16:45	210	17	8	4	0	3	0	242
1 Hr	765	71	22	12	5	12	0	887

16:00	78	23	7	3	0	2	0	113
16:15	87	29	1	3	1	1	0	122
16:30	123	20	5	4	2	2	0	156
16:45	102	16	2	2	2	1	0	125
1 Hr	390	88	15	12	5	6	0	516

17:00	196	13	4	2	1	0	0	216
17:15	199	16	0	3	1	7	0	226
17:30	211	13	3	1	3	1	0	232
17:45	203	18	2	3	0	2	2	230
1 Hr	809	60	9	9	5	10	2	904

17:00	83	28	4	5	0	2	1	123
17:15	87	21	4	3	1	3	0	119
17:30	99	17	8	4	2	3	1	134
17:45	113	19	0	6	0	1	2	141
1 Hr	382	85	16	18	3	9	4	517

6 Hrs	3550	362	104	88	20	40	3	4167
-------	------	-----	-----	----	----	----	---	------

6 Hrs	2342	458	134	97	18	25	8	3082
-------	------	-----	-----	----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Thursday 19th June 2014

AM Weather: Mild & Cloudy
 PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	182	13	3	1	0	1	0	200
18:15	203	15	3	2	1	3	1	228
18:30	196	17	1	1	0	0	0	215
18:45	156	17	2	4	0	2	1	182
1 Hr	737	62	9	8	1	6	2	825

18:00	88	16	0	1	1	0	0	106
18:15	102	8	2	1	0	2	0	115
18:30	87	14	4	3	1	0	0	109
18:45	82	10	3	1	0	0	0	96
1 Hr	359	48	9	6	2	2	0	426

19:00	198	19	3	1	1	0	0	222
19:15	143	14	3	2	1	1	0	164
19:30	121	15	0	3	0	0	0	139
19:45	99	17	2	5	0	3	1	127
1 Hr	561	65	8	11	2	4	1	652

19:00	78	6	3	2	1	2	0	92
19:15	86	6	1	4	2	1	0	100
19:30	49	7	0	2	1	0	0	59
19:45	49	5	1	2	0	2	0	59
1 Hr	262	24	5	10	4	5	0	310

20:00	75	6	2	2	2	0	0	87
20:15	50	8	2	1	0	0	0	61
20:30	58	3	1	3	0	0	0	65
20:45	50	4	0	0	0	1	0	55
1 Hr	233	21	5	6	2	1	0	268

20:00	28	2	0	0	0	0	0	30
20:15	36	5	0	0	0	2	0	43
20:30	23	4	1	1	1	0	0	30
20:45	22	3	1	0	0	1	0	27
1 Hr	109	14	2	1	1	3	0	130

21:00	40	1	0	1	1	3	0	46
21:15	43	4	0	2	0	1	0	50
21:30	45	0	0	2	0	0	1	48
21:45	25	3	1	0	0	0	0	29
1 Hr	153	8	1	5	1	4	1	173

21:00	23	2	0	2	0	1	0	28
21:15	22	5	0	0	0	0	0	27
21:30	21	4	0	3	0	0	0	28
21:45	20	3	0	0	0	2	0	25
1 Hr	86	14	0	5	0	3	0	108

22:00	45	5	1	1	0	1	0	53
22:15	55	1	0	0	0	1	0	57
22:30	42	0	0	0	0	0	0	42
22:45	25	3	1	0	0	1	0	30
1 Hr	167	9	2	1	0	3	0	182

22:00	29	6	0	1	0	6	0	42
22:15	20	3	1	0	0	0	0	24
22:30	14	2	1	0	0	4	0	21
22:45	16	2	0	0	0	0	0	18
1 Hr	79	13	2	1	0	10	0	105

23:00	21	1	0	0	0	0	0	22
23:15	13	0	0	0	0	0	0	13
23:30	9	1	0	2	0	0	0	12
23:45	9	0	0	1	0	0	0	10
1 Hr	52	2	0	3	0	0	0	57

23:00	18	2	0	0	0	1	0	21
23:15	8	2	0	0	0	0	0	10
23:30	9	1	0	0	0	0	0	10
23:45	1	0	0	1	0	0	1	3
1 Hr	36	5	0	1	0	1	1	44

6 Hrs	1903	167	25	34	6	18	4	2157
-------	------	-----	----	----	---	----	---	------

6 Hrs	931	118	18	24	7	24	1	1123
-------	-----	-----	----	----	---	----	---	------

12 Hrs	5453	529	129	122	26	58	7	6324
--------	------	-----	-----	-----	----	----	---	------

12 Hrs	3273	576	152	121	25	49	9	4205
--------	------	-----	-----	-----	----	----	---	------

Total	7440	1013	347	242	50	76	14	9182
-------	------	------	-----	-----	----	----	----	------

Total	6674	992	319	234	49	84	23	8375
-------	------	-----	-----	-----	----	----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Friday 20th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	11	0	2	0	0	0	0	13
00:15	4	0	3	0	0	0	0	7
00:30	8	0	0	0	0	0	0	8
00:45	4	0	0	0	0	0	0	4
1 Hr	27	0	5	0	0	0	0	32
01:00	2	1	0	0	0	0	0	3
01:15	6	1	0	0	0	0	0	7
01:30	0	1	0	0	0	0	0	1
01:45	4	1	1	0	0	0	0	6
1 Hr	12	4	1	0	0	0	0	17
02:00	1	1	1	1	0	0	0	4
02:15	2	0	0	0	0	0	0	2
02:30	4	0	0	1	0	0	0	5
02:45	2	0	2	2	0	0	0	6
1 Hr	9	1	3	4	0	0	0	17
03:00	1	1	0	3	0	0	0	5
03:15	5	0	0	1	0	0	0	6
03:30	3	0	0	1	0	0	0	4
03:45	2	0	3	1	1	0	0	7
1 Hr	11	1	3	6	1	0	0	22
04:00	3	0	1	0	0	0	0	4
04:15	2	0	1	0	0	0	0	3
04:30	6	4	0	4	0	0	0	14
04:45	1	6	0	2	1	0	1	11
1 Hr	12	10	2	6	1	0	1	32
05:00	6	2	1	2	0	1	0	12
05:15	3	2	1	2	0	0	0	8
05:30	9	2	1	2	0	0	0	14
05:45	14	9	4	4	0	0	0	31
1 Hr	32	15	7	10	0	1	0	65
6 Hrs	103	31	21	26	2	1	1	185

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	7	0	0	0	0	0	0	7
00:15	3	0	0	0	0	0	0	3
00:30	4	1	1	1	0	0	0	7
00:45	4	2	1	1	0	0	0	8
1 Hr	18	3	2	2	0	0	0	25
01:00	3	0	0	0	0	0	0	3
01:15	0	1	0	0	0	0	0	1
01:30	0	0	0	0	0	0	0	0
01:45	3	1	0	1	0	0	0	5
1 Hr	6	2	0	1	0	0	0	9
02:00	2	0	0	1	0	0	0	3
02:15	0	0	0	0	0	0	0	0
02:30	1	0	0	1	0	0	0	2
02:45	2	0	0	0	0	0	0	2
1 Hr	5	0	0	2	0	0	0	7
03:00	2	1	0	0	0	0	0	3
03:15	5	0	2	0	0	0	0	7
03:30	3	0	0	1	0	0	0	4
03:45	2	0	1	3	0	0	0	6
1 Hr	12	1	3	4	0	0	0	20
04:00	8	0	0	2	0	0	0	10
04:15	4	0	0	1	0	0	0	5
04:30	6	3	2	2	0	0	0	13
04:45	2	1	0	4	0	0	0	7
1 Hr	20	4	2	9	0	0	0	35
05:00	10	4	2	3	0	0	0	19
05:15	12	3	2	4	0	0	0	21
05:30	18	3	1	0	0	0	0	22
05:45	26	10	2	8	0	1	0	47
1 Hr	66	20	7	15	0	1	0	109
6 Hrs	127	30	14	33	0	1	0	205

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	1	0	0	1
16:45	0	0	0	0
1 Hr	1	0	0	1
17:00	1	0	0	1
17:15	0	0	0	0
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	1	0	0	1
18:00	0	0	0	0
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	0	0	0	0
3 Hrs	2	0	0	2
6 Hrs	2	0	0	2

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	2	0	2
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	2	0	2
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	2	0	2
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	0	0	0
1 Hr	0	0	0
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	1	0	1
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	1	0	1
3 Hrs	1	0	1
6 Hrs	3	0	3

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	25	6	4	3	1	0	0	39
06:15	31	9	3	4	1	0	0	48
06:30	30	23	5	5	2	1	0	66
06:45	39	17	11	8	0	1	0	76
1 Hr	125	55	23	20	4	2	0	229

06:00	42	9	2	5	0	2	0	60
06:15	44	7	3	5	0	0	0	59
06:30	46	9	0	6	0	3	1	65
06:45	78	27	4	5	0	0	0	114
1 Hr	210	52	9	21	0	5	1	298

07:00	51	29	9	10	1	1	0	101
07:15	73	26	13	4	2	1	0	119
07:30	92	27	7	2	1	1	0	130
07:45	92	23	9	8	0	2	1	135
1 Hr	308	105	38	24	4	5	1	485

07:00	102	22	5	2	0	0	0	131
07:15	122	26	4	9	1	0	0	162
07:30	134	26	5	5	0	1	0	171
07:45	152	23	6	2	1	1	0	185
1 Hr	510	97	20	18	2	2	0	649

08:00	71	27	14	6	0	0	1	119
08:15	103	26	8	5	0	0	0	142
08:30	98	18	9	9	0	1	2	137
08:45	93	25	9	5	2	0	0	134
1 Hr	365	96	40	25	2	1	3	532

08:00	141	16	4	1	1	5	0	168
08:15	119	15	10	2	3	4	0	153
08:30	128	9	7	3	3	3	0	153
08:45	133	11	5	3	0	0	0	152
1 Hr	521	51	26	9	7	12	0	626

09:00	81	20	6	7	2	0	0	116
09:15	100	20	11	6	1	0	0	138
09:30	96	23	9	5	1	0	0	134
09:45	93	14	12	6	4	0	0	129
1 Hr	370	77	38	24	8	0	0	517

09:00	140	14	8	4	1	0	0	167
09:15	136	10	6	5	0	0	0	157
09:30	130	15	3	7	2	2	1	160
09:45	121	15	3	8	1	3	0	151
1 Hr	527	54	20	24	4	5	1	635

10:00	112	21	8	5	1	0	0	147
10:15	131	29	8	3	1	1	0	173
10:30	152	22	5	5	0	3	0	187
10:45	30	17	10	6	1	4	0	68
1 Hr	425	89	31	19	3	8	0	575

10:00	107	11	7	2	0	3	0	130
10:15	142	14	7	5	1	1	0	170
10:30	96	18	4	5	0	1	0	124
10:45	160	19	9	3	2	2	0	195
1 Hr	505	62	27	15	3	7	0	619

11:00	139	25	7	7	2	1	0	181
11:15	149	14	6	5	1	2	0	177
11:30	148	17	9	3	1	0	0	178
11:45	155	14	14	4	2	3	1	193
1 Hr	591	70	36	19	6	6	1	729

11:00	122	13	4	5	0	3	0	147
11:15	135	17	8	5	2	1	0	168
11:30	135	11	5	6	0	1	0	158
11:45	123	18	3	3	1	1	0	149
1 Hr	515	59	20	19	3	6	0	622

6 Hrs	2184	492	206	131	27	22	5	3067
-------	------	-----	-----	-----	----	----	---	------

6 Hrs	2788	375	122	106	19	37	2	3449
-------	------	-----	-----	-----	----	----	---	------

12 Hrs	2287	523	227	157	29	23	6	3252
--------	------	-----	-----	-----	----	----	---	------

12 Hrs	2915	405	136	139	19	38	2	3654
--------	------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Friday 20th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	169	13	4	5	0	3	1	195
12:15	153	25	5	3	0	2	0	188
12:30	166	26	9	5	0	2	0	208
12:45	140	23	2	4	1	3	0	173
1 Hr	628	87	20	17	1	10	1	764

12:00	111	16	5	3	0	1	0	136
12:15	125	6	8	4	1	1	0	145
12:30	109	15	6	5	0	1	0	136
12:45	122	16	4	2	0	4	0	148
1 Hr	467	53	23	14	1	7	0	565

13:00	163	18	8	4	2	1	0	196
13:15	132	30	7	3	2	2	1	177
13:30	158	24	4	3	0	3	0	192
13:45	150	23	6	3	0	2	0	184
1 Hr	603	95	25	13	4	8	1	749

13:00	104	10	7	6	1	0	0	128
13:15	149	8	4	3	1	2	0	167
13:30	128	13	11	2	0	2	0	156
13:45	115	13	9	1	1	5	0	144
1 Hr	496	44	31	12	3	9	0	595

14:00	134	32	4	1	1	2	0	174
14:15	155	24	8	4	1	1	0	193
14:30	147	26	9	4	3	0	0	189
14:45	170	19	2	2	0	1	0	194
1 Hr	606	101	23	11	5	4	0	750

14:00	144	17	9	6	2	0	0	178
14:15	198	27	9	7	2	1	0	244
14:30	112	22	4	5	2	0	0	145
14:45	111	14	8	3	0	2	0	138
1 Hr	565	80	30	21	6	3	0	705

15:00	152	19	5	5	2	1	0	184
15:15	178	23	7	2	1	2	0	213
15:30	180	18	3	2	0	3	0	206
15:45	199	23	2	2	0	1	0	227
1 Hr	709	83	17	11	3	7	0	830

15:00	114	22	6	1	1	0	0	144
15:15	105	16	3	2	0	3	0	129
15:30	122	22	2	5	2	1	1	155
15:45	117	27	4	0	2	5	0	155
1 Hr	458	87	15	8	5	9	1	583

16:00	174	27	1	3	0	5	0	210
16:15	178	27	3	2	1	0	1	212
16:30	184	32	4	2	1	1	0	224
16:45	195	31	0	4	2	3	1	236
1 Hr	731	117	8	11	4	9	2	882

16:00	106	22	5	5	2	1	1	142
16:15	111	16	3	2	0	0	0	132
16:30	134	14	6	3	1	1	0	159
16:45	121	12	3	1	0	4	0	141
1 Hr	472	64	17	11	3	6	1	574

17:00	207	21	2	4	2	5	1	242
17:15	225	22	5	4	2	3	0	261
17:30	220	11	3	2	4	2	0	242
17:45	256	18	2	0	2	1	0	279
1 Hr	908	72	12	10	10	11	1	1024

17:00	99	20	10	1	1	2	0	133
17:15	113	20	6	1	1	1	1	143
17:30	115	13	3	2	2	0	0	135
17:45	123	7	5	3	1	5	0	144
1 Hr	450	60	24	7	5	8	1	555

6 Hrs	4185	555	105	73	27	49	5	4999
-------	------	-----	-----	----	----	----	---	------

6 Hrs	2908	388	140	73	23	42	3	3577
-------	------	-----	-----	----	----	----	---	------

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	233	14	11	0	0	1	0	259
18:15	243	19	5	2	1	0	1	271
18:30	201	16	5	4	0	1	1	228
18:45	224	16	4	1	0	0	2	247
1 Hr	901	65	25	7	1	2	4	1005

18:00	114	7	4	2	1	0	0	128
18:15	142	9	0	1	0	3	3	158
18:30	112	11	1	1	1	0	1	127
18:45	100	8	1	1	0	2	0	112
1 Hr	468	35	6	5	2	5	4	525

19:00	177	10	5	1	0	4	6	203
19:15	202	16	3	1	1	0	0	223
19:30	190	11	3	1	0	3	1	209
19:45	128	9	0	1	0	2	2	142
1 Hr	697	46	11	4	1	9	9	777

19:00	100	6	3	3	1	1	0	114
19:15	106	6	0	1	2	1	0	116
19:30	76	2	3	0	1	2	0	84
19:45	67	10	1	0	0	1	0	79
1 Hr	349	24	7	4	4	5	0	393

20:00	145	5	1	1	1	1	0	154
20:15	135	12	0	0	1	0	0	148
20:30	120	4	0	0	0	0	0	124
20:45	94	8	1	0	0	0	0	103
1 Hr	494	29	2	1	2	1	0	529

20:00	61	4	0	1	0	0	0	66
20:15	48	4	1	1	0	1	0	55
20:30	43	5	0	0	1	2	0	51
20:45	47	6	2	0	0	0	0	55
1 Hr	199	19	3	2	1	3	0	227

21:00	95	6	2	2	1	0	0	106
21:15	73	5	2	2	0	0	0	82
21:30	63	4	0	1	1	0	0	69
21:45	70	2	0	2	0	1	0	75
1 Hr	301	17	4	7	2	1	0	332

21:00	56	3	0	0	0	2	0	61
21:15	33	3	1	0	0	1	0	38
21:30	39	1	0	1	0	0	0	41
21:45	37	5	3	1	0	1	0	47
1 Hr	165	12	4	2	0	4	0	187

22:00	52	3	0	0	0	0	0	55
22:15	46	2	0	0	0	0	0	48
22:30	43	4	0	0	0	1	0	48
22:45	41	2	0	0	0	1	0	44
1 Hr	182	11	0	0	0	2	0	195

22:00	32	4	1	0	0	1	0	38
22:15	30	1	2	1	0	1	0	35
22:30	17	1	1	0	0	1	0	20
22:45	23	1	0	1	0	1	0	26
1 Hr	102	7	4	2	0	4	0	119

23:00	35	0	0	0	0	0	0	35
23:15	31	1	0	0	0	0	0	32
23:30	25	0	0	0	0	2	0	27
23:45	18	1	0	1	0	0	0	20
1 Hr	109	2	0	1	0	2	0	114

23:00	12	2	1	1	0	0	0	16
23:15	15	1	0	0	0	1	0	17
23:30	15	0	0	1	0	1	0	17
23:45	11	1	0	0	0	0	0	12
1 Hr	53	4	1	2	0	2	0	62

6 Hrs	2684	170	42	20	6	17	13	2952
-------	------	-----	----	----	---	----	----	------

6 Hrs	1336	101	25	17	7	23	4	1513
-------	------	-----	----	----	---	----	---	------

12 Hrs	6869	725	147	93	33	66	18	7951
--------	------	-----	-----	----	----	----	----	------

12 Hrs	4244	489	165	90	30	65	7	5090
--------	------	-----	-----	----	----	----	---	------

Total	9156	1248	374	250	62	89	24	11203
-------	------	------	-----	-----	----	----	----	-------

Total	7159	894	301	229	49	103	9	8744
-------	------	-----	-----	-----	----	-----	---	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 21st June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	12	1	1	0	0	0	0	14
00:15	17	2	1	0	0	0	0	20
00:30	13	1	0	0	0	0	0	14
00:45	13	2	1	0	0	0	0	16
1 Hr	55	6	3	0	0	0	0	64
01:00	9	1	0	2	0	0	0	12
01:15	6	0	1	1	0	0	0	8
01:30	5	1	0	0	0	0	0	6
01:45	7	0	0	0	0	0	0	7
1 Hr	27	2	1	3	0	0	0	33
02:00	6	1	0	1	0	0	0	8
02:15	3	0	1	0	0	0	0	4
02:30	1	0	0	0	0	0	1	2
02:45	6	1	1	0	0	0	1	9
1 Hr	16	2	2	1	0	0	2	23
03:00	5	0	0	1	0	0	0	6
03:15	2	0	1	2	0	0	0	5
03:30	7	1	0	1	0	0	0	9
03:45	2	0	0	0	0	0	0	2
1 Hr	16	1	1	4	0	0	0	22
04:00	4	3	3	2	0	0	0	12
04:15	4	3	0	1	0	0	0	8
04:30	11	2	0	3	0	0	0	16
04:45	3	1	0	3	0	0	0	7
1 Hr	22	9	3	9	0	0	0	43
05:00	3	1	1	1	0	1	0	7
05:15	8	0	2	0	0	1	0	11
05:30	7	1	1	3	0	0	0	12
05:45	15	8	2	1	0	0	0	26
1 Hr	33	10	6	5	0	2	0	56
6 Hrs	169	30	16	22	0	2	2	241

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	12	1	0	0	0	0	0	13
00:15	3	0	0	0	0	0	0	3
00:30	5	1	0	0	0	0	0	6
00:45	6	1	0	0	0	1	0	8
1 Hr	26	3	0	0	0	1	0	30
01:00	6	0	1	0	0	0	0	7
01:15	5	0	0	0	0	0	0	5
01:30	5	0	0	0	0	0	0	5
01:45	2	2	0	0	0	0	0	4
1 Hr	18	2	1	0	0	0	0	21
02:00	6	1	0	0	0	0	0	7
02:15	1	0	0	0	0	0	0	1
02:30	7	2	0	1	0	0	0	10
02:45	2	0	0	0	0	0	0	2
1 Hr	16	3	0	1	0	0	0	20
03:00	2	1	0	0	0	0	0	3
03:15	2	0	1	0	0	0	0	3
03:30	3	0	1	0	0	0	0	4
03:45	0	0	0	0	0	0	0	0
1 Hr	7	1	2	0	0	0	0	10
04:00	5	0	0	0	0	0	0	5
04:15	4	0	0	0	0	0	0	4
04:30	6	0	0	0	0	0	0	6
04:45	5	0	0	1	0	0	0	6
1 Hr	20	0	0	1	0	0	0	21
05:00	11	0	1	1	0	1	0	14
05:15	10	2	1	2	0	1	1	17
05:30	19	1	0	1	0	1	0	22
05:45	17	1	3	2	0	0	0	23
1 Hr	57	4	5	6	0	3	1	76
6 Hrs	144	13	8	8	0	4	1	178

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	1	0	0	1
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	1	0	0	1
09:00	0	0	0	0
09:15	0	0	0	0
09:30	2	0	0	2
09:45	1	0	0	1
1 Hr	3	0	0	3
3 Hr	4	0	0	4
16:00	0	0	0	0
16:15	2	0	0	2
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	2	0	0	2
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	0	0	0	0
18:00	0	0	0	0
18:15	0	0	0	0
18:30	0	0	0	0
18:45	3	0	0	3
1 Hr	3	0	0	3
3 Hrs	5	0	0	5
6 Hrs	9	0	0	9

	Direction : Westbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	1	1	0	2
07:45	0	0	0	0
1 Hr	1	1	0	2
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	1	0	0	1
1 Hr	1	0	0	1
3 Hr	2	1	0	3
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	2	0	0	2
17:15	0	0	0	0
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	2	0	0	2
18:00	0	0	0	0
18:15	0	0	0	0
18:30	1	0	0	1
18:45	2	0	0	2
1 Hr	3	0	0	3
3 Hrs	5	0	0	5
6 Hrs	7	1	0	8



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 21st June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	16	3	2	4	0	1	0	26
06:15	21	5	4	2	0	0	0	32
06:30	23	3	1	0	1	0	0	28
06:45	22	9	4	2	0	0	0	37
1 Hr	82	20	11	8	1	1	0	123

13	9	0	1	0	0	0	23
20	8	0	0	0	0	0	28
31	7	1	1	1	0	0	41
45	13	2	3	0	0	0	63
109	37	3	5	1	0	0	155

07:00	46	6	3	3	0	0	1	59
07:15	52	17	6	3	0	1	0	79
07:30	77	11	2	3	0	0	0	93
07:45	75	15	4	3	0	0	0	97
1 Hr	250	49	15	12	0	1	1	328

43	10	2	0	0	0	0	55
58	14	2	2	1	1	0	78
53	8	1	1	0	1	0	64
69	5	0	0	2	0	0	76
223	37	5	3	3	2	0	273

08:00	85	7	2	4	1	1	1	101
08:15	100	14	1	3	0	1	0	119
08:30	147	8	1	3	0	0	1	160
08:45	168	13	3	1	2	2	0	189
1 Hr	500	42	7	11	3	4	2	569

72	11	4	4	0	2	0	93
90	7	1	1	1	1	1	102
114	9	4	1	1	2	0	131
122	6	2	1	0	0	0	131
398	33	11	7	2	5	1	457

09:00	178	14	7	1	1	2	0	203
09:15	190	17	0	1	3	3	1	215
09:30	307	14	2	2	4	3	0	332
09:45	227	10	1	2	1	1	0	242
1 Hr	902	55	10	6	9	9	1	992

141	13	3	0	1	0	0	158
161	13	1	1	0	0	1	177
188	19	1	3	2	3	1	217
136	12	5	0	1	15	0	169
626	57	10	4	4	18	2	721

10:00	185	17	1	1	0	2	1	207
10:15	208	10	1	1	1	4	0	225
10:30	217	13	3	2	1	3	0	239
10:45	240	17	1	2	1	9	0	270
1 Hr	850	57	6	6	3	18	1	941

169	18	3	1	1	3	0	195
167	8	2	1	0	2	0	180
170	13	1	2	3	0	0	189
129	8	1	2	0	0	0	140
635	47	7	6	4	5	0	704

11:00	229	11	1	0	0	2	0	243
11:15	238	12	0	1	1	2	0	254
11:30	224	11	1	3	1	9	0	249
11:45	239	16	1	0	1	4	0	261
1 Hr	930	50	3	4	3	17	0	1007

194	7	3	0	0	0	1	205
130	8	2	0	0	0	2	142
163	10	3	2	0	2	2	182
120	16	2	1	1	0	0	140
607	41	10	3	1	2	5	669

6 Hrs	3514	273	52	47	19	50	5	3960
-------	------	-----	----	----	----	----	---	------

2598	252	46	28	15	32	8	2979
------	-----	----	----	----	----	---	------

12 Hrs	3683	303	68	69	19	52	7	4201
--------	------	-----	----	----	----	----	---	------

2742	265	54	36	15	36	9	3157
------	-----	----	----	----	----	---	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 21st June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	202	14	2	0	0	0	0	218
12:15	198	11	3	0	1	14	0	227
12:30	198	3	0	1	0	2	1	205
12:45	221	7	0	1	1	4	0	234
1 Hr	819	35	5	2	2	20	1	884

12:00	137	17	3	2	0	0	0	159
12:15	119	10	4	1	0	3	0	137
12:30	145	8	0	0	2	4	0	159
12:45	125	12	2	1	0	7	0	147
1 Hr	526	47	9	4	2	14	0	602

13:00	170	13	0	2	1	3	0	189
13:15	177	8	1	0	1	12	0	199
13:30	214	15	2	0	0	4	1	236
13:45	176	10	1	2	0	2	0	191
1 Hr	737	46	4	4	2	21	1	815

13:00	139	10	1	1	0	4	1	156
13:15	131	13	3	1	0	6	0	154
13:30	105	9	4	1	1	1	0	121
13:45	96	12	3	1	0	5	1	118
1 Hr	471	44	11	4	1	16	2	549

14:00	169	9	0	1	0	3	0	182
14:15	183	9	3	0	2	1	0	198
14:30	142	12	0	0	0	2	0	156
14:45	181	10	3	3	0	2	0	199
1 Hr	675	40	6	4	2	8	0	735

14:00	148	4	2	0	0	1	0	155
14:15	135	5	1	1	0	9	0	151
14:30	113	7	2	0	1	3	0	126
14:45	152	11	3	1	1	8	0	176
1 Hr	548	27	8	2	2	21	0	608

15:00	143	9	1	0	0	2	0	155
15:15	140	7	0	1	1	3	0	152
15:30	134	8	0	0	0	6	0	148
15:45	137	5	0	0	0	1	0	143
1 Hr	554	29	1	1	1	12	0	598

15:00	131	13	0	0	0	3	0	147
15:15	120	3	0	1	1	12	2	139
15:30	116	4	2	0	0	2	0	124
15:45	122	12	3	0	0	6	0	143
1 Hr	489	32	5	1	1	23	2	553

16:00	169	9	2	0	0	1	2	183
16:15	165	8	1	1	4	1	0	180
16:30	149	10	1	0	1	2	2	165
16:45	122	8	0	0	0	1	0	131
1 Hr	605	35	4	1	5	5	4	659

16:00	164	6	1	0	0	4	0	175
16:15	153	7	0	0	1	2	0	163
16:30	151	12	0	0	0	5	0	168
16:45	150	4	1	0	0	2	0	157
1 Hr	618	29	2	0	1	13	0	663

17:00	146	6	0	1	0	4	0	157
17:15	143	7	0	0	2	4	0	156
17:30	122	11	0	2	1	3	0	139
17:45	132	7	0	1	0	0	0	140
1 Hr	543	31	0	4	3	11	0	592

17:00	162	8	0	0	1	4	1	176
17:15	185	8	1	0	0	5	1	200
17:30	153	5	0	0	1	1	0	160
17:45	115	11	2	0	1	0	1	130
1 Hr	615	32	3	0	3	10	3	666

6 Hrs	3933	216	20	16	15	77	6	4283
-------	------	-----	----	----	----	----	---	------

6 Hrs	3267	211	38	11	10	97	7	3641
-------	------	-----	----	----	----	----	---	------

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	127	9	1	0	1	3	2	143
18:15	113	6	2	0	0	1	0	122
18:30	106	4	1	0	0	2	1	114
18:45	102	5	0	1	0	1	0	109
1 Hr	448	24	4	1	1	7	3	488

18:00	127	4	0	0	3	1	0	135
18:15	161	6	0	0	2	4	4	177
18:30	136	4	1	0	3	4	0	148
18:45	169	6	0	0	1	6	0	182
1 Hr	593	20	1	0	9	15	4	642

19:00	103	5	0	0	1	3	0	112
19:15	102	2	0	0	1	0	0	105
19:30	74	5	0	1	0	1	0	81
19:45	93	5	1	0	1	2	0	102
1 Hr	372	17	1	1	3	6	0	400

19:00	116	6	1	0	2	1	0	126
19:15	142	6	4	0	1	2	0	155
19:30	107	5	0	0	1	3	0	116
19:45	99	3	1	0	1	7	0	111
1 Hr	464	20	6	0	5	13	0	508

20:00	77	1	0	0	1	2	0	81
20:15	58	2	0	1	0	1	0	62
20:30	57	5	2	0	0	0	0	64
20:45	51	2	0	0	1	1	0	55
1 Hr	243	10	2	1	2	4	0	262

20:00	100	2	0	0	0	0	0	102
20:15	67	3	0	0	0	0	0	70
20:30	72	2	1	1	1	2	0	79
20:45	56	1	0	1	0	1	0	59
1 Hr	295	8	1	2	1	3	0	310

21:00	50	1	0	0	1	0	0	52
21:15	47	2	1	0	0	0	0	50
21:30	41	3	1	0	0	0	0	45
21:45	47	3	0	0	0	0	0	50
1 Hr	185	9	2	0	1	0	0	197

21:00	58	1	0	0	0	5	0	64
21:15	62	3	0	0	0	6	0	71
21:30	56	0	0	0	0	1	0	57
21:45	49	0	0	0	0	1	0	50
1 Hr	225	4	0	0	0	13	0	242

22:00	43	2	0	0	0	0	0	45
22:15	38	1	0	0	0	0	0	39
22:30	40	0	0	0	0	0	0	40
22:45	42	1	0	0	0	0	0	43
1 Hr	163	4	0	0	0	0	0	167

22:00	52	2	0	0	0	0	0	54
22:15	21	3	0	0	0	0	0	24
22:30	45	0	1	0	0	0	1	47
22:45	29	1	0	0	0	1	1	32
1 Hr	147	6	1	0	0	1	2	157

23:00	34	2	0	0	0	1	0	37
23:15	24	1	0	0	0	1	0	26
23:30	27	3	1	0	0	0	0	31
23:45	24	1	0	0	0	0	0	25
1 Hr	109	7	1	0	0	2	0	119

23:00	35	1	0	1	0	0	0	37
23:15	23	1	0	0	0	0	0	24
23:30	26	0	0	0	0	0	0	26
23:45	10	1	0	0	0	0	0	11
1 Hr	94	3	0	1	0	0	0	98

6 Hrs	1520	71	10	3	7	19	3	1633
-------	------	----	----	---	---	----	---	------

6 Hrs	1818	61	9	3	15	45	6	1957
-------	------	----	---	---	----	----	---	------

12 Hrs	5453	287	30	19	22	96	9	5916
--------	------	-----	----	----	----	----	---	------

12 Hrs	5085	272	47	14	25	142	13	5598
--------	------	-----	----	----	----	-----	----	------

Total	9136	590	98	88	41	148	16	10117
-------	------	-----	----	----	----	-----	----	-------

Total	7827	537	101	50	40	178	22	8755
-------	------	-----	-----	----	----	-----	----	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Monday 16th June - Saturday 21st June 2014

Summary of Counts

		Direction : Eastbound							Total	
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total	
Day 1	Monday	16/06/2014	6973	860	245	295	57	55	17	8502
Day 2	Tuesday	17/06/2014	6541	915	288	316	47	98	14	8219
Day 3	Wednesday	18/06/2014	7355	937	300	237	55	123	30	9037
Day 4	Thursday	19/06/2014	7440	1013	347	242	50	76	14	9182
Day 5	Friday	20/06/2014	9156	1248	374	250	62	89	24	11203
Day 6	Saturday	21/06/2014	9136	590	98	88	41	148	16	10117
			46601	5563	1652	1428	312	589	115	56260

		Direction : Westbound							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total
		6912	1034	271	287	56	62	18	8640
		6454	973	343	300	55	97	15	8237
		6704	1117	293	233	58	132	25	8562
		6674	992	319	234	49	84	23	8375
		7159	894	301	229	49	103	9	8744
		7827	537	101	50	40	178	22	8755
		41730	5547	1628	1333	307	656	112	51313

		Direction Eastbound					Total
		Adult	Unaccompanied Child	Accompanied Child	Unaccompanied Adult	Accompanied Adult	Total
		5	0	0	0	0	5
		2	0	0	0	0	2
		7	0	0	0	0	7
		5	0	0	0	0	5
		2	0	0	0	0	2
		9	0	0	0	0	9
		30	0	0	0	0	30

		Direction Westbound					Total
		Adult	Unaccompanied Child	Accompanied Child	Unaccompanied Adult	Accompanied Adult	Total
		5	0	0	0	0	5
		1	0	0	0	0	1
		3	0	0	0	0	3
		2	0	0	0	0	2
		3	0	0	0	0	3
		7	1	0	0	0	8
		21	1	0	0	0	22

		Direction : Combined Counts							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	PC	Total

Day 1	Monday	16/06/2014	13885	1894	516	582	113	117	35	17142
Day 2	Tuesday	17/06/2014	12995	1888	631	616	102	195	29	16456
Day 3	Wednesday	18/06/2014	14859	2054	593	470	113	255	55	17699
Day 4	Thursday	19/06/2014	14114	2005	666	476	99	160	37	17557
Day 5	Friday	20/06/2014	16315	2142	675	479	111	192	33	19947
Day 6	Saturday	21/06/2014	16963	1127	199	138	81	326	38	18872
			88331	11110	3280	2761	619	1245	227	107573

		Direction : Combined Counts					Total
		Adult	Unaccompanied Child	Accompanied Child	Unaccompanied Adult	Accompanied Adult	Total

		10	0	0	0	0	10
		3	0	0	0	0	3
		10	0	0	0	0	10
		7	0	0	0	0	7
		5	0	0	0	0	5
		16	1	0	0	0	17
		51	1	0	0	0	52

Averages Vehicles

		Direction : Eastbound							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total
Day 1	AM	87.42	22.75	6.67	4.50	1.17	0.25	0.00	122.75
	PM	143.67	12.33	2.87	3.17	0.75	1.75	0.75	165.08
	00:00-12:00	47.52	9.35	3.19	2.71	0.58	0.27	0.00	63.63
	12:00-24:00	97.75	8.56	1.92	3.44	0.60	0.88	0.35	113.50
	24 Hrs	72.64	8.96	2.55	3.07	0.59	0.57	0.18	88.56

		Direction : Westbound							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total
		134.25	19.67	4.50	4.33	1.17	1.42	0.58	165.92
		107.92	18.08	3.50	3.42	0.75	0.92	0.17	134.75
		64.88	9.96	2.35	3.08	0.56	0.63	0.19	81.65
		79.13	11.58	3.29	2.90	0.60	0.67	0.19	98.35
		72.00	10.77	2.82	2.99	0.58	0.65	0.19	90.00

Pedestrians

		Direction Eastbound				Total
		Adult	Ac Child	Un Child	Un Adult	Total
AM		0.00	0.00	0.00	0.00	0.00
PM		0.42	0.00	0.00	0.42	0.42
6 Hrs		0.21	0.00	0.00	0.21	0.21

		Direction Westbound				Total
		Adult	Ac Child	Un Child	Un Adult	Total
AM		0.25	0.00	0.00	0.00	0.25
PM		0.17	0.00	0.00	0.17	0.17
6 Hrs		0.21	0.00	0.00	0.00	0.21

		Direction : Eastbound							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total
Day 2	AM	81.83	22.42	8.08	5.33	0.83	0.58	0.08	119.17
	PM	144.00	17.00	3.00	3.17	0.75	3.58	0.50	172.00
	00:00-12:00	43.02	9.46	3.69	3.42	0.52	0.29	0.10	60.50
	12:00-24:00	93.25	9.60	2.31	3.17	0.46	1.75	0.19	110.73
	24 Hrs	68.14	9.53	3.00	3.29	0.49	1.02	0.15	85.61

		137.42	18.75	6.08	4.50	0.75	2.00	0.33	169.83
		114.42	17.67	4.42	3.83	1.42	1.75	0.42	143.92
		60.04	9.25	3.04	3.46	0.40	0.77	0.08	77.04
		74.42	11.02	4.10	2.79	0.75	1.25	0.23	94.56
		67.23	10.14	3.57	3.13	0.57	1.01	0.16	85.80

AM		0.00	0.00	0.00	0.00	0.00
PM		0.17	0.00	0.00	0.17	0.17
6 Hrs		0.08	0.00	0.00	0.08	0.08

AM		0.00	0.00	0.00	0.00	0.00
PM		0.08	0.00	0.00	0.08	0.08
6 Hrs		0.04	0.00	0.00	0.04	0.04

		Direction : Eastbound							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total
Day 3	AM	77.67	21.67	7.25	4.67	1.00	0.67	0.17	113.08
	PM	193.33	16.08	3.00	2.17	0.75	4.42	0.92	220.67
	00:00-12:00	40.58	9.83	3.60	2.81	0.58	0.35	0.10	57.88
	12:00-24:00	112.65	9.69	2.65	2.13	0.56	2.21	0.52	130.40
	24 Hrs	76.61	9.76	3.13	2.47	0.57	1.28	0.31	94.14

		172.83	20.42	5.00	4.08	1.25	1.25	0.75	205.58
		95.08	18.58	3.92	1.67	1.58	1.67	0.25	122.75
		71.02	10.40	2.79	2.98	0.50	0.63	0.29	88.60
		68.65	12.88	3.31	1.88	0.71	2.13	0.23	89.77
		69.83	11.64	3.05	2.43	0.60	1.38	0.26	89.19

AM		0.08	0.00	0.00	0.00	0.08
PM		0.50	0.00	0.00	0.50	0.50
6 Hrs		0.29	0.00	0.00	0.29	0.29

AM		0.00	0.00	0.00	0.00	0.00
PM		0.25	0.00	0.00	0.25	0.25
6 Hrs		0.13	0.00	0.00	0.13	0.13

		Direction : Eastbound							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total
Day 4	AM	77.42	22.08	9.42	4.08	1.17	0.58	0.17	114.92
	PM	192.58	16.08	3.33	2.42	0.92	2.33	0.33	218.00
	00:00-12:00	41.40	10.08	4.54	2.50	0.50	0.38	0.15	59.54
	12:00-24:00	113.60	11.02	2.69	2.54	0.54	1.21	0.15	131.75
	24 Hrs	77.50	10.55	3.61	2.52	0.52	0.79	0.15	95.65

		168.67	18.67	5.83	2.58	1.17	1.75	0.67	199.33
		94.25	18.42	3.33	3.00	0.83	1.42	0.33	121.58
		70.85	8.67	3.48	2.35	0.50	0.73	0.29	86.88
		68.19	12.00	3.17	2.52	0.52	1.02	0.19	87.60
		69.52	10.33	3.32	2.44	0.51	0.88	0.24	87.24

AM		0.08	0.00	0.00	0.00	0.08
PM		0.33	0.00	0.00	0.33	0.33
6 Hrs		0.21	0.00	0.00	0.21	0.21

AM		0.00	0.00	0.00	0.00	0.00
PM		0.17	0.00	0.00	0.17	0.17
6 Hrs		0.08	0.00	0.00	0.08	0.08


		Direction : Eastbound							Total
		Car	Lgv	Ogv1	Ogv2	Psv	MC	P/C	Total
Day 5	AM	86.92	23.17	9.67	6.08	1.17	0.50	0.33	127.83
	PM	211.67	21.17	3.75	2.33	1.25	1.83	0.58	242.58
	00:00-12:00	47							




Sky High

Count On Us

Client : Lincolnshire County Council	Site plan for : EW1 - A158 Wragby Road East
Project : 9320 / Lincoln By Pass	Date : Monday 16th June - Saturday 21st June 2014



Unnamed Road



A518 Wragby Road

A518 Wragby Road



Sky High

Count On Us

Client:	Lincolnshire County Council
Project:	9320 / Lincoln By Pass
Site:	EW1 - A158 Wragby Road East
Survey Date:	Monday 23rd June - Monday 30th June 2014
Survey Period:	07:00 - 19:00
Method:	Video Observation

Incidents / Observations:

There were no incidents reported over the survey period.



Sky High

Count On Us

Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Monday 23rd June 2014

AM Weather: Mild & Cloudy
 PM Weather: Mild & Clear

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	8	1	0	0	0	0	0	9
00:15	11	2	0	0	0	1	0	14
00:30	3	1	0	0	0	0	0	4
00:45	1	1	1	0	0	0	0	3
1 Hr	23	5	1	0	0	1	0	30
01:00	3	0	0	0	0	0	0	3
01:15	5	0	0	0	0	0	0	5
01:30	4	0	1	0	0	0	0	5
01:45	0	0	0	0	0	0	0	0
1 Hr	12	0	1	0	0	0	0	13
02:00	3	0	0	1	0	0	0	4
02:15	1	2	0	0	0	0	0	3
02:30	5	0	0	0	0	0	0	5
02:45	4	0	1	1	0	0	0	6
1 Hr	13	2	1	2	0	0	0	18
03:00	2	1	0	1	0	0	0	4
03:15	1	2	0	1	0	0	0	4
03:30	3	0	0	0	0	0	0	3
03:45	3	0	0	0	0	0	0	3
1 Hr	9	3	0	2	0	0	0	14
04:00	3	0	2	0	0	0	0	5
04:15	1	2	1	0	0	0	0	4
04:30	9	5	0	0	0	1	0	15
04:45	7	1	0	1	0	0	0	9
1 Hr	20	8	3	1	0	1	0	33
05:00	6	1	1	2	0	1	0	11
05:15	7	1	2	2	0	2	0	14
05:30	10	0	1	1	0	0	0	12
05:45	23	7	1	0	0	1	0	32
1 Hr	46	9	5	5	0	4	0	69
6 Hrs	123	27	11	10	0	6	0	177

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	4	0	0	1	0	0	0	5
00:15	10	0	1	0	0	0	0	11
00:30	2	1	1	0	0	0	0	4
00:45	1	0	0	0	0	0	0	1
1 Hr	17	1	2	1	0	0	0	21
01:00	3	0	0	1	0	0	0	4
01:15	5	0	1	0	0	0	0	6
01:30	0	0	0	0	0	0	0	0
01:45	2	2	0	0	0	0	0	4
1 Hr	10	2	1	1	0	0	0	14
02:00	4	1	0	0	0	0	0	5
02:15	1	0	0	0	0	0	0	1
02:30	2	0	0	0	0	0	0	2
02:45	2	1	0	0	0	0	0	3
1 Hr	9	2	0	0	0	0	0	11
03:00	5	0	0	0	0	0	0	5
03:15	5	0	0	0	0	0	0	5
03:30	7	0	0	0	0	0	0	7
03:45	5	1	0	0	0	0	0	6
1 Hr	22	1	0	0	0	0	0	23
04:00	7	1	0	2	0	0	0	10
04:15	13	2	0	3	0	0	0	18
04:30	15	6	0	3	0	0	0	24
04:45	8	3	1	4	0	0	0	16
1 Hr	43	12	1	12	0	0	0	68
05:00	15	5	0	6	0	1	0	27
05:15	22	3	0	8	0	0	0	33
05:30	30	5	2	11	0	0	0	48
05:45	30	8	1	3	0	2	0	44
1 Hr	97	21	3	28	0	3	0	152
6 Hrs	198	39	7	42	0	3	0	289

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	1	0	0	1
17:30	1	0	0	1
17:45	0	0	0	0
1 Hr	2	0	0	2
18:00	2	0	0	2
18:15	0	0	0	0
18:30	1	0	0	1
18:45	0	0	0	0
1 Hr	3	0	0	3
3 Hrs	5	0	0	5
6 Hrs	5	0	0	5

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	1	0	1
08:45	0	0	0
1 Hr	1	0	1
09:00	1	0	1
09:15	2	0	2
09:30	0	0	0
09:45	0	0	0
1 Hr	3	0	3
4	4	0	4
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	0	0	0
1 Hr	0	0	0
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	1	0	1
18:45	0	0	0
1 Hr	1	0	1
3 Hrs	1	0	1
6 Hrs	5	0	5



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Monday 23rd June 2014

AM Weather: Mild & Cloudy
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	20	5	4	1	1	0	0	31
06:15	20	14	2	3	3	1	0	43
06:30	44	17	6	6	1	1	0	75
06:45	46	24	15	7	0	1	0	93
1 Hr	130	60	27	17	5	3	0	242

51	12	0	5	0	0	2	70
51	13	1	5	0	3	0	73
65	14	2	9	2	0	1	93
88	23	5	4	0	1	1	122
255	62	8	23	2	4	4	358

07:00	60	29	3	5	2	2	1	102
07:15	68	19	8	11	2	0	0	108
07:30	94	22	8	5	1	2	0	132
07:45	76	20	13	3	0	0	0	112
1 Hr	298	90	32	24	5	4	1	454

120	25	4	6	0	1	1	157
119	28	7	4	1	2	1	162
169	28	1	6	0	2	1	207
168	17	2	4	2	3	1	197
576	98	14	20	3	8	4	723

08:00	90	23	13	7	0	4	0	137
08:15	81	21	6	7	0	0	0	115
08:30	103	25	9	13	0	0	0	150
08:45	91	20	8	2	2	1	0	124
1 Hr	365	89	36	29	2	5	0	526

169	15	8	6	1	1	0	200
137	6	8	7	3	2	0	163
156	14	4	4	1	4	2	185
150	7	9	4	0	1	1	172
612	42	29	21	5	8	3	720

09:00	86	25	3	2	0	1	0	117
09:15	97	15	8	3	3	1	0	127
09:30	85	26	7	5	0	1	0	124
09:45	110	11	1	8	0	0	0	130
1 Hr	378	77	19	18	3	3	0	498

129	9	7	2	0	0	1	148
120	13	7	3	0	1	1	145
140	14	3	6	1	1	1	166
157	19	7	5	2	0	0	190
546	55	24	16	3	2	3	649

10:00	116	13	7	10	2	1	0	149
10:15	148	18	5	6	1	0	1	179
10:30	130	12	9	7	0	0	0	158
10:45	183	13	5	2	0	1	1	205
1 Hr	577	56	26	25	3	2	2	691

101	18	8	5	1	2	0	135
156	14	11	5	1	2	0	189
130	8	7	2	1	1	0	149
171	13	4	3	2	3	0	196
558	53	30	15	5	8	0	669

11:00	155	15	5	5	3	0	0	183
11:15	156	11	4	6	1	2	0	180
11:30	164	9	4	2	2	0	0	181
11:45	165	8	6	5	2	1	1	188
1 Hr	640	43	19	18	8	3	1	732

132	7	10	2	0	0	1	152
184	19	12	3	1	3	0	222
161	15	4	5	0	1	0	186
130	11	8	6	1	0	1	157
607	52	34	16	2	4	2	717

6 Hrs	2388	415	159	131	26	20	4	3143
-------	------	-----	-----	-----	----	----	---	------

3154	362	139	111	20	34	16	3836
------	-----	-----	-----	----	----	----	------

12 Hrs	2511	442	170	141	26	26	4	3320
--------	------	-----	-----	-----	----	----	---	------

3352	401	146	153	20	37	16	4125
------	-----	-----	-----	----	----	----	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Monday 23rd June 2014

AM Weather: Mild & Cloudy
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	156	17	4	6	1	2	0	186
12:15	155	16	8	3	1	1	1	185
12:30	144	11	5	7	0	1	0	168
12:45	166	17	3	6	1	1	0	194
1 Hr	621	61	20	22	3	5	1	733

12:00	163	14	6	5	0	1	0	189
12:15	154	7	5	4	1	0	0	171
12:30	102	6	5	4	4	1	0	122
12:45	134	18	10	6	0	2	0	170
1 Hr	553	45	26	19	5	4	0	652

13:00	123	15	4	5	0	2	0	149
13:15	145	14	5	3	2	0	0	169
13:30	141	11	5	7	0	2	0	166
13:45	136	14	3	9	1	0	0	163
1 Hr	545	54	17	24	3	4	0	647

13:00	102	8	4	4	0	1	0	119
13:15	144	10	4	3	0	1	0	162
13:30	89	18	5	4	1	2	0	119
13:45	110	18	8	2	0	1	0	139
1 Hr	445	54	21	13	1	5	0	539

14:00	125	14	1	3	0	2	1	146
14:15	115	12	5	6	1	5	0	144
14:30	135	6	3	5	2	0	0	151
14:45	138	16	8	5	1	4	2	174
1 Hr	513	48	17	19	4	11	3	615

14:00	115	17	10	1	2	2	0	147
14:15	118	15	7	2	1	0	0	143
14:30	117	12	5	2	2	0	0	138
14:45	128	18	4	7	0	0	0	157
1 Hr	478	62	26	12	5	2	0	585

15:00	158	13	4	1	0	4	0	180
15:15	144	8	5	6	2	0	0	165
15:30	170	12	4	3	1	4	0	194
15:45	151	16	6	6	0	2	0	181
1 Hr	623	49	19	16	3	10	0	720

15:00	111	24	8	1	1	2	0	147
15:15	116	14	9	7	0	1	0	147
15:30	145	21	7	5	2	3	0	183
15:45	87	16	10	3	0	1	0	117
1 Hr	459	75	34	16	3	7	0	594

16:00	148	17	4	5	0	1	2	177
16:15	169	17	1	4	2	2	1	196
16:30	146	18	6	2	0	3	1	176
16:45	162	22	3	5	0	1	0	193
1 Hr	625	74	14	16	2	7	4	742

16:00	125	24	9	4	1	1	0	164
16:15	102	21	4	7	1	3	0	138
16:30	120	19	2	4	0	1	2	148
16:45	126	17	2	1	1	0	0	147
1 Hr	473	81	17	16	3	5	2	597

17:00	157	15	4	7	1	2	0	186
17:15	162	17	5	4	2	1	0	191
17:30	154	13	0	0	1	2	0	170
17:45	180	13	5	2	0	2	0	202
1 Hr	653	58	14	13	4	7	0	749

17:00	135	23	4	6	3	4	1	176
17:15	127	23	3	2	1	3	0	159
17:30	122	23	6	4	0	3	0	158
17:45	109	17	4	2	0	2	0	134
1 Hr	493	86	17	14	4	12	1	627

6 Hrs	3580	344	101	110	19	44	8	4206
-------	------	-----	-----	-----	----	----	---	------

6 Hrs	2901	403	141	90	21	35	3	3594
-------	------	-----	-----	----	----	----	---	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Monday 23rd June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	157	11	1	0	1	0	0	170
18:15	122	11	2	2	0	1	3	141
18:30	107	12	0	0	0	1	0	120
18:45	89	13	0	2	0	0	1	105
1 Hr	475	47	3	4	1	2	4	536

18:00	116	17	2	2	2	3	0	142
18:15	107	9	5	2	1	2	0	126
18:30	103	4	2	0	0	1	0	110
18:45	91	6	1	3	1	3	1	106
1 Hr	417	36	10	7	4	9	1	484

19:00	90	3	1	2	1	3	0	100
19:15	88	1	1	1	0	2	0	93
19:30	80	9	0	0	0	0	0	89
19:45	60	4	0	4	0	0	2	70
1 Hr	318	17	2	7	1	5	2	352

19:00	82	7	0	3	1	1	0	94
19:15	65	10	3	0	0	1	0	79
19:30	72	10	2	2	1	0	1	88
19:45	63	4	2	0	0	0	0	69
1 Hr	282	31	7	5	2	2	1	330

20:00	63	6	1	1	0	1	0	72
20:15	73	1	2	1	1	3	1	82
20:30	41	1	0	0	0	3	0	45
20:45	38	1	0	0	0	0	0	39
1 Hr	215	9	3	2	1	7	1	238

20:00	43	2	0	1	0	3	0	49
20:15	41	3	4	1	0	2	0	51
20:30	48	3	1	1	1	0	0	54
20:45	33	7	1	1	0	0	0	42
1 Hr	165	15	6	4	1	5	0	196

21:00	48	4	0	1	1	0	1	55
21:15	31	4	1	1	0	0	0	37
21:30	36	3	1	0	0	0	0	40
21:45	22	1	0	1	0	0	0	24
1 Hr	137	12	2	3	1	0	1	156

21:00	32	3	1	0	0	1	0	37
21:15	29	1	0	0	0	2	0	32
21:30	33	2	0	0	0	0	0	35
21:45	27	1	1	1	0	1	0	31
1 Hr	121	7	2	1	0	4	0	135

22:00	34	0	0	2	0	1	0	37
22:15	31	2	0	0	0	1	0	34
22:30	22	1	0	0	0	0	0	23
22:45	15	2	0	0	0	0	0	17
1 Hr	102	5	0	2	0	2	0	111

22:00	19	1	2	0	0	0	0	22
22:15	14	2	0	0	0	0	0	16
22:30	11	2	1	0	0	0	0	14
22:45	5	3	2	0	0	1	0	11
1 Hr	49	8	5	0	0	1	0	63

23:00	15	3	0	1	0	0	0	19
23:15	11	1	0	0	0	1	0	13
23:30	5	0	0	1	0	0	0	6
23:45	8	0	0	0	0	1	0	9
1 Hr	39	4	0	2	0	2	0	47

23:00	10	0	0	1	0	1	0	12
23:15	8	1	0	0	0	0	0	9
23:30	8	0	0	0	0	0	0	8
23:45	5	1	0	0	0	0	0	6
1 Hr	31	2	0	1	0	1	0	35

6 Hrs	1286	94	10	20	4	18	8	1440
-------	------	----	----	----	---	----	---	------

6 Hrs	1065	99	30	18	7	22	2	1243
-------	------	----	----	----	---	----	---	------

12 Hrs	4866	438	111	130	23	62	16	5646
--------	------	-----	-----	-----	----	----	----	------

12 Hrs	3966	502	171	108	28	57	5	4837
--------	------	-----	-----	-----	----	----	---	------

Total	7377	880	281	271	49	88	20	8962
-------	------	-----	-----	-----	----	----	----	------

Total	7318	903	317	261	48	94	21	8962
-------	------	-----	-----	-----	----	----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Tuesday 24th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	8	1	1	1	0	0	0	11
00:15	4	1	0	0	0	0	0	5
00:30	3	0	0	1	0	0	0	4
00:45	4	0	0	2	0	0	0	6
1 Hr	19	2	1	4	0	0	0	26
01:00	0	0	1	1	0	0	0	2
01:15	0	0	0	0	0	0	0	0
01:30	0	0	0	0	0	0	0	0
01:45	4	0	0	0	0	0	0	4
1 Hr	4	0	1	1	0	0	0	6
02:00	2	0	4	1	0	0	0	7
02:15	1	0	0	1	0	0	0	2
02:30	0	1	0	1	0	0	0	2
02:45	4	0	0	0	0	0	0	4
1 Hr	7	1	4	3	0	0	0	15
03:00	0	1	1	0	0	0	0	2
03:15	0	0	0	0	0	0	0	0
03:30	4	1	1	0	0	0	0	6
03:45	1	0	1	1	0	0	0	3
1 Hr	5	2	3	1	0	0	0	11
04:00	1	0	1	0	0	0	0	2
04:15	1	1	1	0	0	0	0	3
04:30	4	7	3	0	0	0	0	14
04:45	3	4	1	4	0	0	1	13
1 Hr	9	12	6	4	0	0	1	32
05:00	5	2	2	2	0	0	0	11
05:15	6	0	3	1	0	0	0	10
05:30	11	1	2	2	0	0	0	16
05:45	12	7	2	3	0	0	0	24
1 Hr	34	10	9	8	0	0	0	61
6 Hrs	78	27	24	21	0	0	1	151

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	5	1	0	2	0	0	0	8
00:15	8	1	0	0	0	1	0	10
00:30	2	4	1	0	0	0	0	7
00:45	5	0	0	0	0	0	0	5
1 Hr	20	6	1	2	0	1	0	30
01:00	3	2	0	1	0	0	0	6
01:15	0	1	1	0	0	0	0	2
01:30	3	0	0	1	0	0	0	4
01:45	2	0	0	0	0	0	0	2
1 Hr	8	3	1	2	0	0	0	14
02:00	3	0	0	1	0	0	0	4
02:15	1	0	0	0	0	0	0	1
02:30	3	1	0	0	0	0	0	4
02:45	2	0	0	0	0	1	0	3
1 Hr	9	1	0	1	0	1	0	12
03:00	3	1	0	0	0	0	0	4
03:15	1	0	0	1	0	0	0	2
03:30	2	0	1	1	0	0	0	4
03:45	3	0	1	0	0	0	0	4
1 Hr	9	1	2	2	0	0	0	14
04:00	3	3	0	0	0	0	0	6
04:15	3	2	1	1	0	0	0	7
04:30	7	2	0	6	0	0	0	15
04:45	7	1	0	3	0	0	0	11
1 Hr	20	8	1	10	0	0	0	39
05:00	6	2	1	3	0	0	0	12
05:15	14	0	4	3	0	0	0	21
05:30	28	3	0	3	0	0	0	34
05:45	25	5	0	5	0	1	1	37
1 Hr	73	10	5	14	0	1	1	104
6 Hrs	139	29	10	31	0	3	1	213

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	1	0	0	1
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	1	0	0	1
09:00	1	0	0	1
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	1	0	0	1
3 Hr	2	0	0	2
16:00	0	0	0	0
16:15	0	0	0	0
16:30	2	0	0	2
16:45	0	0	0	0
1 Hr	2	0	0	2
17:00	0	0	0	0
17:15	0	0	0	0
17:30	1	0	0	1
17:45	0	0	0	0
1 Hr	1	0	0	1
18:00	1	0	0	1
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	1	0	0	1
3 Hrs	4	0	0	4
6 Hrs	6	0	0	6

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	1	0	1
07:30	0	0	0
07:45	0	0	0
1 Hr	1	0	1
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	1	0	1
1 Hr	1	0	1
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	2	0	2
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	0	0	0
1 Hr	0	0	0
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	1	0	1
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	1	0	1
3 Hrs	1	0	1
6 Hrs	3	0	3

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	16	7	4	5	1	0	0	33
06:15	25	11	6	6	2	1	0	51
06:30	34	18	3	4	1	0	0	60
06:45	34	28	12	3	0	0	0	77
1 Hr	109	64	25	18	4	1	0	221

06:00	33	9	2	7	0	0	1	52
06:15	53	9	1	5	0	0	1	69
06:30	55	14	2	7	0	3	1	82
06:45	87	27	4	7	1	1	1	128
1 Hr	228	59	9	26	1	4	4	331

07:00	58	24	13	6	2	0	0	103
07:15	72	25	14	1	1	1	0	114
07:30	88	33	11	7	1	1	1	142
07:45	92	26	12	6	0	1	1	138
1 Hr	310	108	50	20	4	3	2	497

07:00	100	15	4	1	0	0	0	120
07:15	129	26	3	3	1	3	1	166
07:30	163	24	6	6	0	3	2	204
07:45	155	17	5	1	2	1	0	181
1 Hr	547	82	18	11	3	7	3	671

08:00	86	30	22	3	0	0	0	141
08:15	87	38	9	3	0	1	0	138
08:30	100	30	10	2	0	1	0	143
08:45	77	25	12	7	3	0	0	124
1 Hr	264	93	31	12	3	2	0	546

08:00	208	14	8	3	1	4	0	238
08:15	133	11	5	4	3	5	2	163
08:30	109	16	6	4	0	2	0	137
08:45	160	10	6	8	0	3	0	187
1 Hr	402	37	17	16	3	10	2	725

09:00	109	19	6	5	1	0	1	141
09:15	88	26	7	7	2	1	1	132
09:30	95	15	6	6	5	0	1	128
09:45	94	10	9	2	3	1	0	119
1 Hr	386	70	28	20	11	2	3	520

09:00	108	12	7	3	0	0	0	130
09:15	131	14	5	6	1	0	0	157
09:30	147	14	6	10	2	4	0	183
09:45	129	19	4	6	1	0	0	159
1 Hr	515	59	22	25	4	4	0	629

10:00	107	25	14	5	2	2	0	155
10:15	97	19	10	4	2	0	0	132
10:30	110	14	9	2	2	0	0	137
10:45	106	14	9	4	2	0	0	135
1 Hr	420	72	42	15	8	2	0	559

10:00	108	11	4	3	0	1	2	129
10:15	123	11	8	3	1	2	1	149
10:30	106	11	5	5	4	1	2	134
10:45	127	11	7	1	0	0	0	146
1 Hr	464	44	24	12	5	4	5	558

11:00	117	11	4	4	0	5	0	141
11:15	93	23	2	2	2	4	1	127
11:30	102	15	4	5	0	3	0	129
11:45	91	9	5	3	0	1	2	111
1 Hr	403	58	15	14	2	13	3	508

11:00	100	18	6	1	0	1	0	126
11:15	125	10	5	8	0	2	0	150
11:30	89	15	9	6	1	1	0	121
11:45	102	12	6	4	1	3	0	128
1 Hr	416	55	26	19	2	7	0	525

6 Hrs	1892	465	191	99	32	23	8	2851
-------	------	-----	-----	----	----	----	---	------

6 Hrs	2572	336	116	109	18	36	14	3439
-------	------	-----	-----	-----	----	----	----	------

12 Hrs	1970	492	215	120	32	23	9	3002
--------	------	-----	-----	-----	----	----	---	------

12 Hrs	2711	365	126	140	18	39	15	3652
--------	------	-----	-----	-----	----	----	----	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Tuesday 24th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	115	12	6	4	0	4	0	141
12:15	104	12	2	3	1	0	2	124
12:30	100	12	4	2	0	2	0	120
12:45	84	11	4	3	1	2	0	105
1 Hr	403	47	16	12	2	8	2	490

12:00	80	13	5	4	0	0	0	102
12:15	93	16	5	5	0	0	1	120
12:30	77	8	5	3	1	1	0	95
12:45	111	20	10	5	1	0	0	147
1 Hr	361	57	25	17	2	1	1	464

13:00	88	10	2	10	0	1	0	111
13:15	95	15	6	7	2	3	0	128
13:30	101	11	3	5	0	0	0	120
13:45	95	16	8	2	0	0	0	121
1 Hr	379	52	19	24	2	4	0	480

13:00	137	17	11	1	0	2	0	168
13:15	116	10	7	4	0	3	0	140
13:30	86	13	11	4	1	1	0	116
13:45	112	23	8	3	0	0	0	146
1 Hr	451	63	37	12	1	6	0	570

14:00	115	11	3	9	0	5	1	144
14:15	98	11	4	8	1	0	0	122
14:30	104	15	2	6	2	0	1	130
14:45	108	12	4	5	0	1	1	131
1 Hr	425	49	13	28	3	6	3	527

14:00	94	22	10	1	0	0	0	127
14:15	155	19	11	8	2	1	1	197
14:30	123	10	10	4	2	0	0	149
14:45	95	16	7	2	1	3	0	124
1 Hr	467	67	38	15	5	4	1	597

15:00	124	11	3	3	1	1	0	143
15:15	153	16	1	4	1	0	1	176
15:30	127	23	5	7	0	0	0	162
15:45	133	24	6	3	1	2	1	170
1 Hr	537	74	15	17	3	3	2	651

15:00	124	19	13	2	0	4	1	163
15:15	94	21	13	5	0	2	0	135
15:30	126	15	6	3	5	1	1	157
15:45	105	15	5	1	0	2	0	128
1 Hr	449	70	37	11	5	9	2	583

16:00	149	19	3	2	0	1	1	175
16:15	141	22	2	5	2	1	2	175
16:30	134	20	1	2	1	3	0	161
16:45	162	21	2	3	0	1	0	189
1 Hr	586	82	8	12	3	6	3	700

16:00	135	22	10	4	1	1	0	173
16:15	125	32	3	3	2	2	1	168
16:30	151	30	6	4	1	2	0	194
16:45	116	25	5	1	1	0	0	148
1 Hr	527	109	24	12	5	5	1	683

17:00	152	16	1	2	1	2	0	174
17:15	156	17	2	3	0	7	1	186
17:30	151	14	4	4	3	1	0	177
17:45	139	12	3	0	0	0	2	156
1 Hr	598	59	10	9	4	10	3	693

17:00	99	15	5	2	3	1	0	125
17:15	95	14	5	4	3	0	0	121
17:30	121	27	8	2	0	0	0	158
17:45	119	28	7	1	3	2	0	160
1 Hr	434	84	25	9	9	3	0	564

6 Hrs	2928	363	81	102	17	37	13	3541
-------	------	-----	----	-----	----	----	----	------

6 Hrs	2689	450	186	76	27	28	5	3461
-------	------	-----	-----	----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Tuesday 24th June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	127	10	1	1	1	2	0	142
18:15	101	7	3	5	0	0	2	118
18:30	77	9	3	1	0	2	0	92
18:45	79	8	0	1	0	1	1	90
1 Hr	384	34	7	8	1	5	3	442

18:00	84	6	2	5	2	1	0	100
18:15	90	14	5	4	1	3	0	117
18:30	98	10	1	2	0	1	0	112
18:45	88	6	1	4	0	0	0	99
1 Hr	360	36	9	15	3	5	0	428

19:00	82	12	1	3	1	0	0	99
19:15	82	2	1	2	0	3	0	90
19:30	49	7	1	1	0	1	0	59
19:45	75	3	1	2	1	1	0	83
1 Hr	288	24	4	8	2	5	0	331

19:00	70	3	4	0	2	0	1	80
19:15	69	6	1	0	0	0	1	77
19:30	44	4	0	1	1	1	2	53
19:45	55	5	3	1	0	0	0	64
1 Hr	238	18	8	2	3	1	4	274

20:00	87	0	0	0	1	0	1	89
20:15	51	2	0	0	0	0	0	53
20:30	55	5	1	1	0	2	0	64
20:45	62	4	4	1	0	1	2	74
1 Hr	255	11	5	2	1	3	3	280

20:00	38	5	1	1	0	3	0	48
20:15	48	5	1	0	0	0	0	54
20:30	39	4	0	1	1	0	0	45
20:45	26	3	0	0	0	0	0	29
1 Hr	151	17	2	2	1	3	0	176

21:00	57	3	0	0	1	0	0	61
21:15	60	4	0	1	0	0	0	65
21:30	35	1	0	0	0	0	0	36
21:45	58	3	0	0	0	1	0	62
1 Hr	210	11	0	1	1	1	0	224

21:00	31	2	0	1	0	0	0	34
21:15	31	3	1	0	0	1	0	36
21:30	26	3	0	0	0	2	0	31
21:45	24	2	1	0	0	0	0	27
1 Hr	112	10	2	1	0	3	0	128

22:00	42	3	0	0	0	0	0	45
22:15	35	1	1	0	0	1	0	38
22:30	36	0	1	2	0	0	0	39
22:45	28	0	1	0	0	0	0	29
1 Hr	141	4	3	2	0	1	0	151

22:00	18	1	1	0	1	1	0	22
22:15	20	1	1	0	0	0	0	22
22:30	17	1	4	0	0	0	0	22
22:45	12	0	0	0	0	0	0	12
1 Hr	67	3	6	0	1	1	0	78

23:00	19	5	1	0	0	0	0	25
23:15	14	2	2	0	0	0	0	18
23:30	16	0	0	0	0	0	0	16
23:45	12	0	0	0	0	0	0	12
1 Hr	61	7	3	0	0	0	0	71

23:00	7	1	0	3	0	0	0	11
23:15	14	2	0	0	0	0	0	16
23:30	5	0	1	0	0	0	0	6
23:45	7	1	0	0	0	0	0	8
1 Hr	33	4	1	3	0	0	0	41

6 Hrs	1339	91	22	21	5	15	6	1499
-------	------	----	----	----	---	----	---	------

6 Hrs	961	88	28	23	8	13	4	1125
-------	-----	----	----	----	---	----	---	------

12 Hrs	4267	454	103	123	22	52	19	5040
--------	------	-----	-----	-----	----	----	----	------

12 Hrs	3650	538	214	99	35	41	9	4586
--------	------	-----	-----	----	----	----	---	------

Total	6237	946	318	243	54	75	28	8042
-------	------	-----	-----	-----	----	----	----	------

Total	6361	903	340	239	53	80	24	8238
-------	------	-----	-----	-----	----	----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Wednesday 25th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	10	0	0	2	0	0	0	12
00:15	11	1	0	1	0	0	0	13
00:30	6	1	0	1	0	2	0	10
00:45	6	0	0	1	0	0	0	7
1 Hr	33	2	0	5	0	2	0	42
01:00	5	0	0	1	0	0	0	6
01:15	1	0	1	0	0	0	0	2
01:30	4	0	0	0	0	0	0	4
01:45	2	0	0	1	0	0	0	3
1 Hr	12	0	1	2	0	0	0	15
02:00	7	1	0	0	0	1	0	9
02:15	3	1	0	1	0	0	1	6
02:30	3	0	0	0	0	0	0	3
02:45	0	0	1	1	0	0	0	2
1 Hr	13	2	1	2	0	1	1	20
03:00	3	1	0	1	0	0	0	5
03:15	4	0	0	0	0	0	0	4
03:30	2	0	1	1	0	0	0	4
03:45	2	0	1	0	0	0	0	3
1 Hr	11	1	2	2	0	0	0	16
04:00	3	0	1	0	0	0	0	4
04:15	7	1	2	0	0	0	0	10
04:30	6	6	1	3	0	0	0	16
04:45	4	0	5	0	0	0	0	9
1 Hr	20	7	9	3	0	0	0	39
05:00	4	3	2	1	0	0	0	10
05:15	2	0	8	1	0	1	0	12
05:30	11	3	3	5	0	0	0	22
05:45	22	6	4	1	0	0	1	34
1 Hr	39	12	17	8	0	1	1	78
6 Hrs	128	24	30	22	0	4	2	210

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	3	0	0	0	0	0	0	3
00:15	4	2	0	0	0	0	0	6
00:30	5	1	1	1	0	0	0	8
00:45	0	0	1	1	0	0	0	2
1 Hr	12	3	2	2	0	0	0	19
01:00	3	0	0	0	0	0	0	3
01:15	4	1	0	1	0	0	0	6
01:30	2	1	0	1	0	0	0	4
01:45	3	0	1	0	0	0	0	4
1 Hr	12	2	1	2	0	0	0	17
02:00	1	2	0	0	0	0	0	3
02:15	3	2	0	1	0	0	0	6
02:30	3	0	0	2	0	0	0	5
02:45	1	0	0	1	0	0	0	2
1 Hr	8	4	0	4	0	0	0	16
03:00	6	0	0	0	0	0	0	6
03:15	3	0	0	0	0	0	0	3
03:30	0	0	1	1	0	0	0	2
03:45	4	0	1	1	0	0	0	6
1 Hr	13	0	2	2	0	0	0	17
04:00	7	2	0	1	0	0	0	10
04:15	6	0	0	3	0	0	0	9
04:30	9	3	1	3	0	0	0	16
04:45	7	2	0	4	0	0	0	13
1 Hr	29	7	1	11	0	0	0	48
05:00	8	5	0	4	0	0	1	18
05:15	17	3	4	3	0	0	0	27
05:30	22	5	0	5	1	0	1	34
05:45	29	7	2	3	0	1	0	42
1 Hr	76	20	6	15	1	1	2	121
6 Hrs	150	36	12	36	1	1	2	238

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	1	0	0	1
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	1	0	0	1
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	0	0	0	0
18:00	0	0	0	0
18:15	2	0	0	2
18:30	1	0	0	1
18:45	0	0	0	0
1 Hr	3	0	0	3
3 Hrs	4	0	0	4
6 Hrs	4	0	0	4

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	1	0	1
1 Hr	1	0	1
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	1	0	1
16:00	1	0	1
16:15	0	0	0
16:30	2	0	2
16:45	0	0	0
1 Hr	3	0	3
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	0	0	0
18:30	0	0	0
18:45	0	0	0
1 Hr	0	0	0
3 Hrs	3	0	3
6 Hrs	4	0	4



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Wednesday 25th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	17	10	2	1	1	0	0	31
06:15	21	10	7	2	2	0	0	42
06:30	34	18	8	6	1	1	0	68
06:45	31	23	10	7	0	0	0	71
1 Hr	103	61	27	16	4	1	0	212

27	5	1	6	0	0	0	39
41	18	2	7	0	2	0	70
81	11	1	6	1	2	1	103
80	22	4	1	0	1	0	108
229	56	8	20	1	5	1	320

07:00	66	22	11	2	1	0	0	102
07:15	75	35	18	3	2	1	0	134
07:30	66	22	4	6	1	1	0	100
07:45	89	29	13	4	0	0	0	135
1 Hr	296	108	46	15	4	2	0	471

53	15	0	6	0	1	0	75
141	43	7	6	1	0	2	200
148	21	7	4	0	1	1	182
170	14	4	3	1	3	0	195
512	93	18	19	2	5	3	652

08:00	82	22	11	6	0	0	0	121
08:15	94	20	7	4	0	0	0	125
08:30	106	13	10	4	0	0	0	133
08:45	104	29	10	6	0	1	0	150
1 Hr	304	62	27	14	0	1	0	529

169	18	4	2	2	2	0	197
156	13	10	1	3	2	0	185
148	19	7	3	3	2	1	183
157	13	12	4	0	4	1	191
461	45	29	8	6	8	2	756

09:00	97	29	13	6	2	6	0	153
09:15	94	27	15	2	6	1	1	146
09:30	111	18	9	2	3	0	0	143
09:45	86	15	12	2	3	3	0	121
1 Hr	388	89	49	12	14	10	1	563

162	11	4	5	0	0	1	183
135	7	7	3	0	2	0	154
124	7	10	6	1	0	0	148
132	13	5	8	3	2	0	163
553	38	26	22	4	4	1	648

10:00	119	11	10	4	2	1	0	147
10:15	117	14	13	5	4	1	0	154
10:30	128	13	13	6	1	5	0	166
10:45	132	17	7	2	0	2	0	160
1 Hr	496	55	43	17	7	9	0	627

120	15	8	7	1	0	0	151
108	13	6	8	1	1	0	137
125	15	10	5	2	2	0	159
101	12	5	7	2	1	0	128
454	55	29	27	6	4	0	575

11:00	123	23	5	3	1	3	0	158
11:15	108	18	7	4	2	1	0	140
11:30	123	13	6	2	0	3	0	147
11:45	109	21	5	3	0	1	0	139
1 Hr	463	75	23	12	3	8	0	584

125	8	7	1	1	0	0	142
106	13	8	2	0	0	1	130
120	11	5	1	2	1	0	140
94	14	6	4	1	2	0	121
445	46	26	8	4	3	1	533

6 Hrs	2050	450	215	86	32	31	1	2986
-------	------	-----	-----	----	----	----	---	------

2654	333	136	104	23	29	8	3484
------	-----	-----	-----	----	----	---	------

12 Hrs	2178	474	245	108	32	35	3	3196
--------	------	-----	-----	-----	----	----	---	------

2804	369	148	140	24	30	10	3722
------	-----	-----	-----	----	----	----	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Wednesday 25th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	86	18	3	2	0	10	0	119
12:15	117	14	2	6	1	0	1	141
12:30	122	11	5	4	0	0	0	142
12:45	101	13	8	2	1	2	0	127
1 Hr	426	56	18	14	2	12	1	529

118	10	8	4	0	2	0	142
105	15	4	9	0	0	0	133
106	16	4	5	1	0	0	132
103	10	9	3	1	0	0	126
432	51	25	21	2	2	0	533

13:00	89	10	8	6	0	1	0	114
13:15	110	13	8	5	2	1	1	140
13:30	118	9	4	4	0	1	0	136
13:45	107	15	5	12	0	1	0	140
1 Hr	424	47	25	27	2	4	1	530

111	4	9	5	0	1	0	130
113	17	6	2	0	1	0	139
100	18	6	4	1	1	1	131
78	20	6	2	0	0	1	107
402	59	27	13	1	3	2	507

14:00	129	14	3	4	0	3	0	153
14:15	87	23	6	1	1	2	1	121
14:30	121	10	4	1	2	4	0	142
14:45	111	11	7	7	0	0	0	136
1 Hr	448	58	20	13	3	9	1	552

108	21	8	1	1	1	0	140
77	12	6	1	1	1	0	98
93	8	4	1	4	4	0	114
69	18	3	3	0	0	0	93
347	59	21	6	6	6	0	445

15:00	129	10	4	2	0	2	1	148
15:15	144	11	3	6	2	3	0	169
15:30	141	12	1	9	0	3	0	166
15:45	128	22	4	1	0	1	0	156
1 Hr	542	55	12	18	2	9	1	639

145	20	10	6	0	2	0	183
113	14	5	7	0	1	0	140
117	25	9	5	0	2	0	158
108	20	6	2	1	1	0	138
483	79	30	20	1	6	0	619

16:00	141	23	5	4	0	3	0	176
16:15	158	18	2	4	0	2	1	185
16:30	150	24	4	1	2	10	2	193
16:45	160	15	2	2	0	2	2	183
1 Hr	609	80	13	11	2	17	5	737

107	21	5	3	1	0	0	137
133	27	6	3	1	4	0	174
115	19	1	2	1	1	0	139
106	19	3	4	2	2	0	136
461	86	15	12	5	7	0	586

17:00	157	25	4	1	1	3	2	193
17:15	158	20	0	3	1	12	1	195
17:30	167	18	3	2	2	5	1	198
17:45	134	21	1	2	1	14	0	173
1 Hr	616	84	8	8	5	34	4	759

142	21	7	4	2	3	0	179
112	21	11	2	0	1	0	147
110	17	2	6	1	6	0	142
132	27	3	4	0	3	1	170
496	86	23	16	3	13	1	638

6 Hrs	3065	380	96	91	16	85	13	3746
-------	------	-----	----	----	----	----	----	------

2621	420	141	88	18	37	3	3328
------	-----	-----	----	----	----	---	------

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	137	20	1	5	0	14	0	177
18:15	129	15	0	4	2	11	1	162
18:30	109	16	3	2	0	18	0	148
18:45	134	12	1	3	0	16	1	167
1 Hr	509	63	5	14	2	59	2	654

18:00	134	22	5	2	3	3	0	169
18:15	109	6	3	3	4	5	0	130
18:30	125	14	0	3	3	1	0	146
18:45	89	6	5	3	2	4	0	109
1 Hr	457	48	13	11	12	13	0	554

19:00	107	4	1	0	1	4	0	117
19:15	100	7	2	2	0	4	0	115
19:30	98	8	0	1	0	2	0	109
19:45	92	9	2	0	1	1	0	105
1 Hr	397	28	5	3	2	11	0	446

19:00	78	6	5	1	2	3	0	95
19:15	93	9	0	0	0	1	1	104
19:30	82	11	0	0	1	5	0	99
19:45	47	2	0	1	0	3	1	54
1 Hr	300	28	5	2	3	12	2	352

20:00	71	4	1	1	1	2	1	81
20:15	56	6	0	1	0	3	0	66
20:30	56	4	0	1	0	1	0	62
20:45	51	7	0	0	0	1	0	59
1 Hr	234	21	1	3	1	7	1	268

20:00	78	4	0	0	0	1	0	83
20:15	50	2	0	0	0	1	0	53
20:30	39	8	3	1	1	0	0	52
20:45	58	2	1	1	0	18	0	80
1 Hr	225	16	4	2	1	20	0	268

21:00	75	3	0	0	1	0	0	79
21:15	59	5	0	0	0	0	0	64
21:30	57	2	1	1	0	1	0	62
21:45	48	4	2	2	0	1	0	57
1 Hr	239	14	3	3	1	2	0	262

21:00	29	6	2	0	0	18	0	55
21:15	37	4	0	1	0	20	0	62
21:30	27	0	1	1	0	23	0	52
21:45	28	2	0	0	0	17	0	47
1 Hr	121	12	3	2	0	78	0	216

22:00	37	3	2	0	0	0	0	42
22:15	34	2	1	2	0	0	0	39
22:30	31	1	0	1	0	0	0	33
22:45	25	4	0	0	0	2	0	31
1 Hr	127	10	3	3	0	2	0	145

22:00	27	1	1	0	0	16	0	45
22:15	13	2	0	1	0	6	0	22
22:30	26	1	0	1	0	5	0	33
22:45	13	2	0	1	0	0	0	16
1 Hr	79	6	1	3	0	27	0	116

23:00	26	2	0	1	0	0	0	29
23:15	22	1	0	1	0	0	0	24
23:30	24	1	0	0	0	0	0	25
23:45	12	2	1	1	0	0	0	16
1 Hr	84	6	1	3	0	0	0	94

23:00	15	0	0	0	0	0	0	15
23:15	7	2	0	0	0	0	0	9
23:30	13	0	1	1	0	0	0	15
23:45	8	1	0	0	0	0	0	9
1 Hr	43	3	1	1	0	0	0	48

6 Hrs	1590	142	18	29	6	81	3	1869
-------	------	-----	----	----	---	----	---	------

6 Hrs	1225	113	27	21	16	150	2	1554
-------	------	-----	----	----	----	-----	---	------

12 Hrs	4655	522	114	120	22	166	16	5615
--------	------	-----	-----	-----	----	-----	----	------

12 Hrs	3846	533	168	109	34	187	5	4882
--------	------	-----	-----	-----	----	-----	---	------

Total	6833	996	359	228	54	201	19	8811
-------	------	-----	-----	-----	----	-----	----	------

Total	6650	902	316	249	58	217	15	8604
-------	------	-----	-----	-----	----	-----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Thursday 26th June 2014

AM Weather: Mild & Clear
PM Weather: Mild & Clear

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	10	0	0	1	0	0	0	11
00:15	9	1	0	2	0	0	0	12
00:30	5	2	0	0	0	0	0	7
00:45	2	1	0	1	0	0	0	4
1 Hr	26	4	0	4	0	0	0	34
01:00	4	3	0	2	0	0	0	9
01:15	2	3	0	0	0	0	0	5
01:30	2	1	0	0	0	0	0	3
01:45	5	0	0	2	0	0	0	7
1 Hr	13	7	0	4	0	0	0	24
02:00	4	0	1	1	0	0	0	6
02:15	3	0	0	0	0	0	0	3
02:30	5	0	0	1	0	0	0	6
02:45	1	0	0	0	0	0	0	1
1 Hr	13	0	1	2	0	0	0	16
03:00	2	0	1	2	0	0	0	5
03:15	1	0	0	0	0	0	0	1
03:30	1	1	1	2	0	0	0	5
03:45	2	0	0	0	0	0	0	2
1 Hr	6	1	2	4	0	0	0	13
04:00	1	0	0	0	0	0	0	1
04:15	5	0	1	0	0	0	0	6
04:30	7	4	2	2	0	0	0	15
04:45	3	2	1	2	0	0	1	9
1 Hr	16	6	4	4	0	0	1	31
05:00	0	2	3	12	0	1	0	18
05:15	3	2	1	3	0	0	0	9
05:30	12	3	0	8	0	1	0	24
05:45	9	6	0	3	0	0	0	18
1 Hr	24	13	4	26	0	2	0	69
6 Hrs	98	31	11	44	0	2	1	187

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	6	0	0	2	0	0	0	8
00:15	6	1	0	0	0	0	0	7
00:30	4	0	0	1	0	0	0	5
00:45	5	0	0	0	0	0	0	5
1 Hr	21	1	0	3	0	0	0	25
01:00	2	1	1	0	0	0	0	4
01:15	2	1	0	1	0	0	0	4
01:30	0	0	1	0	0	0	0	1
01:45	5	0	0	0	0	0	0	5
1 Hr	9	2	2	1	0	0	0	14
02:00	2	1	0	0	0	0	0	3
02:15	4	0	0	2	0	0	0	6
02:30	0	0	1	1	0	0	0	2
02:45	2	0	0	1	0	0	0	3
1 Hr	8	1	1	4	0	0	0	14
03:00	2	1	0	1	0	1	0	5
03:15	4	0	0	2	0	0	0	6
03:30	1	0	0	0	0	0	0	1
03:45	1	1	0	2	0	0	0	4
1 Hr	8	2	0	5	0	1	0	16
04:00	2	0	0	0	0	0	0	2
04:15	3	0	2	3	0	0	0	8
04:30	10	1	0	5	0	0	0	16
04:45	2	0	0	2	0	0	1	5
1 Hr	17	1	2	10	0	0	1	31
05:00	7	2	0	3	0	0	0	12
05:15	14	3	1	3	0	0	0	21
05:30	24	3	1	3	0	0	0	31
05:45	42	1	2	5	0	1	0	51
1 Hr	87	9	4	14	0	1	0	115
3 Hrs	150	16	9	37	0	2	1	215

	Direction : Eastbound				Total
	Adult	Accompanied Child	Unaccompanied Child		
07:00	0	0	0	0	0
07:15	0	0	0	0	0
07:30	0	0	0	0	0
07:45	0	0	0	0	0
1 Hr	0	0	0	0	0
08:00	0	0	0	0	0
08:15	0	0	0	0	0
08:30	0	0	0	0	0
08:45	0	0	0	0	0
1 Hr	0	0	0	0	0
09:00	0	0	0	0	0
09:15	0	0	0	0	0
09:30	0	0	0	0	0
09:45	0	0	0	0	0
1 Hr	0	0	0	0	0
3 Hr	0	0	0	0	0
16:00	0	0	0	0	0
16:15	0	0	0	0	0
16:30	0	0	0	0	0
16:45	0	0	0	0	0
1 Hr	0	0	0	0	0
17:00	1	0	0	1	1
17:15	1	0	0	1	1
17:30	1	0	0	1	1
17:45	0	0	0	0	0
1 Hr	3	0	0	3	3
18:00	0	0	0	0	0
18:15	0	0	0	0	0
18:30	0	0	0	0	0
18:45	1	0	0	1	1
1 Hr	1	0	0	1	1
3 Hrs	4	0	0	4	4
6 Hrs	4	0	0	4	4

	Direction : Westbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	1	0	0	1
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	1	0	0	1
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	1	0	0	1
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	1	0	0	1
1 Hr	1	0	0	1
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	0	0	0	0
18:00	0	0	0	0
18:15	0	0	0	0
18:30	1	0	0	1
18:45	0	0	0	0
1 Hr	1	0	0	1
3 Hrs	2	0	0	2
6 Hrs	3	0	0	3

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	14	11	9	3	1	0	0	38
06:15	32	14	6	1	2	1	0	56
06:30	36	15	10	6	0	0	0	67
06:45	45	9	13	5	0	0	0	72
1 Hr	127	49	38	15	3	1	0	233

32	5	0	0	0	1	0	38
49	11	3	9	0	2	1	75
82	16	0	5	0	1	0	104
91	19	5	6	0	1	1	123
254	51	8	20	0	5	2	340

07:00	66	12	14	5	2	2	0	101
07:15	75	30	15	3	1	0	0	124
07:30	86	16	12	3	1	1	0	119
07:45	106	27	16	4	1	1	1	156
1 Hr	333	85	57	15	5	4	1	500

84	14	4	2	0	0	2	106
133	42	4	4	1	1	0	185
138	19	5	5	0	2	0	169
132	18	7	3	1	5	2	168
487	93	20	14	2	8	4	628

08:00	87	26	12	5	0	1	0	131
08:15	92	26	16	6	0	2	0	142
08:30	101	16	13	5	0	0	0	135
08:45	82	23	13	5	1	1	0	125
1 Hr	275	65	42	16	1	3	0	533

170	22	3	4	2	1	1	203
108	15	6	1	2	2	0	134
135	13	9	2	0	2	0	161
158	20	6	9	1	0	0	194
401	48	21	12	3	4	0	692

09:00	92	22	4	6	2	1	0	127
09:15	87	16	4	4	2	0	0	113
09:30	107	17	10	2	0	0	1	137
09:45	120	13	10	6	4	0	0	153
1 Hr	406	68	28	18	8	1	1	530

126	17	6	7	0	0	0	156
127	17	10	6	0	1	1	162
120	17	1	6	1	1	0	146
123	16	10	6	1	0	0	156
496	67	27	25	2	2	1	620

10:00	104	17	15	4	5	1	0	146
10:15	120	10	13	4	1	0	0	148
10:30	130	11	7	3	0	1	0	152
10:45	119	19	13	5	1	0	0	157
1 Hr	473	57	48	16	7	2	0	603

103	20	3	2	0	2	0	130
133	25	8	6	1	1	0	174
122	18	4	10	3	1	0	158
116	11	7	1	0	2	0	137
474	74	22	19	4	6	0	599

11:00	147	14	7	5	1	0	0	174
11:15	131	22	7	5	1	1	1	168
11:30	139	18	6	4	1	2	0	170
11:45	125	13	6	1	0	1	0	146
1 Hr	542	67	26	15	3	4	1	658

114	13	8	4	1	1	0	141
108	15	4	5	0	1	0	133
105	18	7	7	1	2	0	140
135	19	5	10	0	2	0	171
462	65	24	26	2	6	0	585

6 Hrs	2156	391	239	95	27	15	3	3057
-------	------	-----	-----	----	----	----	---	------

2574	398	122	116	13	31	7	3464
------	-----	-----	-----	----	----	---	------

12 Hrs	2254	422	250	139	27	17	4	3244
--------	------	-----	-----	-----	----	----	---	------

2724	414	131	153	13	33	8	3679
------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Thursday 26th June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	114	3	8	2	0	0	0	127
12:15	109	16	4	2	2	3	0	136
12:30	126	13	3	7	0	2	0	151
12:45	101	14	7	8	0	1	0	131
1 Hr	450	46	22	19	2	6	0	545

12:00	103	9	9	3	0	1	0	125
12:15	89	10	10	5	0	2	0	116
12:30	83	18	11	4	2	1	0	119
12:45	120	13	4	3	0	0	0	140
1 Hr	395	50	34	15	2	4	0	500

13:00	103	14	7	8	0	1	0	133
13:15	118	11	2	3	2	0	0	136
13:30	108	12	8	5	0	5	0	138
13:45	117	15	6	6	0	1	0	145
1 Hr	446	52	23	22	2	7	0	552

13:00	98	18	9	5	0	0	0	130
13:15	93	12	5	0	1	2	0	113
13:30	109	16	10	9	1	3	1	149
13:45	118	15	12	3	0	3	0	151
1 Hr	418	61	36	17	2	8	1	543

14:00	116	12	3	6	0	1	0	138
14:15	127	11	4	2	2	1	0	147
14:30	108	20	6	4	1	3	0	142
14:45	135	14	4	5	0	2	0	160
1 Hr	486	57	17	17	3	7	0	587

14:00	97	18	5	3	0	6	1	130
14:15	118	16	5	2	2	0	0	143
14:30	95	19	12	4	2	0	0	132
14:45	104	11	5	5	0	0	0	125
1 Hr	414	64	27	14	4	6	1	530

15:00	120	17	3	8	0	1	0	149
15:15	138	18	3	2	1	3	1	166
15:30	120	17	5	4	0	0	0	146
15:45	154	22	7	2	1	2	0	188
1 Hr	532	74	18	16	2	6	1	649

15:00	107	22	10	6	0	1	0	146
15:15	145	20	6	6	0	1	1	179
15:30	136	19	4	6	2	1	0	168
15:45	125	23	5	3	0	1	1	158
1 Hr	513	84	25	21	2	4	2	651

16:00	164	14	2	4	0	2	0	186
16:15	165	20	8	6	2	2	0	203
16:30	156	16	6	2	0	3	0	183
16:45	160	20	2	8	0	0	0	190
1 Hr	645	70	18	20	2	7	0	762

16:00	106	30	5	4	1	3	0	149
16:15	114	23	6	7	0	1	0	151
16:30	147	32	4	4	2	3	0	192
16:45	114	29	7	4	2	2	0	158
1 Hr	481	114	22	19	5	9	0	650

17:00	170	21	1	5	1	3	0	201
17:15	164	15	0	0	1	4	0	184
17:30	166	19	3	2	2	2	0	194
17:45	164	16	2	4	0	1	0	187
1 Hr	664	71	6	11	4	10	0	766

17:00	107	22	2	4	1	0	0	136
17:15	130	19	5	2	3	2	1	162
17:30	109	15	6	0	3	4	0	137
17:45	125	18	3	2	3	4	1	156
1 Hr	471	74	16	8	10	10	2	591

6 Hrs	3223	370	104	105	15	43	1	3861
-------	------	-----	-----	-----	----	----	---	------

6 Hrs	2692	447	160	94	25	41	6	3465
-------	------	-----	-----	----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Thursday 26th June 2014

AM Weather: Mild & Clear
 PM Weather: Mild & Clear

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	161	14	2	0	0	4	0	181
18:15	135	9	0	4	1	3	0	152
18:30	118	9	1	2	0	2	0	132
18:45	128	8	2	0	0	0	0	138
1 Hr	542	40	5	6	1	9	0	603

18:00	103	25	4	2	3	1	0	138
18:15	105	14	3	2	2	0	1	127
18:30	115	16	0	2	1	0	0	134
18:45	86	9	0	5	0	2	0	102
1 Hr	409	64	7	11	6	3	1	501

19:00	107	14	3	3	1	2	0	130
19:15	120	4	1	2	0	1	0	128
19:30	96	5	2	1	0	2	0	106
19:45	110	4	1	2	1	0	0	118
1 Hr	433	27	7	8	2	5	0	482

19:00	104	14	2	5	1	1	0	127
19:15	80	8	3	1	1	0	1	94
19:30	70	5	3	1	1	2	0	82
19:45	55	3	1	0	0	2	0	61
1 Hr	309	30	9	7	3	5	1	364

20:00	112	4	1	2	1	5	0	125
20:15	79	4	2	0	0	3	0	88
20:30	66	5	1	0	1	1	0	74
20:45	58	7	2	0	0	2	0	69
1 Hr	315	20	6	2	2	11	0	356

20:00	57	2	1	3	0	3	0	66
20:15	46	4	0	1	0	0	1	52
20:30	53	2	1	4	1	3	0	64
20:45	52	4	1	0	0	0	0	57
1 Hr	208	12	3	8	1	6	1	239

21:00	59	1	0	0	1	2	0	63
21:15	68	3	1	0	0	0	0	72
21:30	55	2	0	1	0	0	0	58
21:45	52	4	0	1	0	0	0	57
1 Hr	234	10	1	2	1	2	0	250

21:00	41	1	1	0	0	1	0	44
21:15	28	2	0	2	0	1	0	33
21:30	23	2	1	1	0	2	0	29
21:45	40	2	0	0	0	0	0	42
1 Hr	132	7	2	3	0	4	0	148

22:00	43	1	0	1	0	2	0	47
22:15	36	3	2	0	0	0	1	42
22:30	47	4	0	0	0	0	0	51
22:45	32	2	0	0	1	0	0	35
1 Hr	158	10	2	1	1	2	1	175

22:00	24	2	1	0	0	0	0	27
22:15	25	1	1	0	0	0	0	27
22:30	19	0	0	0	0	0	0	19
22:45	19	1	0	1	0	0	0	21
1 Hr	87	4	2	1	0	0	0	94

23:00	20	1	0	0	0	0	0	21
23:15	24	2	0	1	0	0	0	27
23:30	17	0	0	0	0	1	0	18
23:45	10	0	0	1	0	0	0	11
1 Hr	71	3	0	2	0	1	0	77

23:00	15	1	0	0	0	0	0	16
23:15	11	0	0	1	0	0	0	12
23:30	10	1	1	0	0	0	0	12
23:45	8	0	0	0	0	0	0	8
1 Hr	44	2	1	1	0	0	0	48

6 Hrs	1753	110	21	21	7	30	1	1943
-------	------	-----	----	----	---	----	---	------

6 Hrs	1189	119	24	31	10	18	3	1394
-------	------	-----	----	----	----	----	---	------

12 Hrs	4976	480	125	126	22	73	2	5804
--------	------	-----	-----	-----	----	----	---	------

12 Hrs	3881	566	184	125	35	59	9	4859
--------	------	-----	-----	-----	----	----	---	------

Total	7230	902	375	265	49	90	6	9048
-------	------	-----	-----	-----	----	----	---	------

Total	6605	980	315	278	48	92	17	8538
-------	------	-----	-----	-----	----	----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Friday 27th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Light Rain

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	14	0	1	3	0	0	0	18
00:15	10	2	1	3	0	0	0	16
00:30	7	1	1	1	0	0	0	10
00:45	3	0	1	0	0	0	0	4
1 Hr	34	3	4	7	0	0	0	48
01:00	9	1	1	1	0	0	0	12
01:15	5	1	0	0	0	0	0	6
01:30	7	1	0	0	0	0	0	8
01:45	6	0	2	0	0	0	0	8
1 Hr	27	3	3	1	0	0	0	34
02:00	5	2	0	0	0	1	0	8
02:15	5	1	1	2	0	0	0	9
02:30	3	0	0	2	0	0	0	5
02:45	3	0	0	0	0	0	0	3
1 Hr	16	3	1	4	0	1	0	25
03:00	2	1	0	1	0	0	0	4
03:15	2	1	3	0	0	1	0	7
03:30	2	0	0	0	0	0	0	2
03:45	5	0	0	1	0	0	0	6
1 Hr	11	2	3	2	0	1	0	19
04:00	2	1	1	0	0	0	0	4
04:15	4	0	3	1	0	0	0	8
04:30	2	2	0	2	0	0	0	6
04:45	3	5	0	2	0	0	1	11
1 Hr	11	8	4	5	0	0	1	29
05:00	0	1	2	1	1	0	0	5
05:15	7	2	3	1	0	0	0	13
05:30	11	4	0	3	0	0	0	18
05:45	12	7	6	3	0	0	0	28
1 Hr	30	14	11	8	1	0	0	64
6 Hrs	129	33	26	27	1	2	1	219

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	10	0	0	2	1	0	0	13
00:15	5	1	0	0	0	0	0	6
00:30	3	0	0	1	0	1	0	5
00:45	5	2	0	1	0	0	0	8
1 Hr	23	3	0	4	1	1	0	32
01:00	1	3	0	0	0	0	0	4
01:15	3	0	1	0	0	0	0	4
01:30	0	0	0	0	0	0	0	0
01:45	3	0	1	1	0	0	0	5
1 Hr	7	3	2	1	0	0	0	13
02:00	2	1	0	0	0	0	0	3
02:15	1	0	0	0	0	0	0	1
02:30	0	0	1	1	0	0	0	2
02:45	1	0	0	0	0	1	0	2
1 Hr	4	1	1	1	0	1	0	8
03:00	1	2	0	1	0	0	0	4
03:15	3	0	0	1	0	0	0	4
03:30	4	1	0	1	0	0	0	6
03:45	7	2	0	0	0	0	0	9
1 Hr	15	5	0	3	0	0	0	23
04:00	3	0	0	2	0	0	0	5
04:15	2	1	1	1	0	0	0	5
04:30	2	0	0	17	0	0	0	19
04:45	4	1	1	1	0	0	0	7
1 Hr	11	2	2	21	0	0	0	36
05:00	17	5	2	3	0	0	0	27
05:15	14	1	2	2	0	0	0	19
05:30	13	5	1	3	0	0	0	22
05:45	30	5	2	6	0	0	0	43
1 Hr	74	16	7	14	0	0	0	111
6 Hrs	134	30	12	44	1	2	0	223

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	0	0	0	0
16:00	0	0	0	0
16:15	0	0	0	0
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	0	0	0	0
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	0	0	0	0
1 Hr	0	0	0	0
18:00	2	0	0	2
18:15	0	0	0	0
18:30	0	0	0	0
18:45	1	0	0	1
1 Hr	3	0	0	3
3 Hrs	3	0	0	3
6 Hrs	3	0	0	3

	Direction : Westbound		Total
	Accompanied Child	Unaccompanied Child	
07:00	0	0	0
07:15	0	0	0
07:30	0	0	0
07:45	0	0	0
1 Hr	0	0	0
08:00	0	0	0
08:15	0	0	0
08:30	0	0	0
08:45	0	0	0
1 Hr	0	0	0
09:00	0	0	0
09:15	0	0	0
09:30	0	0	0
09:45	0	0	0
1 Hr	0	0	0
3 Hr	0	0	0
16:00	0	0	0
16:15	0	0	0
16:30	0	0	0
16:45	0	0	0
1 Hr	0	0	0
17:00	0	0	0
17:15	0	0	0
17:30	0	0	0
17:45	0	0	0
1 Hr	0	0	0
18:00	0	0	0
18:15	1	0	1
18:30	0	0	0
18:45	0	0	0
1 Hr	1	0	1
3 Hrs	1	0	1
6 Hrs	1	0	1



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Friday 27th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Light Rain

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	15	6	3	9	1	0	0	34
06:15	28	4	3	7	2	0	0	44
06:30	30	17	7	8	0	1	1	64
06:45	52	26	6	8	1	0	0	93
1 Hr	125	53	19	32	4	1	1	235

32	7	1	5	0	1	0	46
41	12	2	5	0	1	0	61
58	17	3	3	0	0	0	81
88	31	0	3	1	1	0	124
219	67	6	16	1	3	0	312

07:00	56	19	10	5	2	0	0	92
07:15	60	21	12	4	1	1	0	99
07:30	83	29	17	3	1	0	0	133
07:45	89	23	11	5	0	1	1	130
1 Hr	288	92	50	17	4	2	1	454

81	17	6	3	0	0	1	108
112	26	4	5	1	1	1	150
138	17	4	4	0	1	0	164
162	16	3	4	2	2	1	190
493	76	17	16	3	4	3	612

08:00	75	16	8	8	1	0	0	108
08:15	96	20	13	3	0	0	0	132
08:30	86	22	9	8	0	1	0	126
08:45	91	21	7	5	2	0	0	126
1 Hr	273	63	29	16	2	1	0	492

175	17	6	2	2	5	0	207
149	13	10	1	3	2	1	179
143	16	2	6	0	0	0	167
137	11	7	4	0	1	1	161
429	40	19	11	3	3	2	714

09:00	87	17	8	4	1	0	0	117
09:15	95	17	10	8	0	0	0	130
09:30	106	16	11	4	1	0	0	138
09:45	91	14	11	3	2	3	0	124
1 Hr	379	64	40	19	4	3	0	509

141	7	11	5	0	1	2	167
142	17	7	7	1	3	0	177
138	19	11	5	1	0	1	175
147	12	11	8	1	0	0	179
568	55	40	25	3	4	3	698

10:00	119	24	3	2	1	1	0	150
10:15	108	16	10	3	3	0	0	140
10:30	146	15	8	3	0	2	0	174
10:45	139	14	11	2	1	0	0	167
1 Hr	512	69	32	10	5	3	0	631

142	11	9	1	2	0	0	165
137	19	5	7	1	2	0	171
172	17	9	4	2	0	0	204
195	16	8	3	1	1	0	224
646	63	31	15	6	3	0	764

11:00	160	11	12	6	0	3	0	192
11:15	175	17	4	1	2	2	0	201
11:30	155	16	5	6	1	1	0	184
11:45	144	18	4	4	1	3	0	174
1 Hr	634	62	25	17	4	9	0	751

176	18	5	6	0	0	0	205
180	13	8	3	0	0	0	204
193	23	10	3	1	0	0	230
156	9	3	2	1	0	0	171
705	63	26	14	2	0	0	810

6 Hrs	2211	403	195	111	23	19	2	3072
-------	------	-----	-----	-----	----	----	---	------

3060	364	139	97	18	17	8	3910
------	-----	-----	----	----	----	---	------

12 Hrs	2340	436	221	138	24	21	3	3291
--------	------	-----	-----	-----	----	----	---	------

3194	394	151	141	19	19	8	4133
------	-----	-----	-----	----	----	---	------



Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Friday 27th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Light Rain

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	156	17	7	4	0	0	0	184
12:15	170	17	4	4	1	5	0	201
12:30	161	21	3	10	0	1	0	196
12:45	160	19	2	3	1	0	0	185
1 Hr	647	74	16	21	2	6	0	766

12:00	153	13	5	1	0	1	0	173
12:15	137	18	6	2	0	0	0	163
12:30	132	15	10	3	2	1	0	163
12:45	162	15	5	4	0	0	0	186
1 Hr	584	61	26	10	2	2	0	685

13:00	154	11	7	3	2	1	0	178
13:15	156	14	4	4	2	0	0	180
13:30	163	20	3	2	0	0	0	188
13:45	173	13	6	6	1	0	0	199
1 Hr	646	58	20	15	5	1	0	745

13:00	135	24	17	4	0	0	0	180
13:15	134	21	8	2	0	0	0	165
13:30	140	23	11	0	1	1	1	177
13:45	115	16	9	5	1	1	0	147
1 Hr	524	84	45	11	2	2	1	669

14:00	159	17	7	5	0	1	0	189
14:15	160	17	5	5	1	1	0	189
14:30	198	13	1	3	1	0	0	216
14:45	190	12	5	4	1	0	1	213
1 Hr	707	59	18	17	3	2	1	807

14:00	124	24	7	5	0	1	0	161
14:15	120	26	7	2	0	0	0	155
14:30	122	30	5	6	5	0	0	168
14:45	112	14	5	1	0	3	0	135
1 Hr	478	94	24	14	5	4	0	619

15:00	190	9	8	6	1	2	0	216
15:15	176	15	3	3	1	2	0	200
15:30	176	15	8	5	0	1	0	205
15:45	226	23	4	7	0	0	0	260
1 Hr	768	62	23	21	2	5	0	881

15:00	108	13	7	1	2	3	0	134
15:15	133	22	7	1	1	0	0	164
15:30	112	20	4	2	1	2	0	141
15:45	120	16	7	3	5	0	1	152
1 Hr	473	71	25	7	9	5	1	591

16:00	204	22	10	4	0	3	0	243
16:15	204	17	4	3	2	1	0	231
16:30	213	22	6	3	1	0	0	245
16:45	226	16	5	0	0	3	0	250
1 Hr	847	77	25	10	3	7	0	969

16:00	115	27	5	1	0	0	1	149
16:15	120	23	8	2	3	1	1	158
16:30	130	27	3	0	3	1	0	164
16:45	109	11	6	5	0	0	0	131
1 Hr	474	88	22	8	6	2	2	602

17:00	203	23	4	0	0	7	1	238
17:15	243	15	2	3	1	0	1	265
17:30	202	7	2	0	3	0	2	216
17:45	245	13	3	2	1	3	0	267
1 Hr	893	58	11	5	5	10	4	986

17:00	133	21	5	4	3	0	0	166
17:15	102	14	2	1	4	0	0	123
17:30	114	15	6	0	2	0	0	137
17:45	128	10	3	2	0	0	1	144
1 Hr	477	60	16	7	9	0	1	570

6 Hrs	4508	388	113	89	20	31	5	5154
-------	------	-----	-----	----	----	----	---	------

6 Hrs	3010	458	158	57	33	15	5	3736
-------	------	-----	-----	----	----	----	---	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Friday 27th June 2014

AM Weather: Mild & Cloudy
 PM Weather: Mild & Light Rain

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	213	23	7	3	1	0	0	247
18:15	218	12	2	1	2	0	0	235
18:30	215	20	0	2	0	1	0	238
18:45	264	16	2	5	0	0	0	287
1 Hr	910	71	11	11	3	1	0	1007

18:00	96	13	2	0	1	0	0	112
18:15	100	5	1	2	1	0	0	109
18:30	127	12	2	2	1	0	0	144
18:45	102	13	1	2	0	0	0	118
1 Hr	425	43	6	6	3	0	0	483

19:00	199	12	0	3	0	0	0	214
19:15	216	14	1	1	1	1	0	234
19:30	192	8	2	3	0	1	0	206
19:45	147	11	2	0	0	1	0	161
1 Hr	754	45	5	7	1	3	0	815

19:00	73	4	3	2	2	0	0	84
19:15	95	4	0	1	0	1	0	101
19:30	77	5	2	1	1	0	0	86
19:45	43	3	0	0	0	1	0	47
1 Hr	288	16	5	4	3	2	0	318

20:00	122	5	1	0	1	0	0	129
20:15	85	10	0	0	1	0	1	97
20:30	123	11	4	0	0	0	0	138
20:45	122	11	0	0	0	0	0	133
1 Hr	452	37	5	0	2	0	1	497

20:00	56	8	1	1	1	0	0	67
20:15	54	3	1	0	0	0	0	58
20:30	49	2	1	2	1	0	0	55
20:45	50	3	1	0	0	1	1	56
1 Hr	209	16	4	3	2	1	1	236

21:00	82	6	0	0	2	0	0	90
21:15	89	7	1	0	0	0	0	97
21:30	91	7	0	1	0	0	0	99
21:45	64	6	0	0	0	0	0	70
1 Hr	326	26	1	1	2	0	0	356

21:00	38	2	0	0	0	0	0	40
21:15	35	3	0	1	0	0	0	39
21:30	29	0	0	2	0	1	0	32
21:45	39	4	1	0	0	0	0	44
1 Hr	141	9	1	3	0	1	0	155

22:00	45	2	2	1	0	0	0	50
22:15	52	2	0	0	1	0	0	55
22:30	47	1	0	0	0	1	0	49
22:45	35	1	1	1	0	0	0	38
1 Hr	179	6	3	2	1	1	0	192

22:00	28	2	2	1	0	0	0	33
22:15	34	2	2	0	0	0	0	38
22:30	25	1	1	0	1	0	0	28
22:45	21	0	0	0	0	0	0	21
1 Hr	108	5	5	1	1	0	0	120

23:00	34	2	0	1	0	0	0	37
23:15	39	1	1	1	0	0	0	42
23:30	25	2	0	1	0	0	0	28
23:45	24	1	0	0	0	0	1	26
1 Hr	122	6	1	3	0	0	1	133

23:00	17	1	0	0	0	0	0	18
23:15	19	1	2	0	0	0	0	22
23:30	20	0	0	1	0	0	0	21
23:45	12	3	0	1	0	0	0	16
1 Hr	68	5	2	2	0	0	0	77

6 Hrs	2743	191	26	24	9	5	2	3000
-------	------	-----	----	----	---	---	---	------

6 Hrs	1239	94	23	19	9	4	1	1389
-------	------	----	----	----	---	---	---	------

12 Hrs	7251	579	139	113	29	36	7	8154
--------	------	-----	-----	-----	----	----	---	------

12 Hrs	4249	552	181	76	42	19	6	5125
--------	------	-----	-----	----	----	----	---	------

Total	9591	1015	360	251	53	57	10	11445
-------	------	------	-----	-----	----	----	----	-------

Total	7443	946	332	217	61	38	14	9258
-------	------	-----	-----	-----	----	----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 28th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	21	0	0	1	0	0	0	22
00:15	16	2	0	0	0	0	0	18
00:30	21	0	2	0	1	0	0	24
00:45	13	0	0	0	0	0	0	13
1 Hr	71	2	2	1	1	0	0	77
01:00	10	1	0	1	0	0	0	12
01:15	5	0	0	0	0	0	0	5
01:30	3	0	0	0	0	0	0	3
01:45	7	0	0	0	0	0	0	7
1 Hr	25	1	0	1	0	0	0	27
02:00	7	0	0	1	0	0	0	8
02:15	10	0	0	0	0	0	0	10
02:30	3	1	3	1	0	0	0	8
02:45	5	0	0	1	0	0	0	6
1 Hr	25	1	3	3	0	0	0	32
03:00	1	0	1	1	0	0	0	3
03:15	9	0	0	0	0	0	0	9
03:30	8	0	0	0	0	0	0	8
03:45	2	0	0	1	0	0	0	3
1 Hr	20	0	1	2	0	0	0	23
04:00	11	2	2	1	0	0	0	16
04:15	3	2	0	0	0	1	0	6
04:30	4	4	1	3	0	0	0	12
04:45	4	1	1	0	0	0	0	6
1 Hr	22	9	4	4	0	1	0	40
05:00	3	2	1	3	0	0	0	9
05:15	6	1	2	3	0	0	0	12
05:30	2	0	0	3	0	0	0	5
05:45	11	3	2	4	0	0	0	20
1 Hr	22	6	5	13	0	0	0	46
6 Hrs	185	19	15	24	1	1	0	245

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	11	2	1	0	0	0	0	14
00:15	11	1	0	0	0	0	1	13
00:30	6	0	0	1	0	0	0	7
00:45	7	1	1	1	0	0	0	10
1 Hr	35	4	2	2	0	0	1	44
01:00	5	2	0	0	0	0	1	8
01:15	9	0	0	0	0	0	0	9
01:30	12	0	0	2	0	0	0	14
01:45	5	0	0	0	0	0	0	5
1 Hr	31	2	0	2	0	0	1	36
02:00	4	0	0	0	0	0	0	4
02:15	1	0	0	0	0	0	0	1
02:30	2	0	0	0	0	0	0	2
02:45	6	0	1	0	0	1	0	8
1 Hr	13	0	1	0	0	1	0	15
03:00	3	0	0	0	0	0	0	3
03:15	1	0	0	0	0	0	0	1
03:30	4	2	1	0	0	0	0	7
03:45	2	0	0	0	0	0	0	2
1 Hr	10	2	1	0	0	0	0	13
04:00	5	0	0	0	0	0	0	5
04:15	5	0	1	0	0	0	0	6
04:30	8	1	0	0	0	0	0	9
04:45	2	1	4	1	0	0	0	8
1 Hr	20	2	5	1	0	0	0	28
05:00	9	0	0	0	0	0	0	9
05:15	7	1	0	1	0	0	0	9
05:30	11	2	1	0	0	2	1	17
05:45	12	4	0	0	0	1	0	17
1 Hr	39	7	1	1	0	3	1	52
6 Hrs	148	17	10	6	0	4	3	188

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	1	0	0	1
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	1	0	0	1
08:00	0	0	0	0
08:15	1	0	0	1
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	1	0	0	1
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	2	0	0	2
16:00	0	0	0	0
16:15	1	0	0	1
16:30	0	0	0	0
16:45	1	0	0	1
1 Hr	2	0	0	2
17:00	0	0	0	0
17:15	0	0	0	0
17:30	1	0	0	1
17:45	1	0	0	1
1 Hr	2	0	0	2
18:00	0	0	0	0
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	0	0	0	0
3 Hrs	4	0	0	4
6 Hrs	6	0	0	6

	Direction : Westbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	1	0	0	1
08:30	0	0	0	0
08:45	2	0	0	2
1 Hr	3	0	0	3
09:00	0	0	0	0
09:15	0	0	0	0
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	0	0	0	0
3 Hr	3	0	0	3
16:00	0	0	0	0
16:15	1	0	0	1
16:30	0	0	0	0
16:45	0	0	0	0
1 Hr	1	0	0	1
17:00	0	0	0	0
17:15	0	0	0	0
17:30	1	0	0	1
17:45	0	0	0	0
1 Hr	1	0	0	1
18:00	0	0	0	0
18:15	0	0	0	0
18:30	0	0	0	0
18:45	1	0	0	1
1 Hr	1	0	0	1
3 Hrs	3	0	0	3
6 Hrs	6	0	0	6



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 28th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	10	3	1	0	0	1	1	16
06:15	24	1	2	1	1	0	0	29
06:30	22	2	4	0	0	1	0	29
06:45	46	8	7	3	1	0	0	65
1 Hr	102	14	14	4	2	2	1	139

20	1	1	1	0	0	0	23
16	2	2	1	0	0	0	21
26	4	0	0	0	0	0	30
34	9	1	2	0	0	0	46
96	16	4	4	0	0	0	120

07:00	46	7	4	0	0	0	0	57
07:15	59	10	8	1	0	0	0	78
07:30	64	10	5	0	0	0	0	79
07:45	57	11	3	0	0	0	0	71
1 Hr	226	38	20	1	0	0	0	285

48	12	2	1	0	0	0	63
49	10	1	2	3	0	1	66
57	7	4	0	0	1	0	69
80	9	2	0	2	0	0	93
234	38	9	3	5	1	1	291

08:00	80	7	1	1	1	0	0	90
08:15	99	11	0	2	0	0	0	112
08:30	86	10	5	1	0	0	0	102
08:45	122	11	3	0	2	3	0	141
1 Hr	307	32	8	3	2	3	0	445

76	6	1	1	0	0	0	84
84	6	5	1	2	0	0	98
144	8	1	0	0	1	0	154
130	15	5	1	0	1	0	152
358	29	11	2	2	2	0	488

09:00	102	11	3	0	1	0	0	117
09:15	148	12	3	1	3	1	0	168
09:30	150	17	4	0	0	2	0	173
09:45	149	2	1	1	2	0	0	155
1 Hr	549	42	11	2	6	3	0	613

132	11	5	0	0	1	0	149
125	3	3	0	0	1	0	132
161	7	4	3	1	1	0	177
202	7	3	3	2	2	0	219
620	28	15	6	3	5	0	677

10:00	144	9	5	1	1	0	0	160
10:15	194	7	4	0	1	0	0	206
10:30	186	11	1	1	0	0	0	199
10:45	197	9	3	2	1	2	0	214
1 Hr	721	36	13	4	3	2	0	779

130	5	0	0	1	0	0	136
191	10	7	1	2	1	0	212
171	11	2	2	2	0	0	188
189	6	9	2	0	0	0	206
681	32	18	5	5	1	0	742

11:00	168	7	1	0	1	3	0	180
11:15	189	10	4	0	1	0	1	205
11:30	201	8	4	0	1	3	0	217
11:45	191	5	2	0	0	0	1	199
1 Hr	749	30	11	0	3	6	2	801

173	7	2	0	0	0	0	182
193	8	3	0	0	4	0	208
187	5	3	2	1	2	0	200
172	14	1	1	0	0	0	188
725	34	9	3	1	6	0	778

6 Hrs	2654	192	77	14	16	16	3	3062
-------	------	-----	----	----	----	----	---	------

2714	177	66	23	16	15	1	3096
------	-----	----	----	----	----	---	------

12 Hrs	2839	211	92	38	17	17	3	3307
--------	------	-----	----	----	----	----	---	------

2862	194	76	29	16	19	4	3284
------	-----	----	----	----	----	---	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Saturday 28th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	177	8	1	1	0	4	0	191
12:15	194	11	2	1	1	2	1	212
12:30	182	8	1	0	0	0	1	192
12:45	172	9	2	0	0	3	0	186
1 Hr	725	36	6	2	1	9	2	781

12:00	142	8	2	0	0	3	1	156
12:15	132	8	1	0	0	1	0	142
12:30	146	13	2	0	2	1	0	164
12:45	149	6	1	0	1	1	0	158
1 Hr	569	35	6	0	3	6	1	620

13:00	146	7	1	0	1	0	0	155
13:15	176	7	0	0	1	2	0	186
13:30	179	7	0	2	0	1	1	190
13:45	172	3	0	1	0	4	0	180
1 Hr	673	24	1	3	2	7	1	711

13:00	135	12	1	0	0	3	0	151
13:15	149	10	1	2	0	0	0	162
13:30	139	8	2	0	1	0	0	150
13:45	117	9	2	0	0	3	0	131
1 Hr	540	39	6	2	1	6	0	594

14:00	179	3	2	2	1	1	0	188
14:15	181	10	2	1	2	1	0	197
14:30	145	6	1	0	0	3	0	155
14:45	158	9	1	0	0	0	0	168
1 Hr	663	28	6	3	3	5	0	708

14:00	126	14	2	2	0	0	0	144
14:15	119	7	3	1	1	6	0	137
14:30	102	10	2	2	1	0	0	117
14:45	115	6	1	0	0	5	0	127
1 Hr	462	37	8	5	2	11	0	525

15:00	174	7	0	2	0	2	0	185
15:15	178	8	3	0	1	3	0	193
15:30	167	1	1	0	0	5	2	176
15:45	165	5	0	0	0	0	0	170
1 Hr	684	21	4	2	1	10	2	724

15:00	115	3	1	0	0	3	0	122
15:15	125	6	0	1	0	0	0	132
15:30	105	2	2	2	2	5	1	119
15:45	104	6	3	0	0	1	0	114
1 Hr	449	17	6	3	2	9	1	487

16:00	172	7	0	2	0	3	1	185
16:15	176	7	1	0	2	2	1	189
16:30	187	3	0	1	0	3	0	194
16:45	160	1	0	1	1	1	0	164
1 Hr	695	18	1	4	3	9	2	732

16:00	115	7	2	0	1	1	0	126
16:15	113	5	0	2	0	1	0	121
16:30	108	4	1	1	1	0	0	115
16:45	109	6	5	0	1	0	0	121
1 Hr	445	22	8	3	3	2	0	483

17:00	159	5	0	1	0	0	1	166
17:15	162	14	1	1	1	1	0	180
17:30	170	8	0	0	1	3	0	182
17:45	148	8	0	0	0	2	2	160
1 Hr	639	35	1	2	2	6	3	688

17:00	141	3	1	0	0	0	0	145
17:15	122	5	1	0	0	1	0	129
17:30	106	6	1	1	1	0	0	115
17:45	107	5	0	0	2	3	0	117
1 Hr	476	19	3	1	3	4	0	506

6 Hrs	4079	162	19	16	12	46	10	4344
-------	------	-----	----	----	----	----	----	------

6 Hrs	2941	169	37	14	14	38	2	3215
-------	------	-----	----	----	----	----	---	------

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	120	9	1	1	1	1	0	133
18:15	147	4	0	0	0	2	0	153
18:30	123	5	0	0	0	2	1	131
18:45	121	4	0	0	2	1	0	128
1 Hr	511	22	1	1	3	6	1	545

18:00	151	11	1	0	1	0	0	164
18:15	112	9	0	2	1	1	0	125
18:30	95	3	0	1	2	1	0	102
18:45	120	3	1	0	1	0	0	125
1 Hr	478	26	2	3	5	2	0	516

19:00	79	2	1	2	1	1	0	86
19:15	88	2	0	0	1	1	0	92
19:30	74	4	1	1	0	1	0	81
19:45	88	1	1	0	2	2	0	94
1 Hr	329	9	3	3	4	5	0	353

19:00	122	10	2	0	2	2	0	138
19:15	86	7	0	1	1	1	0	96
19:30	77	2	1	0	2	2	0	84
19:45	95	5	0	0	1	1	0	102
1 Hr	380	24	3	1	6	6	0	420

20:00	65	3	2	0	1	0	0	71
20:15	63	6	0	0	0	0	0	69
20:30	47	2	0	0	0	0	0	49
20:45	54	5	0	0	0	0	0	59
1 Hr	229	16	2	0	1	0	0	248

20:00	82	9	2	1	0	0	0	94
20:15	49	1	0	2	0	0	0	52
20:30	53	2	0	2	1	1	0	59
20:45	47	3	0	0	0	0	0	50
1 Hr	231	15	2	5	1	1	0	255

21:00	48	4	1	0	1	0	0	54
21:15	56	3	0	1	0	0	0	60
21:30	47	3	0	0	0	0	0	50
21:45	50	1	0	0	0	0	0	51
1 Hr	201	11	1	1	1	0	0	215

21:00	45	4	0	0	0	0	0	49
21:15	57	2	1	0	0	0	0	60
21:30	48	2	0	0	0	1	0	51
21:45	42	2	0	0	0	0	0	44
1 Hr	192	10	1	0	0	1	0	204

22:00	33	0	0	0	0	0	0	33
22:15	35	2	1	0	0	1	0	39
22:30	36	1	1	0	0	0	0	38
22:45	31	3	0	0	0	0	0	34
1 Hr	135	6	2	0	0	1	0	144

22:00	45	3	0	1	0	0	0	49
22:15	39	1	0	0	0	0	0	40
22:30	37	1	0	0	0	0	0	38
22:45	26	2	1	0	0	1	0	30
1 Hr	147	7	1	1	0	1	0	157

23:00	31	1	1	0	0	0	0	33
23:15	32	0	0	0	0	0	1	33
23:30	33	2	0	0	0	0	0	35
23:45	24	2	0	0	0	0	0	26
1 Hr	120	5	1	0	0	0	1	127

23:00	26	2	1	0	0	0	0	29
23:15	44	0	0	0	0	0	0	44
23:30	16	0	0	0	0	0	0	16
23:45	32	1	1	0	0	0	0	34
1 Hr	118	3	2	0	0	0	0	123

6 Hrs	1525	69	10	5	9	12	2	1632
-------	------	----	----	---	---	----	---	------

6 Hrs	1546	85	11	10	12	11	0	1675
-------	------	----	----	----	----	----	---	------

12 Hrs	5604	231	29	21	21	58	12	5976
--------	------	-----	----	----	----	----	----	------

12 Hrs	4487	254	48	24	26	49	2	4890
--------	------	-----	----	----	----	----	---	------

Total	8443	442	121	59	38	75	15	9283
-------	------	-----	-----	----	----	----	----	------

Total	7349	448	124	53	42	68	6	8174
-------	------	-----	-----	----	----	----	---	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Monday 30th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

	Direction : Eastbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	4	2	1	1	0	0	0	8
00:15	8	0	0	0	0	0	0	8
00:30	6	0	1	0	0	0	0	7
00:45	2	0	0	0	0	0	0	2
1 Hr	20	2	2	1	0	0	0	25
01:00	4	0	1	0	0	0	0	5
01:15	0	2	0	0	0	0	0	2
01:30	6	1	1	1	0	0	0	9
01:45	4	0	1	0	0	0	0	5
1 Hr	14	3	3	1	0	0	0	21
02:00	1	0	0	1	0	0	0	2
02:15	4	0	0	0	0	0	0	4
02:30	1	0	0	1	0	0	0	2
02:45	0	0	0	1	0	0	1	2
1 Hr	6	0	0	3	0	0	1	10
03:00	3	0	0	0	0	0	0	3
03:15	2	0	0	0	0	0	0	2
03:30	0	0	1	0	0	0	0	1
03:45	3	0	0	0	1	0	0	4
1 Hr	8	0	1	0	1	0	0	10
04:00	1	0	0	0	0	0	0	1
04:15	3	3	1	0	0	0	0	7
04:30	4	4	3	1	0	0	0	12
04:45	3	0	2	1	0	0	0	6
1 Hr	11	7	6	2	0	0	0	26
05:00	5	3	2	1	0	0	0	11
05:15	5	1	2	0	0	0	0	8
05:30	7	2	1	1	0	0	0	11
05:45	13	5	1	0	0	1	0	20
1 Hr	30	11	6	2	0	1	0	50
6 Hrs	89	23	18	9	1	1	1	142

	Direction : Westbound							Total
	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	
00:00	3	1	1	1	0	0	0	6
00:15	4	1	1	0	0	0	0	6
00:30	2	0	0	0	0	0	0	2
00:45	5	0	0	0	0	0	0	5
1 Hr	14	2	2	1	0	0	0	19
01:00	3	0	0	0	0	0	0	3
01:15	4	1	0	1	0	0	0	6
01:30	1	0	0	0	0	0	0	1
01:45	1	0	0	0	1	0	0	2
1 Hr	9	1	0	1	1	0	0	12
02:00	3	0	0	0	0	0	0	3
02:15	1	0	0	0	0	0	0	1
02:30	2	1	0	0	0	0	0	3
02:45	1	0	0	0	0	0	0	1
1 Hr	7	1	0	0	0	0	0	8
03:00	3	0	0	1	0	0	0	4
03:15	3	1	0	0	0	0	0	4
03:30	2	0	0	1	0	0	0	3
03:45	4	1	1	0	0	0	0	6
1 Hr	12	2	1	2	0	0	0	17
04:00	8	1	0	1	0	0	0	10
04:15	11	0	1	3	0	0	0	15
04:30	3	1	0	6	0	0	0	10
04:45	14	2	2	3	0	0	0	21
1 Hr	36	4	3	13	0	0	0	56
05:00	10	6	1	1	1	1	0	20
05:15	21	4	0	5	0	0	0	30
05:30	30	5	0	5	0	1	1	42
05:45	31	6	2	4	0	1	0	44
1 Hr	92	21	3	15	1	3	1	136
6 Hrs	170	31	9	32	2	3	1	248

	Direction : Eastbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	1	0	0	1
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	1	0	0	1
08:00	0	0	0	0
08:15	0	0	0	0
08:30	0	0	0	0
08:45	0	0	0	0
1 Hr	0	0	0	0
09:00	0	0	0	0
09:15	1	0	0	1
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	1	0	0	1
3 Hr	2	0	0	2
16:00	0	0	0	0
16:15	0	0	0	0
16:30	1	0	0	1
16:45	1	0	0	1
1 Hr	2	0	0	2
17:00	0	0	0	0
17:15	0	0	0	0
17:30	1	0	0	1
17:45	0	0	0	0
1 Hr	1	0	0	1
18:00	1	0	0	1
18:15	0	0	0	0
18:30	0	0	0	0
18:45	2	0	0	2
1 Hr	3	0	0	3
3 Hrs	6	0	0	6
6 Hrs	8	0	0	8

	Direction : Westbound			Total
	Adult	Accompanied Child	Unaccompanied Child	
07:00	0	0	0	0
07:15	0	0	0	0
07:30	0	0	0	0
07:45	0	0	0	0
1 Hr	0	0	0	0
08:00	0	0	0	0
08:15	1	0	0	1
08:30	0	0	0	0
08:45	1	0	0	1
1 Hr	2	0	0	2
09:00	0	0	0	0
09:15	1	0	0	1
09:30	0	0	0	0
09:45	0	0	0	0
1 Hr	1	0	0	1
3 Hr	3	0	0	3
16:00	1	0	0	1
16:15	0	0	0	0
16:30	1	0	0	1
16:45	1	0	0	1
1 Hr	3	0	0	3
17:00	0	0	0	0
17:15	0	0	0	0
17:30	0	0	0	0
17:45	1	0	0	1
1 Hr	1	0	0	1
18:00	1	0	0	1
18:15	0	0	0	0
18:30	0	0	0	0
18:45	0	0	0	0
1 Hr	1	0	0	1
3 Hrs	5	0	0	5
6 Hrs	8	0	0	8



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Monday 30th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

06:00	17	10	6	3	1	1	0	38
06:15	20	10	7	2	2	0	0	41
06:30	43	11	7	1	0	0	0	62
06:45	45	17	11	14	0	0	0	87
1 Hr	125	48	31	20	3	1	0	228

37	7	0	8	0	0	0	52
60	17	1	6	0	1	0	85
64	18	2	4	1	2	1	92
85	19	2	2	0	1	1	110
246	61	5	20	1	4	2	339

07:00	70	23	16	4	1	1	0	115
07:15	67	17	11	3	1	1	0	100
07:30	82	27	10	5	1	1	0	126
07:45	87	31	13	18	1	2	0	152
1 Hr	306	98	50	30	4	5	0	493

104	21	2	7	0	0	1	135
152	35	4	3	1	0	0	195
161	22	4	6	0	6	0	199
136	16	6	1	0	3	0	162
553	94	16	17	1	9	1	691

08:00	81	25	18	2	0	0	0	126
08:15	88	18	16	16	0	2	1	141
08:30	82	26	17	6	0	0	0	131
08:45	88	19	20	3	2	0	0	132
1 Hr	339	88	71	27	2	2	1	530

208	18	10	3	3	2	1	245
154	14	5	3	2	2	2	182
144	15	6	6	1	3	0	175
137	15	10	1	0	2	0	165
643	62	31	13	6	9	3	767

09:00	91	29	10	1	0	0	0	131
09:15	74	22	10	14	1	0	0	121
09:30	80	12	18	5	1	1	1	118
09:45	88	25	14	2	0	1	0	130
1 Hr	333	88	52	22	2	2	1	500

136	15	11	7	2	0	0	171
128	10	6	4	0	1	1	150
156	15	1	6	2	0	2	182
138	15	9	6	2	0	1	171
558	55	27	23	6	1	4	674

10:00	102	23	6	20	3	2	0	156
10:15	126	21	6	2	2	2	0	159
10:30	129	17	10	5	1	2	0	164
10:45	138	9	7	1	1	4	0	160
1 Hr	495	70	29	28	7	10	0	639

132	18	3	7	0	0	0	160
137	18	9	3	1	3	0	171
128	14	3	2	1	1	2	151
149	10	6	6	2	1	0	174
546	60	21	18	4	5	2	656

11:00	133	16	17	3	0	3	1	173
11:15	172	20	9	3	1	1	0	206
11:30	157	11	7	5	2	1	0	183
11:45	164	12	6	6	0	1	0	189
1 Hr	626	59	39	17	3	6	1	751

156	12	9	0	0	0	0	177
142	8	5	6	0	1	2	164
141	18	9	8	1	2	0	179
134	19	9	3	1	1	0	167
573	57	32	17	2	4	2	687

6 Hrs	2224	451	272	144	21	26	3	3141
-------	------	-----	-----	-----	----	----	---	------

3119	389	132	108	20	32	14	3814
------	-----	-----	-----	----	----	----	------

12 Hrs	2313	474	290	153	22	27	4	3283
--------	------	-----	-----	-----	----	----	---	------

3289	420	141	140	22	35	15	4062
------	-----	-----	-----	----	----	----	------



Sky High

Count On Us

Client : Lincolnshire County Council
Project : 9320 / Lincoln By Pass
Site : EW1 - A158 Wragby Road East
Date : Monday 30th June 2014

AM Weather: Mild & Cloudy
PM Weather: Mild & Cloudy

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

12:00	156	11	8	8	1	1	0	185
12:15	126	17	2	7	2	2	1	157
12:30	131	14	4	2	0	1	1	153
12:45	123	12	7	4	1	1	0	148
1 Hr	536	54	21	21	4	5	2	643

12:00	122	13	10	7	1	3	1	157
12:15	102	20	11	4	0	3	0	140
12:30	128	13	9	3	1	0	0	154
12:45	118	14	5	3	0	0	0	140
1 Hr	470	60	35	17	2	6	1	591

13:00	132	13	4	3	0	3	0	155
13:15	131	12	7	2	1	2	0	155
13:30	144	9	3	5	0	0	1	162
13:45	113	11	2	3	1	1	0	131
1 Hr	520	45	16	13	2	6	1	603

13:00	135	13	9	5	0	1	0	163
13:15	134	12	5	6	1	1	0	159
13:30	126	13	14	1	0	1	1	156
13:45	112	12	13	5	1	1	1	145
1 Hr	507	50	41	17	2	4	2	623

14:00	125	14	6	5	1	3	0	154
14:15	121	11	2	6	1	0	1	142
14:30	135	12	6	10	2	2	0	167
14:45	126	8	3	2	2	2	2	145
1 Hr	507	45	17	23	6	7	3	608

14:00	127	27	7	5	0	1	0	167
14:15	115	16	4	7	0	0	1	143
14:30	154	19	5	3	2	0	1	184
14:45	133	22	6	7	1	4	0	173
1 Hr	529	84	22	22	3	5	2	667

15:00	144	14	7	4	0	5	0	174
15:15	136	14	9	4	2	2	1	168
15:30	131	12	4	4	2	1	0	154
15:45	136	18	3	4	0	3	0	164
1 Hr	547	58	23	16	4	11	1	660

15:00	153	14	8	6	1	4	0	186
15:15	121	16	6	6	0	1	0	150
15:30	101	24	3	4	2	1	2	137
15:45	117	22	6	5	2	0	0	152
1 Hr	492	76	23	21	5	6	2	625

16:00	128	10	6	10	0	2	0	156
16:15	150	24	8	2	3	8	3	198
16:30	161	18	5	5	0	2	0	191
16:45	188	22	1	2	0	3	0	216
1 Hr	627	74	20	19	3	15	3	761

16:00	123	28	7	7	1	2	0	168
16:15	131	22	7	4	0	2	0	166
16:30	132	17	4	0	1	2	0	156
16:45	146	26	3	3	2	2	0	182
1 Hr	532	93	21	14	4	8	0	672

17:00	165	20	6	2	1	4	0	198
17:15	152	10	5	4	3	7	0	181
17:30	197	12	3	1	1	9	0	223
17:45	155	11	3	4	0	6	2	181
1 Hr	669	53	17	11	5	26	2	783

17:00	107	17	8	2	2	2	2	140
17:15	116	17	10	4	0	4	1	152
17:30	135	21	6	0	1	4	1	168
17:45	118	22	0	3	0	3	1	147
1 Hr	476	77	24	9	3	13	5	607

6 Hrs	3406	329	114	103	24	70	12	4058
-------	------	-----	-----	-----	----	----	----	------

6 Hrs	3006	440	166	100	19	42	12	3785
-------	------	-----	-----	-----	----	----	----	------

Flowcount

Direction : Eastbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

Direction : Westbound							
Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total

18:00	150	8	2	2	1	5	6	174
18:15	129	6	2	2	0	0	1	140
18:30	116	10	0	1	1	0	2	130
18:45	89	6	2	0	0	2	0	99
1 Hr	484	30	6	5	2	7	9	543

18:00	108	14	2	0	2	2	3	131
18:15	104	13	1	1	1	1	4	125
18:30	99	13	3	5	0	2	0	122
18:45	102	9	4	2	0	3	0	120
1 Hr	413	49	10	8	3	8	7	498

19:00	99	9	2	0	2	2	1	115
19:15	116	6	1	2	0	0	0	125
19:30	93	5	1	1	0	3	1	104
19:45	92	6	0	0	0	2	0	100
1 Hr	400	26	4	3	2	7	2	444

19:00	81	3	2	1	1	4	0	92
19:15	62	9	0	1	1	2	1	76
19:30	66	6	2	3	1	8	0	86
19:45	77	5	1	2	0	1	0	86
1 Hr	286	23	5	7	3	15	1	340

20:00	71	2	3	1	2	1	0	80
20:15	71	3	0	0	0	0	0	74
20:30	60	0	1	0	0	0	0	61
20:45	54	4	0	1	0	0	0	59
1 Hr	256	9	4	2	2	1	0	274

20:00	60	1	0	1	0	4	0	66
20:15	47	2	0	3	0	0	0	52
20:30	43	3	2	0	1	2	1	52
20:45	38	2	0	0	0	2	1	43
1 Hr	188	8	2	4	1	8	2	213

21:00	63	2	1	1	1	1	3	72
21:15	58	3	0	0	0	0	1	62
21:30	43	6	0	1	0	0	0	50
21:45	37	4	1	0	0	1	0	43
1 Hr	201	15	2	2	1	2	4	227

21:00	27	3	1	1	0	1	0	33
21:15	46	2	0	0	0	0	0	48
21:30	33	4	1	0	0	3	0	41
21:45	27	1	0	1	0	1	0	30
1 Hr	133	10	2	2	0	5	0	152

22:00	25	0	0	1	0	0	0	26
22:15	23	0	0	0	0	0	0	23
22:30	22	1	1	1	0	0	0	25
22:45	18	0	0	1	0	0	0	19
1 Hr	88	1	1	3	0	0	0	93

22:00	27	0	1	1	0	0	2	31
22:15	18	0	0	1	0	0	0	19
22:30	11	1	0	1	0	0	0	13
22:45	20	1	0	0	0	0	0	21
1 Hr	76	2	1	3	0	0	2	84

23:00	18	2	0	0	0	0	0	20
23:15	10	1	1	0	0	0	0	12
23:30	17	0	0	1	0	0	0	18
23:45	6	2	0	1	0	0	0	9
1 Hr	51	5	1	2	0	0	0	59

23:00	14	2	0	0	0	0	0	16
23:15	3	0	0	0	0	0	0	3
23:30	4	0	0	0	0	0	0	4
23:45	6	0	0	1	0	0	0	7
1 Hr	27	2	0	1	0	0	0	30

6 Hrs	1480	86	18	17	7	17	15	1640
-------	------	----	----	----	---	----	----	------

6 Hrs	1123	94	20	25	7	36	12	1317
-------	------	----	----	----	---	----	----	------

12 Hrs	4886	415	132	120	31	87	27	5698
--------	------	-----	-----	-----	----	----	----	------

12 Hrs	4129	534	186	125	26	78	24	5102
--------	------	-----	-----	-----	----	----	----	------

Total	7199	889	422	273	53	114	31	8981
-------	------	-----	-----	-----	----	-----	----	------

Total	7418	954	327	265	48	113	39	9164
-------	------	-----	-----	-----	----	-----	----	------



Client : Lincolnshire County Council
 Project : 9320 / Lincoln By Pass
 Site : EW1 - A158 Wragby Road East
 Date : Monday 23rd June - Monday 30th June 2014

Summary of Counts

		Direction : Eastbound							Direction : Westbound								
		Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total
Day 1	Monday 23/06/2014	7377	880	281	271	49	88	20	8966	7318	903	317	261	48	94	21	8962
Day 2	Tuesday 24/06/2014	6237	946	318	243	54	75	28	7901	6361	903	340	239	53	80	24	8000
Day 3	Wednesday 25/06/2014	6833	996	359	228	54	201	19	8690	6650	902	316	249	58	217	15	8407
Day 4	Thursday 26/06/2014	7230	902	375	265	49	90	6	8917	6605	980	315	278	47	92	17	8335
Day 5	Friday 27/06/2014	9591	1015	360	251	53	57	3	11139	7443	946	332	271	61	38	14	8051
Day 6	Saturday 28/06/2014	8443	442	121	59	38	75	15	9193	7349	448	124	53	42	68	6	8090
Day 7	Monday 30/06/2014	7199	889	422	273	53	114	31	8981	7418	954	327	265	48	113	39	9164
		52910	6070	2236	1590	350	700	129	63985	49144	6036	2071	1562	358	702	136	60009

		Direction : Combined Counts							
		Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total
Day 1	Monday 23/06/2014	14695	1783	598	532	97	182	41	17928
Day 2	Tuesday 24/06/2014	12598	1948	658	492	107	155	52	15901
Day 3	Wednesday 25/06/2014	13483	1998	675	477	112	418	34	17097
Day 4	Thursday 26/06/2014	13835	1882	690	543	97	182	23	17252
Day 5	Friday 27/06/2014	17034	1961	692	468	114	95	24	20388
Day 6	Saturday 28/06/2014	15792	890	245	112	80	143	21	17283
Day 7	Monday 30/06/2014	14617	1843	749	538	101	227	70	18145
		102054	12106	4307	3152	708	1402	265	123994

		Direction Eastbound				Direction Westbound			
		Adult	Ac Child	Un Child	Total	Adult	Ac Child	Un Child	Total
		5	0	0	5	5	0	0	5
		6	0	0	6	3	0	0	3
		4	0	0	4	4	0	0	4
		4	0	0	4	3	0	0	3
		3	0	0	3	1	0	0	1
		6	0	0	6	6	0	0	6
		8	0	0	8	8	0	0	8
		36	0	0	36	30	0	0	30

		Direction : Combined Counts			
		Adult	Ac Child	Un Child	Total
		10	0	0	10
		9	0	0	9
		8	0	0	8
		7	0	0	7
		4	0	0	4
		12	0	0	12
		16	0	0	16
		66	0	0	66

Averages

Vehicles

		Direction : Eastbound							Direction : Westbound								
		Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total
Day 1	AM	86.75	21.33	7.25	5.92	0.83	1.00	0.08	123.17	144.50	16.25	5.58	4.75	0.92	1.50	0.83	174.33
	PM	146.08	14.92	2.58	2.75	0.58	1.33	0.67	168.92	115.25	16.92	3.67	3.08	0.92	2.17	0.33	142.33
	00:00-12:00	52.31	9.21	3.54	2.94	0.54	0.54	0.08	69.17	69.83	8.35	3.04	3.19	0.42	0.77	0.33	85.94
	12:00-24:00	101.98	9.13	2.31	2.71	0.48	1.29	0.33	117.63	82.63	10.46	3.58	2.25	0.58	1.19	0.10	109.73
	24 Hrs	76.84	9.17	2.93	2.82	0.51	0.92	0.21	93.40	76.23	9.41	3.20	2.72	0.50	0.98	0.22	93.35

Pedestrians

		Direction Eastbound				Direction Westbound			
		Adult	Ac Child	Un Child	Total	Adult	Ac Child	Un Child	Total
Day 1	AM	0.00	0.00	0.00	0.00	0.33	0.00	0.00	0.33
	PM	0.42	0.00	0.00	0.42	0.08	0.00	0.00	0.08
	6 Hrs	0.21	0.00	0.00	0.21	0.21	0.00	0.00	0.21

		Direction : Eastbound							Direction : Westbound								
		Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total
Day 2	AM	87.17	25.08	10.92	4.58	1.50	0.58	0.42	130.25	139.33	16.00	5.42	4.58	0.92	2.08	0.42	168.75
	PM	130.67	14.58	2.08	2.42	0.67	1.75	0.75	152.92	110.08	19.08	4.83	3.00	1.42	1.08	0.08	139.58
	00:00-12:00	41.04	10.25	4.48	2.50	0.67	0.48	0.19	62.54	56.48	7.60	2.63	2.92	0.38	0.81	0.31	76.08
	12:00-24:00	88.90	9.46	2.15	2.56	0.46	1.06	0.40	105.00	79.04	11.21	4.46	2.27	0.73	0.85	0.19	95.54
	24 Hrs	64.97	9.85	3.31	2.53	0.56	0.78	0.29	83.77	66.26	9.41	3.54	2.49	0.55	0.83	0.25	85.81

		Direction Eastbound				Direction Westbound			
		Adult	Ac Child	Un Child	Total	Adult	Ac Child	Un Child	Total
Day 2	AM	0.17	0.00	0.00	0.17	0.17	0.00	0.00	0.17
	PM	0.33	0.00	0.00	0.33	0.08	0.00	0.00	0.08
	6 Hrs	0.25	0.00	0.00	0.25	0.13	0.00	0.00	0.13

		Direction : Eastbound							Direction : Westbound								
		Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total
Day 3	AM	89.17	23.42	11.08	3.92	1.50	1.08	0.08	130.25	141.25	16.17	6.42	4.25	1.17	1.58	0.50	171.33
	PM	144.50	18.92	2.17	2.75	0.75	9.17	0.92	179.17	117.83	18.33	4.25	3.25	1.67	2.75	0.08	148.17
	00:00-12:00	45.38	8.88	5.10	2.25	0.67	0.73	0.08	66.58	58.42	7.69	3.08	2.92	0.50	0.63	0.21	77.54
	12:00-24:00	96.98	9.46	2.15	2.56	0.46	1.06	0.40	116.98	82.63	10.46	3.58	2.25	0.58	1.19	0.10	109.73
	24 Hrs	71.18	10.38	3.74	2.38	0.56	2.09	0.20	91.78	69.27	9.40	3.29	2.59	0.60	2.26	0.16	89.63

		Direction Eastbound				Direction Westbound			
		Adult	Ac Child	Un Child	Total	Adult	Ac Child	Un Child	Total
Day 3	AM	0.00	0.00	0.00	0.00	0.08	0.00	0.00	0.08
	PM	0.33	0.00	0.00	0.33	0.25	0.00	0.00	0.25
	6 Hrs	0.17	0.00	0.00	0.17	0.17	0.00	0.00	0.17

		Direction : Eastbound							Direction : Westbound								
		Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total
Day 4	AM	91.75	20.33	11.58	4.50	1.17	0.75	0.17	130.25	129.50	19.17	5.92	4.58	0.75	1.25	0.50	161.67
	PM	154.25	15.08	2.42	3.08	0.58	2.17	0.00	177.58	113.42	21.00	3.75	3.17	1.75	1.83	0.25	145.17
	00:00-12:00	46.99	8.79	5.21	2.90	0.58	0.35	0.08	67.59	56.75	8.63	2.73	3.19	0.27	0.69	0.17	76.65
	12:00-24:00	103.67	10.00	2.60	3.63	0.46	1.06	0.40	120.92	82.63	11.10	4.46	2.27	0.73	0.85	0.19	109.73
	24 Hrs	75.31	9.40	3.91	2.76	0.51	0.94	0.06	94.25	68.80	10.21	3.28	2.90	0.50	0.96	0.18	89.94

		Direction Eastbound				Direction Westbound			
		Adult	Ac Child	Un Child	Total	Adult	Ac Child	Un Child	Total
Day 4	AM	0.00	0.00	0.00	0.00	0.08	0.00	0.00	0.08
	PM	0.33	0.00	0.00	0.33	0.17	0.00	0.00	0.17
	6 Hrs	0.17	0.00	0.00	0.17	0.13	0.00	0.00	0.13

		Direction : Eastbound							Direction : Westbound								
		Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total
Day 5	AM	84.58	19.58	10.58	5.00	0.92	0.50	0.08	121.25	138.75	15.67	6.83	4.50	0.92	1.33	0.67	168.67
	PM	220.83	17.17	3.92	2.17	0.92	1.50	0.33	246.83	114.67	15.92	3.67	1.75	1.50	0.17	0.25	137.92
	00:00-12:00	48.75	9.08	4.60	2.88	0.50	0.44	0.06	68.56	66.54	8.21	3.15	2.94	0.40	0.40	0.17	86.10
	12:00-24:00	151.89	14.86	2.90	2.35	0.60	0.75	0.15	169.80	89.52	11.50	3.77	1.58	0.86	0.40	0.13	109.77
	24 Hrs	99.91	10.57	3.75	2.61	0.55	0.59	0.10	119.22	77.53	9.85	3.46	2.26	0.64	0.40	0.15	96.44

		Direction Eastbound				Direction Westbound			
		Adult	Ac Child	Un Child	Total	Adult	Ac Child	Un Child	Total
Day 5	AM	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
	PM	0.25	0.00	0.00	0.25	0.08	0.00	0.00	0.08
	6 Hrs	0.13	0.00	0.00	0.13	0.04	0.00	0.00	0.04

		Direction : Eastbound							Direction : Westbound								
		Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total	Car	Lgv	Ogv1	Ogv2	Psv	M/C	P/C	Total
Day 6	AM	96.83	9.92	3.33	0.58	0.75	0.50	0.00	111.92	107.33	8.42	3.00	1.00	0.83	0.67	0.08	121.33
	PM	153.75	6.25	0.25	0.58	0.67	1.75	0.50	163.75	116.58	5.58	1.08	0.58	0.92	0.67	0.00	125.42
	00:00-12:00	59.15	4.40	1.92	0.79	0.35	0.35	0.06	68.90	59.63	4.04	1.58	0.60	0.33	0.40		




Sky High

Count On Us

Client : Lincolnshire County Council	Site plan for : EW1 - A158 Wragby Road East
Project : 9320 / Lincoln By Pass	Date : Monday 23rd June - Monday 30th June 2014



Unnamed Road



A518 Wragby Road